
Cookiejar development evidence: greater pose availability does not ensure better surface reconstruction
Pose: failures remain in the denominator
Passing frames / all 295 frames (%)
Origin-error threshold (mm)
Original Point2Pose
Correctness fork
BundleTrack
Surface: same post-hoc frame 150, 4 mm grid
Sampled points within 10 mm (%)
47.5
47.5
64.1
76.8
61.8
99.7
Reconstruction → model
Model → reconstruction