
Lab 1 Post - Nick Molo


9.1
A and B are the redundant sensors. C is the low priority sensor, and D is the high priority sensor.

			Α	В	
		00	01	11	10
С	00	0	0	0	0
D	01	1	1	1	1
	11	1	1	1	1
	10	0	1	1	1


Α	В	С	D	F(ABCD)
0	0	0	0	0
0	0	0	1	1
0	0	1	0	0
	0	1	1	1
0	1	0	0	0
0	1	0	1	1
0	1	1	0	1
0	1	1	1	1
1	0	0	0	0
1	0	0	1	1
1	0	1	0	1
1	0	1	1	1
1	1	0	0	0
1	1	0	1	1
1	1	1	0	1
1	1	1	1	1

9.2 Moore Model






9.3.1



9.3.2



9.3.3

