
NOTES

- 1. BREAK ALL SHARP EDGES AND CORNERS.
- 2. VINDICATES FEATURE/DIMENSION TO BE CHECKED AT INCOMING INSPECTION

-2X 5.0 X 45" CHAMFER

[.20]



CLAMP, HINGE, OUTER LID

.×4 0.04

B00.0 .xx.

**** 0.004 0.0020 K4 [.0

x.x. 0.2

E-FE G-10

2

UNIGRAPHICS DZ: 1500 Hatal

