NOTES: 1. BREAK ALL SHARP EDGES R.005 - .015 (OR x 45°) 2. PASSIVATE PER 00-P-35, EXCEPT WAIVE SALT SPRAY TEST.

3. VINDICATES KEY DIMENSIONS TO BE CHECKED AT INCOMING O.C.

	t
R 1.00 R 1.00 R 1.00 R 1.00 R 1.00 R 1.00 R 1.000 R 1.000 R 1.000 R 1.000 R 1.000 R 1.250 R 1.000	#4-40UNC-2B THRU .189 R. FULL Ø .094 THRU BOTH SIDES (.360) (.360) .135 +.005 .000 02 × 45° ALL AROUND Ø .141 THRU (1) WALL
.010 × 45° EDGE BREAK (3X) 1.091 4X R .125 +.020005	2X #10-32UNF-2B . 20 MIN \$\tilde{6}\$ CONDITION NOT BREAK THRUI
SECTION A - A .219	THE PRINTED AND STELLIFICATIONS ARE THE PREPARED TO CONTRIBUTE OF CONTRIBUTION