NOTES

 NOT ALL FEATURES OF THIS PART ARE DIMENSIONED ON THIS DRAWING, REFER TO CAD MODEL FOR FEATURES NOT DIMENSIONED.


2. BREAK ALL SHARP EDGES AND CORNERS.


3. VINDICATES FEATURE/DIMENSION TO BE CHECKED AT INCOMING INSPECTION.

1/4. MATERIAL CERTIFICATION REQUIRED.

REVISION DESCRIPTION BY DATE ECO .

A INITIAL RELEASE, REPLACES 777073-643 KMK 12/1847 BCT021285





A SEE SHT. 2

