

← BACK TO DASHBOARD

RESOLVED

ID: rep-001


Report Resolution

Blueprint

100 Feet Rd, Indiranagar, Ward 3 - Indiranagar & Domlur

Export
PDF

Update
Status



DEVICE ID

Unit-442B

SOURCE CHANNEL

CivicConnect Web Portal

Status Check: Live Sensor Loop Active

ISSUE
CATEGORY

Pothole

AI
CONFIDENCE

1%

RISK
SEVERITY

High

JURISDICTION

Mu

Operations
Timeline

Incident
Submitted

Citizen visual
payload
logged.

AI
Verification
Completed

Vision
diagnostics
scan
confirmed.

Officer
Dispatch

Ticket routed
to municipal
ward desk.

Engineer
Allocated

Preparing document for print/PDF export...

site repairs.



AI MODEL LOGIC & EXPLAINABILITY

VISUAL EVIDENCE

Deep surface depression with surrounding radial asphalt cracking and loose gravel.

SEVERITY REASONING

High risk due to high traffic volume on Indiranagar 100 feet road.

AUTHORITY ASSIGNMENT

Routed to BBMP Roads Department for asphalt resurfacing.

RECOMMENDED ACTIONS

Excavate base layers, fill sub-grade, and roll hot asphalt level.



Inspection Scheduled

Field assessment scheduled.



Repair Operations Active

Crews dispatched with materials.



Repair Logged Complete

Crews reported site repairs finalized.



Resolution Confirmed

Citizen verification accepted.



OPERATIONAL & COST ESTIMATES

REPAIR COST

\$1,200

REQUIRED CREW

4

workers

EST. DURATION

6 h

COMPLEXITY

Medium



AI REPAIR VERIFICATION



Repair fully verified by AI and ticket closed.

MATERIALS CHECKLIST

- Asphalt Cold-Mix
- Sub-base Crushed Stone
- Sealant Coat



AI-Generated Department Action Plan

LOCATION HUD & GEOCODES

Spatial Intelligence Mapped

FORMATTED POSTAL ADDRESS

100 Feet Rd,

- 1

Dispatch field inspector to 100 Feet Rd, Indiranagar within 24 hours.
- 2

Deploy contractor for excavation and base fill.
- 3

Conduct post-repair quality verification.

Indiranagar,
Bengaluru,
Karnataka, 560038,
India

LOCALITY ZONE	ASSIGNED WARD
100 Feet...	Ward 3 ...
CITY DISTRICT	POSTAL CODE
Bengal...	560038

 GPS

12.97190,
Coordinates 77.64120

INCIDENT ENVIRONMENT
CONTEXT

Weather
Conditions

 Optimal grid
humidity, dry
asphalt

Local Traffic
Impact

 Low
congestion
index path

 **Administrative
Notice Draft**

 **Copy
Draft**

To,
The Ward
Officer /
Executive
Engineer,
Municipal
Corporation
Roads
Department,
Ward 3 -
Indiranagar &
Domlur, Civic
Administration.



© 2026 CIVICEYE AI. POWERED BY
GOOGLE AI.

[PRIVACY POLICY](#)

[TERMS OF SERVICE](#)

[SUPPORT](#)

[CONTACT](#)