
Quantum Gates
Reset
Measurement
Classical Control
q_0 |0⟩
q_1 |0⟩
q_2 |0⟩
q_3 |0⟩
X
X
H
H
T
$T^\dagger$
T
$T^\dagger$
|0⟩
If
X
2
c 0
0
1
0x1