

Companion to difftrx (FPP Remote pHAT). Cat5 in on J14; four WS2811 data outputs; twelve fused 12 V outputs. RJ45 pairs (same as difftrx): port1 = 1(+)/2(-), port2 = 3(+)/6(-), port3 = 4(+)/5(-), port4 = 7(+)/8(-).

RJ45 pairs (same as diff tx): port1 = 1(+)/2(-), port2 = 3(+)/6(-), port3 = 4(+)/5(-), port4 = 7(+)/8(-).

Terminal poles are silk marked + / D / - and read left to right in that order on both rows of the board.

