




Vermilion Parish Vicinity Map





		,		AMAZZONA	2 - 14" D/A FLOOD CHATES				
			ļ	+		-	<del>                                      </del>		
				4	100	der =	o.w		
		,	W -	7	1	-	+	1	
	SCALE	u 2	EXISTING 24° PIRES	PROTECT	TON A	EVEE	5.3	4	
	.n		B 24°	1 21	اخرا	1		0,	
	, <del> </del>	\$	PIPES		1		-		
			4 4	500	000		ZNISTING.		
			MSTALLED	SECTIO	1	HEARSH	347.45		
			0	SECTION A-A	Ph.	E/6X			
				4- A	6	0.3.	>	_Z_	-
						3.5			
Pour Lationas 2/24/12	PROM		-	1					
	Sec &								
enflete.	AURORE RANCH  RRONSED REVISION  FLAT GATE GREST WEIR  O SOFT CONSTRUCTION STREET								
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			1					
	E EV								



SCALE. AZ SHOWN

Box 64810-413 24-11

4

## Typical Operational Schedule for Water-Control Structures

F-1 practice: start Sept. 15-year 1

Exterior flap gate closed, Interior stop log bay boarded to achieve at least a 6 inch interior water level.

Oct. Year 1:

Exterior flap gate closed, Interior stop log bay boarded to 6 inches.

Nov. Year 1:

Exterior flap gate closed, Interior stop log bay boarded to 6 inches.

Dec. Year 1:

Exterior flap gate closed, Interior stop log bay boarded to 6 inches.

F-1 practice: end <u>Jan.30</u>

Exterior flap gate operating, slowly remove Interior stop log bay boards to gradually lower interior water levels to a moist soil condition.

FE-5 practice: Start Feb.1 year 2

Exterior flap gate closed, Interior stop log bay boarded to 6 inches.

March. Year 2

Exterior flap gate closed, Interior stop log bay boarded to 6 inches

April. Year 2

Exterior flap gate closed, Interior stop log bay boarded to 6 inches

May. Year 2

Exterior flap gate closed, Interior stop log bay boarded to 6 inches

June. Year 2

Exterior flap gate operating, slowly pull stop logs to begin gradual release of water.

July. Year 2

Exterior flap gate open No stop logs in interior bay

## August Year 2

Exterior flap gate open No stop logs in interior bay

F-1 practice <u>September. Year 2</u>

Exterior flap gate closed, Interior stop log bay boarded to 6 inches.

Structure operation will repeat this sequence until the year 2016.