3/11/2011 Request to leave-in-place Two (2) Chromate-Copper-Arsenate (CCA)-treated wooden piles broken and driven below mud line around Queen Bess Island

Coastal Use Permit Number P20101047

US Army Corps Permit: MVN 2010-1722-EBB


Location of submerged piles stubs to remain in place

The second secon				
				Date Driven
5				deeper
Point			Date	below mud
Number	Lat	Long	Broken	line
Z3#25	29°18'06.74"	89°57'22.70"	2/5/2011	n/a
Z3#12	29°18'28.13"	89°57'38.40"	2/5/2011	2/5/2011

These 2 treated wooden piles, originally 40 feet in length, broke below the mud line during the extraction process on February 5. One broke more than 10 foot below the mud line, the other was driven more than 10 feet below the mud line per the request of regulatory agencies, so as not to pose any future threat to navigation or fisheries in the area. This information is summarized on the attached vicinity map, plan view and cross-sectional view.

Attached plats:

- 1. Queen Bess Vicinity Map
- 2. Queen Bess Pilings Plan View and Cross-sectional representation



Request to leave broken piles Broken Piles that could not be entirely extracted in place, P20101047 Piles that have been removed Pile Locations Pile Status Detail O 52 (D) Deepwater Horizon - 3/11/2011 Island 0 0 Bess Queen Feet

