

54					
reezer Doors – attach door	traceability lab	els he	re		
				PG	250Prep-2-2-25659
EST Electrical Testing	ESTID: JH7302	10			
				PG250Prep	-2-2-A240925659
∪nit 	Serial Number:			:#2 S	erial # Label Here
UEGOF	ED-U240913231				
			inature	comments	
Check Unit model on serial # lab	el matches		/		OA
BOM and Unit transfer label match's BoM.			/_		DASS
Electrical Safety Test to GEN 017		1			FAOC
Passed Signature:	90	/	n	Date:	19/14
			Р	G250Prep-2-2l_	JH7302_25659
RTS Performance Testing	RTS:10 JH7302				
			PG250Prep-	-2-2_JH7302_A	240925659
These functions operate (tick if O	K)	/			
ights Evap Fan	Cond fan	/	PIR Sensor		Door Switches
Sweat Wire Pillar Checks:	Frame		Top Element		Solenoid valve
Test Bay No: 3 Operator:	2 Door Elemen		Failed:		Ambient Temp <sup>0</sup> C 24
Carry out any model specific tests	using correct QRT	form			
RTS Comments:	114				
				-	1 1
Passed Signature:				Date:	13/9/24

## FINAL ASSEMBLY CHECKLIST



## Cab Types PG & PGF Hori

	Checked OK	Comments
Centre pillar cover flush with cabinet	1	
Shelf support strips are level to each other	1	
Panels are clean and free from scratches or damage	/	
Doors are torsioned, aligned & seal. Lock holes align	1	
Drawers glide easily, close, align well and seal	/	
Benchtop (if fitted) firmly secured	/	
No sharp edges on pizza or prep cabinets	/	
Ensure correct unit fitted	/	
Quantity of shelves and clips matches BOM	/	
Ensure castors and shelf runners are secured to shelf	1	
Unit cover closes properly and controller is central in unit cover aperture	/	
Control panel fits neatly and is square to doors	/	

Date:
10/9/24



PRE-FOAM, BUILDING & FOAMING CHECKLIST		Cab BOM Part # TOC Sheet #		JH7302/X10192		
				<u>#24955</u>		
PG250-2 4D S/	S PREP CA	AST/6	#1	- N 2	Comments	Signature
Foamed in Jig # (Circle jig used)	1	2		(3)		T-S
Plug #						
Check the sweat wire "out the bag" (if in the BOM), does not have any cuts or breaks by using a continuity and/or 500V insulation test to QPS 240-013			Reject any failures			
Check the correct jig set-up					RAH	
Check the inside of the jig walls and lid are free from any old build-up, protruding screws, rivets, tape or foam that could affect foaming.					RAY	
<ul> <li>Check all holes are taped over and sweat wire is secure.</li> <li>Earth bonding/anti-static strap fitted to ALL models.</li> </ul>				QPS 240-001 refers	RAY	
Pierce cab back tape to allow air venting (if available)					144	
Foam the Cabinet			Report any issues	RAY		
Check cabinet extern scratches, crashing, of foaming issues for the	dents, and v	oids. Corr		У	Note any repairs	RAY
Remove the tape from a foaming	around the inj	jection hole	ASAP a	after	Easier to remove when warm	RAY
Check castors spin freely and do not foul on plinths/cross members. Check panels for scratches, defects, or blemishes			Report any failures	RAY		
Check foaming plug for any old foam build-up, protruding screws, rivets or damage that could affect foaming			Report any issues	7.5		
Check cabinet once foamed for damage, foam leaks, scratches, dents; correct any build issues for the next build			Record any Paintshop repairs below - Report any damage	T.S		
Recheck sweat wire (if in the BOM), after building by using a continuity and/or 500V insulation test to QPS 240-013			Report any failures; repair to GEN 004	7.5		
Attach this form to the cabinet and send to assembly if all OK			All OK	7-5		
Describe any Paintsho	op repairs c	arried out	<b>:</b>			



Cabinet Assembly Checklist NOTE: Using the diagrams below, identify to	ocation and circle any dam	aged area.		
VER	<b>FICAL &amp; HORIZONT</b>	AL CABINETS		
	COMPONENTS	INITIALS or N/A		
	Pillar secured – rivets	Tajkn		
	Hinges – Top & Bottom	ma		
	Lights	WIRING	INITIALS	or N/A
	DOORS		et top/bottom g is completed	the
	Door configuration	XI-	wires are	7
	Door tensioned	instal	17.05	rtc
BARRO TO THE STATE OF THE STATE	Doors have not	CABINET	-	
	scratches/defects		ternal damage	190
/ Killing	Sliding doors glide	No ex	ternal damage	17
7 7	easily and are square and seal.		/	
	Door sensors			
	OPEN DECK	<u> </u>		
		OMPONENTS	INITIALS or N/A	
	Г	Fit heater wire through		
	- V	black sleeve	1	
		Fit lighting wires		
		Honeycomb		
[ ]	<del></del>	Ducts back and top		
1		Place tyco plug to the heater wire		
		Shelves		
<u>                                   </u>		Night-blind assy		
		PIR sensor		
		Clips on shelf brackets		
		to run lighting wires		
		ABINET	5,000	
11 11 11		No internal damage		
Hermanianananananananananananananananananan		No external damage	25000	
To one messasses in transfer and a series of the series of				
COMMENTS Comment if any iss	sues/fixes are comp	oleted:		
PAINTSHOP Describe any Paint	shop repairs carrie	d out:		

Tue 10/Sep/2024 07:21:06

Booth 13 Test # 215548 UUT: PG250PREP-2-2-A240925659

Operator: 2
Ambient Temperature: 24.5

Test Start Time: 09/Sep/2024 15:17:06 Elapsed Test Time: 1:51:00 Test Status: Test completed - Passed Fault: None

Pulldown Rate Cycle Rise Time Cycle Fall Time Cycle High Temp Cycle Low Temp	Parameter
0.1 5.9 3.9 1.1 -5.1	Min
1.1 10 6 2.7 -2.5	Rec
999 18 8.1 5.4	Max

Tue 10/Sep/2024 07:21:06