

PRE-FOAM, BUILDING & FOAMING CHECKLIST		Cab BOM Part #	SL004/001L-49 #24982		
		TOC Sheet #			
SL.4.GSW LH C	AB ASSY		Comments	Signature	
Foamed in Jig # (Circle jig used)	1	2	3		many
Plug # 7.					
Check the sweat wire "chave any cuts or breaks insulation test to QPS 2	by using a c	Reject any failures			
Check the correct jig se	and the same of the same		RAY		
Check the inside of the build-up, protruding scr affect foaming.			RAY		
Check all holes are tEarth bonding/anti-s		QPS 240-001 refers	RAY		
Pierce cab back tape to	allow air ven		17/		
Foam the Cabinet		Report any issues	RAY		
Check cabinet exterr scratches, crashing, foaming issues for th	dents, and v	Note any repairs	RAY		
Remove the tape from a foaming	Charles of Landson Street, Street	Easier to remove when warm	RAY		
Check castors spin freel members. Check panels		Report any failures	RAY		
Check foaming plug for screws, rivets or damag			Report any issues	Mann	
Check cabinet once foamed for damage, foam le dents; correct any build issues for the next build				Record any Paintshop repairs below - Report any damage	manh
Recheck sweat wire (if in the BOM), after building using a continuity and/or 500V insulation test to				Report any failures; repair to GEN 004	manh
Attach this form to the cabinet and send to asse		embly if all OK	All OK	mann	
Describe any Paintsh	op repairs o	carried out	t:		



OTE: Using the diagrams below, identify I VER	TICAL & HORIZONT		S		
	COMPONENTS	INITIALS or N/A			
	Pillar secured – rivets & screws				
	Hinges – Top & Bottom				
	Lights		WIRING		INITIALS or N/
	DOORS		Cabinet top/bottom wiring is completed Earth wires are		
	Door configuration				
gr vi	Door tensioned		installed		
MIN 2 2 2	Doors have not scratches/defects			CABINET No internal damage	
	Sliding doors glide			No external damage	
Lesses Lesses	easily and are square				
	and seal.				
	Door sensors				
	OPEN DECK	S			
	С	OMPONENTS		INITIALS or	N/A
		Fit heater wire through black sleeve			
		Fit lighting wire	≘s		
		Honeycomb			
::::::::::::::::::::::::::::::::::::::		Ducts – back and top			
		Place tyco plug to the heater wire			
		Shelves			
		Night-blind assy			
		PIR sensor			
		Clips on shelf b	rackets		
		to run lighting wires			
		ABINET			
11 1/1		No internal damage			
тининининининининин		No external damage			
Comment if any iss	sues/fixes are comp	pleted:			
Describe any Paint INTSHOP	shop repairs carrie	d out:			