

Freezer Doors -	- attach doo	r trac	eability lal	oels h	ere				
EST Electrica	l Testing	ES MT138	TID: 1	1		SKT130	(T1300NS	3-A-25891 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
Cassette	e Serial Number:		UTHC	:NI-	0010			al # Label Here	
					ecked OK ignature	Comme	nts		
Check Unit model BOM and Unit tra	Check Unit model on serial # label matches BOM and Unit transfer label match's BoM.				/			QA	
Electrical Safety Test to GEN 017						PASS			
Passed Signat	ure:			_	n	Date:	20	5/9/24	
RTS Perform Testing	ance		RTS:20 T13SZN		SKT13	SKT1300	DNS-AI_M	T13SZN_25891	
These functions of	oerate (tick if C)K)	/			_			
Lights	Evap Fan	/	Cond fan	/	PIR Sensor		[Door Switches	
Sweat Wire	Pillar	//	Frame		Top Element		5	Solenoid valve	
Checks: Test Bay No:	Operator:	7	Door Eleme	nt	Failed:		/	Ambient Temp ⁰ C	9.9
Carry out any mod	lel specific test	s using	correct QRT	form	•				7
RTS Comment	:s:								
Passed Signat	ure:	_	~		-	Date	2	3/9/24	

FINAL ASSEMBLY CHECKLIST



Cab Types SKT, SKB & TME - N & RL (ActiveCore)

(ActiveCore)						
	Checked OK	Comments				
Ensure lights are off when standby/eco mode is activated						
Ensure earth wire is attached to liner top for TME1500N as explained in the QPS						
Motion sensor works properly	/	1				
Centre pillar cover flush with cabinet	/					
Shelf support strips are level to each other	1					
No rivet stems protruding on support strips	(
Panels are clean and free from scratches or damage	/					
Doors are torsioned, aligned & seal. Lock holes align	1	ıt.				
Door magnets fitted in correct location	/					
Door handle pedestals are tight and facing correct way	NA					
Door handles are secured to rear duct or top shelf	NA	4				
Ensure correct unit fitted – ie cassette for 1500 has "B" branding and black condenser coil	1	1				
Quantity of shelves and clips matches BOM	/	*				
Sign/SRP/kickpanel fits neatly and sits square to door and aligned centrally around controller	1					
Uplighting; if fitted is neat and tidy with wires passing through notches in cover, not caught	/					
If fitted for tropical version, heated door traceability labels have been removed from top of door frame and attached to paperwork						
All Above Checks Completed						
Final Inspection Comments:						
Final Quality Check Sign-off Signatur	e:	Date:				
	KWA	23/9/24				



PRE-FOAM, BUILDING & FOAMING CHECKLIST			Cab BOM Part # TOC Sheet #		MT13SZN/W1043			
					<u>#25034</u>			
SKT1300NS-A S	SRP BLAC	K INT/E	XT #	1	Comments	Signature		
Foamed in Jig # (Circle jig used)	1	2		3		ED		
Plug # 2								
Check the sweat wire "out the bag" (if in the BOM), does not have any cuts or breaks by using a continuity and/or 500V insulation test to QPS 240-013					Reject any failures			
Check the correct jig se	t-up							
Check the inside of the jig walls and lid are free from any old build-up, protruding screws, rivets, tape or foam that could affect foaming.						0		
 Check all holes are taped over and sweat wire is secure. Earth bonding/anti-static strap fitted to ALL models. 					QPS 240-001 refers	2		
Pierce cab back tape to	allow air ven	iting (if ava	ilable)			9		
Foam the Cabinet					Report any issues	9		
Check cabinet external for damage, foam leaks, scratches, crashing, dents, and voids. Correct any foaming issues for the next cabinet					Note any repairs	25		
Remove the tape from around the injection hole ASAP after foaming				Easier to remove when warm	25			
Check castors spin freely and do not foul on plinths/cross members. Check panels for scratches, defects, or blemishes			Report any failures	25				
Check foaming plug for screws, rivets or damage	any old foam	n build-up,	protrudin		Report any issues	ED		
Check cabinet once foamed for damage, foam le dents; correct any build issues for the next build			leaks, scr d	atches,	Record any Paintshop repairs below – Report any damage	ED		
Recheck sweat wire (if using a continuity and/				0-013	Report any failures; repair to GEN 004	ED		
Attach this form to the cabinet and send to assembly if all OK			All OK					
using a continuity and/	or 500V insulations or 500	ation test to send to asse	o QPS 24 embly if a		repair to GEN 004			



<u>TE: Using the diagrams below, identify lo</u> VERT	TCAL & HORIZONT		
	COMPONENTS	INITIALS or N/A	
	Diffar secured – rivets	11111	
	& screws	A Dent Con	15
	Hinges – Top & Bottom	AIITALD	
	DOORS	WIRING	INITIALS or let top/bottom
	Door configuration		g is completed
/	Door tensioned	AL E	wires are
0	Doors have not	insta CABINET	led
/ 11/	scratches/defects		ternal damage
1000	Sliding doors glide	No ex	kternal damage
2 2	easily and are square		OP
-	and seal. Door sensors	ZANAS-	(
<u></u>		CAIVE	
	OPEN DECK	S	
	C	OMPONENTS	INITIALS or N/A
		Fit heater wire through	
		black sleeve	
		Fit lighting wires	
	<u> </u>	Honeycomb	
EVER EXPERIENCE OF THE PARTY OF		Ducts – back and top	
		Place tyco plug to the	
FISCESSES		heater wire	-
		Shelves	
1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2		Night-blind assy	
		PIR sensor	
		Clips on shelf brackets	
		to run lighting wires	
	CA	ABINET	
		No internal damage	
		No external damage	
Comment if any issu	ues/fixes are comp	oleted:	
Describe any Paints	hop repairs carried	l out:	

Mon 23/Sep/2024 07:12:59

Booth 4 Test # 215805 UUT: SKT1300NS-A-A240925891

Operator: 2 Ambient Temperature: 24.4

Test Start Time: 20/Sep/2024 14:23:48 Elapsed Test Time: 1:36:00 Test Status: Test completed - Passed Fault: None

Pulldown Rate Cycle Rise Time Cycle Fall Time Cycle High Temp Cycle Low Temp	Parameter
0.3	Min
0.9 14 5 3.9 2.2	Rec
999 25.1 10.1 5.1 3.6	Max