

Freezer Doors - attach door traceability labels here SKB600N-A-25715 **EST Electrical Testing** ESTID: 7 MB60GYN ! Serial # Label Here UBHCNI-0008 Comments Checked OK Signature Check Unit model on serial # label matches BOM and Unit transfer label match's BoM. Electrical Safety Test to GEN 017 Date: **Passed Signature:** SKB600N-AI MB60GYN_25715 **RTS Performance RTS:52 Testing** MB60GYN These functions operate (tick if OK) Door Switches PIR Sensor Cond fan Evap Fan Lights Solenoid valve Top Element Frame Sweat Wire Pillar Checks: Ambient Temp °C Door Element Failed: Operator: Test Bay No: Carry out any model specific tests using correct QRT form **RTS Comments:** Date: **Passed Signature:**

era dos

FINAL ASSEMBLY CHECKLIST



Cab Types SKT, SKB & TME - N & RL

(ActiveCor	e)	V
	Checked Ok	Comments
Ensure lights are off when standby/eco mode is activated		
Ensure earth wire is attached to liner top for TME1500N as explained in the QPS		
Motion sensor works properly	/	
Centre pillar cover flush with cabinet		
Shelf support strips are level to each other	/	
No rivet stems protruding on support strips	1	
Panels are clean and free from scratches or damage	/	
Doors are torsioned, aligned & seal. Lock holes align	/	al.
Door magnets fitted in correct location	1	
Door handle pedestals are tight and facing correct way	/	
Door handles are secured to rear duct or top shelf	/	
Ensure correct unit fitted — ie cassette for 1500 has "B" branding and black condenser coil	(4)	·
Quantity of shelves and clips matches BOM	/	
Sign/SRP/kickpanel fits neatly and sits square to door and aligned centrally around controller	/	
Uplighting; if fitted is neat and tidy with wires passing through notches in cover, not caught	1	
If fitted for tropical version, heated door traceability labels have been removed from top of door frame and attached to paperwork		
All Above Checks Completed		
Final Inspection Comments:		
Final Quality Check Sign-off Signatur	e:	Date:
7	Ktrold	12/9/24



PRE-FOAM, E	BUILDII	NG &	Cab BOM Part #	MB60GYN/WC)491
FOAMING CH	IECKLIS	ST	TOC Sheet	#24977	
SKB600N-A RH	DR NO SI	GN BLAC	CK #2	Comments	Signature
Foamed in Jig # (Circle jig used)	D	2	3		1
Plug #					
Check the sweat wire "chave any cuts or breaks insulation test to QPS 24	by using a co			Reject any failures	
Check the correct jig se					Oh
Check the inside of the build-up, protruding screaffect foaming.					JI
Check all holes are toEarth bonding/anti-s				QPS 240-001 refers	Jn
Pierce cab back tape to	allow air vent	ting (if avai	ilable)		
Foam the Cabinet				Report any issues	
Check cabinet extern scratches, crashing, of foaming issues for the	dents, and v	oids. Corr		Note any repairs	OM
Remove the tape from a foaming	around the inj	ection hole	ASAP after	Easier to remove when warm	JH
Check castors spin freel members. Check panels				Report any failures	JH
Check foaming plug for screws, rivets or damag				Report any issues	e))
Check cabinet once foar dents; correct any build				Record any Paintshop repairs below – Report any damage	3 CD
Recheck sweat wire (if i using a continuity and/c				Report any failures; repair to GEN 004	JH en
Attach this form to the	cabinet and se	end to asse	embly if all OK	All OK	
Describe any Paintsh Scratch	op repairs c <i>O</i> ∽	arried out	estal c		



E: Using the diagrams below, identify location VERTICAL	AL & HORIZONT		S			
COM	MPONENTS	INITIALS or N/A				
	Pillar secured – rivets	sile				
A	& screws	781				
	Hinges - Top & Bottom	1.1	WIRING		Laurence	- 51/6
	Lights	XV		top/bottom	INITIALS	II N/A
	Door configuration	X III	wiring i	s completed	a	yo.
	Door tensioned	TYA	Earth w		del	be
	Doors have not		CABINET	u.	000	
/ / / /	scratches/defects	/ 4"		rnal damage	Ju	5
8000	Sliding doors glide	1	No exte	ernal damage	de	101
¥ ¥ ¥	easily and are square and seal.	1			1	
	Door sensors	Canto				
	OPEN DECK	6				
	29	OMPONENTS	4	MATERIA C	- 80 (0	
	10			INITIALS of	FN/A	
		Fit heater wire black sleeve	through			
	_					
		Fit lighting wir	es			
		Honeycomb		_		
		Ducts – back a				
		Place tyco plug	g to the			
	7 -	heater wire Shelves				
		Night-blind ass	· ·			
	7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	PIR sensor	.,			
	/ h	Clips on shelf t	arackets			
	/ r -	to run lighting				
	C.	ABINET				
11 11 11		No internal da	mage			
		No external da	mage			
Comment if any issues	s/fixes are comp	No external da				
Describe any Paintsho	p repairs carrie	d out:				

Wed 11/Sep/2024 12:48:38

Booth 4 Test # 215603 UUT: SKB600N-A-A240925715

Operator: 2
Ambient Temperature: 23.5

Test Start Time: 11/Sep/2024 11:26:15 Elapsed Test Time: 1:21:00 Test Status: Test completed - Passed Fault: None

 arameter	ault: None
 Min	
 Rec	

٠	000
2.1	566
19	0.7
G	10.1
4.1	6.1
0.1	1.1
	1.9 19 1.9 5 0.9 4.1 -1.6 0.1

