



SCOPE OF WORK
1400 REDMAN BLVD, ST. LOUIS,
MO 63138

TABLE OF CONTENTS
1400 REDMAN BLVD, ST. LOUIS,
MO 63138

Property Details.....	3
Summary Overview	4
Before Pictures	5-9
After Pictures	10-14
Disclaimer	15

PROPERTY DETAILS



Size of Home

Square Footage: 900 sqft

Lot Size: 0.19 Acres

Bedrooms: 3

Bathrooms: 1.5

Year Built

1968

SUMMARY OVERVIEW

- **Exterior**

New Roof; repair / replace rotten wood; repair driveway; paint exterior; paint trim; pressure wash exterior; paint shutters; new exterior light fixtures; new mailbox; trim bushes / other minor landscaping;

- **Interior**

paint ceiling; paint trim; new door knobs; new door hinges; new door stops; new light fixtures; new ceiling fans; new windows; repair windows / glass panes; new window blinds; new smoke detectors; refinish hardwood floors;

- **Bathrooms**

new ceramic tile; new tub surround; refinish tub; new toilet; new vanity; new sink fixtures; new tub fixtures; new vanity mirror;

- **Kitchen**

new ceramic tile; new kitchen cabinets; new countertops; new sink; new faucet; new under sink plumbing; new ventahood; New stove and refrigerator ;

- **Mechanical and Other Items**

major plumbing; new water heater supply lines; new water heater; major electrical work; new receptacles, switches, covers; convert fuses to breakers; new furnace; new condenser;

- **Contractor Overview**

Multiple contractors were needed to complete this project. Licensed contractors are used for electrical, plumbing and HVAC install.

Total Value Improvement Cost: \$ 38,675.29

EXTERIOR (BEFORE)



INTERIOR (BEFORE)



BATHROOMS (BEFORE)



KITCHEN (BEFORE)



MECHANICAL (BEFORE)



EXTERIOR (AFTER)



KITCHEN (AFTER)



BATHROOMS (AFTER)



INTERIOR (AFTER)



MECHANICAL (AFTER)



DISCLAIMER

Age of water heater/HVAC and other property details are available in the home inspection report if and only if home inspection was ordered by buyer at the time of contract.

This document has been provided to buyer as a courtesy by Legacy Invest and has been sent to email address provided by buyer. Legacy Invest has done their best to provide accurate information herein, and cannot be held liable for any accidental errors or omissions.

If Legacy Invest does not hear anything back from buyer within 72 hours of this message being sent, buyer is satisfied with the information and photographs.