

SCOPE OF WORK
6545 JOSEPH AVE, ST. LOUIS, MO 63133



TABLE OF CONTENTS

Property Details..... 3


Summary Overview 4

Before Pictures 5-11

After Pictures 12-18

Disclaimer 19

PROPERTY DETAILS



Size of Home

Square Footage: 1151 sqft

Lot Size: 0.14 Acres

Bedrooms: 3

Bathrooms: 1.5

Year Built

1904

SUMMARY OVERVIEW

Exterior

Repair and paint steps and walkway and rail. Pressure wash and paint the house and garage. Install regular exterior door to garage. Replace the broken window in the basement. Repair front porch. Clean yard and garage. Clean gutters and add extensions. New roof on garage and house.

Interior

Paint Interior. New Window Blinds. New Interior Doors. Doorknobs, hinges and stoppers. New Light Fixtures. New smoke and co2 detectors. Vinyl planks downstairs. Refinish living room and bedroom floors. Added 3rd bedroom.

Bathrooms

Tile both bathrooms and hallway. Refinish tub and surround. 2 new toilets and 2 new vanities.

Kitchen

Tile kitchen floor. Install new cabinets and countertops. All new faucets. New stove, refrigerator, and ventahood.

Mechanical and Other Items

Hot water tank. Washing machine faucets. New receptacles. switches. Plate covers. New furnace. New Condenser. Minor plumbing.

Contractor Overview

Multiple contractors were needed to complete this project. Licensed contractors are used for electrical, plumbing and HVAC install.

Total Value Improvement Cost: \$ 37,680.45

EXTERIOR (BEFORE)




INTERIOR (BEFORE)



BATHROOMS (BEFORE)



BATHROOMS (BEFORE)



KITCHEN (BEFORE)



GARAGE (BEFORE)



MECHANICAL (BEFORE)



EXTERIOR (AFTER)



INTERIOR (AFTER)



BATHROOMS (AFTER)



BATHROOMS (AFTER)




KITCHEN (AFTER)



GARAGE (AFTER)



MECHANICAL (AFTER)



DISCLAIMER

Age of water heater/HVAC and other property details are available in the home inspection report if and only if home inspection was ordered by buyer at the time of contract.

This document has been provided to buyer as a courtesy by Legacy Invest and has been sent to email address provided by buyer. Legacy Invest has done their best to provide accurate information herein, and cannot be held liable for any accidental errors or omissions.

If Legacy Invest does not hear anything back from buyer within 72 hours of this message being sent, buyer is satisfied with the information and photographs.