4.1.10 - Animal Feed / Animal Feed--General

AOAC Official Method 942.05 Ash of Animal Feed

First Action 1942 Final Action

Weigh 2 g test portion into porcelain crucible and place in temperature controlled furnace preheated to 600°C. Hold at this temperature 2 h. Transfer crucible directly to desiccator, cool, and weigh immediately, reporting percent ash to first decimal place.

References:

JAOAC 25, 857(1942); 26, 220(1943).

© 2002 AOAC INTERNATIONAL