AOAC Official Method 945.46 Ash of Milk

Gravimetric Method First Action 1945 Final Action

Into suitable Pt dish weigh ca 5 g prepared test portion, <u>925.21</u> (*see* 33.2.02), and evaporate to dryness on steam bath. Ignite in furnace at 550°C until ash is C-free. Cool in desiccator, weigh, and calculate % ash.

References:

JAOAC 23, 453(1940); 28, 211(1945); 34, 239(1951).