HP LaserJet Pro M404dn Service Manual

Edition 1, 03/2023

Product Family: LaserJet Pro M400 Series

Models: M404n, M404dn, M404dw

Error Codes:

• 13.01 - Paper jam in input tray

• 49.XX.YY - Critical firmware error

• 59.XY - Motor error

Part Numbers:

- CF258A Black toner cartridge
- RM2-5582 Fuser assembly
- RM2-5583 Transfer roller

Technical Specifications

Print Speed: Up to 38 ppm (A4), 40 ppm (Letter)

First Page Out: As fast as 7.3 seconds

Monthly Duty Cycle: Up to 80,000 pages

Memory: 256 MB (standard)

Common Error Resolution:

1. Check paper path for obstructions

2. Verify toner cartridge installation

3. Clean transfer path components

4. Update firmware to latest version

Version Information:

• Firmware Version: 2404.001.00.004

• Document Version: v2.1

• Last Updated: March 2023