



Engineering Bulletin Volume 1-3

By National Lumber Bureau

RareBooksClub. Paperback. Book Condition: New. This item is printed on demand. Paperback. 62 pages. Dimensions: 9.7in. x 7.4in. x 0.1in. This historic book may have numerous typos and missing text. Purchasers can usually download a free scanned copy of the original book (without typos) from the publisher. Not indexed. Not illustrated. 1916 edition. Excerpt: . . . a laminated floor. Each of these floors is covered with two or more thicknesses of waterproof paper or similar material and then by a top, or wearing floor laid at right angles to the direction of the Where plank floors are laid flat, the boards should be two bays in length if possible and laid to break joints every 4 feet. With laminated floors, it may be difficult to obtain plank two bays in length. A strong and stiff floor will result if the planks underfloor. Material is surfaced on all sides and edges of plank beveled to serve as a finish on the ceiling below. are laid with the ends extending between centers of girders with one plank laid across the girder at frequent intervals (every sixth or eighth piece) to act as a tie in the floor. Or, by another method, the...



Reviews

This pdf may be worth purchasing. This is for anyone who statte there was not a really worth reading. I found out this pdf from my i and dad encouraged this pdf to understand.

-- Mrs. Annamae Raynor

If you need to adding benefit, a must buy book. This really is for all who statte that there had not been a well worth reading. It is extremely difficult to leave it before concluding, once you begin to read the book.

-- Claud Bernhard