

February 27, 2020

American Family Mutual Insurance Company, S.I.

Claim Scanning Center 6000 American Parkway Madison, WI 53783-0001

Phone: 1-866-881-4318 Fax: 1-866-774-4561

\$23,471.90

Email: catfax11@amfam.com

EFRAINS INCORPORATED & GOMEZ, JORGE

& GRACIELA, GARCIA 101 E CLEVELAND ST LAFAYETTE, CO 80026 Claim Number: 00225274580 Date of Loss: 7/5/2019

The attached estimate of damages has been prepared for your property. The estimate has used common prices for labor and material from your area.

Enclosed is our draft for the actual cash value of your damaged property. For Dwelling and Structure damages, we may have included your mortgage company on the draft as required by your policy.

Summary For Building Limit

Replacement Cost Value	Less Recoverable Depreciation	Less Non Recoverable Depreciation	Actual Cash Value (ACV)
\$53,959.28	(\$14,560.26)		\$39,399.02
Less Deductible			(\$500.00)
Total ACV Settlement			\$38,899.02
Less ACV Payments Mac	de		(\$15,427.12)
Total Outstanding ACV So	ettlement		\$23,471.90

Summary For Code Upgrade

Replacement Cost Value	Paid When Incurred	Less Non Recoverable Depreciation	Actual Cash Value (ACV)
\$965.94	(\$965.94)		\$0.00
Total ACV Settlement			\$0.00

See the enclosed estimate for details of your settlement which may include other itemized details not shown above.

Depending on the type of policy listed below, if an amount is shown in the Recoverable Depreciation column, you may make a claim under the Replacement Cost provisions of the policy by:

Commercial Policies:

Total Outstanding ACV Settlement (All Coverages)

- 1. Replacing or Repairing the damaged items as soon as reasonably possible.
- 2. You must submit a final bill or purchase receipt showing the item(s) has been repaired or replaced.

Farm/Ranch Policies:

1. You must have the item(s) replaced or repaired within one year from your date of loss. *Exception: For Washington



policies ONLY - Please refer to your policy language as well as the section of this estimate titled Claiming Recoverable Depreciation following the Estimate Recap or Coverage Limit Details sections.

2. You must submit a final repair bill or purchase receipt showing the item(s) has been repaired or replaced.

Some items may not be eligible for Replacement Cost coverage. Dependent on your type of policy, other conditions may also apply. Please refer to your policy under either Valuation of Covered Property or Optional Coverages; Replacement Cost. For Farm/Ranch policies, please refer to the specific Dwelling Form and/or Farm Outbuilding Replacement Cost Coverage Endorsement, if applicable.

The attached estimate is what we expect to be the reasonable cost to repair or replace the property. This estimate may not include permit fees. If total charges for repair/replacement plus permits exceed the amount shown here for that repair/replacement, prior to any deductible, then additional amounts may be payable. If the actual cost is more or less, the final payment will be adjusted accordingly. If you wish, you may repair or replace with higher quality items, however, you will be responsible for any increase in cost.

Please present this estimate to a contractor or repair facility of your choice BEFORE you authorize the start of repairs. We will not accept any supplements for damage unless they have had prior approval by a representative of American Family Insurance. If you, your contractor, or repair facility have any questions, please contact us at (608) 852-5242.

American Family Insurance appreciates your business.

Thank You, Jehanna Vann National Field Team



Insured: EFRAINS INCORPORATED & GOMEZ, JORGE

& GRACIELA, GARCIA 101 E CLEVELAND ST LAFAYETTE, CO 80026

Claim Rep.: Jehanna Vann Estimator: Jehanna Vann

Claim Number: 00225274580 Policy Number: 05XG974003 Type of Loss: Hail

Coverage	Deductible	Policy Limit
Building Limit	\$500.00	\$770,254.00
Code Upgrade	\$0.00	\$10,000.00

Date Contacted: 7/31/2019 3:00 PM

Date of Loss: 7/5/2019 12:00 PM
Date Est. Completed: 8/14/2019 10:22 PM

Price List: COBO8X_FEB20_1

Restoration/Service/Remodel

Sales Taxes: Material Sales Tax @ 8.150%

Manuf. Home Tax @ 8.150% Storage Rental Tax @ 8.150% Local Food Tax @ 5.250%

Overhead: 8.0% Profit: 8.0% Phone: (303) 912-6871



Estimate Recap For Building Limit

Description	RCV	Recoverable Depreciation	Non-recoverable Depreciation	ACV
Building - Exterior - Roofing - Building	32,276.33	11,942.23	0.00	20,334.10
Building - Exterior - Gutters/Downspouts	3,522.16	1,543.18	0.00	1,978.98
Building - Exterior - Windows	667.54	123.93	0.00	543.61
Building - Exterior - Painting/Staining	1,805.36	950.92	0.00	854.44
Building - Exterior - Screens	435.18	0.00	0.00	435.18
Building - Exterior - Awnings	14,998.72	0.00	0.00	14,998.72
Building - Exterior - AC/Electrical Repair	253.99	0.00	0.00	253.99
	53,959.28	14,560.26	0.00	39,399.02

Estimate Recap For Code Upgrade

Description	RCV	Recoverable Depreciation	Non-recoverable Depreciation	ACV
Building - Exterior - Roofing - Building	965,94	965.94	0.00	0.00
	965.94	965.94	0.00	0.00

IMPORTANT - Please read the definitions below

What is replacement cost (RCV)?

Replacement cost is the cost to repair the damaged item with an item of like kind and quality, without deduction for depreciation.

What is depreciation?

Depreciation is the amount deducted from the replacement cost based upon the age and condition of the item being replaced.

What is actual cash value (ACV)?

Actual cash value is based on the cost to repair or replace the damaged item with an item of like kind and quality, **less depreciation**.

The Actual Cash Value (ACV) is based on an items: **Age divided by normal Useful life**, unless otherwise





noted. Deviation from Age divided by normal Useful life is common due to inspection evaluation, condition of the item, obsolescence, product research, expert opinions, utility/functional value, market value and in some cases all or some of the above. For further information on ACV and the depreciation applied, please contact your claim representative.

Physical mail you submit: American Family Insurance appreciates your assistance in the handling of your claim. Any documentation you submit will be scanned and electronically retained in your claim file. Please include the claim number on the items submitted. The original documentation will be destroyed after 30 days. If you would like your documents returned, please indicate this on the documents and provide the address to which you would like the documents returned.

E-mail: Our goal is to provide outstanding customer service. If you choose to use e-mail to communicate with us regarding your claim, please be sure to include your name and claim number on the subject line. Please forward any e-mail correspondence regarding your claim to the e-mail address listed below. Thank you for being our customer.

E-mail: jvann@amfam.com

It is unlawful to knowingly provide false, incomplete, or misleading facts or information to an insurance company for the purpose of defrauding or attempting to defraud the company. Penalties may include imprisonment, fines, denial of insurance and civil damages. Any insurance company or agent of an insurance company who knowingly provides false, incomplete, or misleading facts or information to a policyholder or claimant for the purpose of defrauding or attempting to defraud the policyholder or claimant with regard to a settlement or award payable for insurance proceeds shall be reported to the Colorado Division of Insurance within the Department of Regulatory Agencies.



EFRAINS_INCORPORATED

Building

Exterior

Roofing

Building

d includes a se of comp. 46.73 SQ se of modific	s based on our iny/all necessar shingles - Lami \$58.03 ed bitumen roof \$45.61 hingle rfg w/or \$111.32	ry hip/ridge cap, sonated \$433.88 fing \$8.84 ut felt \$1,035.18	r roof, its age	of 10 years, condit d normal installati \$3,145.62 \$64.03 \$7,505.08	ion, and useful life. ion waste\$1,163.88 (37%) -\$23.70 (37%)	\$1,981.7 \$40.3 \$4,728.1
d includes a se of comp. se of modifice 1.21 SQ d - comp. sh 53.74 SQ bitumen roce 1.21 SQ	s based on our inny/all necessar shingles - Lami \$58.03 ed bitumen roof \$45.61 hingle rfg w/or \$111.32	inspection of you ry hip/ridge cap, s nated \$433.88 fing \$8.84 ut felt \$1,035.18	r roof, its age of starter row and \$0.00	\$3,145.62 \$64.03	-\$1,163.88 (37%) -\$23.70 (37%)	\$40.3
se of comp. 1 46.73 SQ se of modific 1.21 SQ d - comp. sh 53.74 SQ bitumen roc 1.21 SQ	shingles - Lami \$58.03 ed bitumen roof \$45.61 ningle rfg w/or \$111.32	\$433.88 fing \$8.84 ut felt \$1,035.18	\$0.00 \$0.00	\$3,145.62 \$64.03	-\$1,163.88 (37%) -\$23.70 (37%)	\$40.3
46.73 SQ se of modified 1.21 SQ d - comp. sh 53.74 SQ bitumen rocc 1.21 SQ	\$58.03 ed bitumen roof \$45.61 hingle rfg w/or \$111.32	\$433.88 fing \$8.84 ut felt \$1,035.18	\$0.00	\$64.03	-\$23.70 (37%)	\$40.3
se of modified 1.21 SQ d - comp. sh 53.74 SQ bitumen rocc 1.21 SQ	ed bitumen roof \$45.61 ningle rfg w/or \$111.32	\$8.84 ut felt \$1,035.18	\$0.00	\$64.03	-\$23.70 (37%)	\$40.3
1.21 SQ d - comp. sh 53.74 SQ bitumen roc 1.21 SQ	\$45.61 ningle rfg w/or \$111.32	\$8.84 ut felt \$1,035.18				
d - comp. sh 53.74 SQ bitumen roc 1.21 SQ	ningle rfg w/or \$111.32	ut felt \$1,035.18				
53.74 SQ bitumen roc 1.21 SQ	\$111.32	\$1,035.18	\$487.56	\$7,505.08	-\$2,776.89 (37%)	\$4,728.1
bitumen roc 1.21 SQ	of		\$487.56	\$7,505.08	-\$2,776.89 (37%)	\$4,728.1
1.21 SQ						
1.21 SQ						
tumen roof		\$20.44	\$9.63	\$148.20	-\$54.83 (37%)	\$93.3
1.21 SQ	\$297.33	\$57.56	\$0.00	\$417.33	-\$154.41 (37%)	\$262.9
- comp. shin	gle rfg w/out	felt				
53.74 SQ	\$150.94	\$1,297.84	\$0.00	\$9,409.36	-\$3,481.46 (37%)	\$5,927.9
ge for steep	roof - 7/12 to 9	0/12 slope				
11.10 SQ	\$12.52	\$22.24	\$0.00	\$161.21	-\$59.64 (37%)	\$101.5
ge for steep	roof - 7/12 to 9	/12 slope				
11.10 SQ	\$55.82	\$99.14	\$0.00	\$718.74	-\$265.93 (37%)	\$452.8
512.16 LF	\$2.73	\$228.66	\$30.89	\$1,657.75	-\$613.36 (37%)	\$1,044.3
/C/TPO clac	d metal					
18.27 LF	\$4.51	\$13.94	\$4.81	\$101.15	-\$37.43 (37%)	\$63.7
15 lb.						
33.37 SQ	\$37.22	\$201.12	\$15.01	\$1,458.16	-\$539.52 (37%)	\$918.6
	, JORGE	0022527	4580		2/27/2020	Pag
7	11.10 SQ 12.16 LF 7C/TPO clac 18.27 LF 15 lb. 33.37 SQ	11.10 SQ \$55.82 12.16 LF \$2.73 C/TPO clad metal 18.27 LF \$4.51	\$228.66 C/TPO clad metal 18.27 LF \$4.51 \$13.94 15 lb. 33.37 SQ \$37.22 \$201.12	11.10 SQ \$55.82 \$99.14 \$0.00 12.16 LF \$2.73 \$228.66 \$30.89 C/TPO clad metal 18.27 LF \$4.51 \$13.94 \$4.81 15 lb. 33.37 SQ \$37.22 \$201.12 \$15.01	11.10 SQ \$55.82 \$99.14 \$0.00 \$718.74 12.16 LF \$2.73 \$228.66 \$30.89 \$1,657.75 C/TPO clad metal 18.27 LF \$4.51 \$13.94 \$4.81 \$101.15 15 lb. 33.37 SQ \$37.22 \$201.12 \$15.01 \$1,458.16	11.10 SQ \$55.82 \$99.14 \$0.00 \$718.74 -\$265.93 (37%) 12.16 LF \$2.73 \$228.66 \$30.89 \$1,657.75 -\$613.36 (37%) (C/TPO clad metal 18.27 LF \$4.51 \$13.94 \$4.81 \$101.15 -\$37.43 (37%) 15 lb. 33.37 SQ \$37.22 \$201.12 \$15.01 \$1,458.16 -\$539.52 (37%)

Building continued...

Description Qty	Unit Price	Overhead & Profit		Replacement	Less	Actual Cash
		Tront	Taxes	Cost Total	Depreciation	Value
12. Replace Roofing felt - 15 lb	_	_				
13.36 S	Q \$65.46	\$141.66	\$10.88	\$1,027.09	-\$380.03 (37%)	\$647.06
13. Replace Flashing - pipe jack						
6.00 E	A \$49.47	\$48.26	\$4.69	\$349.77	-\$129.42 (37%)	\$220.35
14. Prime & paint roof jack						
8.00 E	A \$28.46	\$37.16	\$4.61	\$269.45	-\$99.69 (37%)	\$169.76
15. Replace Exhaust cap - through	roof - up to 4"					
1.00 E	•	\$14.52	\$2.04	\$105.35	-\$38.98 (37%)	\$66.37
16. Prime & paint roof vent						
11.00 E	A \$28.46	\$51.10	\$6.34	\$370.50	-\$137.08 (37%)	\$233.42
17. Replace Roof vent - turtle type	- Metal					
4.00 E	A \$68.17	\$44.40	\$4.89	\$321.97	-\$119.12 (37%)	\$202.85
18. Replace Exhaust cap - through	roof - 6" to 8"					
4.00 E	A \$96.79	\$63.66	\$10.76	\$461.58	-\$170.79 (37%)	\$290.79
19a. Remove Furnace vent - rain c	ap and storm colla	r, 6"				
1.00 E	A \$9.60	\$1.54	\$0.00	\$11.14	-\$4.11 (37%)	\$7.03
19b. Replace Furnace vent - rain ca	ap and storm colla	r, 6"				
1.00 E	A \$75.45	\$12.44	\$2.24	\$90.13	-\$33.35 (37%)	\$56.78
20. Replace Flashing - pipe jack - s	split boot					
1.00 E	A \$83.47	\$13.88	\$3.19	\$100.54	-\$37.20 (37%)	\$63.34
21. Replace Roofer - per hour						
1.00 H	R \$171.03	\$27.36	\$0.00	\$198.39	-\$73.40 (37%)	\$124.99
ALLOWANCE TO MANIPULA	TE SHINGLES	AROUND SWAM	P COOLER A	AND AC UNIT.		
22. Replace Flashing - rain diverte	r					
1.00 E	A \$46.78	\$7.60	\$0.80	\$55.18	-\$20.43 (37%)	\$34.75
The following line items added to	facilitate roof repla	acement				
41. Replace Valley metal						
					\$454.05 (QEQ)	ф 77 4 С4
166.25 I	F \$6.23	\$169.60	\$24.25	\$1,229.59	-\$454.95 (37%)	\$774.64



T	• • •	1.	4.	
К	1111	aıng	continu	1ea

Description	Qty	Unit Price	Overhead & Profit	Taxes	Replacement Cost Total	Less Depreciation	Actual Cash Value
42. Replace Ridge cap	o - composition s	shingles					
	164.42 LF	\$4.98	\$133.46	\$15.41	\$967.68	-\$358.04 (37%)	\$609.64
43. Replace Step flash	ning						
	131.24 LF	\$11.45	\$242.76	\$14.55	\$1,760.01	-\$651.20 (37%)	\$1,108.81
44. Replace Flashing	- L flashing - co	lor finish					
	29.50 LF	\$4.87	\$23.62	\$4.04	\$171.33	-\$63.39 (37%)	\$107.94
The following line ite	m accounts for a	dditional ventil	ation per the City	of Lafayette CO	O code requirement		
55. PWI Replace Roo	f vent - turtle ty _l	oe - Metal					
	12.00 EA	\$68.17	\$133.22	\$14.68	\$965.94	-\$965.94	\$0.00
The payment for this	item has not yet	been incurred.					
Totals			\$4,585.08	\$671.27	\$33,242.27	-\$12,908.17	\$20,334.10
			Gutters/Dov	vnspouts			
Description	Qty	Unit Price	Overhead & Profit	Taxes	Replacement Cost Total	Less Depreciation	Actual Cash Value

The following line items account for the replacement of the gutters on all eave edges.

Left: 12 L/F Downspout. Back: 12 L/F Downspout.

Includes: Gutter or downspout, fittings, silicone caulk and installation labor. Aluminum gutter up to 5" with or without baked on enamel finish Note: May be seamless

ls			\$485.78	\$90.02	\$3,522.16	-\$1,543.18	\$1,978.
	324.00 LF	\$1.32	\$69.48	\$6.60	\$503.76	-\$335.84 (10/15yr)	\$167
45. Prime & paint gut	ter / downspout						
The following line ite	m accounts for pain	ting to gutter s	ystem. Adjuster p	hotos reflect th	e existing gutters	s are painted	
	24.00 LF	\$9.59	\$38.54	\$10.80	\$279.50	-\$111.80 (10/25yr)	\$167.
24b. Replace Gutter /	downspout - alumii	num - 6"					
	24.00 LF	\$0.45	\$1.72	\$0.00	\$12.52	-\$5.00 (10/25yr)	\$7.
24a. Remove Gutter /	downspout - alumi	num - 6"					
	324.00 LF	\$6.58	\$352.72	\$72.62	\$2,557.26	-\$1,022.90 (10/25yr)	\$1,534.
23b. Replace Gutter /	downspout - alumin	num - up to 5"					
	324.00 LF	\$0.45	\$23.32	\$0.00	\$169.12	-\$67.64 (10/25yr)	\$101.
				+0.00	****		



Windows

Description	Qty	Unit Price	Overhead & Profit	Taxes	Replacement Cost Total	Less Depreciation	Actual Cash Value
The following line it	tem(s) accounts f	or the replace	ment of the dama	ged window(s)	on the BACK ele	vation(s).	
Back elevation: 1	[
25a. Remove Vinyl v	vindow, single hu	ng, 4-8 sf					
	1.00 EA	\$20.22	\$3.24	\$0.00	\$23.46	-\$7.82 (10/30yr)	\$15.64
25b. Replace Vinyl w	vindow, single hu	ng, 4-8 sf					
	1.00 EA	\$205.78	\$34.84	\$11.96	\$252.58	-\$84.20 (10/30yr)	\$168.33
26. Replace Addition	al charge for a re	trofit window,	3-11 sf				
	1.00 EA	\$81.69	\$13.22	\$0.83	\$95.74	-\$31.91 (10/30yr)	\$63.8
The following line it	tem is to account	for the replac	ement of the glazi	ing bead whicl	ı was damaged by	hail.	
27a. Remove Glazing	g bead - Vinyl						
	40.00 LF	\$0.30	\$1.92	\$0.00	\$13.92	-\$0.00	\$13.92
27b. Replace Glazing	g bead - Vinyl						
	40.00 LF	\$2.61	\$17.76	\$6.62	\$128.78	-\$0.00	\$128.7
28. Haul debris - per	pickup truck load	l - including du	mp fees				
1	1.00 EA	\$131.94	\$21.12	\$0.00	\$153.06	-\$0.00	\$153.0
tals			\$92.10	\$19.41	\$667.54	-\$123.93	\$543.6
			Painting/S	taining			
Description	Qty	Unit Price	Overhead & Profit	Taxes	Replacement Cost Total	Less Depreciation	Actual Cas Value
						•	
The following line ite	ems account for p	aint repairs for	damage to the rear	elevation base	ed on photo docume	ntation provided by C J	Restoration.
Depreciation for pain			age of 10 years, a	verage condition	on for a life expecta	ncy of 15 years	
46. Clean with pressu	738.88 SF	y \$0.36	\$42.66	\$0.60	\$309.26	-\$0.00 (10/0yr)	\$309.2
	/30.00 3F	\$0.50	\$42.00	\$0.00	\$309.20	-\$0.00 (10/0y1)	\$309.2
49. Clean fascia							
15. Cican rascia	81.20 LF	\$0.74	\$9.62	\$0.00	\$69.71	-\$0.00 (10/0yr)	\$69.7
	01.20 E1	φο., τ	Ψ3.02	φο.σσ	Ψ0.71	φο.σο (1σ/σ <i>j</i> 1)	φοσ.,
50. Seal & paint woo	d siding						
	738.88 SF	\$1.12	\$136.26	\$24.10	\$987.91	-\$658.60 (10/15yr)	\$329.3
51. Prime & paint ex	tarior fascia - woo	od 4" 6" wide					
51. 1 mile & paint ex	81.20 LF	\$1.34	\$17.56	\$1.06	\$127.43	-\$84.95 (10/15yr)	\$42.4
	81.2U LF	\$1.54	\$17.30	\$1.00	\$127.43	-p04.93 (1U/13yt)	\$42.4
52. Seal & paint trim	- two coats						
INS INCORPORAT	ED & GOMEZ	, JORGE	0022527	4580		2/27/2020	Page
INS INCORPORAT ACIELA, GARCIA	ED & GOMEZ	, JORGE	0022527	4580		2/27/2020	Pag

Painting/Staining co	ontinued
----------------------	----------

		ŀ	'ainting/Staining	g continued	•		
Description	Qty	Unit Price	Overhead & Profit	Taxes	Replacement Cost Total	Less Depreciation	Actual Cash Value
	36.00 LF	\$1.13	\$6.56	\$0.32	\$47.56	-\$31.71 (10/15yr)	\$15.85
53. Paint door or windo	ow opening - 1	coat (per side)					
	10.00 EA	\$16.72	\$27.16	\$2.45	\$196.81	-\$131.20 (10/15yr)	\$65.61
54. Painter - per hour							
	1.00 HR	\$57.48	\$9.20	\$0.00	\$66.68	-\$44.46 (10/15yr)	\$22.22
otals			\$249.02	\$28.53	\$1,805.36	-\$950.92	\$854.44
			Scree	ns			
Description	Qty	Unit Price	Overhead & Profit	Taxes	Replacement Cost Total	Less Depreciation	Actual Cash Value
The following line iter	n(s) accounts	for the repair (of the damaged sc	reens.			
Back 9		-	Ü				
No depreciation appl	ied as this is a	repair only.					
29. Replace Window so	creen, 1 - 9 SF						
	9.00 EA	\$38.84	\$60.02	\$25.60	\$435.18	-\$0.00	\$435.18
Totals			\$60.02	\$25.60	\$435.18	-\$0.00	\$435.18
			Awnir	ıgs			
Description	Qty	Unit Price	Overhead & Profit	Taxes	Replacement Cost Total	Less Depreciation	Actual Cash Value
37a. Remove Patio Co	ver - Attached -	- Canvas (fixed)) - High grade				
	264.00 SF	\$0.45	\$19.00	\$0.00	\$137.80	-\$0.00	\$137.80
37b. Replace Patio Cov	ver - Attached -	Canvas (fixed)	- High grade				
	264.00 SF	\$19.62	\$887.54	\$367.49	\$6,434.71	-\$0.00	\$6,434.71
40a. Remove Awning -	- Window/door	- Canvas (fixed	1)				
	37.00 LF	\$0.81	\$4.80	\$0.00	\$34.77	-\$0.00	\$34.77
40b. Replace Awning -	Window/door	- Canvas (fixed	1)				
	37.00 LF	\$186.63	\$1,157.44	\$328.69	\$8,391.44	-\$0.00	\$8,391.44
otals			\$2,068.78	\$696.18	\$14,998.72	-\$0.00	\$14,998.72
			AC/Electrica	al Repair			
Description	Qty	Unit P	Overhe Price Prof		olacement ost Total	Less Depreciation	Actual Cash Value
AINS INCORPORATE	 D & GOME7	JORGE	0022527	4580		2/27/2020	Page: 1



AC/Electrical Repair continued...

Description	Qty	Unit Price	Overhead & Profit	Replacement Cost Total	Less Depreciation	Actual Cash Value
The following line item	n(s) accounts for the	e repair of the hail	il damaged AC uni	t fins.		
No depreciation appli	ed as this is a repair	r only.				
30. Replace Comb and s	straighten a/c conden	nser fins - with trip	charge			
	1.00 EA	\$218.95	\$35.04	\$253.99	-\$0.00	\$253.99
Totals			\$35.04	\$253.99	-\$0.00	\$253.99
		Overhe Prof		Replacement Cost Total	Less Depreciation	Actual Cash Value
Estimate Totals		\$7.5	575.82 \$1,53	1.01 \$54,925.22	-\$15,526.20	\$39,399.02

If the section above is titled "Labor Minimums Applied," additional amounts may have been added to your estimate.

These additional amounts are designed to accommodate a contractor's minimum fee for coming to your property and completing all or part of the repairs included in this estimate. In situations where an average contractor's minimum fee has been met or exceeded in the scope of repairs in the above estimate, the "Labor Minimums Applied" section may not be present.