6/22/16

Allie Hexley

Today's Progress...

- Cut all layers on laser cutter
- Loaded flies
- Vent holes and loading hole was too large. Reduce in size by ¼ and ½ respectively
- Redid design with smaller vent holes, and more screw holes, and reduced size of top layer for easier loading

To work on tomorrow...

- Convert AutoCAD drawings to SolidWorks parts for laser cutter
- Recut with smaller vents and loading holes and add more screw holes for tighter seal
- Go to machine shop to get optical railing cut to size for insertion mechanism
- Play with camera