7/12/16

Allie Hexley

Today's Progress...

- Holes tapped for PCB board
- Lighting issue resolved (sort of) but LEDs need to be close to the chamber, is this a problem?

To work on tomorrow...

- Tap holes into frame for chamber loading
- Secure frame structure with LEDs in place and tape foamboard around edge to see if it keeps light out
- Ensure you can reconstruct flies
- PCB test
- Journal club
- Odor breakout reading