LS7560N LS7561N

LSI Computer Systems, Inc. 1235 Walt Whitman Road, Melville, NY 11747 (631) 271-0400 FAX (631) 271-0405

BRUSHLESS DC MOTOR CONTROLLER

March 2006

FEATURES

- · Open loop motor control
- · Tachometer output for closed loop motor control
- · Error Amplifier and PWM Speed Comparator with full accessibility
- · High noise immunity Schmitt Triggers on Sensor inputs
- 6V Reference Supply for external sensors
- · Cycle-by-cycle current sensing
- · Static, or current limited dynamic, motor braking
- Output enable delay on speed direction reversal
- · Enable input with fault sensing capability
- Fault Indicator output
- 60°/300° or 120°/240° electrical sensor spacing selection
- Selectable PWM of top and bottom drivers or bottom drivers only
- · CMOS compatible motor outputs with drive capability
- · Selectable top driver polarity
- Low power dissipation
- +10V to +18V Power Supply (VDD Vss)
- LS7560N, LS7561N (DIP); LS7560N-SD, LS7561N-SD (Skinny DIP); LS7560N-S, LS7561N-S (SOIC); LS7560N-TS, LS7561N-TS (TSSOP)
 - See Figure 1 -
- Note: LS7560N/LS7561N are backward compatible with LS7560/LS7561

GENERAL DESCRIPTION

The LS7560N/LS7561N are designed to control three or four phase brushless DC motors in a closed or open loop configuration. The IC consists of a decoder which provides proper commutation sequencing, a frequency-to-pulse width converter and error amplifier for closed loop motor speed control, a PWM comparator and sawtooth oscillator for external driver power control and a 6V reference generator for supplying power to motor sensors. Also included is Fault detection and indication, overcurrent sensing, dynamic motor braking, forward/ reverse input, sensor spacing selections and an enable input control. The overcurrent sense condition will disable all output drivers when using the LS7560N and only the bottom drivers when using the LS7561N.

The IC operates from 10V to 18V and provides CMOS compatible outputs for interfacing with external power devices. Operating below 10V will activate a Fault Indication Output and disable all Output Drivers.


INPUT/OUTPUT DESCRIPTION: (See Figure 2)

SEQUENCE SELECT Input (Pin 1)

A High on this input selects 60°/300° and a Low selects 120°/ 240° electrical sensor separation. Use of a 300° or 240° motor will cause opposite direction rotation as compared to a 60° or 120° motor.

F/R Input (Pin 27)

A High on this input selects Forward direction and a Low selects Reverse direction. The motor drive outputs are disabled for 2 clock cycles at the onset of a direction change.



S1, S2, S3 Inputs (Pins 24, 25, 26)

Hall Sensor inputs which are decoded to determine the Motor Commutation Sequence. An invalid input code disables all motor outputs. Inputs have Schmitt Trigger buffers for noise immunity.

BRAKE Input (Pin 23)

With the Brake Select input Low, a High on the Brake input forces the Top Drivers to an Off condition and the Bottom Drivers to a PWM On condition. If the Motor is under Closed Loop control, the Loop must be opened and the error amplifier output connected to the Error Amp (-) input. By controlling the voltage at the Error Amp (+) input, the PWM duty cycle is controlled during braking (see Figure 8). This manner of braking prevents the Bottom Motor Drivers from drawing excessive current, a condition which can occur during normal braking, when the Bottom Drivers are turned ON unconditionally. With the Brake Select input High, a High on the Brake input unconditionally causes the Top Drivers to turn Off and the Bottom Drivers to turn On. The Brake function has priority over all other functions.

BRAKE SELECT Input (Pin 22)

A Low on this input selects PWM control of braking and a High selects unconditional braking.

ENABLE Input (Pin 2)

When the Enable input is above VR/2, all Output Drivers are enabled and when it is below VR/2.2, all Output Drivers are disabled. This input has a nominal hysteresis of 0.05VR, where VR is the internally generated Reference Voltage available on Pin 19. Because the Enable input is level sensitive, it can easily be used to control operation of the IC based on an Analog Fault Condition.

OSCILLATOR (Pin 9)

An external RC network is connected to this input to set the frequency of the Sawtooth Schmitt Trigger Oscillator. The Sawtooth is applied to the PWM Comparator along with the output of the Error Amplifier. The output of the PWM Comparator is a Pulse Width Modulated Signal which is used to vary the effective drive to the motor and, hence, the motor speed.

OVERCURRENT SENSE (Pins 10, 11)

The input to Pin 10 comes from the high side of a fractional ohm current sensing resistor. The voltage at this input is compared to an internal 100mV Reference. When the voltage exceeds the 100mV Reference, an Overcurrent Condition exists and the Output Drivers are switched Off until the end of the sawtooth oscillator ramp-up. When the sawtooth switches low, the Overcurrent Condition is sampled, and if it no longer exists, the Output Drivers are switched On again. Otherwise, the Output Drivers remain Off until the end of the next sawtooth. The input to Pin 11 comes from the low side (Gnd) of the current sensing resistor and connects to the low side of the internal 100mV Reference.

PWM CONTROL Input (Pin 21)

A High on this input causes only the Bottom Drivers to be Pulse Width Modulated. A Low on this input causes both Top and Bottom Drivers to have PWM.

TACHOMETER Output (Pin 5)

The output of the Frequency To Pulse Width Converter is tied to this pin. The Converter uses the three Sensor Inputs and external RC Network to generate a variable frequency output with a fixed positive pulse width.

RC Input (Pin 4)

The external RC network connected to this input programs the positive pulse width of the Frequency to Pulse Width Converter.

Vss (Pin 18) Supply Voltage negative terminal.

ERROR AMPLIFIER Inputs (Pins 6, 7) Output (Pin 8)

For closed loop control, the Tachometer Output is applied through a resistor to the negative input of the Error Amplifier on Pin 7. A speed control potentiometer is connected to the positive input of the Error Amplifier on Pin 6. A parallel RC Network is connected between the Output of the Error Amplifier on Pin 8 and Pin 7. The Amplifier, configured this way, enables the variable pulse width to be converted to a DC voltage which is used to control the motor speed. The potentiometer is used to set the desired motor speed. For open loop control, configure the Error Amplifier as a voltage follower by connecting Pin 7 directly to Pin 8 and do not connect the Tachometer Output signal to the Error Amplifier.

TOP DRIVER POLARITY SELECT Input (Pin 20)

A High on this input selects a High Polarity to enable the Top Output Motor Drivers and a Low selects a Low Polarity to enable the Top Output Motor Drivers.

OUTPUT DRIVERS (Pins 12, 13, 14, 15, 16, 17)

Each Driver Output provides a CMOS compatible signal for driving Buffers/Power Transistors. The Outputs are capable of sinking/sourcing 25mA with a 1.5V drop across the IC, at VDD = 12V.

FAULT INDICATOR Output (Pin 3)

Open drain output to provide sinking current for driving an external device, such as a LED, through an emitter follower (see Figure 3) to indicate a malfunction condition. The output occurs under any of the following conditions:

- 1) Overcurrent Sense condition
- 2) Enable Input below VR / 2.2
- 3) Invalid Sensor code
- 4) Chip power supply less than 9V
- 5) VR Output less than 4.1V

VR Output (Pin 19)

6V Reference Voltage Output that can supply 20mA of current at VDD = 12V for powering input Sensors.

VDD (Pin 28) Supply Voltage positive terminal.

MAXIMUM RATINGS (Voltages referenced to Vss)


| , - | SYMBOL | VALUE | UNIT |
|----------------------------------|--------|-----------------|------|
| Power Supply Voltage | VDD | 20 | V |
| Voltage at any input | VIN | Vss - 0.5 to VR | V |
| Operating Temperature | TA | -25 to +85 | °C |
| Storage Temperature | Tstg | -65 to +150 | °C |
| Output Drive Sink/Source Current | lo | 75 | mA |
| VR Output Source Current | lR | 30 | mA |

ELECTRICAL CHARACTERISTICS

VDD = 12V, RT = 47k , CT = 0.001μ F, Rs = 10k , Cs= 0.01μ F, Rf = 5.6k (See Figure 3) TA = 25° C, unless otherwise specified

| PARAMETER | SYMBOL | MIN | TYP | MAX | UNIT |
|---|--|----------------------------------|-------------------|-------------------------|---------------------------------|
| Reference Voltage | VR | 5.7 | 6.0 | 6.35 | V |
| Line Regulation | VR | - | 100 | 200 | mV |
| VDD = 10V to $18V$, $IREF = 1.0mA$ | | | | | |
| Temperature Stability | | | | | |
| TA = 0°C to 70 °C | VR | - | +/- 1.0 | - | % |
| $TA = 0^{\circ}C$ to $85^{\circ}C$ | VR | - | +/- 1.3 | - | % |
| Error Amplifier: Input Offset Voltage Input Current Input Common Mode Voltage Range Open Loop Voltage Gain (RL = 15k) Common Mode Rejection Ratio Power Supply Rejection Ratio | VIO IIN VICR AVOL CMRR PSRR | - (0 to VR) 70 60 60 | 5 0 80 - | 15 10 - - - | mV nA V dB dB dB |

| Output High State (RL = 15k to Ground) Output Low State (RL = 15k to VR) Output Source or Sink Current Oscillator: Oscillator Frequency Percentage Frequency Change per Volt (VDD = 10V to 18V) Sawtooth High Voltage Sawtooth Low Voltage Capacitor Discharge Current Logic Inputs: Input Threshold Voltage (Pins 1, 20, 21, 22, 23, 24, 25, 26, 27) Brake and Sensor (Pins 23, 24, 25, 26) High State Input Current (VIL = 0V) Industry Select, PWM Control, Brake Select, and FiR Select (Pins 1, 20, 21, 22, 27) High State Input Current (VIN = 4V) Low State Input Current (VIN = 0V) Enable Input Threshold Voltage (Pin 2) Hysteresis Enable Input Current Overcurrent Sense Comparator: Input Threshold Voltage Input Current Output Brise Closed Loop Control Section: Tachometer Out Output High Voltage (Isink = 5mA) Pulse Width Tw Capacitor Discharge Current (RC Terminal) Output Drivers (Pins 12, 13, 14, 15, 16, 17) Sourcing 25mA Sourcing 25mA Sourcing 50mA Sinking 25mA Switching Times CL = 1000pF) Fault Output Lot Cutple (Isink = 2mA) Fig. 1000pF) Fault Output Current Fosc Fosc Fosc Fosc Fosc Fosc Fosc Fosc | VR | 24 0.4 3.8 1.0 1.0 2.3 1.8 -27 -40 | -1.0 1.0 1.0 27 1.0 4.5 -2.5 -1.4 -20 -30 -8 -10 3.2 0.4 10 | V V MA kHz %/V V MA V V MA μA μA μA |
|--|---|--|---|---|
| Output Source or Sink Current Oscillator: Oscillator Frequency Percentage Frequency Change per Volt (VDD = 10V to 18V) Sawtooth High Voltage Sawtooth Low Voltage Sawtooth Low Voltage Capacitor Discharge Current Logic Inputs: Input Threshold Voltage (Pins 1, 20, 21, 22, 23, 24, 25, 26, 27) Brake and Sensor (Pins 23, 24, 25, 26) High State Input Current (VIN = 4V) Low State Input Current (VIL = 0V) Ill Sequence Select, Top Driver Polarity Select, PWM Control, Brake Select, and F/R Select (Pins 1, 20, 21, 22, 27) High State Input Current (VIN = 4V) Low State Input Current (VIL = 0V) Ill Enable Input Threshold Voltage (Pin 2) Hysteresis Enable Input Current Overcurrent Sense Comparator: Input Threshold Voltage Input Current Input Threshold Voltage ViH Input Current Output High Voltage (Isink = 5mA) Vol Output High Voltage (Isink = 5mA) Vol Pulse Width Coutput Discharge Current (RC Terminal) Output Drivers (Pins 12, 13, 14, 15, 16, 17) Sourcing 25mA Sourcing 25mA Sourcing 25mA Sourcing 50mA Sinking 25mA Sourcing Times (CL = 250pF) Switching Times (CL = 1000pF) Fault Output Voltage (Isink = 2mA) VFO | - 21 - 0.7 0.6 3.0 - 36 - 50 | 0.4 3.8 1.0 1.0 2.3 1.8 -27 -40 -12 -17 2.8 | 1.0 27 1.0 4.5 - 2.5 - 1.4 -20 -30 -8 -10 3.2 0.4 10 | MA kHz %/V V V mA V γ μΑ μΑ μΑ ν V |
| Oscillator Frequency Percentage Frequency Change per Volt (VDD = 10V to 18V) Sawtooth High Voltage Sawtooth Low Voltage Capacitor Discharge Current Logic Inputs: Input Threshold Voltage (Pins 1, 20, 21, 22, 23, 24, 25, 26, 27) Brake and Sensor (Pins 23, 24, 25, 26) High State Input Current (VIN = 4V) Low State Input Current (VIL = 0V) Sequence Select, Top Driver Polarity Select, PWM Control, Brake Select, and F/R Select (Pins 1, 20, 21, 22, 27) High State Input Current (VIL = 0V) Ill Low State Input Current (VIL = 0V) Ill Sequence Select, Top Driver Polarity Select, PWM Control, Brake Select, and F/R Select (Pins 1, 20, 21, 22, 27) High State Input Current (VIL = 0V) Ill Overcurrent Sense Comparator: Input Threshold Voltage (Pin 2) Hysteresis Enable Input Current Overcurrent Sense Comparator: Input Threshold Voltage Input Current Ill Outputs: Closed Loop Control Section: Tachometer Out Output High Voltage (Isource = 1.5mA) Voltuput Low Voltage (Isource = 1.5mA) Voltuput Drivers (Pins 12, 13, 14, 15, 16, 17) Sourcing 25mA Voltoutput Drivers (Pins 12, 13, 14, 15, 16, 17) Sourcing 50mA Voltoutput Drivers (Pins 12, 13, 14, 15, 16, 17) Sourcing 50mA Voltoutput Drivers (Pins 12, 13, 14, 15, 16, 17) Switching Times (CL = 250pF) Switching Times (CL = 1000pF) Fault Output Voltage (Isink = 2mA) VFO | - 0.7 0.6 3.0 - -36 -50 | 0.4 3.8 1.0 1.0 2.3 1.8 -27 -40 | 1.0 4.5 - 2.5 - 1.4 -20 -30 -8 -10 3.2 0.4 10 | %/V V V mA V V μA μA V V |
| Percentage Frequency Change per Volt (VDD = 10V to 18V) Sawtooth High Voltage Sawtooth Low Voltage Capacitor Discharge Current Logic Inputs: Input Threshold Voltage (Pins 1, 20, 21, 22, 23, 24, 25, 26, 27) Brake and Sensor (Pins 23, 24, 25, 26) High State Input Current (VIN = 4V) Low State Input Current (VIN = 0V) Ill Sequence Select, Top Driver Polarity Select, PWM Control, Brake Select, and F/R Select (Pins 1, 20, 21, 22, 27) High State Input Current (VIN = 4V) Low State Input Current (VIN = 0V) Ill Ill Senable Input Threshold Voltage (Pin 2) Hysteresis Enable Input Current VIH Hysteresis VH Enable Input Current VIH UN Overcurrent Sense Comparator: Input Threshold Voltage Input Current Ill Outputs: Closed Loop Control Section: Tachometer Out Output High Voltage (Isource = 1.5mA) Output Low Voltage (Isource = 1.5mA) Vol Pulse Width Tw Capacitor Discharge Current (RC Terminal) Output Drivers (Pins 12, 13, 14, 15, 16, 17) Sourcing 25mA Vol Sinking 25mA Vol Sinking 25mA Vol Sinking 25mA Vol Sinking 50mA Switching Times (CL = 250pF) Tr Fault Output Voltage (Isink = 2mA) VFO | - 0.7 0.6 3.0 - -36 -50 | 0.4 3.8 1.0 1.0 2.3 1.8 -27 -40 | 1.0 4.5 - 2.5 - 1.4 -20 -30 -8 -10 3.2 0.4 10 | %/V V V mA V V μA μA V V |
| Sawtooth High Voltage Sawtooth Low Voltage Capacitor Discharge Current Logic Inputs: Input Threshold Voltage (Pins 1, 20, 21, 22, 23, 24, 25, 26, 27) Brake and Sensor (Pins 23, 24, 25, 26) High State Input Current (VIN = 4V) Low State Input Current (VIN = 0V) Ill Sequence Select, Top Driver Polarity Select, PWM Control, Brake Select, and F/R Select (Pins 1, 20, 21, 22, 27) High State Input Current (VIN = 4V) Low State Input Current (VIN = 0V) Ill Enable Input Threshold Voltage (Pin 2) Hysteresis VH Enable Input Current Input Threshold Voltage Input Threshold Voltage Input Current | 0.7 0.6 3.0 - -36 -50 | 3.8 1.0 1.0 2.3 1.8 -27 -40 | 4.5 - 2.5 - 1.4 -20 -30 -8 -10 3.2 0.4 10 | V V MA V V μA μA V V |
| Sawtooth High Voltage Sawtooth Low Voltage Capacitor Discharge Current Logic Inputs: Input Threshold Voltage (Pins 1, 20, 21, 22, 23, 24, 25, 26, 27) Brake and Sensor (Pins 23, 24, 25, 26) High State Input Current (VIN = 4V) Low State Input Current (VIN = 0V) Sequence Select, Top Driver Polarity Select, PWM Control, Brake Select, and F/R Select (Pins 1, 20, 21, 22, 27) High State Input Current (VIN = 4V) Low State Input Current (VIN = 0V) Ill Enable Input Threshold Voltage (Pin 2) Hysteresis Enable Input Current Overcurrent Sense Comparator: Input Threshold Voltage Input Current Ilin Output Threshold Voltage Input Current Inn Inn Inn Inn Inn Inn Inn Inn Inn I | 0.7 0.6 3.0 - -36 -50 | 1.0 1.0 2.3 1.8 -27 -40 | -2.5 -1.4 -20 -30 -8 -10 3.2 0.4 10 | V mA V V μA μA V V |
| Sawtooth Low Voltage Voscv Capacitor Discharge Current ID Logic Inputs: Input Threshold Voltage VIH (Pins 1, 20, 21, 22, 23, 24, 25, 26, 27) VIL Brake and Sensor (Pins 23, 24, 25, 26) IIIH High State Input Current (VIN = 4V) IIH Low State Input Current (VIL = 0V) IIL Sequence Select, Top Driver Polarity Select, PWM Control, Brake Select, and F/R Select (Pins 1, 20, 21, 22, 27) High State Input Current (VIN = 4V) IIH Low State Input Current (VIL = 0V) IIL Enable Input Threshold Voltage (Pin 2) VIH Hysteresis VH Enable Input Current IIN Overcurrent Sense Comparator: Input Threshold Voltage Input Threshold Voltage VIH Input Current IIN Outputs: Closed Loop Control Section: Tachometer Out VOL Output High Voltage (Isink = 5mA) VOH Output Drivers (Pins 12, 13, 14, 15, 16, 17) VOH Sourcing 25mA VOL Sourcing 25mA VOL Sinking 25mA | 0.7 0.6 3.0 - -36 -50 | 1.0 1.0 2.3 1.8 -27 -40 | -2.5 -1.4 -20 -30 -8 -10 3.2 0.4 10 | V mA V V μA μA V V |
| Capacitor Discharge Current Logic Inputs: Input Threshold Voltage (Pins 1, 20, 21, 22, 23, 24, 25, 26, 27) Brake and Sensor (Pins 23, 24, 25, 26) High State Input Current (VIN = 4V) Low State Input Current (VIL = 0V) Sequence Select, Top Driver Polarity Select, PWM Control, Brake Select, and F/R Select (Pins 1, 20, 21, 22, 27) High State Input Current (VIN = 4V) Low State Input Current (VIN = 4V) Low State Input Current (VIN = 0V) Enable Input Threshold Voltage (Pin 2) Hysteresis Enable Input Current Overcurrent Sense Comparator: Input Threshold Voltage Input Current Output Select (Isource = 1.5mA) Output High Voltage (Isource = 1.5mA) Output High Voltage (Isource = 1.5mA) Output Low Voltage (Isource = 1.5mA) Output Low Voltage (Isource = 1.5mA) Output Drivers (Pins 12, 13, 14, 15, 16, 17) Sourcing 50mA Vol Sourcing 50mA Vol Sinking 50mA Vol Switching Times (CL = 250pF) Tip Switching Times (CL = 250pF) Tip Fault Output Voltage (Isink = 2mA) Vilh VIH | 0.6 3.036 -50 -16 -25 2.1 | 1.0 2.3 1.8 -27 -40 -12 -17 2.8 | - 1.4 -20 -30 -8 -10 3.2 0.4 10 | mA V V μA μA V V |
| Input Threshold Voltage (Pins 1, 20, 21, 22, 23, 24, 25, 26, 27) Brake and Sensor (Pins 23, 24, 25, 26) High State Input Current (Vin = 4V) Low State Input Current (Vin = 0V) Sequence Select, Top Driver Polarity Select, PWM Control, Brake Select, and F/R Select (Pins 1, 20, 21, 22, 27) High State Input Current (Vin = 4V) Low State Input Current (Vin = 4V) Low State Input Current (Vin = 0V) III Enable Input Threshold Voltage (Pin 2) Hysteresis Enable Input Current VIH Hysteresis VIH IN Overcurrent Sense Comparator: Input Threshold Voltage Input Current | 3.0 - -36 -50 -16 -25 2.1 | 2.3 1.8 -27 -40 -12 -17 2.8 | - 1.4 -20 -30 -8 -10 3.2 0.4 10 | V V µA µA µA V V |
| Input Threshold Voltage (Pins 1, 20, 21, 22, 23, 24, 25, 26, 27) Brake and Sensor (Pins 23, 24, 25, 26) High State Input Current (VIN = 4V) Low State Input Current (VIL = 0V) Sequence Select, Top Driver Polarity Select, PWM Control, Brake Select, and F/R Select (Pins 1, 20, 21, 22, 27) High State Input Current (VIN = 4V) Low State Input Current (VIN = 4V) Low State Input Current (VIN = 0V) III Enable Input Threshold Voltage (Pin 2) Hysteresis Enable Input Current III Overcurrent Sense Comparator: Input Threshold Voltage Input Current III Output Threshold Voltage Input Current III Output S: Closed Loop Control Section: Tachometer Out Output High Voltage (Isource = 1.5mA) Output Low Voltage (Isource = 1.5mA) Vol Pulse Width Capacitor Discharge Current (RC Terminal) Output Drivers (Pins 12, 13, 14, 15, 16, 17) Sourcing 25mA Vol Sourcing 25mA Vol Sinking 25mA Vol Sinking 50mA Sinking 50mA Switching Times (CL = 250pF) Switching Times TR CL = 1000pF) Fault Output Voltage (Isink = 2mA) Vil | -36 -50 -16 -25 | -12 -17 -28 | -20 -30 -8 -10 3.2 0.4 10 | V μΑ μΑ μΑ V V |
| Pins 1, 20, 21, 22, 23, 24, 25, 26, 27 VIL | -36 -50 -16 -25 | -12 -17 -28 | -20 -30 -8 -10 3.2 0.4 10 | V μΑ μΑ μΑ V V |
| Brake and Sensor (Pins 23, 24, 25, 26) High State Input Current (VIN = 4V) Low State Input Current (VIL = 0V) Sequence Select, Top Driver Polarity Select, PWM Control, Brake Select, and F/R Select (Pins 1, 20, 21, 22, 27) High State Input Current (VIN = 4V) Low State Input Current (VIN = 4V) Low State Input Current (VIL = 0V) Enable Input Threshold Voltage (Pin 2) Hysteresis Enable Input Current Unput Current Unput Threshold Voltage Input Threshold Voltage Input Threshold Voltage Input Current Input Current Unput Threshold Voltage Input Current Input Cur | -50 -16 -25 2.1 | -27 -40 -12 -17 2.8 | -20 -30 -8 -10 3.2 0.4 10 | μΑ μΑ μΑ ν ν |
| High State Input Current (VIN = 4V) Low State Input Current (VIL = 0V) Sequence Select, Top Driver Polarity Select, PWM Control, Brake Select, and F/R Select (Pins 1, 20, 21, 22, 27) High State Input Current (VIN = 4V) Low State Input Current (VIN = 0V) Enable Input Threshold Voltage (Pin 2) Hysteresis Enable Input Current UIN Overcurrent Sense Comparator: nput Threshold Voltage nput Current IIN Outputs: Closed Loop Control Section: Tachometer Out Output High Voltage (Isource = 1.5mA) Output Low Voltage (Isink = 5mA) Pulse Width Capacitor Discharge Current (RC Terminal) Output Drivers (Pins 12, 13, 14, 15, 16, 17) Sourcing 25mA Sourcing 50mA Sinking 25mA Vol Sinking 50mA Switching Times (CL = 250pF) Switching Times TR CL = 1000pF) Fault Output Voltage (Isink = 2mA) VFO | -50 -16 -25 2.1 | -40 -12 -17 2.8 | -8 -10 3.2 0.4 10 | μA μA μA V V |
| Low State Input Current (VIL = 0V) Sequence Select, Top Driver Polarity Select, PWM Control, Brake Select, and F/R Select (Pins 1, 20, 21, 22, 27) High State Input Current (VIN = 4V) Low State Input Current (VIL = 0V) Enable Input Threshold Voltage (Pin 2) Hysteresis Enable Input Current Overcurrent Sense Comparator: Input Threshold Voltage Input Current Output Current IIN Outputs: Closed Loop Control Section: Tachometer Out Output High Voltage (Isource = 1.5mA) Output High Voltage (Isource = 1.5mA) Output Low Voltage (Isink = 5mA) Pulse Width Capacitor Discharge Current (RC Terminal) Output Drivers (Pins 12, 13, 14, 15, 16, 17) Sourcing 25mA Sourcing 50mA Vol Sinking 25mA Vol Sinking 50mA Vol Switching Times (CL = 250pF) Switching Times CL = 1000pF) Fault Output Voltage (Isink = 2mA) VFO | -50 -16 -25 2.1 | -40 -12 -17 2.8 | -8 -10 3.2 0.4 10 | μA μA V V |
| Sequence Select, Top Driver Polarity Select, PWM Control, Brake Select, and F/R Select (Pins 1, 20, 21, 22, 27) High State Input Current (VIN = 4V) Low State Input Current (VIL = 0V) Enable Input Threshold Voltage (Pin 2) Hysteresis Enable Input Current UN Overcurrent Sense Comparator: Input Threshold Voltage Input Current IIN Outputs: Closed Loop Control Section: Tachometer Out Output High Voltage (Isource = 1.5mA) Output High Voltage (Isource = 1.5mA) VoL Pulse Width Capacitor Discharge Current (RC Terminal) Output Drivers (Pins 12, 13, 14, 15, 16, 17) Sourcing 25mA VoH Sourcing 50mA VoH Sinking 25mA VoL Sinking 25mA VoL Sinking 50mA VoL Switching Times (CL = 250pF) Fault Output Voltage (Isink = 2mA) VFO | -16 -25 2.1 | -12 -17 2.8 | -8 -10 3.2 0.4 10 | μΑ μΑ V V |
| Select, PWM Control, Brake Select, and F/R Select (Pins 1, 20, 21, 22, 27) High State Input Current (VIN = 4V) IIIL Enable Input Threshold Voltage (Pin 2) VIH Hysteresis VH Enable Input Current IIIN Divercurrent Sense Comparator: Input Threshold Voltage VIH Input Current IIIN Dutputs: Closed Loop Control Section: Tachometer Out Output High Voltage (Isource = 1.5mA) VOH Output Low Voltage (Isink = 5mA) VOL Pulse Width Tw Capacitor Discharge Current (RC Terminal) ID Output Drivers (Pins 12, 13, 14, 15, 16, 17) Sourcing 25mA VOH Sourcing 25mA VOH Sinking 25mA VOL Sinking 50mA VOL Sinking 50mA VOL Switching Times TR CL = 250pF) TF Switching Times TR CL = 1000pF) Fault Output Voltage (Isink = 2mA) VFO | -25 2.1 | -17 2.8 | -10 3.2 0.4 10 | μA V V |
| and F/R Select (Pins 1, 20, 21, 22, 27) High State Input Current (VIN = 4V) Low State Input Current (VIL = 0V) Enable Input Threshold Voltage (Pin 2) Hysteresis Enable Input Current UN Overcurrent Sense Comparator: Input Threshold Voltage Input Current UN Output Threshold Voltage Input Current UN Output Low Voltage (Isource = 1.5mA) Output High Voltage (Isource = 1.5mA) Vol Output Low Voltage (Isink = 5mA) Pulse Width Capacitor Discharge Current (RC Terminal) Output Drivers (Pins 12, 13, 14, 15, 16, 17) Sourcing 25mA Vol Sourcing 50mA Vol Sinking 25mA Vol Sinking 50mA Vol Switching Times In CL = 1000pF) Fault Output Voltage (Isink = 2mA) Vih III VIH HIN VIH HIN VIH HIN VIH HIN VOH OUTPUT VIH IIN VOH OUTPUT VOH VOH VOH VOH VOH VOH VOH VO | -25 2.1 | -17 2.8 | -10 3.2 0.4 10 | μA V V |
| High State Input Current (VIN = 4V) Low State Input Current (VIL = 0V) Enable Input Threshold Voltage (Pin 2) Hysteresis Enable Input Current UN Overcurrent Sense Comparator: nput Threshold Voltage nput Current IIN Outputs: Closed Loop Control Section: Tachometer Out Output High Voltage (Isource = 1.5mA) Output Low Voltage (Isink = 5mA) Vol Pulse Width Capacitor Discharge Current (RC Terminal) Output Drivers (Pins 12, 13, 14, 15, 16, 17) Sourcing 25mA Vol Sourcing 25mA Vol Sinking 25mA Vol Sinking 25mA Vol Sinking 50mA Vol Sinking 50mA Vol Switching Times (CL = 250pF) Switching Times TR CL = 1000pF) Fault Output Voltage (Isink = 2mA) VIH HIN VIH HIN VIH HIN VIH HIN VIH HIN VIH HIN VOH VOH OUTPUT VIH HIN VOH VOH OUTPUT VIH HIN VOH VOH OUTPUT TW OUTPUT VOH OUTPUT TW OUTPUT VOH OUTPUT TW OUTPUT VOH OUTPUT VOH OUTPUT VOH OUTPUT TW OUTPUT VOH OUT | -25 2.1 | -17 2.8 | -10 3.2 0.4 10 | μA V V |
| Enable Input Threshold Voltage (Pin 2) Hysteresis Enable Input Current Hysteresis Enable Input Current Overcurrent Sense Comparator: Input Threshold Voltage Input Current Input Current Output Current Input Current Outputs: Closed Loop Control Section: Tachometer Out Output High Voltage (Isource = 1.5mA) Output Low Voltage (Isink = 5mA) Pulse Width Capacitor Discharge Current (RC Terminal) Output Drivers (Pins 12, 13, 14, 15, 16, 17) Sourcing 25mA Sourcing 50mA Sourcing 50mA Sinking 25mA Vol Sinking 50mA Switching Times (CL = 250pF) Switching Times CL = 1000pF) Fault Output Voltage (Isink = 2mA) VIH HIN VIH HIN VOH VOH VOH VOH VOH VOH VOH VO | -25 2.1 | -17 2.8 | -10 3.2 0.4 10 | μA V V |
| Hysteresis VH Enable Input Current IIIN Divercurrent Sense Comparator: Input Threshold Voltage VIH Input Current IIIN Outputs: Closed Loop Control Section: Tachometer Out Output High Voltage (Isource = 1.5mA) VOH Output Low Voltage (Isink = 5mA) VOL Pulse Width Tw Capacitor Discharge Current (RC Terminal) ID Output Drivers (Pins 12, 13, 14, 15, 16, 17) Sourcing 25mA VOH Sourcing 50mA VOH Sinking 25mA VOL Sinking 50mA VOL Switching Times TR (CL = 250pF) TF Switching Times TR CL = 1000pF) Fault Output Voltage (Isink = 2mA) VFO | | | 0.4 10 | V |
| Hysteresis VH Enable Input Current IIIN Divercurrent Sense Comparator: Input Threshold Voltage VIH Input Current IIIN Outputs: Closed Loop Control Section: Tachometer Out Output High Voltage (Isource = 1.5mA) VOH Output Low Voltage (Isink = 5mA) VOL Pulse Width Tw Capacitor Discharge Current (RC Terminal) ID Output Drivers (Pins 12, 13, 14, 15, 16, 17) Sourcing 25mA VOH Sourcing 50mA VOH Sinking 25mA VOL Sinking 50mA VOL Switching Times TR (CL = 250pF) TF Switching Times TR CL = 1000pF) Fault Output Voltage (Isink = 2mA) VFO | | | 0.4 10 | V |
| Enable Input Current Divercurrent Sense Comparator: Input Threshold Voltage Input Current Outputs: Closed Loop Control Section: Tachometer Out Output High Voltage (Isource = 1.5mA) Output Low Voltage (Isink = 5mA) Vol Pulse Width Capacitor Discharge Current (RC Terminal) Output Drivers (Pins 12, 13, 14, 15, 16, 17) Sourcing 25mA Sourcing 50mA Sourcing 50mA Sinking 25mA Vol Sinking 50mA Switching Times (CL = 250pF) Switching Times CL = 1000pF) Fault Output Voltage (Isink = 2mA) VIH IIN VIH IIN VOH VOH VOH VOH VOL Switching Times TR CL = 1000pF) Fault Output Voltage (Isink = 2mA) VIH IIN VIH IIN VOH VOH VOH TW TW COH TOH IIN VOH TW TW TOH IIN VOH TW TOH IIN TOH IIN VOH TW TOH IIN TOH IIN VOH TW TOH IIN THE II | - | - | 10 | = |
| nput Threshold Voltage nput Current Dutputs: Closed Loop Control Section: Tachometer Out Dutput High Voltage (Isource = 1.5mA) Output Low Voltage (Isink = 5mA) Pulse Width Capacitor Discharge Current (RC Terminal) Dutput Drivers (Pins 12, 13, 14, 15, 16, 17) Sourcing 25mA Sourcing 50mA Sourcing 50mA Sinking 25mA Vol Sinking 50mA Switching Times (CL = 250pF) Switching Times CL = 1000pF) Fault Output Voltage (Isink = 2mA) VIH IIN VIH IIN VOH VOH VOH VOH VOL Switching Times TR CL = 1000pF) Fault Output Voltage (Isink = 2mA) VIH IIN VOH VOH VOH VOH VOH Switching Times TR CL = 1000pF) Fault Output Voltage (Isink = 2mA) | | | | |
| nput Threshold Voltage nput Current Dutputs: Closed Loop Control Section: Tachometer Out Output High Voltage (Isource = 1.5mA) Output Low Voltage (Isink = 5mA) Pulse Width Capacitor Discharge Current (RC Terminal) Dutput Drivers (Pins 12, 13, 14, 15, 16, 17) Sourcing 25mA Sourcing 50mA Sourcing 50mA Sinking 25mA Vol Sinking 50mA Switching Times (CL = 250pF) Switching Times CL = 1000pF) Fault Output Voltage (Isink = 2mA) VIH IIN VIH IIN VOH VOH VOH VOH VOL TR (CL = 250pF) TF Switching Times TR CL = 1000pF) Fault Output Voltage (Isink = 2mA) VIH IIN VOH VOH VOH VOH TOH IIN VOH TW COH TOH IIN VOH TOH TOH IIN VOH TOH VOH SWITCHING TOH TOH IIN VOH TOH TOH IIN VOH TOH TOH IIN VOH TOH TOH TOH TOH TOH TOH TOH | | | 4.4- | |
| Outputs: Closed Loop Control Section: Tachometer Out Output High Voltage (Isource = 1.5mA) Output Low Voltage (Isink = 5mA) Output Low Voltage (Isink = 5mA) Pulse Width Capacitor Discharge Current (RC Terminal) Output Drivers (Pins 12, 13, 14, 15, 16, 17) Sourcing 25mA Voh Sourcing 50mA Voh Sinking 25mA Vol Sinking 50mA Vol Switching Times (CL = 250pF) Switching Times CL = 1000pF) Fault Output Voltage (Isink = 2mA) VOH VOH VFO | 85 | 100 | 115 | mV |
| Closed Loop Control Section: Tachometer Out Output High Voltage (Isource = 1.5mA) Output Low Voltage (Isink = 5mA) Pulse Width Capacitor Discharge Current (RC Terminal) Output Drivers (Pins 12, 13, 14, 15, 16, 17) Sourcing 25mA Voh Sourcing 50mA Voh Sinking 25mA Vol Sinking 50mA Vol Switching Times (CL = 250pF) Switching Times CL = 1000pF) Fault Output Voltage (Isink = 2mA) VOH VOH VOH Tr Tr Tr Tr Tr Tr Tr Tr Tr T | - | - | 10 | nA |
| Tachometer Out Output High Voltage (Isource = 1.5mA) Output Low Voltage (Isink = 5mA) Pulse Width Capacitor Discharge Current (RC Terminal) Output Drivers (Pins 12, 13, 14, 15, 16, 17) Sourcing 25mA VoH Sourcing 50mA VoH Sinking 25mA VoL Sinking 50mA VoL Switching Times (CL = 250pF) Switching Times CL = 1000pF) Fault Output Voltage (Isink = 2mA) VOH VOH VOH STR | | | | |
| Output High Voltage (Isource = 1.5mA) VOH Output Low Voltage (Isink = 5mA) VOL Pulse Width TW Capacitor Discharge Current (RC Terminal) ID Output Drivers (Pins 12, 13, 14, 15, 16, 17) VOH Sourcing 25mA VOH Sourcing 50mA VOL Sinking 25mA VOL Sinking 50mA VOL Switching Times TR (CL = 250pF) TF Switching Times TR CL = 1000pF) TF Fault Output Voltage (Isink = 2mA) VFO | | | | |
| Output Low Voltage (Isink = 5mA) Pulse Width Capacitor Discharge Current (RC Terminal) Output Drivers (Pins 12, 13, 14, 15, 16, 17) Sourcing 25mA Voh Sourcing 50mA Voh Sinking 25mA Vol Sinking 50mA Vol Switching Times (CL = 250pF) Switching Times CL = 1000pF) Fault Output Voltage (Isink = 2mA) Vol Vol Twitten Times Tr Tr Tr Tr Tr Tr Tr Tr Tr T | Vr - 0.8 | VR - 0.5 | VR - 0.3 | V |
| Pulse Width Tw Capacitor Discharge Current (RC Terminal) Dutput Drivers (Pins 12, 13, 14, 15, 16, 17) Sourcing 25mA Voh Sourcing 50mA Voh Sinking 25mA Vol Sinking 50mA Vol Switching Times TR (CL = 250pF) TF Switching Times TR CL = 1000pF) Fault Output Voltage (Isink = 2mA) | VR - 0.8 0.18 | VR - 0.5 0.27 | 0.40 | V V |
| Capacitor Discharge Current (RC Terminal) ID Output Drivers (Pins 12, 13, 14, 15, 16, 17) Sourcing 25mA VOH Sourcing 50mA VOH Sinking 25mA VOL Sinking 50mA VOL Switching Times TR (CL = 250pF) TF Switching Times TR CL = 1000pF) TF Fault Output Voltage (Isink = 2mA) VFO | 0.18 95 | 105 | 0. 4 0 115 | v µs |
| Sourcing 25mA VOH Sourcing 50mA VOH Sinking 25mA VOL Sinking 50mA VOL Switching Times TR (CL = 250pF) TF Switching Times TR CL = 1000pF) TF Fault Output Voltage (Isink = 2mA) VFO | 1.8 | 3 | 7.5 | mA |
| Sourcing 25mA VOH Sourcing 50mA VOH Sinking 25mA VOL Sinking 50mA VOL Switching Times TR (CL = 250pF) TF Switching Times TR CL = 1000pF) TF Fault Output Voltage (Isink = 2mA) VFO | | | | |
| Sourcing 50mA VOH Sinking 25mA VOL Sinking 50mA VOL Switching Times TR (CL = 250pF) TF Switching Times TR CL = 1000pF) TF Fault Output Voltage (Isink = 2mA) VFO | 9.5 | 10.5 | 11 | V |
| Sinking 25mA Vol Sinking 50mA Vol Switching Times TR (CL = 250pF) TF Switching Times TR CL = 1000pF) TF Fault Output Voltage (Isink = 2mA) VFO | 8 | 8.8 | 9.5 | V |
| Sinking 50mA Vol Switching Times TR (CL = 250pF) TF Switching Times TR CL = 1000pF) TF Fault Output Voltage (Isink = 2mA) VFO | 1.0 | 1.30 | 2.0 | V |
| Switching Times TR (CL = 250pF) TF Switching Times TR CL = 1000pF) TF Fault Output Voltage (Isink = 2mA) VFO | 2.75 | 3.40 | 4.2 | V |
| Switching Times TR CL = 1000pF) TF Fault Output Voltage (Isink = 2mA) VFO | 30 | 45 | 60 | ns |
| <u>CL = 1000pF)</u> TF <u>Fault Output Voltage (Isink = 2mA)</u> VFO | 35 | 50 | 65 | ns |
| Fault Output Voltage (Isink = 2mA) VFO | 100 | 150 | 200 | ns |
| | 130 | 180 | 230 | ns |
| and the trade Lagrana | | - | 0.5 | V |
| Fault Off-State Leakage | - | 10 | - | nA |
| Under Voltage Lockout: | - | | 40 | |
| For VDD Vuv | - | 0.5 | 10 | V |
| Hysteresis VH | 7.0 | 8.5 | 0.85 | V |
| For VR VuvR Hysteresis VH | 7.0 0.45 | 0.65 | | |
| | 7.0 | | 4.8 0.4 | V V |
| Power Supply Current VDD = 10V IDD | 7.0 0.45 3.5 | 0.65 4.1 | 4.8 | |
| VDD = 12V IDD | 7.0 0.45 3.5 | 0.65 4.1 | 4.8 | |
| VDD = 18V IDD | 7.0 0.45 3.5 | 0.65 4.1 0.3 | 4.8 0.4 | V |



7560N-030906-4




FIGURE 3.

The closed loop motor control operation is achieved by applying the Tachometer Output at Pin 5 into the negative terminal of the Error Amplifier (Pin 7) through an R1-C1-R2 integrating network. The R1-C1 network is configured as a feedback circuit around the amplifier. Since the Tachometer Output has a fixed positive pulse width, the average value of the pulse train is directly proportional to the motor speed. The desired speed is selected by applying a voltage at the positive input (Pin 6) of the Error Amplifier. The resultant output voltage of the Error Amplifier is applied to an internal Comparator along with a ramp waveform generated by the RC Network at Pin 9. The PWM signal at the Comparator output is used to drive outputs 1 thru 6 and complete the closed loop. For this configuration, Pin 20, the Top Driver Polarity Select must be tied to Ground.

** Switch used to connect the error amplifier out and (-) input together when Brake Select input is low and Brake is applied. The speed setting selected by R3 also sets the PWM rate during braking.




FIGURE 4. THREE-PHASE HALF-WAVE MOTOR CONTROLLER

FIGURE 4. This three phase half wave motor controller has no top power transistor to disconnect the windings from the power supply when the BRAKE is applied. Instead, a switching transistor is used which will permit braking for a time determined by the RC time constant. When the capacitor discharges past the ENABLE input switching point, the outputs will be turned off.




FIGURE 5. OPEN LOOP CONTROLLER

FIGURE 5. In this configuration, the PWM output duty cycle to the motor drivers is directly proportional to the DC voltage applied to Pin 6, since Pins 7 and 8 are tied together.




FIGURE 6. FOUR-PHASE FULL-WAVE MOTOR CONTROLLER

FIGURE 6. Four phase motor control requires only two Hall Sensor inputs spaced 90 electrical degrees apart. S1 is connected to one sensor and S2 and S3 are tied together and connected to the other sensor (Refer to Table 1). The Brake input (Pin 23) is used to control the Top Driver Select (Pin 20) and the Top Motor Drivers. When the Brake input is applied, the Top Motor drivers are turned off and the Top Driver Polarity Select is forced low turning on the Outputs 1 and 3. Since Outputs 4 and 6 are also turned on, the motor windings become shorted together.

The information included herein is believed to be accurate and reliable. However, LSI Computer Systems, Inc. assumes no responsibilities for inaccuracies, nor for any infringements of patent rights of others which may result from its use.




FIGURE 7. FOUR-PHASE HALF-WAVE MOTOR CONTROLLER

FIGURE 7. This four phase half wave motor controller uses the same Brake circuit as in Figure 4 and switches the Top Driver Select from a high to a low as in Figure 6.




FIGURE 8.

Using an analog switch (such as the CD4066) PWM Braking can be employed when the brake is applied. At that time, the error amplifier is configured as a voltage follower and its input is switched from the speed adjustment control to the PWM rate control. By adjusting the PWM rate control, the average motor current during braking can be controlled.

TABLE 1. OUTPUT COMMUTATION SEQUENCE FOR THREE-PHASE OPERATION LS7560N

| SE | EPA 60° | RAT | ION 1 | 20° | ICAL 2, S3 | F/R | EN | BRK | ocs | DF | | ERS , 03 | DF | OTTO RIVE O5, | | FAULT | |
|----|------------|-----|----------|-----|----------------------|-----|----|-----|-----|----|---|--------------------|----|---------------------|---|-------|--------------------|
| 0 | 0 | 0 | 0 | 0 | 1 | 1 | 1 | 0 | 0 | 0 | 1 | 1 | 0 | 1 | 0 | 1 | |
| 1 | 0 | 0 | 1 | 0 | 1 | 1 | 1 | 0 | 0 | 1 | 1 | 0 | 0 | 1 | 0 | 1 | |
| 1 | 1 | 0 | 1 | 0 | 0 | 1 | 1 | 0 | 0 | 1 | 1 | 0 | 1 | 0 | 0 | 1 | |
| 1 | 1 | 1 | 1 | 1 | 0 | 1 | 1 | 0 | 0 | 1 | 0 | 1 | 1 | 0 | 0 | 1 | |
| 0 | 1 | 1 | 0 | 1 | 0 | 1 | 1 | 0 | 0 | 1 | 0 | 1 | 0 | 0 | 1 | 1 | EN = ENABLE |
| 0 | 0 | 1 | 0 | 1 | 1 | 1 | 1 | 0 | 0 | 0 | 1 | 1 | 0 | 0 | 1 | 1 | EN - LNABLL |
| 0 | 1 | 0 | 0 | 0 | 0 | Х | Χ | 0 | Х | 1 | 1 | 1 | 0 | 0 | 0 | 0 | BRK = BRAKE |
| 1 | 0 | 1 | 1 | 1 | 1 | Х | Χ | 0 | Х | 1 | 1 | 1 | 0 | 0 | 0 | 0 | DITT - BIVARE |
| 0 | 0 | 0 | 0 | 0 | 1 | 0 | 1 | 0 | 0 | 1 | 0 | 1 | 1 | 0 | 0 | 1 | OCS = OVER |
| 1 | 0 | 0 | 1 | 0 | 1 | 0 | 1 | 0 | 0 | 1 | 0 | 1 | 0 | 0 | 1 | 1 | CURRENT |
| 1 | 1 | 0 | 1 | 0 | 0 | 0 | 1 | 0 | 0 | 0 | 1 | 1 | 0 | 0 | 1 | 1 | SENSE |
| 1 | 1 | 1 | 1 | 1 | 0 | 0 | 1 | 0 | 0 | 0 | 1 | 1 | 0 | 1 | 0 | 1 | 02.102 |
| 0 | 1 | 1 | 0 | 1 | 0 | 0 | 1 | 0 | 0 | 1 | 1 | 0 | 0 | 1 | 0 | 1 | |
| 0 | 0 | 1 | 0 | 1 | 1 | 0 | 1 | 0 | 0 | 1 | 1 | 0 | 1 | 0 | 0 | 1 | |
| 0 | 1 | 0 | 0 | 0 | 0 | Х | Х | 0 | Х | 1 | 1 | 1 | 0 | 0 | 0 | 0 | |
| 1 | 0 | 1 | 1 | 1 | 1 | Х | Χ | 0 | Х | 1 | 1 | 1 | 0 | 0 | 0 | 0 | |
| Х | Χ | Х | Х | Χ | Χ | Х | Х | 1 | X | 1 | 1 | 1 | 1 | 1 | 1 | 1 | |
| Х | Χ | Х | Х | Χ | Х | Х | Χ | 0 | 1 | 1 | 1 | 1 | 0 | 0 | 0 | 0 | |
| Х | Χ | Х | Х | Х | Х | Х | 0 | 0 | Х | 1 | 1 | 1 | 0 | 0 | 0 | 0 | |

NOTE 1: This Table assumes the Top Driver Polarity Select (Pin 20) = Logic 0. For Pin 20 = Logic 1, invert the polarity of the top drivers.

NOTE 2: For the LS7561N, the Overcurrent Sense = Logic 1 only forces the bottom drivers to a Logic 0. It has no effect on the top driver outputs which are determined by the other inputs as shown in the table.

TABLE 2. OUTPUT COMMUTATION SEQUENCE FOR FOUR-PHASE OPERATION LS7560N

| | OR ELECT RATION = | _ | | | | TOP | воттом | | |
|------------|----------------------|-----|----|-----|-----|--------------------------|--------------------------|-------|--------------------|
| S 1 | S2, S3 | F/R | EN | BRK | ocs | DRIVERS 01, 03 | DRIVERS 04, 06 | FAULT | |
| 0 | 0 | 1 | 1 | 0 | 0 | 1 0 | 0 0 | 1 | EN = ENABLE |
| 1 | 0 | 1 | 1 | 0 | 0 | 0 1 | 0 0 | 1 | EN - LIVADEL |
| 1 | 1 | 1 | 1 | 0 | 0 | 0 0 | 1 0 | 1 | BRK = BRAKE |
| 0 | 1 | 1 | 1 | 0 | 0 | 0 0 | 0 1 | 1 | DKK = DKAKE |
| 0 | 0 | 0 | 1 | 0 | 0 | 0 0 | 1 0 | 1 | OCS = OVER |
| 1 | 0 | 0 | 1 | 0 | 0 | 0 0 | 0 1 | 1 | |
| 1 | 1 | 0 | 1 | 0 | 0 | 1 0 | 0 0 | 1 | CURRENT SENSE |
| 0 | 1 | 0 | 1 | 0 | 0 | 0 1 | 0 0 | 1 | SENSE |
| Х | X | X | Х | 1 | X | 0 0 | 1 1 | 1 | |
| Х | x | Х | Х | 0 | 1 | 0 0 | 0 0 | 0 | |
| | v | v | 0 | 0 | v | 0 0 | 0 0 | ^ | |

NOTE 1: Sequence Input (Pin 1) set at a Logic 1.

NOTE 2: This Table assumes the Top Driver Polarity Select (Pin 20) = Logic 1. For Pin 20 = Logic 0, invert the polarity of the top drivers.

NOTE 3: For the LS7561N, the Overcurrent Sense = Logic 1 only forces the bottom drivers to a Logic 0. It has no effect on the Top Driver Outputs which are determined by the other inputs as shown on the table.