

WiFi load does not corrupt ESP32-S3 esp_dmx receive

WiFi-scan load on core 0 throughout B and C. The 128-byte UART FIFO + IRAM ISR absorb the WiFi-MAC interrupt latency: ~0 corrupted frames whether the DMX receive ISR shares the WiFi core (B) or is isolated (C). (Frame *gaps* in all three are the gateway source's own output jitter, present without WiFi too, not a receiver effect.)

framing / overrun errors (90 s run)

