s112 nrf52 release notes

Introduction to the s112 nrf52 release notes

About the document

These release notes describe the changes in the s112 nrf52 from version to version.

The release notes are intended to list all relevant changes in a given version. They are kept brief to make it easy to get an overview of the changes. More details regarding changes and new features can be found in the s112_nrf52 migration document (normally available for major releases only).

Issue numbers in parentheses are for internal use and should be disregarded by the customer.

Copyright (c) Nordic Semiconductor ASA. All rights reserved.

s112 nrf52810 5.1.0

This release is the first production version of the S112. The S112 is a size-optimized peripheral-only BLE SoftDevice for Nordic Semiconductor's nRF52810 chip. The S112 API is a compatible subset of the S132 SoftDevice API. For features that are common to S112 and S132, the API is the same. To show the API compatibility, the S112 follows the same version numbering as S132.

The main change relative to the s112_nrf52810_5.1.0-2.alpha is that the observer role functionality is removed from the SoftDevice. The SoftDevice also has some minor updates and bug fixes.

Notes:

• The priority of SoftDevice interrupts SD_EVT_IRQn (SWI2_IRQn) and RADIO_NOTIFICATION_IRQn (SWI3_IRQn) is 6. This is different from S132 4.x and previous SoftDevices (DRGN-9245).

SoftDevice properties

- The S112 SoftDevice Specification document will be available at http://infocenter.nordicsemi.com/.
- This version of the SoftDevice contains the Master Boot Record (MBR) version 2.2.2 (DRGN-9537).
- The combined MBR and SoftDevice memory requirements for this version are as follows:
 - Flash: 96 kB (0x18000 bytes).
 - RAM: 3.68 kB (0xeb8 bytes). This is the minimum required memory. The actual requirements depend on the configuration chosen at sd_ble_enable() time.

Device Compatibility

The SoftDevice is built, production tested, and qualified for use with nRF52810.

The SoftDevice is not production tested and qualified for use with nRF52832. However, the SoftDevice can be used for development purposes on the nRF52832 if minor performance and stability issues are accepted during development.

New functionality

This release has no new features compared to the s112_nrf52810_5.1.0-2.alpha.

Changes

Relative to the s112_nrf52810_5.1.0-2.alpha:

- GAP
- · Observer role is no longer supported, and the following functions, structures, defines, and events have been removed

(DRGN-9298):

- BLE_GAP_EVT_ADV_REPORT
- BLE_GAP_TIMEOUT_SRC_SCAN
- BLE_GAP_SCAN_INTERVAL_MIN, BLE_GAP_SCAN_INTERVAL_MAX
- BLE_GAP_SCAN_WINDOW_MIN, BLE_GAP_SCAN_WINDOW_MAX
- BLE_GAP_SCAN_TIMEOUT_MIN, BLE_GAP_SCAN_TIMEOUT_MAX
- ble_gap_scan_params_t
- ble_gap_evt_adv_report_t
- sd_ble_gap_scan_start()
- sd_ble_gap_scan_stop()
- LL
- The SoftDevice now sends LL_REJECT_EXT_IND instead of LL_REJECT_IND if the peer has indicated support for LL_REJECT_EXT_IND (DRGN-9539).

Relative to the s132_nrf52_5.0.0:

- SoftDevice
 - sd_flash_protect() will now return NRF_ERROR_NOT_SUPPORTED if a non-zero value is given for a BPROT configuration register that is not available on the platform (DRGN-9336). (This was also part of the s112_nrf52810_5.1.0-2.alpha release.)
 - References to EGU* have been removed from nrf_soc.h and nrf_nvic.h as the SoftDevice is using SWI and not EGU to generate interrupts (DRGN-9257). (This was also part of the s112_nrf52810_5.1.0-2.alpha release.)

See the release notes for the s112_nrf52810_5.1.0-2.alpha for the rest of the changes.

Bug fixes

Compared to the s112_nrf52810_5.1.0-2.alpha, the following bugs have been fixed:

- SoftDevice
 - Fixed an issue where sd_ble_gatts_attr_get() and sd_ble_gatts_value_get() could return undocumented BLE
 _ERROR_INVALID_ATTR_HANDLE error code in a situation where they should have returned NRF_ERROR_NOT_FOUND (DR
 GN-9216).
 - Fixed an issue where the API documentation was referencing removed APIs (DRGN-9484).
 - Fixed an issue where some include directives were missing in ble_gatts.h (DRGN-9467).
- GATT
 - Fixed an issue where the SoftDevice could assert if ATT packets longer than the LL packet size were sent and received at the same time (DRGN-9328).
- LL
- Fixed an issue where the SoftDevice could assert while doing radio or flash activity (DRGN-9463).
- Fixed an issue where the SoftDevice could send LL_FEATURE_RSP with incorrect FeatureSet (DRGN-9551).
- Fixed an issue where the slave disconnect event reason code was set to HCI_LOCAL_HOST_TERMINATED_CONNECTION in stead of HCI_STATUS_CODE_PIN_OR_KEY_MISSING. This occurred if the LTK (Long Term Key) was missing during the re-encryption of the link (DRGN-9190). (This was also fixed in the s112_nrf52810_5.1.0-2.alpha release.)

Limitations

- SoftDevice
 - If Radio Notifications are enabled, flash write and flash erase operations initiated through the SoftDevice API will be notified
 to the application as Radio Events (FORT-809).
 - Synthesized low frequency clock source is not tested or intended for use with the BLE stack.
 - Applications must not modify the SEVONPEND flag in the SCR register when running in priority levels higher than 6
 (priority level numerical values lower than 6) as this can lead to undefined behavior.
- GATTS
 - To conform to the Bluetooth Core Specification v 5.0, there shall be no secondary service that is not referenced somehow by a primary service. The SoftDevice does not enforce this (DRGN-906).

Known Issues

- GAP
- The SoftDevice can assert if the whitelist and identity list is set at the same time with matching addresses. A workaround for this issue is to clear the whitelist before setting the identity list (DRGN-9535).

s112_nrf52810_5.1.0-2.alpha

The S112 is a size-optimized peripheral only BLE SoftDevice for Nordic Semiconductor's nRF52810 chip. The S112 API is a compatible subset of the S132 SoftDevice API. For features that are common to S112 and S132, the API is the same. To show the API compatibility, the S112 follows the same version numbering as S132. See the section "Changes" below for features that are not available in the S112 compared to the S132.

SoftDevice properties

- The combined MBR and SoftDevice memory requirements for this version are as follows:
 - Flash: 100 kB (0x19000 bytes)
 - RAM: 3.65 kB (0xe98 bytes)

Device Compatibility

This SoftDevice is built and tested for nRF52810.

For development purposes this SoftDevice can be run on the nRF52832, but some of the Errata workarounds for that device are not present in this version of the alpha SoftDevice. This may result in minor performance and stability issues on nRF52832.

New functionality

This release is the first version of the S112. It is based upon the s132_nrf52_5.0.0, and has no new functionality compared to that version.

Changes

Compared to the s132_nrf52_5.0.0, the following features have been removed:

- SoftDevice:
 - MWU is not supported, as the nrf52810 does not have MWU (DRGN-9341).
 - Cache is not supported, as the nrf52810 does not have Cache (DRGN-9256).
- GAP:
 - Observer role is still present in this alpha version of the SoftDevice, but might be removed for the production version.
 - Central Role is no longer supported and the following functions, structures, defines and events have been removed (DRGN-9145):
 - sd_ble_gap_connect() , sd_ble_gap_connect_cancel()
 - sd_ble_gap_encrypt()
 - BLE_GAP_EVT_CONN_PARAM_UPDATE_REQUEST
 - ble_gap_evt_conn_param_update_request_t
 - BLE_GAP_OPT_COMPAT_MODE_1
 - ble_gap_opt_compat_mode_1_t
 - BLE_GAP_ROLE_CENTRAL , BLE_GAP_ROLE_COUNT_CENTRAL_DEFAULT , BLE_GAP_ROLE_COUNT_CENTRAL_SEC_DEFAULT
 - LE Data Length Extension is no longer supported and the following structures, defines and events have been removed (DRGN-9242):
 - sd_ble_gap_data_length_update()
 - BLE_GAP_EVT_DATA_LENGTH_UPDATE_REQUEST , BLE_GAP_EVT_DATA_LENGTH_UPDATE
 - BLE_GAP_DATA_LENGTH_AUTO
 - ble_gap_data_length_params_t , ble_gap_data_length_limitation_t
 - ble_gap_evt_data_length_update_request_t , ble_gap_evt_data_length_update_t
- L2CAP:
 - L2CAP Connection Oriented Channels is no longer supported and the header file ble_l2cap.h with it's functions, structures, defines and events has been removed (DRGN-923 8):
 - sd_ble_12cap_ch_setup() , sd_ble_12cap_ch_release() , sd_ble_12cap_ch_rx() , sd_ble_12cap_ch_tx() , sd_ble_12cap_ch_flow_control()
 - ble_12cap_ch_rx_params_t , ble_12cap_ch_setup_params_t , ble_12cap_ch_tx_params_t , ble_12cap_conn_cfg_t
 - BLE_L2CAP_EVT_CH_SETUP_REQUEST, BLE_L2CAP_EVT_CH_SETUP_REFUSED , BLE_L2CAP_EVT_CH_SE TUP , BLE_L2CAP_EVT_CH_RELEASED , BLE_L2CAP_EVT_CH_SDU_BUF_RELEASED , BLE_L2CAP_EVT_CH_CREDIT , BLE_L2CAP_EVT_CH_RX , B LE_L2CAP_EVT_CH_TX

• ble_12cap_evt_t, ble_12cap_evt_ch_tx_t , ble_12cap_evt_ch_rx_t , ble_12cap_evt_ch_cred it_t , ble_12cap_evt_ch_sdu_buf_released_t , ble_12cap_evt_ch_setup_request_t , ble_12cap_evt_ch_setup_refused_t , ble_12cap_evt_ch_setup_t

Bug fixes

Compared to the s132_nrf52_5.0.0, the following bugs have been fixed:

- SoftDevice
 - Fixed an issue where Radio Notification could be suppressed between connection events when Connection Event Length Extension was enabled (DRGN-7687).

Limitations

- SoftDevice
 - If Radio Notifications are enabled, flash write and flash erase operations initiated through the SoftDevice API will be notified
 to the application as Radio Events (FORT-809).
 - Synthesized low frequency clock source is not tested or intended for use with the BLE stack.
 - Applications must not modify the SEVONPEND flag in the SCR register when running in priority levels higher than 6 (priority level numerical values lower than 6) as this can lead to undefined behavior.
- GATTS
 - To conform to the Bluetooth Core Specification v 5.0, there shall be no secondary service that is not referenced somehow by a primary service. The SoftDevice does not enforce this (DRGN-906).

Known Issues

No known issues.