

Sudden braking incidents

3,726 row(s). One row per existing is_braking=true segment; no new incident detection/grouping was applied.

Source: trips.geojson

Scope: Existing classified incidents and stored trip measurements

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
26/01/2026 09:04:26	52.353810	4.809150	70	Sudden braking	2.00	2.00	21.2	20.3	1.00	2	5.2	1.000	602CA_Trip195	1
26/01/2026 09:07:11	52.356113	4.826721	90	Sudden braking	2.20	2.20	18.9	18.9	1.00	2	4.4	1.000	602CA_Trip195	1
26/01/2026 09:07:12	52.356111	4.826785	92	Sudden braking	2.10	2.10	17.5	16.8	1.00	2	3.5	1.000	602CA_Trip195	1
26/01/2026 09:07:19	52.355922	4.826866	167	Sudden braking	2.10	2.10	10.0	7.2	1.00	1	1.8	1.000	602CA_Trip195	1
26/01/2026 09:07:42	52.356065	4.827126	28	Sudden braking	2.20	2.20	8.7	6.2	1.00	2	1.4	1.000	602CA_Trip195	1
26/01/2026 09:12:16	52.354950	4.849996	89	Sudden braking	2.20	2.20	17.1	18.9	1.00	2	4.3	1.000	602CA_Trip195	1
26/01/2026 09:12:17	52.354950	4.850059	89	Sudden braking	2.70	2.70	15.5	16.2	1.00	2	3.6	1.000	602CA_Trip195	1
26/01/2026 09:12:18	52.354951	4.850112	89	Sudden braking	2.80	2.80	14.7	13.4	1.00	2	2.4	1.000	602CA_Trip195	1
26/01/2026 09:12:19	52.354951	4.850148	89	Sudden braking	2.70	2.70	13.7	10.7	1.00	2	2.1	1.000	602CA_Trip195	1
26/01/2026 09:12:20	52.354951	4.850179	89	Sudden braking	2.50	2.50	12.6	8.2	1.00	2	1.5	1.000	602CA_Trip195	1
26/01/2026 09:17:45	52.361595	4.881540	56	Sudden braking	2.10	2.10	20.2	21.1	1.00	2	5.1	1.000	602CA_Trip195	1
26/01/2026 09:17:46	52.361622	4.881600	52	Sudden braking	2.40	2.40	19.4	18.7	1.00	2	4.1	1.000	602CA_Trip195	1
26/01/2026 09:17:47	52.361647	4.881644	50	Sudden braking	3.60	3.60	18.5	15.1	1.00	3	3.4	1.000	602CA_Trip195	1
26/01/2026 09:17:48	52.361669	4.881678	40	Sudden braking	4.30	4.30	17.4	10.8	1.00	2	2.6	1.000	602CA_Trip195	1
26/01/2026 09:19:46	52.359644	4.890081	112	Sudden braking	2.00	2.00	22.0	23.7	1.00	2	6.0	1.000	602CA_Trip195	1
26/01/2026 09:19:47	52.359619	4.890159	114	Sudden braking	2.40	2.40	20.2	21.3	1.00	2	4.9	1.000	602CA_Trip195	1
26/01/2026 09:19:48	52.359601	4.890226	116	Sudden braking	2.70	2.70	18.2	18.6	1.00	2	4.3	1.000	602CA_Trip195	1
26/01/2026 09:19:49	52.359576	4.890273	125	Sudden braking	2.80	2.80	16.1	15.8	1.00	2	3.4	1.000	602CA_Trip195	1
26/01/2026 09:19:50	52.359559	4.890315	124	Sudden braking	2.60	2.60	14.0	13.2	1.00	2	2.8	1.000	602CA_Trip195	1
26/01/2026 09:19:51	52.359550	4.890353	117	Sudden braking	2.30	2.30	12.9	10.9	1.00	2	2.5	1.000	602CA_Trip195	1
26/01/2026 09:19:52	52.359548	4.890389	108	Sudden braking	2.00	2.00	11.7	8.9	1.00	2	1.9	1.000	602CA_Trip195	1
26/01/2026 09:19:53	52.359551	4.890417	99	Sudden braking	2.10	2.10	9.8	6.8	1.00	2	1.3	1.000	602CA_Trip195	1
26/01/2026 09:21:53	52.359336	4.897922	77	Sudden braking	2.40	2.40	17.5	19.3	1.00	2	4.5	1.000	602CA_Trip195	1
26/01/2026 09:21:54	52.359344	4.897988	77	Sudden braking	2.70	2.70	16.0	16.6	1.00	2	3.6	1.000	602CA_Trip195	1
26/01/2026 09:21:55	52.359351	4.898040	77	Sudden braking	2.70	2.70	14.2	13.9	1.00	2	2.8	1.000	602CA_Trip195	1
26/01/2026 09:21:56	52.359358	4.898079	77	Sudden braking	2.40	2.40	13.3	11.5	1.00	2	2.5	1.000	602CA_Trip195	1
26/01/2026 09:21:57	52.359364	4.898114	78	Sudden braking	2.10	2.10	12.2	9.4	1.00	2	2.0	1.000	602CA_Trip195	1
26/01/2026 09:21:58	52.359365	4.898143	78	Sudden braking	2.20	2.20	11.0	7.2	1.00	2	1.8	1.000	602CA_Trip195	1
26/01/2026 09:24:07	52.361025	4.907867	84	Sudden braking	2.10	2.10	15.8	15.3	1.00	2	4.0	1.000	602CA_Trip195	1
26/01/2026 09:26:26	52.367061	4.912459	29	Sudden braking	2.70	2.70	22.9	26.4	1.00	2	5.7	1.000	602CA_Trip195	1
26/01/2026 09:26:27	52.367103	4.912505	29	Sudden braking	3.90	3.90	21.7	22.5	1.00	2	4.4	1.000	602CA_Trip195	1
26/01/2026 09:26:28	52.367131	4.912550	29	Sudden braking	4.10	4.10	20.4	18.4	1.00	3	2.9	1.000	602CA_Trip195	1
26/01/2026 09:26:29	52.367149	4.912582	29	Sudden braking	3.40	3.40	19.1	15.0	1.00	3	2.6	1.000	602CA_Trip195	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
26/01/2026 09:26:30	52.367168	4.912604	29	Sudden braking	2.00	2.00	17.8	13.0	1.00	2	1.7	1.000	602CA_Trip195	1
26/01/2026 09:27:36	52.369475	4.912277	299	Sudden braking	2.00	2.00	15.2	14.6	1.00	2	4.0	1.000	602CA_Trip195	1
26/01/2026 09:30:06	52.372399	4.918303	36	Sudden braking	2.00	2.00	12.5	11.5	1.00	2	3.5	1.000	602CA_Trip195	1
26/01/2026 09:30:07	52.372431	4.918313	21	Sudden braking	2.30	2.30	11.8	9.2	1.00	2	2.4	1.000	602CA_Trip195	1
26/01/2026 09:30:08	52.372445	4.918287	351	Sudden braking	2.10	2.10	11.1	7.1	1.00	2	1.1	1.000	602CA_Trip195	1
20/02/2026 07:45:07	52.353679	4.807277	151	Sudden braking	2.00	2.00	11.4	10.0	1.00	2	1.8	1.000	602CA_Trip196	1
20/02/2026 07:45:08	52.353665	4.807289	152	Sudden braking	2.30	2.30	10.6	7.7	1.00	2	1.8	1.000	602CA_Trip196	1
20/02/2026 07:45:09	52.353650	4.807296	154	Sudden braking	2.30	2.30	8.9	5.4	1.00	2	1.6	1.000	602CA_Trip196	1
20/02/2026 07:49:14	52.356113	4.826831	90	Sudden braking	2.00	2.00	18.5	19.5	1.00	2	4.8	1.000	602CA_Trip196	1
20/02/2026 07:49:15	52.356112	4.826901	90	Sudden braking	2.20	2.20	17.1	17.3	1.00	2	3.7	1.000	602CA_Trip196	1
20/02/2026 07:49:16	52.356114	4.826955	89	Sudden braking	2.20	2.20	15.6	15.1	1.00	2	2.9	1.000	602CA_Trip196	1
20/02/2026 07:49:17	52.356112	4.826997	93	Sudden braking	2.10	2.10	14.3	13.0	1.00	2	3.3	1.000	602CA_Trip196	1
20/02/2026 07:53:11	52.355713	4.847620	90	Sudden braking	2.20	2.20	17.9	18.4	1.00	2	4.5	1.000	602CA_Trip196	1
20/02/2026 07:53:12	52.355707	4.847686	94	Sudden braking	2.40	2.40	17.0	16.0	1.00	2	3.3	1.000	602CA_Trip196	1
20/02/2026 07:53:13	52.355693	4.847729	106	Sudden braking	2.20	2.20	16.1	13.8	1.00	2	2.8	1.000	602CA_Trip196	1
20/02/2026 07:53:58	52.354960	4.850146	89	Sudden braking	2.20	2.20	14.2	12.4	1.00	2	2.6	1.000	602CA_Trip196	1
20/02/2026 07:53:59	52.354960	4.850184	89	Sudden braking	2.20	2.20	13.2	10.2	1.00	2	2.0	1.000	602CA_Trip196	1
20/02/2026 07:54:56	52.354775	4.855067	72	Sudden braking	2.50	2.50	17.5	18.6	1.00	2	4.1	1.000	602CA_Trip196	1
20/02/2026 07:54:57	52.354787	4.855125	72	Sudden braking	3.10	3.10	16.9	15.5	1.00	2	3.5	1.000	602CA_Trip196	1
20/02/2026 07:54:58	52.354799	4.855174	69	Sudden braking	3.80	3.80	16.1	11.7	1.00	3	2.0	1.000	602CA_Trip196	1
20/02/2026 07:54:59	52.354807	4.855200	62	Sudden braking	3.20	3.20	15.0	8.5	1.00	3	1.4	1.000	602CA_Trip196	1
20/02/2026 07:59:59	52.361637	4.881725	49	Sudden braking	2.30	2.30	11.9	9.1	1.00	2	2.2	1.000	602CA_Trip196	1
20/02/2026 08:00:00	52.361653	4.881743	42	Sudden braking	2.10	2.10	11.1	7.0	1.00	2	1.0	1.000	602CA_Trip196	1
20/02/2026 08:01:24	52.362503	4.883528	47	Sudden braking	2.70	2.70	12.4	11.9	1.00	2	3.1	1.000	602CA_Trip196	1
20/02/2026 08:01:25	52.362522	4.883560	45	Sudden braking	2.50	2.50	12.0	9.4	1.00	2	2.6	1.000	602CA_Trip196	1
20/02/2026 08:08:56	52.368512	4.913726	30	Sudden braking	2.10	2.10	18.5	19.8	1.00	2	4.7	1.000	602CA_Trip196	1
20/02/2026 08:08:57	52.368549	4.913761	30	Sudden braking	2.40	2.40	17.3	17.4	1.00	3	3.4	1.000	602CA_Trip196	1
20/02/2026 08:08:58	52.368576	4.913785	30	Sudden braking	2.30	2.30	16.1	15.1	1.00	3	2.9	1.000	602CA_Trip196	1
20/02/2026 08:10:44	52.371026	4.915068	75	Sudden braking	2.00	2.00	10.2	7.1	1.00	2	1.5	1.000	602CA_Trip196	1
21/02/2026 17:16:45	52.371057	4.913207	282	Sudden braking	2.50	2.50	14.4	12.1	1.00	1	2.5	1.000	602CA_Trip378	1
21/02/2026 17:16:46	52.371059	4.913171	278	Sudden braking	2.60	2.60	13.8	9.5	1.00	1	2.0	1.000	602CA_Trip378	1
21/02/2026 17:19:25	52.366718	4.911888	212	Sudden braking	2.00	2.00	10.9	9.6	1.00	2	2.2	1.000	602CA_Trip378	1
21/02/2026 17:19:26	52.366701	4.911871	212	Sudden braking	2.10	2.10	10.3	7.5	1.00	2	1.6	1.000	602CA_Trip378	1
21/02/2026 17:21:14	52.364441	4.906660	263	Sudden braking	2.20	2.20	18.0	18.3	1.00	2	4.3	1.000	602CA_Trip378	1
21/02/2026 17:21:15	52.364440	4.906597	271	Sudden braking	2.00	2.00	17.4	16.3	1.00	2	3.4	1.000	602CA_Trip378	1
21/02/2026 17:25:14	52.359734	4.898713	203	Sudden braking	2.00	2.00	14.9	14.6	1.00	2	3.6	1.000	602CA_Trip378	1
21/02/2026 17:25:15	52.359703	4.898700	203	Sudden braking	2.10	2.10	14.0	12.5	1.00	2	2.6	1.000	602CA_Trip378	1
21/02/2026 17:28:25	52.362572	4.883937	309	Sudden braking	2.30	2.30	15.5	16.7	1.00	2	3.5	1.000	602CA_Trip378	1
21/02/2026 17:28:26	52.362592	4.883897	309	Sudden braking	2.80	2.80	13.8	13.9	1.00	2	2.5	1.000	602CA_Trip378	1
21/02/2026 17:28:27	52.362607	4.883869	310	Sudden braking	2.80	2.80	12.1	11.1	1.00	2	1.9	1.000	602CA_Trip378	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
21/02/2026 17:28:28	52.362614	4.883843	309	Sudden braking	2.30	2.30	11.1	8.8	1.00	2	1.5	1.000	602CA_Trip378	1
21/02/2026 17:34:25	52.354974	4.855911	248	Sudden braking	2.00	2.00	16.2	16.9	1.00	2	4.4	1.000	602CA_Trip378	1
21/02/2026 17:34:26	52.354966	4.855847	253	Sudden braking	2.20	2.20	14.8	14.7	1.00	2	3.5	1.000	602CA_Trip378	1
21/02/2026 17:34:27	52.354957	4.855797	253	Sudden braking	2.10	2.10	13.4	12.6	1.00	2	2.5	1.000	602CA_Trip378	1
21/02/2026 17:40:44	52.356345	4.827562	302	Sudden braking	2.20	2.20	12.9	11.6	1.00	2	2.7	1.000	602CA_Trip378	1
21/02/2026 17:40:45	52.356361	4.827533	307	Sudden braking	2.40	2.40	12.3	9.2	1.00	2	2.1	1.000	602CA_Trip378	1
23/02/2026 07:28:43	52.354148	4.810755	71	Sudden braking	2.00	2.00	15.9	15.9	1.00	2	6.9	1.000	602CA_Trip379	1
23/02/2026 07:31:32	52.356113	4.826911	89	Sudden braking	2.10	2.10	17.4	18.7	1.00	2	4.4	1.000	602CA_Trip379	1
23/02/2026 07:31:33	52.356114	4.826975	90	Sudden braking	2.50	2.50	15.8	16.2	1.00	2	3.3	1.000	602CA_Trip379	1
23/02/2026 07:31:34	52.356109	4.827023	95	Sudden braking	2.70	2.70	14.0	13.5	1.00	2	3.0	1.000	602CA_Trip379	1
23/02/2026 07:31:35	52.356100	4.827065	105	Sudden braking	2.30	2.30	12.2	11.2	1.00	2	2.2	1.000	602CA_Trip379	1
23/02/2026 07:35:49	52.355700	4.847667	94	Sudden braking	2.10	2.10	17.5	16.5	1.00	2	3.8	1.000	602CA_Trip379	1
23/02/2026 07:50:58	52.366073	4.911548	30	Sudden braking	2.30	2.30	17.3	17.8	1.00	2	4.0	1.000	602CA_Trip379	1
23/02/2026 07:50:59	52.366104	4.911577	30	Sudden braking	2.50	2.50	15.8	15.3	1.00	2	3.0	1.000	602CA_Trip379	1
23/02/2026 07:51:00	52.366125	4.911604	30	Sudden braking	2.50	2.50	14.4	12.8	1.00	2	2.7	1.000	602CA_Trip379	1
23/02/2026 07:51:01	52.366140	4.911635	30	Sudden braking	2.00	2.00	13.1	10.8	1.00	2	2.2	1.000	602CA_Trip379	1
02/03/2026 08:25:30	52.353793	4.809064	74	Sudden braking	2.10	2.10	14.6	14.7	1.00	2	3.8	1.000	602CA_Trip380	1
02/03/2026 08:25:31	52.353811	4.809111	70	Sudden braking	2.10	2.10	13.0	12.6	1.00	2	2.7	1.000	602CA_Trip380	1
02/03/2026 08:29:26	52.356103	4.826794	89	Sudden braking	2.20	2.20	18.2	19.0	1.00	2	4.2	1.000	602CA_Trip380	1
02/03/2026 08:29:27	52.356108	4.826856	88	Sudden braking	2.40	2.40	16.5	16.6	1.00	2	3.8	1.000	602CA_Trip380	1
02/03/2026 08:29:28	52.356109	4.826912	90	Sudden braking	2.30	2.30	14.8	14.3	1.00	2	3.4	1.000	602CA_Trip380	1
02/03/2026 08:29:29	52.356110	4.826961	90	Sudden braking	2.00	2.00	13.9	12.3	1.00	2	2.8	1.000	602CA_Trip380	1
02/03/2026 08:34:34	52.354772	4.853539	100	Sudden braking	2.50	2.50	14.6	15.6	1.00	3	5.1	1.000	602CA_Trip380	1
02/03/2026 08:34:35	52.354766	4.853614	99	Sudden braking	2.70	2.70	13.0	12.9	1.00	3	2.2	1.000	602CA_Trip380	1
02/03/2026 08:34:36	52.354774	4.853644	89	Sudden braking	2.50	2.50	11.5	10.4	1.00	2	2.3	1.000	602CA_Trip380	1
02/03/2026 08:34:37	52.354794	4.853655	65	Sudden braking	2.60	2.60	10.2	7.8	1.00	2	2.1	1.000	602CA_Trip380	1
02/03/2026 08:34:38	52.354803	4.853681	57	Sudden braking	2.10	2.10	9.0	5.7	1.00	2	2.5	1.000	602CA_Trip380	1
02/03/2026 08:39:37	52.361601	4.881703	62	Sudden braking	2.40	2.40	16.7	18.9	1.00	2	4.6	1.000	602CA_Trip380	1
02/03/2026 08:39:38	52.361623	4.881761	60	Sudden braking	3.00	3.00	15.9	15.9	1.00	2	3.1	1.000	602CA_Trip380	1
02/03/2026 08:39:39	52.361639	4.881799	60	Sudden braking	3.00	3.00	15.0	12.9	1.00	2	1.4	1.000	602CA_Trip380	1
02/03/2026 08:39:40	52.361650	4.881787	55	Sudden braking	3.40	3.40	13.9	9.5	1.00	2	2.7	1.000	602CA_Trip380	1
02/03/2026 08:39:41	52.361664	4.881818	54	Sudden braking	3.40	3.40	11.5	6.1	1.00	2	1.6	1.000	602CA_Trip380	1
02/03/2026 08:42:38	52.359511	4.890996	100	Sudden braking	2.30	2.30	15.1	17.2	1.00	1	4.2	1.000	602CA_Trip380	1
02/03/2026 08:42:39	52.359505	4.891057	100	Sudden braking	3.00	3.00	14.5	14.2	1.00	1	2.8	1.000	602CA_Trip380	1
02/03/2026 08:42:40	52.359504	4.891098	98	Sudden braking	3.00	3.00	12.6	11.2	1.00	1	1.7	1.000	602CA_Trip380	1
02/03/2026 08:42:41	52.359499	4.891121	103	Sudden braking	2.80	2.80	11.6	8.4	1.00	1	1.3	1.000	602CA_Trip380	1
02/03/2026 08:42:42	52.359496	4.891140	104	Sudden braking	2.70	2.70	10.4	5.7	1.00	1	1.1	1.000	602CA_Trip380	1
02/03/2026 08:44:35	52.359333	4.898110	77	Sudden braking	2.60	2.60	16.4	17.1	1.00	2	5.1	1.000	602CA_Trip380	1
02/03/2026 08:44:36	52.359339	4.898184	78	Sudden braking	2.40	2.40	14.8	14.7	1.00	2	1.1	1.000	602CA_Trip380	1
02/03/2026 08:44:37	52.359342	4.898200	78	Sudden braking	2.20	2.20	13.9	12.5	1.00	2	2.3	0.999	602CA_Trip380	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
02/03/2026 08:44:38	52.359349	4.898231	78	Sudden braking	2.40	2.40	12.9	10.1	1.00	2	2.3	1.000	602CA_Trip380	1
02/03/2026 08:44:39	52.359356	4.898263	78	Sudden braking	2.20	2.20	11.8	7.9	1.00	2	1.8	1.000	602CA_Trip380	1
02/03/2026 08:46:48	52.360975	4.907616	72	Sudden braking	3.00	3.00	17.7	19.4	1.00	2	4.2	1.000	602CA_Trip380	1
02/03/2026 08:46:49	52.360984	4.907677	73	Sudden braking	3.60	3.60	15.9	15.8	1.00	2	2.7	1.000	602CA_Trip380	1
02/03/2026 08:46:50	52.360990	4.907715	71	Sudden braking	3.30	3.30	14.0	12.5	1.00	2	1.9	1.000	602CA_Trip380	1
02/03/2026 08:46:51	52.361001	4.907737	66	Sudden braking	2.70	2.70	12.1	9.8	1.00	2	2.2	1.000	602CA_Trip380	1
02/03/2026 08:46:52	52.361010	4.907766	66	Sudden braking	2.00	2.00	10.9	7.8	1.00	2	1.9	1.000	602CA_Trip380	1
02/03/2026 08:49:12	52.364719	4.910793	343	Sudden braking	2.40	2.40	19.8	20.6	1.00	2	4.9	1.000	602CA_Trip380	1
02/03/2026 08:49:13	52.364760	4.910770	344	Sudden braking	2.60	2.60	19.5	18.0	1.00	2	3.9	1.000	602CA_Trip380	1
02/03/2026 08:49:14	52.364792	4.910747	344	Sudden braking	2.20	2.20	18.7	15.8	1.00	2	3.0	1.000	602CA_Trip380	1
02/03/2026 08:49:40	52.366039	4.911558	30	Sudden braking	2.10	2.10	17.7	18.7	1.00	3	4.2	1.000	602CA_Trip380	1
02/03/2026 08:49:41	52.366070	4.911591	30	Sudden braking	2.30	2.30	16.4	16.4	1.00	3	3.8	1.000	602CA_Trip380	1
02/03/2026 08:49:42	52.366101	4.911615	30	Sudden braking	2.30	2.30	15.0	14.1	1.00	3	3.8	1.000	602CA_Trip380	1
02/03/2026 08:49:43	52.366133	4.911636	30	Sudden braking	2.00	2.00	13.8	12.1	1.00	3	2.9	1.000	602CA_Trip380	1
02/03/2026 08:51:03	52.369476	4.912364	299	Sudden braking	2.10	2.10	18.5	18.0	1.00	2	3.9	1.000	602CA_Trip380	1
02/03/2026 08:51:04	52.369498	4.912319	299	Sudden braking	2.30	2.30	17.4	15.7	1.00	2	4.0	1.000	602CA_Trip380	1
02/03/2026 08:52:06	52.371000	4.914957	60	Sudden braking	2.00	2.00	15.6	14.8	1.00	2	3.4	1.000	602CA_Trip380	1
02/03/2026 08:52:07	52.371007	4.915006	69	Sudden braking	2.10	2.10	14.1	12.7	1.00	2	3.0	1.000	602CA_Trip380	1
02/03/2026 08:52:08	52.371012	4.915049	74	Sudden braking	2.30	2.30	13.1	10.4	1.00	2	2.1	1.000	602CA_Trip380	1
01/04/2026 09:07:55	52.374505	4.915053	255	Sudden braking	2.07	2.07	16.9	16.0	0.97	3	5.3	0.967	602CA_Trip194	1
01/04/2026 09:09:00	52.376584	4.914058	340	Sudden braking	2.30	2.30	16.9	16.0	1.00	2	4.4	0.999	602CA_Trip194	1
01/04/2026 09:11:15	52.373886	4.920184	226	Sudden braking	2.54	2.54	18.0	17.4	0.95	2	4.0	0.946	602CA_Trip194	1
01/04/2026 09:11:16	52.373860	4.920144	217	Sudden braking	2.29	2.29	18.0	15.0	1.05	2	6.0	1.050	602CA_Trip194	1
08/04/2026 13:26:31	52.375050	4.914063	211	Sudden braking	2.00	2.00	12.0	13.3	1.00	3	5.3	1.001	602DE_Trip197	1
08/04/2026 13:26:32	52.375008	4.914025	210	Sudden braking	2.90	2.90	11.7	10.4	1.00	3	3.4	0.999	602DE_Trip197	1
08/04/2026 13:26:33	52.374983	4.913994	213	Sudden braking	2.40	2.40	11.5	8.0	1.00	3	1.7	1.000	602DE_Trip197	1
08/04/2026 13:28:23	52.372704	4.917601	138	Sudden braking	2.80	2.80	15.2	13.2	1.00	2	3.4	1.000	602DE_Trip197	1
08/04/2026 13:28:24	52.372674	4.917609	155	Sudden braking	2.00	2.00	14.9	11.2	1.00	2	3.0	1.001	602DE_Trip197	1
08/04/2026 13:46:17	52.376684	4.913279	91	Sudden braking	2.40	2.40	13.1	12.8	1.00	3	3.8	1.000	602DE_Trip198	1
08/04/2026 13:47:25	52.375175	4.914090	187	Sudden braking	2.10	2.10	9.8	7.2	1.00	3	4.9	1.000	602DE_Trip198	1
08/04/2026 14:22:00	52.372656	4.917755	141	Sudden braking	2.40	2.40	17.5	19.6	1.00	2	6.4	1.000	602DE_Trip203	1
08/04/2026 14:22:01	52.372612	4.917815	139	Sudden braking	2.80	2.80	15.4	16.8	1.00	2	4.5	1.000	602DE_Trip203	1
08/04/2026 14:22:02	52.372579	4.917855	140	Sudden braking	3.20	3.20	12.3	13.6	1.00	2	3.2	1.000	602DE_Trip203	1
08/04/2026 14:22:03	52.372557	4.917886	139	Sudden braking	4.10	4.10	10.4	9.5	1.00	2	2.8	1.000	602DE_Trip203	1
08/04/2026 14:22:04	52.372538	4.917912	144	Sudden braking	3.30	3.30	9.8	6.2	1.00	2	1.2	0.999	602DE_Trip203	1
08/04/2026 14:22:53	52.376046	4.914151	340	Sudden braking	2.80	2.80	15.5	15.0	1.00	3	4.6	1.000	602D3_Trip201	1
08/04/2026 14:22:54	52.376087	4.914158	352	Sudden braking	2.80	2.80	15.3	12.2	1.00	2	1.0	1.000	602D3_Trip201	1
08/04/2026 14:23:13	52.376727	4.913543	281	Sudden braking	2.10	2.10	15.5	16.0	1.00	3	4.0	1.000	602D3_Trip201	1
08/04/2026 14:23:14	52.376728	4.913484	279	Sudden braking	2.20	2.20	15.1	13.8	1.00	3	3.9	1.000	602D3_Trip201	1
08/04/2026 14:23:15	52.375194	4.921292	12	Sudden braking	2.10	2.10	19.4	20.2	1.00	2	5.6	0.999	602DE_Trip203	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
08/04/2026 14:23:16	52.375243	4.921315	15	Sudden braking	2.20	2.20	18.1	18.0	1.00	2	4.7	1.000	602DE_Trip203	1
08/04/2026 14:23:17	52.374275	4.914652	67	Sudden braking	2.40	2.40	13.1	12.6	1.00	3	5.3	1.000	602D6_Trip200	1
08/04/2026 14:23:17	52.375283	4.921336	18	Sudden braking	2.10	2.10	16.8	15.9	1.00	3	3.9	1.000	602DE_Trip203	1
08/04/2026 14:23:18	52.375318	4.921349	11	Sudden braking	2.00	2.00	16.0	13.9	1.00	3	3.5	1.001	602DE_Trip203	1
08/04/2026 14:23:26	52.375515	4.921395	331	Sudden braking	2.10	2.10	6.1	6.2	1.00	2	1.6	0.999	602DE_Trip203	1
08/04/2026 14:23:27	52.375526	4.921381	322	Sudden braking	2.20	2.20	5.7	4.0	1.00	2	0.5	1.000	602DE_Trip203	1
08/04/2026 14:23:44	52.375616	4.920558	282	Sudden braking	2.40	2.40	15.5	14.9	1.00	2	4.1	1.001	602DE_Trip203	1
08/04/2026 14:23:45	52.375625	4.920500	280	Sudden braking	2.40	2.40	13.8	12.5	1.00	3	3.2	1.000	602DE_Trip203	1
08/04/2026 14:24:00	52.375189	4.914251	205	Sudden braking	2.50	2.50	15.2	16.4	1.00	3	5.8	1.000	602D3_Trip201	1
08/04/2026 14:24:01	52.375139	4.914226	200	Sudden braking	2.30	2.30	14.6	14.1	1.00	3	1.9	1.000	602D3_Trip201	1
08/04/2026 14:24:02	52.375131	4.914251	178	Sudden braking	2.80	2.80	14.3	11.3	1.00	3	5.8	1.000	602D3_Trip201	1
08/04/2026 14:24:03	52.375080	4.914273	168	Sudden braking	2.70	2.70	14.2	8.6	1.00	2	1.9	1.000	602D3_Trip201	1
08/04/2026 14:24:45	52.376621	4.914305	284	Sudden braking	2.50	2.50	22.3	22.2	1.00	3	6.5	1.001	602DE_Trip203	1
08/04/2026 14:24:46	52.376637	4.914213	285	Sudden braking	2.60	2.60	21.5	19.6	1.00	3	5.3	1.000	602DE_Trip203	1
08/04/2026 14:24:48	52.372400	4.918247	46	Sudden braking	2.70	2.70	9.3	8.9	1.00	2	2.1	1.000	602CA_Trip202	1
08/04/2026 14:34:03	52.374789	4.915445	98	Sudden braking	2.00	2.00	6.4	4.9	1.00	2	1.2	1.000	604F0_Trip204	1
08/04/2026 14:44:56	52.376400	4.903268	216	Sudden braking	2.50	2.50	11.4	9.5	1.00	1	2.1	1.000	602CA_Trip206	1
08/04/2026 14:44:57	52.376385	4.903249	216	Sudden braking	2.70	2.70	10.9	6.8	1.00	1	1.1	1.000	602CA_Trip206	1
08/04/2026 14:48:54	52.369022	4.902478	121	Sudden braking	2.00	2.00	13.9	13.2	1.00	2	3.1	1.000	602CA_Trip206	1
08/04/2026 14:48:55	52.369008	4.902517	121	Sudden braking	2.60	2.60	12.2	10.6	1.00	2	2.7	1.000	602CA_Trip206	1
08/04/2026 14:48:56	52.368995	4.902551	122	Sudden braking	2.50	2.50	11.3	8.1	1.00	1	1.5	1.000	602CA_Trip206	1
08/04/2026 14:50:38	52.376574	4.914062	350	Sudden braking	2.00	2.00	20.5	18.6	1.00	3	4.4	1.000	604F0_Trip207	1
08/04/2026 14:51:17	52.376114	4.910694	243	Sudden braking	2.30	2.30	18.2	17.6	1.00	3	3.7	1.000	604F0_Trip207	1
08/04/2026 14:51:18	52.376095	4.910649	239	Sudden braking	2.00	2.00	17.2	15.6	1.00	3	3.5	1.000	604F0_Trip207	1
08/04/2026 14:51:25	52.375873	4.910650	178	Sudden braking	2.10	2.10	10.0	8.7	1.00	3	1.2	1.000	604F0_Trip207	1
08/04/2026 14:51:26	52.375862	4.910650	176	Sudden braking	2.10	2.10	9.5	6.6	1.00	2	1.0	1.000	604F0_Trip207	1
08/04/2026 14:52:23	52.378135	4.908219	283	Sudden braking	2.70	2.70	24.2	27.4	1.00	2	8.2	1.000	604F0_Trip207	1
08/04/2026 14:52:24	52.378152	4.908102	283	Sudden braking	4.50	4.50	23.4	22.9	1.00	2	5.7	1.000	604F0_Trip207	1
08/04/2026 14:52:25	52.378162	4.908019	283	Sudden braking	5.60	5.60	20.5	17.3	1.00	2	2.4	1.000	604F0_Trip207	1
08/04/2026 14:52:26	52.378167	4.907984	283	Sudden braking	2.75	2.75	19.2	11.8	2.00	2	1.2	2.000	604F0_Trip207	1
08/04/2026 14:52:28	52.378171	4.907968	283	Sudden braking	2.15	2.15	13.1	7.5	2.00	2	1.6	2.000	604F0_Trip207	1
08/04/2026 14:55:16	52.382925	4.893696	267	Sudden braking	2.30	2.30	27.3	28.7	1.00	3	7.9	1.000	604F0_Trip207	1
08/04/2026 14:55:17	52.382922	4.893580	269	Sudden braking	2.80	2.80	26.0	25.9	1.00	3	8.5	1.000	604F0_Trip207	1
08/04/2026 14:55:18	52.382941	4.893458	285	Sudden braking	3.10	3.10	24.9	22.8	1.00	2	8.0	1.000	604F0_Trip207	1
08/04/2026 14:55:19	52.382992	4.893374	311	Sudden braking	2.70	2.70	24.1	20.1	1.00	2	6.5	1.000	604F0_Trip207	1
08/04/2026 14:56:18	52.388519	4.891958	345	Sudden braking	2.90	2.90	30.7	33.7	1.00	2	9.0	1.000	604F0_Trip207	1
08/04/2026 14:56:19	52.388597	4.891925	345	Sudden braking	3.90	3.90	28.3	29.8	1.00	2	7.8	1.000	604F0_Trip207	1
08/04/2026 14:56:20	52.388664	4.891894	345	Sudden braking	4.30	4.30	25.8	25.5	1.00	2	6.0	1.000	604F0_Trip207	1
08/04/2026 14:56:21	52.388717	4.891874	345	Sudden braking	4.10	4.10	23.2	21.4	1.00	2	4.7	1.000	604F0_Trip207	1
08/04/2026 14:56:22	52.388758	4.891857	345	Sudden braking	3.50	3.50	20.7	17.9	1.00	2	3.8	1.000	604F0_Trip207	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
08/04/2026 14:56:23	52.388792	4.891844	345	Sudden braking	2.70	2.70	18.3	15.2	1.00	2	3.6	0.999	604F0_Trip207	1
08/04/2026 14:56:23	52.388823	4.891831	345	Sudden braking	2.00	2.00	16.2	13.2	1.00	2	3.5	1.000	604F0_Trip207	1
08/04/2026 14:56:41	52.368134	4.903576	215	Sudden braking	2.20	2.20	12.6	14.4	1.00	1	4.0	1.000	602CA_Trip206	1
08/04/2026 14:56:42	52.368105	4.903542	215	Sudden braking	2.80	2.80	12.3	11.6	1.00	1	1.6	1.000	602CA_Trip206	1
08/04/2026 14:56:43	52.368093	4.903530	212	Sudden braking	3.30	3.30	10.8	8.3	1.00	1	1.0	1.000	602CA_Trip206	1
08/04/2026 14:56:44	52.368085	4.903522	212	Sudden braking	3.30	3.30	10.0	5.0	1.00	1	1.2	1.000	602CA_Trip206	1
08/04/2026 14:57:31	52.390491	4.885584	300	Sudden braking	2.70	2.70	19.9	21.7	1.00	2	4.7	1.000	604F0_Trip207	1
08/04/2026 14:57:32	52.390512	4.885523	300	Sudden braking	3.20	3.20	19.1	18.5	1.00	2	2.9	1.000	604F0_Trip207	1
08/04/2026 14:57:33	52.390525	4.885485	300	Sudden braking	3.20	3.20	18.2	15.3	1.00	2	2.4	1.000	604F0_Trip207	1
08/04/2026 14:57:34	52.390535	4.885455	300	Sudden braking	3.30	3.30	17.1	12.0	1.00	2	2.6	1.000	604F0_Trip207	1
08/04/2026 14:57:35	52.390547	4.885422	300	Sudden braking	2.40	2.40	15.8	9.6	1.00	2	2.7	1.000	604F0_Trip207	1
08/04/2026 14:59:28	52.361424	4.907718	161	Sudden braking	2.00	2.00	11.0	11.4	1.00	2	3.5	1.000	602CA_Trip206	1
08/04/2026 14:59:29	52.361394	4.907735	161	Sudden braking	2.50	2.50	10.4	8.9	1.00	2	2.5	1.000	602CA_Trip206	1
08/04/2026 14:59:30	52.361373	4.907747	161	Sudden braking	2.50	2.50	9.8	6.4	1.00	2	1.4	1.000	602CA_Trip206	1
08/04/2026 15:00:03	52.392922	4.868645	259	Sudden braking	2.10	2.10	33.7	35.5	1.00	2	9.4	1.000	604F0_Trip207	1
08/04/2026 15:00:03	52.360454	4.908301	159	Sudden braking	2.30	2.30	12.2	11.4	1.00	2	2.9	1.001	602CA_Trip206	1
08/04/2026 15:00:04	52.392889	4.868518	249	Sudden braking	2.90	2.90	32.4	32.6	1.00	3	8.4	1.000	604F0_Trip207	1
08/04/2026 15:00:05	52.392845	4.868417	242	Sudden braking	3.10	3.10	31.2	29.5	1.00	2	6.7	1.000	604F0_Trip207	1
08/04/2026 15:00:05	52.360430	4.908315	159	Sudden braking	2.90	2.90	10.2	8.5	1.00	2	2.0	1.000	602CA_Trip206	1
08/04/2026 15:00:06	52.392807	4.868341	235	Sudden braking	2.40	2.40	30.1	27.1	1.00	2	5.5	1.000	604F0_Trip207	1
08/04/2026 15:00:06	52.360413	4.908326	159	Sudden braking	2.40	2.40	9.3	6.1	1.00	2	1.3	1.000	602CA_Trip206	1
08/04/2026 15:00:38	52.359983	4.908578	161	Sudden braking	2.90	2.90	14.1	12.6	1.00	1	3.2	1.000	602CA_Trip206	1
08/04/2026 15:00:39	52.359956	4.908594	161	Sudden braking	3.70	3.70	13.6	8.9	1.00	1	1.6	1.000	602CA_Trip206	1
08/04/2026 15:01:26	52.375525	4.914356	19	Sudden braking	2.00	2.00	11.5	14.4	1.00	3	7.0	1.000	602D6_Trip208	1
08/04/2026 15:01:27	52.375569	4.914431	23	Sudden braking	2.10	2.10	10.2	12.3	1.00	2	6.2	1.000	602D6_Trip208	1
08/04/2026 15:01:28	52.375525	4.914487	37	Sudden braking	2.60	2.60	9.8	9.7	1.00	2	10.0	1.000	602D6_Trip208	1
08/04/2026 15:01:29	52.375593	4.914581	65	Sudden braking	2.10	2.10	9.5	7.6	1.00	2	2.3	1.000	602D6_Trip208	1
08/04/2026 15:02:20	52.376555	4.911995	259	Sudden braking	2.40	2.40	14.5	14.8	1.00	2	5.8	1.000	602D6_Trip208	1
08/04/2026 15:02:21	52.376534	4.911916	253	Sudden braking	2.40	2.40	13.3	12.4	1.00	2	1.7	1.000	602D6_Trip208	1
08/04/2026 15:02:22	52.376537	4.911940	256	Sudden braking	2.30	2.30	12.3	10.1	1.00	2	5.3	1.001	602D6_Trip208	1
08/04/2026 15:02:23	52.376504	4.911885	237	Sudden braking	2.30	2.30	11.1	7.8	1.00	2	4.5	1.000	602D6_Trip208	1
08/04/2026 15:02:31	52.376331	4.911354	232	Sudden braking	2.00	2.00	10.9	12.7	1.00	2	1.2	1.000	602D6_Trip208	1
08/04/2026 15:02:32	52.376333	4.911338	239	Sudden braking	2.20	2.20	11.1	10.5	1.00	2	2.9	1.000	602D6_Trip208	1
08/04/2026 15:02:33	52.376320	4.911301	240	Sudden braking	2.30	2.30	11.4	8.2	1.00	2	3.2	1.000	602D6_Trip208	1
08/04/2026 15:02:41	52.376151	4.910767	242	Sudden braking	2.00	2.00	12.5	14.7	1.00	2	2.8	1.000	602D6_Trip208	1
08/04/2026 15:03:19	52.376645	4.910311	351	Sudden braking	2.50	2.50	15.7	16.4	1.00	2	3.8	1.000	602D6_Trip208	1
08/04/2026 15:03:20	52.376613	4.910330	357	Sudden braking	2.80	2.80	15.3	13.6	1.00	2	2.0	1.000	602D6_Trip208	1
08/04/2026 15:03:21	52.376628	4.910346	11	Sudden braking	2.60	2.60	15.0	11.0	1.00	3	1.9	1.000	602D6_Trip208	1
08/04/2026 15:03:47	52.377920	4.909788	301	Sudden braking	2.50	2.50	14.3	14.9	1.00	2	6.1	1.000	602D6_Trip208	1
08/04/2026 15:03:48	52.377934	4.909701	289	Sudden braking	2.50	2.50	13.2	12.4	1.00	2	4.1	1.000	602D6_Trip208	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
08/04/2026 15:04:14	52.378236	4.907507	292	Sudden braking	2.00	2.00	15.8	17.0	1.00	2	5.1	1.000	602D6_Trip208	1
08/04/2026 15:04:15	52.378249	4.907435	291	Sudden braking	2.50	2.50	14.6	14.5	1.00	2	2.5	1.000	602D6_Trip208	1
08/04/2026 15:04:16	52.378256	4.907399	285	Sudden braking	2.40	2.40	13.4	12.1	1.00	2	1.8	1.000	602D6_Trip208	1
08/04/2026 15:04:17	52.378265	4.907377	296	Sudden braking	2.10	2.10	12.3	10.0	1.00	2	2.0	1.000	602D6_Trip208	1
08/04/2026 15:04:52	52.410004	4.829844	307	Sudden braking	2.50	2.50	29.8	31.8	1.00	1	8.3	1.000	604F0_Trip207	1
08/04/2026 15:04:53	52.410050	4.829746	307	Sudden braking	3.30	3.30	27.9	28.5	1.00	1	6.7	1.000	604F0_Trip207	1
08/04/2026 15:04:54	52.410085	4.829667	307	Sudden braking	3.80	3.80	26.0	24.7	1.00	1	5.3	1.000	604F0_Trip207	1
08/04/2026 15:04:55	52.410114	4.829605	308	Sudden braking	3.40	3.40	24.2	21.3	1.00	1	2.5	1.000	604F0_Trip207	1
08/04/2026 15:04:56	52.410128	4.829576	308	Sudden braking	2.40	2.40	22.6	18.9	1.00	1	1.7	1.000	604F0_Trip207	1
08/04/2026 15:05:03	52.410332	4.829272	314	Sudden braking	2.50	2.50	14.1	14.2	1.00	2	4.2	1.000	604F0_Trip207	1
08/04/2026 15:05:04	52.410356	4.829224	314	Sudden braking	3.20	3.20	13.7	11.0	1.00	2	1.5	1.000	604F0_Trip207	1
08/04/2026 15:05:05	52.410365	4.829208	314	Sudden braking	3.20	3.20	13.0	7.8	1.00	2	1.1	1.000	604F0_Trip207	1
08/04/2026 15:06:35	52.416619	4.826423	6	Sudden braking	2.50	2.50	35.1	34.4	1.00	2	9.3	1.001	604F0_Trip207	1
08/04/2026 15:06:37	52.416701	4.826398	1	Sudden braking	2.70	2.70	33.6	31.7	1.00	2	7.4	1.000	604F0_Trip207	1
08/04/2026 15:06:44	52.417091	4.826904	46	Sudden braking	2.00	2.00	30.1	30.1	1.00	2	4.5	1.000	604F0_Trip207	1
08/04/2026 15:06:46	52.417162	4.826936	37	Sudden braking	2.57	2.57	30.2	25.7	1.00	2	18.0	1.000	604F0_Trip207	1
08/04/2026 15:11:55	52.382902	4.909636	40	Sudden braking	2.90	2.90	15.9	15.7	1.00	2	5.5	1.000	602D6_Trip208	1
08/04/2026 15:11:56	52.382938	4.909691	43	Sudden braking	2.70	2.70	15.4	13.0	1.00	2	1.6	1.000	602D6_Trip208	1
08/04/2026 15:11:57	52.382927	4.909674	43	Sudden braking	2.20	2.20	15.1	10.8	1.00	2	3.8	1.000	602D6_Trip208	1
08/04/2026 15:12:21	52.383853	4.909964	41	Sudden braking	2.70	2.70	12.8	11.5	1.00	2	7.3	1.000	602D6_Trip208	1
08/04/2026 15:13:01	52.384648	4.912274	41	Sudden braking	2.40	2.40	8.8	8.9	1.00	2	1.1	1.000	602D6_Trip208	1
08/04/2026 15:13:02	52.384648	4.912291	41	Sudden braking	2.30	2.30	8.8	6.6	1.00	2	1.6	1.000	602D6_Trip208	1
08/04/2026 15:13:52	52.386897	4.916053	54	Sudden braking	2.30	2.30	17.0	20.6	1.00	2	6.2	1.000	602D6_Trip208	1
08/04/2026 15:13:53	52.386930	4.916126	54	Sudden braking	3.30	3.30	16.0	17.3	1.00	2	6.1	1.000	602D6_Trip208	1
08/04/2026 15:13:54	52.386963	4.916198	54	Sudden braking	3.30	3.30	15.5	14.0	1.00	2	7.7	1.000	602D6_Trip208	1
08/04/2026 15:13:55	52.386922	4.916107	54	Sudden braking	2.90	2.90	15.5	11.1	1.00	2	2.0	1.000	602D6_Trip208	1
08/04/2026 15:14:24	52.388079	4.918293	54	Sudden braking	3.60	3.60	16.4	17.2	1.00	2	7.1	1.000	602D6_Trip208	1
08/04/2026 15:14:25	52.388116	4.918378	54	Sudden braking	3.40	3.40	14.7	13.8	1.00	2	10.0	1.000	602D6_Trip208	1
08/04/2026 15:14:26	52.388064	4.918258	54	Sudden braking	2.70	2.70	13.1	11.1	1.00	2	1.2	1.000	602D6_Trip208	1
08/04/2026 15:14:27	52.388070	4.918273	54	Sudden braking	2.90	2.90	11.6	8.2	1.00	2	1.6	1.000	602D6_Trip208	1
08/04/2026 15:15:19	52.389543	4.921970	54	Sudden braking	2.20	2.20	14.9	15.3	1.00	3	5.8	1.000	602D6_Trip208	1
08/04/2026 15:15:20	52.389575	4.922039	54	Sudden braking	2.10	2.10	13.8	13.2	1.00	3	5.4	1.000	602D6_Trip208	1
08/04/2026 15:15:21	52.389527	4.922025	54	Sudden braking	2.10	2.10	13.3	11.1	1.00	3	3.2	1.000	602D6_Trip208	1
08/04/2026 15:16:33	52.391716	4.925957	45	Sudden braking	2.80	2.80	15.8	17.4	1.00	2	6.8	1.000	602D6_Trip208	1
08/04/2026 15:16:34	52.391769	4.926007	40	Sudden braking	2.90	2.90	14.5	14.5	1.00	2	3.8	1.000	602D6_Trip208	1
08/04/2026 15:16:35	52.391737	4.925988	50	Sudden braking	2.70	2.70	13.1	11.8	1.00	2	4.9	1.000	602D6_Trip208	1
08/04/2026 15:16:36	52.391769	4.926039	38	Sudden braking	2.70	2.70	11.8	9.1	1.00	2	2.4	1.000	602D6_Trip208	1
08/04/2026 15:30:47	52.434070	4.816677	251	Sudden braking	3.50	3.50	30.9	32.3	1.00	2	10.2	1.000	604F0_Trip210	1
08/04/2026 15:30:55	52.433983	4.815834	324	Sudden braking	2.90	2.90	25.6	26.6	1.00	4	0.7	1.000	604F0_Trip210	1
08/04/2026 15:30:56	52.433988	4.815830	345	Sudden braking	3.00	3.00	26.2	23.6	1.00	4	0.8	1.000	604F0_Trip210	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
08/04/2026 15:33:22	52.448350	4.808726	352	Sudden braking	2.20	2.20	37.5	37.8	1.00	2	11.0	1.000	604F0_Trip210	1
08/04/2026 15:33:23	52.448448	4.808702	352	Sudden braking	4.50	4.50	37.1	33.3	1.00	2	11.2	1.000	604F0_Trip210	1
08/04/2026 15:33:40	52.449823	4.808006	337	Sudden braking	5.10	5.10	13.5	23.5	1.00	3	4.2	1.000	604F0_Trip210	1
08/04/2026 15:33:41	52.449858	4.807981	337	Sudden braking	5.70	5.70	13.5	17.8	1.00	3	4.4	1.000	604F0_Trip210	1
08/04/2026 15:33:42	52.449895	4.807956	337	Sudden braking	4.10	4.10	12.4	13.7	1.00	2	2.9	1.000	604F0_Trip210	1
08/04/2026 15:33:43	52.449919	4.807940	337	Sudden braking	2.50	2.50	12.4	11.2	1.00	2	2.2	1.000	604F0_Trip210	1
08/04/2026 15:33:44	52.449937	4.807927	337	Sudden braking	2.70	2.70	12.4	8.5	1.00	2	1.4	1.000	604F0_Trip210	1
08/04/2026 15:37:22	52.470088	4.805497	357	Sudden braking	2.40	2.40	33.8	34.9	1.00	2	8.5	1.000	604F0_Trip210	1
08/04/2026 15:37:23	52.470164	4.805490	357	Sudden braking	2.90	2.90	31.6	32.0	1.00	2	6.9	1.000	604F0_Trip210	1
08/04/2026 15:37:24	52.470226	4.805487	358	Sudden braking	3.40	3.40	29.0	28.6	1.00	2	6.8	1.001	604F0_Trip210	1
08/04/2026 15:37:26	52.470287	4.805483	358	Sudden braking	3.70	3.70	23.1	24.9	1.00	2	6.0	1.000	604F0_Trip210	1
08/04/2026 15:37:27	52.470341	4.805480	358	Sudden braking	3.60	3.60	20.0	21.3	1.00	2	4.7	1.000	604F0_Trip210	1
08/04/2026 15:37:28	52.470383	4.805478	358	Sudden braking	3.40	3.40	18.3	17.9	1.00	2	3.0	1.000	604F0_Trip210	1
08/04/2026 15:37:29	52.470409	4.805476	358	Sudden braking	3.30	3.30	15.3	14.6	1.00	2	2.7	1.000	604F0_Trip210	1
08/04/2026 15:37:30	52.470433	4.805474	358	Sudden braking	3.30	3.30	13.6	11.3	1.00	2	2.0	1.000	604F0_Trip210	1
08/04/2026 15:37:31	52.470451	4.805473	358	Sudden braking	3.10	3.10	13.6	8.2	1.00	2	1.7	1.000	604F0_Trip210	1
08/04/2026 15:41:17	52.484983	4.806079	322	Sudden braking	2.90	2.90	28.3	32.3	1.00	2	8.5	1.000	604F0_Trip210	1
08/04/2026 15:41:18	52.485043	4.806003	322	Sudden braking	3.90	3.90	25.1	28.4	1.00	2	7.5	1.000	604F0_Trip210	1
08/04/2026 15:41:19	52.485096	4.805934	320	Sudden braking	5.00	5.00	23.7	23.4	1.00	2	5.7	1.000	604F0_Trip210	1
08/04/2026 15:41:20	52.485132	4.805873	315	Sudden braking	5.70	5.70	22.1	17.7	1.00	2	0.7	1.000	604F0_Trip210	1
08/04/2026 15:41:21	52.485139	4.805874	320	Sudden braking	5.70	5.70	18.5	12.0	1.00	2	2.3	1.000	604F0_Trip210	1
08/04/2026 15:41:22	52.485119	4.805884	23	Sudden braking	4.50	4.50	16.4	7.5	1.00	2	0.6	1.000	604F0_Trip210	1
08/04/2026 15:42:36	52.488515	4.796456	302	Sudden braking	2.80	2.80	31.8	35.0	1.00	2	8.8	1.000	604F0_Trip210	1
08/04/2026 15:42:37	52.488559	4.796348	301	Sudden braking	3.60	3.60	29.6	31.4	1.00	2	6.1	1.000	604F0_Trip210	1
08/04/2026 15:42:38	52.488577	4.796264	301	Sudden braking	4.30	4.30	27.6	27.1	1.00	2	5.2	1.000	604F0_Trip210	1
08/04/2026 15:42:39	52.488597	4.796194	299	Sudden braking	4.40	4.40	25.7	22.7	1.00	2	4.1	1.000	604F0_Trip210	1
08/04/2026 15:42:40	52.488615	4.796141	300	Sudden braking	3.60	3.60	24.1	19.1	1.00	2	1.7	1.000	604F0_Trip210	1
08/04/2026 15:42:41	52.488614	4.796116	251	Sudden braking	2.10	2.10	22.9	17.0	1.00	2	1.9	1.000	604F0_Trip210	1
08/04/2026 15:43:03	52.489527	4.793713	301	Sudden braking	2.00	2.00	34.6	32.6	1.00	3	8.8	1.000	604F0_Trip210	1
08/04/2026 15:44:25	52.492009	4.780694	288	Sudden braking	2.10	2.10	39.3	36.8	1.00	2	12.0	1.000	604F0_Trip210	1
08/04/2026 15:53:39	52.519646	4.706961	339	Sudden braking	2.80	2.80	36.3	34.1	1.00	2	8.4	1.000	604F0_Trip210	1
08/04/2026 15:54:21	52.521947	4.702426	312	Sudden braking	3.70	3.70	26.6	29.5	1.00	3	6.9	1.000	604F0_Trip210	1
08/04/2026 15:54:22	52.521988	4.702350	311	Sudden braking	4.30	4.30	26.6	25.2	1.00	3	4.7	1.000	604F0_Trip210	1
08/04/2026 15:54:23	52.522015	4.702298	314	Sudden braking	3.80	3.80	26.6	21.4	1.00	3	2.5	1.000	604F0_Trip210	1
08/04/2026 15:56:50	52.535775	4.695527	354	Sudden braking	2.60	2.60	33.6	33.9	1.00	3	8.4	1.000	604F0_Trip210	1
08/04/2026 15:56:51	52.535851	4.695514	354	Sudden braking	2.90	2.90	32.5	31.0	1.00	3	6.9	1.000	604F0_Trip210	1
08/04/2026 15:56:52	52.535912	4.695506	355	Sudden braking	2.30	2.30	31.5	28.7	1.00	3	4.9	1.000	604F0_Trip210	1
08/04/2026 15:59:22	52.541475	4.677041	280	Sudden braking	2.20	2.20	31.6	31.2	1.00	3	7.7	1.000	604F0_Trip210	1
08/04/2026 15:59:23	52.541488	4.676929	280	Sudden braking	2.20	2.20	30.7	29.0	1.00	3	6.6	1.000	604F0_Trip210	1
08/04/2026 15:59:40	52.542647	4.676015	311	Sudden braking	2.70	2.70	30.2	32.3	1.00	3	9.3	1.000	604F0_Trip210	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
08/04/2026 15:59:41	52.542697	4.675904	305	Sudden braking	3.50	3.50	29.0	28.8	1.00	3	7.5	1.000	604F0_Trip210	1
08/04/2026 15:59:42	52.542742	4.675821	300	Sudden braking	3.30	3.30	27.9	25.5	1.00	3	5.3	1.000	604F0_Trip210	1
08/04/2026 15:59:43	52.542766	4.675753	300	Sudden braking	2.70	2.70	26.9	22.8	1.00	3	4.8	1.000	604F0_Trip210	1
08/04/2026 17:22:41	52.372686	4.893228	264	Sudden braking	2.20	2.20	5.8	6.4	1.00	2	3.3	1.000	602DE_Trip211	1
08/04/2026 17:22:42	52.372663	4.893197	265	Sudden braking	2.20	2.20	4.6	4.2	1.00	2	1.4	0.999	602DE_Trip211	1
08/04/2026 20:35:08	52.360860	4.912294	344	Sudden braking	2.00	2.00	11.3	10.0	1.00	3	1.3	1.000	602CA_Trip213	1
08/04/2026 20:39:37	52.358115	4.891312	279	Sudden braking	2.00	2.00	14.8	14.8	1.00	2	3.3	1.000	602CA_Trip213	1
08/04/2026 20:39:38	52.358119	4.891264	279	Sudden braking	2.20	2.20	13.9	12.6	1.00	2	3.3	1.000	602CA_Trip213	1
08/04/2026 20:39:39	52.358127	4.891217	283	Sudden braking	2.10	2.10	13.3	10.5	1.00	2	2.3	1.000	602CA_Trip213	1
08/04/2026 20:43:50	52.365929	4.878323	322	Sudden braking	2.40	2.40	15.4	16.3	1.00	3	5.9	1.000	602CA_Trip213	1
08/04/2026 20:43:53	52.366003	4.878218	318	Sudden braking	2.40	2.40	10.7	10.9	1.00	2	2.0	1.000	602CA_Trip213	1
08/04/2026 20:43:54	52.366009	4.878190	317	Sudden braking	2.40	2.40	9.6	8.5	1.00	2	4.4	1.000	602CA_Trip213	1
08/04/2026 20:43:55	52.366043	4.878154	317	Sudden braking	2.20	2.20	8.5	6.3	1.00	3	4.5	1.000	602CA_Trip213	1
08/04/2026 20:44:56	52.368275	4.876648	332	Sudden braking	2.30	2.30	10.8	8.9	1.00	3	2.3	1.000	602CA_Trip213	1
08/04/2026 20:44:57	52.368294	4.876633	332	Sudden braking	2.40	2.40	9.6	6.5	1.00	2	1.5	1.000	602CA_Trip213	1
08/04/2026 20:46:20	52.371700	4.874295	346	Sudden braking	2.30	2.30	13.8	11.7	1.00	2	3.3	1.000	602CA_Trip213	1
08/04/2026 20:46:21	52.371729	4.874284	346	Sudden braking	2.40	2.40	13.1	9.3	1.00	2	1.7	1.000	602CA_Trip213	1
08/04/2026 20:47:52	52.373871	4.875175	357	Sudden braking	2.10	2.10	15.2	13.4	1.00	2	3.3	1.000	602CA_Trip213	1
08/04/2026 20:49:17	52.378342	4.877669	19	Sudden braking	2.10	2.10	13.7	14.5	1.00	1	3.0	1.000	602CA_Trip213	1
08/04/2026 20:49:18	52.378369	4.877677	16	Sudden braking	2.30	2.30	12.9	12.2	1.00	1	3.1	1.000	602CA_Trip213	1
08/04/2026 20:49:19	52.378397	4.877675	1	Sudden braking	2.30	2.30	12.0	9.9	1.00	1	3.6	1.000	602CA_Trip213	1
08/04/2026 20:49:20	52.378429	4.877673	358	Sudden braking	2.30	2.30	11.0	7.6	1.00	1	2.0	1.000	602CA_Trip213	1
08/04/2026 20:49:21	52.378447	4.877681	8	Sudden braking	2.30	2.30	10.0	5.3	1.00	1	1.7	1.000	602CA_Trip213	1
09/04/2026 06:10:22	52.370731	4.916531	302	Sudden braking	2.20	2.20	24.9	25.2	1.00	2	9.0	1.000	602D3_Trip214	1
09/04/2026 06:10:23	52.370752	4.916404	293	Sudden braking	2.20	2.20	24.8	23.0	1.00	2	3.9	1.000	602D3_Trip214	1
09/04/2026 06:43:34	52.391086	4.925890	256	Sudden braking	2.10	2.10	17.9	16.8	1.00	2	2.4	1.000	602D6_Trip215	1
09/04/2026 08:04:28	52.375943	4.906980	297	Sudden braking	2.10	2.10	17.8	17.1	1.00	2	2.8	1.000	602CA_Trip216	1
09/04/2026 08:04:29	52.375955	4.906944	298	Sudden braking	2.00	2.00	17.3	15.1	1.00	2	2.6	1.000	602CA_Trip216	1
09/04/2026 08:05:09	52.376902	4.903903	299	Sudden braking	2.10	2.10	17.8	16.4	1.00	2	3.1	1.000	602CA_Trip216	1
09/04/2026 08:09:31	52.382658	4.890951	260	Sudden braking	2.00	2.00	17.7	19.5	1.00	2	4.7	1.000	602CA_Trip216	1
09/04/2026 08:09:32	52.382654	4.890882	262	Sudden braking	2.40	2.40	17.1	17.1	1.00	2	3.7	1.000	602CA_Trip216	1
09/04/2026 08:09:33	52.382640	4.890832	255	Sudden braking	2.80	2.80	15.3	14.3	1.00	2	2.6	1.000	602CA_Trip216	1
09/04/2026 08:09:34	52.382629	4.890799	249	Sudden braking	2.70	2.70	13.4	11.6	1.00	2	3.0	1.000	602CA_Trip216	1
09/04/2026 08:09:35	52.382606	4.890774	234	Sudden braking	2.10	2.10	11.4	9.5	1.00	2	2.2	1.000	602CA_Trip216	1
09/04/2026 08:10:08	52.382735	4.891631	80	Sudden braking	2.90	2.90	11.5	9.8	1.00	2	2.1	1.000	602CA_Trip216	1
09/04/2026 08:12:36	52.384486	4.883489	313	Sudden braking	2.20	2.20	11.9	11.7	1.00	2	2.6	1.000	602CA_Trip216	1
09/04/2026 08:12:37	52.384502	4.883461	313	Sudden braking	2.10	2.10	11.3	9.6	1.00	2	2.3	1.000	602CA_Trip216	1
09/04/2026 08:13:08	52.384745	4.882560	286	Sudden braking	2.50	2.50	9.7	10.3	1.00	2	2.6	1.000	602CA_Trip216	1
09/04/2026 08:13:09	52.384748	4.882521	284	Sudden braking	2.80	2.80	8.9	7.5	1.00	2	1.2	1.000	602CA_Trip216	1
09/04/2026 08:13:10	52.384755	4.882508	291	Sudden braking	2.20	2.20	8.1	5.3	1.00	2	1.1	1.000	602CA_Trip216	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
09/04/2026 08:14:16	52.384891	4.881711	269	Sudden braking	2.00	2.00	8.9	8.9	1.00	2	1.7	1.000	602CA_Trip216	1
09/04/2026 08:14:17	52.384891	4.881686	269	Sudden braking	2.60	2.60	8.6	6.3	1.00	2	1.2	1.000	602CA_Trip216	1
09/04/2026 08:16:35	52.385491	4.875337	269	Sudden braking	2.00	2.00	15.4	16.6	1.00	2	4.6	1.000	602CA_Trip216	1
09/04/2026 08:16:36	52.385489	4.875269	269	Sudden braking	2.50	2.50	14.6	14.1	1.00	2	4.7	1.000	602CA_Trip216	1
09/04/2026 08:16:37	52.385488	4.875200	269	Sudden braking	2.20	2.20	13.8	11.9	1.00	2	1.8	1.000	602CA_Trip216	1
09/04/2026 08:17:02	52.384545	4.874965	180	Sudden braking	2.70	2.70	16.3	14.5	1.00	2	5.2	1.000	602CA_Trip216	1
09/04/2026 08:17:11	52.384278	4.875172	134	Sudden braking	2.00	2.00	10.2	10.5	1.00	2	3.1	1.000	602CA_Trip216	1
09/04/2026 08:17:37	52.384880	4.875057	352	Sudden braking	2.40	2.40	13.8	15.0	1.00	2	5.7	1.000	602CA_Trip216	1
09/04/2026 08:17:40	52.384954	4.875027	343	Sudden braking	2.50	2.50	12.4	10.0	1.00	2	2.1	1.000	602CA_Trip216	1
09/04/2026 08:17:41	52.384973	4.875025	340	Sudden braking	2.20	2.20	12.1	7.8	1.00	2	4.1	1.000	602CA_Trip216	1
09/04/2026 08:17:49	52.385311	4.875046	359	Sudden braking	2.10	2.10	10.7	11.1	1.00	2	2.4	1.000	602CA_Trip216	1
09/04/2026 08:17:50	52.385332	4.875054	5	Sudden braking	2.00	2.00	10.3	9.1	1.00	2	2.4	1.000	602CA_Trip216	1
09/04/2026 09:39:17	52.377641	4.895270	67	Sudden braking	2.80	2.80	13.2	13.9	1.00	2	4.7	1.000	602DE_Trip217	1
09/04/2026 09:39:18	52.377645	4.895339	88	Sudden braking	2.80	2.80	10.4	11.1	1.00	2	2.7	1.000	602DE_Trip217	1
09/04/2026 09:39:19	52.377644	4.895378	101	Sudden braking	3.10	3.10	8.7	8.0	1.00	2	1.6	1.000	602DE_Trip217	1
09/04/2026 09:39:20	52.377646	4.895402	97	Sudden braking	3.40	3.40	7.7	4.6	1.00	2	1.0	1.000	602DE_Trip217	1
09/04/2026 09:39:21	52.377644	4.895416	103	Sudden braking	2.30	2.30	5.9	2.3	1.00	2	0.1	1.001	602DE_Trip217	1
09/04/2026 09:39:37	52.377707	4.895894	62	Sudden braking	2.00	2.00	12.2	11.5	1.00	2	2.6	0.999	602DE_Trip217	1
09/04/2026 09:39:38	52.377717	4.895929	66	Sudden braking	2.00	2.00	12.0	9.5	1.00	2	2.0	1.001	602DE_Trip217	1
09/04/2026 09:39:52	52.377909	4.896695	70	Sudden braking	2.00	2.00	13.6	14.5	1.00	2	4.0	1.000	602DE_Trip217	1
09/04/2026 09:39:53	52.377920	4.896752	75	Sudden braking	2.20	2.20	12.7	12.3	1.00	2	2.7	0.999	602DE_Trip217	1
09/04/2026 09:39:54	52.377930	4.896789	70	Sudden braking	2.00	2.00	12.7	10.3	1.00	2	2.1	1.000	602DE_Trip217	1
09/04/2026 09:40:25	52.377075	4.898295	138	Sudden braking	2.60	2.60	10.1	11.1	1.00	2	4.0	0.999	602DE_Trip217	1
09/04/2026 09:40:26	52.377046	4.898330	148	Sudden braking	2.70	2.70	9.3	8.4	1.00	2	2.7	1.001	602DE_Trip217	1
09/04/2026 09:40:27	52.377025	4.898350	156	Sudden braking	2.60	2.60	5.9	5.8	1.00	2	1.2	1.000	602DE_Trip217	1
09/04/2026 09:40:28	52.377015	4.898356	162	Sudden braking	2.70	2.70	5.4	3.1	1.00	2	0.5	0.999	602DE_Trip217	1
09/04/2026 09:40:29	52.377011	4.898355	0	Sudden braking	2.00	2.00	4.0	1.1	1.00	2	0.2	1.001	602DE_Trip217	1
09/04/2026 09:43:59	52.371176	4.911924	114	Sudden braking	2.50	2.50	15.8	17.2	1.00	2	5.1	1.001	602DE_Trip217	1
09/04/2026 09:44:00	52.371157	4.911992	114	Sudden braking	2.70	2.70	14.4	14.5	1.00	2	3.7	1.000	602DE_Trip217	1
09/04/2026 09:44:01	52.371143	4.912042	114	Sudden braking	3.20	3.20	12.3	11.3	1.00	2	3.5	1.000	602DE_Trip217	1
09/04/2026 09:44:02	52.371134	4.912091	109	Sudden braking	3.10	3.10	11.5	8.2	1.00	2	2.3	1.000	602DE_Trip217	1
09/04/2026 09:44:50	52.371021	4.915052	81	Sudden braking	2.10	2.10	7.0	7.3	1.00	2	2.1	0.999	602DE_Trip217	1
09/04/2026 09:44:51	52.371023	4.915083	86	Sudden braking	2.00	2.00	7.0	5.3	1.00	2	1.2	1.000	602DE_Trip217	1
09/04/2026 13:21:18	52.372634	4.917688	151	Sudden braking	2.00	2.00	7.7	8.4	1.00	2	2.8	0.999	602DE_Trip218	1
09/04/2026 13:21:21	52.372592	4.917718	160	Sudden braking	2.00	2.00	3.9	2.8	1.00	2	0.8	1.001	602DE_Trip218	1
09/04/2026 14:45:11	52.369094	4.921245	119	Sudden braking	2.80	2.80	18.5	16.8	1.00	2	5.3	1.000	602D3_Trip219	1
09/04/2026 14:46:52	52.366106	4.926485	139	Sudden braking	2.40	2.40	16.1	18.2	1.00	2	5.2	1.000	602D3_Trip219	1
09/04/2026 14:46:53	52.366070	4.926532	143	Sudden braking	3.30	3.30	14.8	14.9	1.00	2	3.4	1.000	602D3_Trip219	1
09/04/2026 14:46:54	52.366045	4.926562	143	Sudden braking	3.30	3.30	13.7	11.6	1.00	2	1.1	1.000	602D3_Trip219	1
09/04/2026 14:46:55	52.366037	4.926572	143	Sudden braking	2.80	2.80	12.9	8.8	1.00	2	1.7	1.000	602D3_Trip219	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
09/04/2026 14:46:56	52.366025	4.926587	143	Sudden braking	2.20	2.20	12.3	6.6	1.00	2	1.6	1.000	602D3_Trip219	1
09/04/2026 14:47:52	52.363783	4.930454	174	Sudden braking	2.00	2.00	18.1	18.5	1.00	2	5.4	1.000	602D3_Trip219	1
09/04/2026 14:47:53	52.363735	4.930465	174	Sudden braking	2.50	2.50	17.3	16.0	1.00	2	5.2	1.000	602D3_Trip219	1
09/04/2026 14:48:40	52.361371	4.930401	186	Sudden braking	2.80	2.80	15.1	15.6	1.00	2	3.7	1.000	602D3_Trip219	1
09/04/2026 14:48:41	52.361340	4.930378	186	Sudden braking	3.00	3.00	13.7	12.6	1.00	2	1.4	1.000	602D3_Trip219	1
09/04/2026 14:48:42	52.361329	4.930367	186	Sudden braking	2.30	2.30	12.3	10.3	1.00	2	1.3	1.000	602D3_Trip219	1
09/04/2026 14:48:43	52.361323	4.930383	186	Sudden braking	2.00	2.00	10.9	8.3	1.00	3	2.0	1.000	602D3_Trip219	1
09/04/2026 15:34:57	52.375999	4.914132	326	Sudden braking	2.00	2.00	14.3	15.4	1.00	3	5.2	1.000	602D6_Trip220	1
09/04/2026 15:35:00	52.376076	4.914173	350	Sudden braking	2.60	2.60	10.8	10.5	1.00	3	2.6	1.000	602D6_Trip220	1
09/04/2026 15:35:01	52.376099	4.914176	354	Sudden braking	2.50	2.50	9.7	8.0	1.00	3	3.0	1.000	602D6_Trip220	1
09/04/2026 15:35:16	52.376664	4.913552	298	Sudden braking	2.00	2.00	21.7	22.6	1.00	2	5.9	1.000	602D6_Trip220	1
09/04/2026 15:35:17	52.376669	4.913466	290	Sudden braking	2.50	2.50	21.2	20.1	1.00	3	5.4	1.000	602D6_Trip220	1
09/04/2026 15:35:18	52.376669	4.913387	280	Sudden braking	2.20	2.20	20.5	17.9	1.00	3	4.6	1.000	602D6_Trip220	1
09/04/2026 15:35:33	52.376576	4.912261	259	Sudden braking	2.50	2.50	13.4	14.3	1.00	2	5.2	1.000	602D6_Trip220	1
09/04/2026 15:35:34	52.376558	4.912190	255	Sudden braking	2.70	2.70	12.3	11.6	1.00	2	3.2	1.000	602D6_Trip220	1
09/04/2026 15:35:35	52.376572	4.912232	259	Sudden braking	2.30	2.30	11.2	9.3	1.00	2	4.6	1.000	602D6_Trip220	1
09/04/2026 15:35:36	52.376594	4.912176	280	Sudden braking	2.10	2.10	10.1	7.2	1.00	2	2.9	1.000	602D6_Trip220	1
09/04/2026 15:37:42	52.378061	4.908716	279	Sudden braking	2.00	2.00	14.3	15.2	1.00	2	5.4	1.000	602D6_Trip220	1
09/04/2026 15:37:45	52.378104	4.908582	305	Sudden braking	2.30	2.30	11.1	10.6	1.00	2	3.2	1.000	602D6_Trip220	1
09/04/2026 15:37:46	52.378093	4.908539	281	Sudden braking	2.00	2.00	9.9	8.6	1.00	2	4.9	1.000	602D6_Trip220	1
09/04/2026 15:38:25	52.378578	4.905912	330	Sudden braking	2.40	2.40	4.0	7.1	1.00	2	1.1	1.000	602D6_Trip220	1
09/04/2026 15:38:26	52.378581	4.905896	331	Sudden braking	2.70	2.70	4.0	4.4	1.00	2	1.4	1.000	602D6_Trip220	1
09/04/2026 15:38:58	52.378583	4.904723	285	Sudden braking	2.20	2.20	13.9	15.2	1.00	2	5.5	1.000	602D6_Trip220	1
09/04/2026 15:38:59	52.378586	4.904643	281	Sudden braking	2.40	2.40	13.3	12.8	1.00	2	1.0	1.000	602D6_Trip220	1
09/04/2026 15:39:00	52.378593	4.904634	293	Sudden braking	2.60	2.60	13.1	10.2	1.00	2	4.3	1.000	602D6_Trip220	1
09/04/2026 15:39:01	52.378624	4.904595	319	Sudden braking	2.40	2.40	13.2	7.8	1.00	2	2.8	1.000	602D6_Trip220	1
09/04/2026 15:39:23	52.379274	4.902729	298	Sudden braking	2.00	2.00	18.0	21.1	1.00	2	4.7	1.000	602D6_Trip220	1
09/04/2026 15:39:24	52.379292	4.902667	297	Sudden braking	3.40	3.40	17.0	17.7	1.00	2	4.5	1.000	602D6_Trip220	1
09/04/2026 15:39:25	52.379312	4.902609	298	Sudden braking	3.60	3.60	16.3	14.1	1.00	3	1.2	1.000	602D6_Trip220	1
09/04/2026 15:39:26	52.379302	4.902617	305	Sudden braking	3.10	3.10	15.7	11.0	1.00	3	4.5	1.000	602D6_Trip220	1
09/04/2026 15:39:44	52.379770	4.901211	306	Sudden braking	3.00	3.00	19.0	16.3	1.00	2	7.3	1.000	602D6_Trip220	1
09/04/2026 15:39:53	52.379925	4.900580	301	Sudden braking	2.80	2.80	7.7	10.5	1.00	2	4.0	1.000	602D6_Trip220	1
09/04/2026 15:39:54	52.379943	4.900530	301	Sudden braking	2.80	2.80	8.2	7.7	1.00	2	3.5	1.000	602D6_Trip220	1
09/04/2026 15:40:05	52.380229	4.899737	301	Sudden braking	2.20	2.20	17.1	18.7	1.00	2	5.4	1.000	602D6_Trip220	1
09/04/2026 15:40:06	52.380274	4.899708	302	Sudden braking	2.40	2.40	16.6	16.3	1.00	2	4.5	1.000	602D6_Trip220	1
09/04/2026 15:40:15	52.380444	4.899368	303	Sudden braking	2.00	2.00	6.5	5.1	1.00	2	3.5	1.000	602D6_Trip220	1
09/04/2026 15:46:12	52.382263	4.903039	43	Sudden braking	2.10	2.10	10.3	11.6	1.00	2	3.0	1.000	602D6_Trip220	1
09/04/2026 15:47:31	52.383840	4.906488	11	Sudden braking	2.20	2.20	15.6	17.7	1.00	2	4.8	1.000	602D6_Trip220	1
09/04/2026 15:47:32	52.383881	4.906466	2	Sudden braking	2.60	2.60	14.4	15.1	1.00	2	7.7	1.000	602D6_Trip220	1
09/04/2026 15:47:33	52.383868	4.906354	3	Sudden braking	2.90	2.90	13.2	12.2	1.00	3	2.8	1.000	602D6_Trip220	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
09/04/2026 15:47:34	52.383893	4.906356	3	Sudden braking	2.80	2.80	12.0	9.4	1.00	3	5.2	1.000	602D6_Trip220	1
09/04/2026 15:48:11	52.385033	4.908466	86	Sudden braking	3.90	3.90	15.7	17.4	1.00	2	4.8	1.000	602D6_Trip220	1
09/04/2026 15:48:12	52.385051	4.908531	83	Sudden braking	3.70	3.70	14.6	13.7	1.00	2	2.3	1.000	602D6_Trip220	1
09/04/2026 15:48:13	52.385052	4.908496	80	Sudden braking	2.90	2.90	13.2	10.8	1.00	2	4.0	1.000	602D6_Trip220	1
09/04/2026 15:48:14	52.385053	4.908555	84	Sudden braking	2.60	2.60	11.8	8.2	1.00	2	3.6	0.999	602D6_Trip220	1
09/04/2026 15:48:46	52.385875	4.911233	44	Sudden braking	2.00	2.00	28.4	34.5	1.00	2	7.2	1.000	602D6_Trip220	1
09/04/2026 15:48:47	52.385871	4.911338	53	Sudden braking	3.60	3.60	27.6	30.9	1.00	2	8.2	1.000	602D6_Trip220	1
09/04/2026 15:48:48	52.385913	4.911437	53	Sudden braking	3.90	3.90	26.9	27.0	1.00	2	1.7	1.000	602D6_Trip220	1
09/04/2026 15:48:49	52.385918	4.911461	51	Sudden braking	3.40	3.40	26.2	23.6	1.00	2	7.5	1.000	602D6_Trip220	1
09/04/2026 15:48:50	52.385946	4.911561	59	Sudden braking	2.40	2.40	25.0	21.2	1.00	3	5.5	1.000	602D6_Trip220	1
09/04/2026 15:49:29	52.387265	4.914255	28	Sudden braking	3.80	3.80	15.7	16.5	1.00	2	6.5	1.000	602D6_Trip220	1
09/04/2026 15:49:30	52.387321	4.914276	26	Sudden braking	2.70	2.70	14.0	13.8	1.00	2	6.9	1.000	602D6_Trip220	1
09/04/2026 15:49:32	52.387271	4.914312	77	Sudden braking	2.20	2.20	11.5	10.0	1.00	2	8.1	1.000	602D6_Trip220	1
09/04/2026 15:50:00	52.388519	4.916201	48	Sudden braking	3.30	3.30	16.6	16.9	1.00	2	5.2	1.000	602D6_Trip220	1
09/04/2026 15:50:01	52.388544	4.916267	51	Sudden braking	3.40	3.40	15.1	13.5	1.00	2	7.3	1.000	602D6_Trip220	1
09/04/2026 15:50:02	52.388478	4.916262	86	Sudden braking	3.19	3.19	13.6	10.3	1.00	2	5.3	1.002	602D6_Trip220	1
09/04/2026 15:50:04	52.388519	4.916300	81	Sudden braking	2.40	2.40	10.8	7.9	1.00	2	1.1	1.000	602D6_Trip220	1
09/04/2026 15:50:33	52.389693	4.917506	60	Sudden braking	2.00	2.00	12.4	12.7	1.00	2	2.9	1.000	602D6_Trip220	1
09/04/2026 15:50:54	52.389452	4.918483	97	Sudden braking	2.00	2.00	10.8	11.8	1.00	2	4.4	1.000	602D6_Trip220	1
09/04/2026 15:52:18	52.391363	4.921210	63	Sudden braking	2.20	2.20	14.8	17.8	1.00	2	1.2	1.000	602D6_Trip220	1
09/04/2026 15:52:24	52.391510	4.921460	51	Sudden braking	2.00	2.00	10.4	9.8	1.00	2	3.1	1.000	602D6_Trip220	1
09/04/2026 15:52:25	52.391538	4.921466	36	Sudden braking	2.20	2.20	9.5	7.6	1.00	2	2.5	0.999	602D6_Trip220	1
09/04/2026 15:53:02	52.390969	4.924127	122	Sudden braking	2.90	2.90	13.7	15.5	1.00	2	3.7	1.000	602D6_Trip220	1
09/04/2026 15:53:03	52.390940	4.924154	131	Sudden braking	2.90	2.90	13.1	12.6	1.00	2	1.7	1.000	602D6_Trip220	1
09/04/2026 15:53:04	52.390951	4.924137	128	Sudden braking	2.70	2.70	12.0	9.9	1.00	2	3.6	1.000	602D6_Trip220	1
09/04/2026 15:53:05	52.390948	4.924190	110	Sudden braking	2.50	2.50	10.9	7.4	1.00	2	3.9	1.000	602D6_Trip220	1
09/04/2026 16:20:00	52.372582	4.917857	138	Sudden braking	2.30	2.30	14.4	15.0	1.00	2	4.8	0.999	602DE_Trip222	1
09/04/2026 16:20:01	52.372553	4.917909	131	Sudden braking	2.70	2.70	13.8	12.3	1.00	2	3.4	0.999	602DE_Trip222	1
09/04/2026 16:21:12	52.371040	4.913214	269	Sudden braking	2.30	2.30	15.9	15.8	1.00	2	4.3	1.001	602DE_Trip222	1
09/04/2026 16:21:13	52.371030	4.913152	241	Sudden braking	3.21	3.21	14.3	12.6	1.00	2	3.8	0.998	602DE_Trip222	1
09/04/2026 16:21:14	52.371007	4.913110	221	Sudden braking	2.40	2.40	13.6	10.2	1.00	2	1.6	1.000	602DE_Trip222	1
09/04/2026 16:23:53	52.376036	4.902929	312	Sudden braking	2.00	2.00	18.9	17.9	1.00	2	4.7	1.000	602DE_Trip222	1
09/04/2026 16:24:13	52.376730	4.902134	328	Sudden braking	2.00	2.00	14.2	14.7	1.00	2	4.1	1.000	602DE_Trip222	1
09/04/2026 16:24:14	52.376762	4.902104	330	Sudden braking	2.10	2.10	13.2	12.6	1.00	2	2.9	1.002	602DE_Trip222	1
09/04/2026 16:24:15	52.376782	4.902077	327	Sudden braking	2.10	2.10	10.6	10.5	1.00	2	2.6	0.998	602DE_Trip222	1
09/04/2026 16:25:11	52.376730	4.898883	307	Sudden braking	2.10	2.10	14.2	14.7	1.00	2	4.1	1.000	602DE_Trip222	1
09/04/2026 16:25:12	52.376751	4.898834	312	Sudden braking	2.20	2.20	13.0	12.5	1.00	2	3.2	0.999	602DE_Trip222	1
09/04/2026 16:25:13	52.376773	4.898803	324	Sudden braking	2.10	2.10	12.3	10.4	1.00	2	2.6	1.001	602DE_Trip222	1
09/04/2026 16:26:56	52.373518	4.893520	223	Sudden braking	3.10	3.10	12.8	14.5	1.00	2	5.0	1.000	602DE_Trip222	1
09/04/2026 16:26:57	52.373485	4.893470	220	Sudden braking	3.20	3.20	11.3	11.3	1.00	2	2.4	0.999	602DE_Trip222	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
09/04/2026 16:26:58	52.373469	4.893447	218	Sudden braking	3.30	3.30	10.4	8.0	1.00	2	1.5	1.001	602DE_Trip222	1
09/04/2026 16:26:59	52.373459	4.893433	216	Sudden braking	3.50	3.50	8.9	4.5	1.00	2	1.5	1.001	602DE_Trip222	1
09/04/2026 16:27:00	52.373447	4.893422	212	Sudden braking	2.10	2.10	7.2	2.4	1.00	2	0.5	0.998	602DE_Trip222	1
09/04/2026 16:27:33	52.372849	4.892310	284	Sudden braking	2.30	2.30	15.7	14.6	1.00	2	3.4	0.999	602DE_Trip222	1
09/04/2026 16:27:34	52.372848	4.892260	274	Sudden braking	2.20	2.20	15.4	12.4	1.00	2	3.1	1.001	602DE_Trip222	1
09/04/2026 19:25:40	52.358643	4.902772	251	Sudden braking	2.80	2.80	21.0	21.8	1.00	2	5.1	1.000	602CA_Trip223	1
09/04/2026 19:25:41	52.358620	4.902707	251	Sudden braking	3.40	3.40	20.2	18.4	1.00	2	6.9	1.000	602CA_Trip223	1
09/04/2026 19:25:42	52.358608	4.902607	251	Sudden braking	2.20	2.20	19.5	16.2	1.00	2	8.4	1.000	602CA_Trip223	1
09/04/2026 19:26:15	52.358016	4.899712	252	Sudden braking	2.00	2.00	18.1	20.6	1.00	2	8.1	1.000	602CA_Trip223	1
09/04/2026 19:26:16	52.357997	4.899597	253	Sudden braking	3.40	3.40	17.5	17.2	1.00	2	3.4	1.000	602CA_Trip223	1
09/04/2026 19:26:17	52.357984	4.899551	253	Sudden braking	4.10	4.10	16.8	13.1	1.00	2	1.2	1.000	602CA_Trip223	1
09/04/2026 19:26:18	52.357978	4.899536	253	Sudden braking	2.15	2.15	15.8	8.8	2.00	2	2.9	2.000	602CA_Trip223	1
09/04/2026 19:27:42	52.357773	4.896436	275	Sudden braking	3.00	3.00	15.0	17.3	1.00	2	5.5	1.000	602CA_Trip223	1
09/04/2026 19:27:43	52.357780	4.896356	274	Sudden braking	3.10	3.10	14.7	14.2	1.00	2	5.2	1.000	602CA_Trip223	1
09/04/2026 19:27:44	52.357789	4.896431	294	Sudden braking	2.90	2.90	13.4	11.3	1.00	3	4.3	1.000	602CA_Trip223	1
09/04/2026 19:27:45	52.357823	4.896401	319	Sudden braking	2.90	2.90	12.0	8.4	1.00	2	2.1	1.000	602CA_Trip223	1
09/04/2026 19:29:40	52.359368	4.888794	317	Sudden braking	2.40	2.40	23.8	23.5	1.00	2	7.1	1.000	602CA_Trip223	1
09/04/2026 19:29:41	52.359416	4.888725	319	Sudden braking	2.50	2.50	23.7	21.0	1.00	2	5.6	1.000	602CA_Trip223	1
09/04/2026 19:31:27	52.362767	4.880549	270	Sudden braking	2.30	2.30	13.7	14.5	1.00	3	5.5	1.000	602CA_Trip223	1
09/04/2026 19:31:30	52.362843	4.880528	354	Sudden braking	2.30	2.30	12.7	8.6	1.00	2	15.1	1.000	602CA_Trip223	1
09/04/2026 19:32:23	52.365566	4.878677	344	Sudden braking	2.00	2.00	17.7	19.1	1.00	3	5.9	1.000	602CA_Trip223	1
09/04/2026 19:32:24	52.365617	4.878648	338	Sudden braking	2.70	2.70	16.3	16.4	1.00	3	5.6	1.000	602CA_Trip223	1
09/04/2026 19:32:25	52.365661	4.878608	335	Sudden braking	2.40	2.40	14.8	14.0	1.00	3	1.3	1.000	602CA_Trip223	1
09/04/2026 19:32:26	52.365666	4.878592	333	Sudden braking	2.90	2.90	13.2	11.1	1.00	3	5.6	1.000	602CA_Trip223	1
09/04/2026 19:33:00	52.366701	4.877320	334	Sudden braking	3.30	3.30	14.5	15.0	1.00	3	5.9	1.000	602CA_Trip223	1
09/04/2026 19:33:01	52.366739	4.877259	334	Sudden braking	2.70	2.70	13.6	12.3	1.00	3	4.0	1.000	602CA_Trip223	1
09/04/2026 19:33:02	52.366710	4.877224	334	Sudden braking	2.70	2.70	12.6	9.6	1.00	3	2.9	1.000	602CA_Trip223	1
09/04/2026 19:33:19	52.367625	4.877044	345	Sudden braking	2.40	2.40	19.2	18.8	1.00	2	6.8	1.000	602CA_Trip223	1
09/04/2026 19:33:57	52.369517	4.875218	345	Sudden braking	2.10	2.10	14.7	15.5	1.00	3	6.7	1.000	602CA_Trip223	1
09/04/2026 19:33:58	52.369575	4.875191	345	Sudden braking	2.00	2.00	13.4	13.5	1.00	3	1.2	1.000	602CA_Trip223	1
09/04/2026 19:33:59	52.369575	4.875209	345	Sudden braking	2.90	2.90	12.2	10.6	1.00	3	6.1	1.000	602CA_Trip223	1
09/04/2026 19:34:00	52.369627	4.875176	345	Sudden braking	2.20	2.20	11.1	8.4	1.00	2	1.9	1.000	602CA_Trip223	1
09/04/2026 19:35:21	52.372733	4.874457	39	Sudden braking	2.50	2.50	16.2	16.9	1.00	3	7.1	1.000	602CA_Trip223	1
09/04/2026 19:35:24	52.372807	4.874588	39	Sudden braking	3.10	3.10	13.3	10.8	1.00	2	3.1	1.000	602CA_Trip223	1
09/04/2026 19:35:25	52.372831	4.874610	39	Sudden braking	2.80	2.80	13.1	8.0	1.00	3	1.4	1.000	602CA_Trip223	1
09/04/2026 19:36:52	52.377849	4.877378	21	Sudden braking	2.30	2.30	16.7	20.0	1.00	2	6.1	1.000	602CA_Trip223	1
09/04/2026 19:36:53	52.377902	4.877401	20	Sudden braking	3.90	3.90	15.1	16.1	1.00	2	4.9	1.000	602CA_Trip223	1
09/04/2026 19:36:54	52.377946	4.877404	21	Sudden braking	3.60	3.60	13.6	12.5	1.00	2	6.0	1.000	602CA_Trip223	1
09/04/2026 19:36:55	52.377896	4.877369	20	Sudden braking	2.10	2.10	12.0	10.4	1.00	2	2.4	1.000	602CA_Trip223	1
09/04/2026 19:37:39	52.379053	4.876392	275	Sudden braking	2.40	2.40	19.3	17.9	1.00	2	5.3	1.000	602CA_Trip223	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
09/04/2026 19:39:53	52.384252	4.870108	346	Sudden braking	2.30	2.30	18.4	19.1	1.00	2	5.1	1.000	602CA_Trip223	1
09/04/2026 19:39:54	52.384298	4.870105	346	Sudden braking	2.60	2.60	17.5	16.5	1.00	2	5.0	1.000	602CA_Trip223	1
10/04/2026 05:56:24	52.377094	4.898230	144	Sudden braking	2.10	2.10	13.9	15.2	1.00	2	5.0	0.999	602DE_Trip224	1
10/04/2026 05:56:25	52.377060	4.898277	143	Sudden braking	2.30	2.30	13.7	12.9	1.00	2	3.4	1.000	602DE_Trip224	1
10/04/2026 05:56:26	52.377035	4.898306	146	Sudden braking	2.10	2.10	13.1	10.8	1.00	2	2.8	1.002	602DE_Trip224	1
10/04/2026 05:59:11	52.375917	4.910698	12	Sudden braking	2.90	2.90	17.3	18.1	1.00	2	6.3	1.001	602DE_Trip224	1
10/04/2026 05:59:12	52.375973	4.910688	5	Sudden braking	3.40	3.40	13.7	14.7	1.00	2	5.1	0.999	602DE_Trip224	1
10/04/2026 05:59:13	52.376014	4.910654	355	Sudden braking	3.20	3.20	13.2	11.5	1.00	2	2.9	1.000	602DE_Trip224	1
10/04/2026 05:59:14	52.376038	4.910637	3	Sudden braking	3.20	3.20	12.2	8.3	1.00	2	2.5	1.001	602DE_Trip224	1
10/04/2026 05:59:15	52.376057	4.910617	5	Sudden braking	2.20	2.20	10.1	6.1	1.00	3	1.9	1.000	602DE_Trip224	1
10/04/2026 06:00:29	52.375244	4.914316	201	Sudden braking	2.20	2.20	20.1	19.1	1.00	2	6.5	1.001	602DE_Trip224	1
11/04/2026 14:37:44	52.367480	4.889765	201	Sudden braking	2.40	2.40	7.1	7.4	1.00	2	1.7	1.000	602DE_Trip225	1
11/04/2026 14:37:45	52.367465	4.889758	193	Sudden braking	2.40	2.40	6.1	5.0	1.00	2	0.8	1.000	602DE_Trip225	1
11/04/2026 14:37:46	52.367460	4.889767	173	Sudden braking	2.20	2.20	5.3	2.8	1.00	2	0.5	1.000	602DE_Trip225	1
11/04/2026 14:39:17	52.368544	4.886999	3	Sudden braking	2.20	2.20	12.3	15.3	1.00	2	4.7	1.000	602DE_Trip225	1
11/04/2026 14:39:18	52.368586	4.887005	4	Sudden braking	2.90	2.90	10.2	12.4	1.00	2	2.9	1.000	602DE_Trip225	1
11/04/2026 14:39:19	52.368612	4.887003	357	Sudden braking	3.50	3.50	9.5	8.9	1.00	2	1.6	1.000	602DE_Trip225	1
11/04/2026 14:39:20	52.368625	4.886996	352	Sudden braking	3.50	3.50	8.0	5.4	1.00	2	0.8	0.999	602DE_Trip225	1
11/04/2026 14:39:21	52.368632	4.886990	352	Sudden braking	2.60	2.60	7.0	2.8	1.00	2	0.4	1.001	602DE_Trip225	1
11/04/2026 14:39:48	52.368819	4.886406	271	Sudden braking	2.50	2.50	7.7	5.2	1.00	3	1.2	1.000	602DE_Trip225	1
11/04/2026 14:40:35	52.368886	4.884083	271	Sudden braking	2.00	2.00	6.2	7.5	1.00	2	2.0	0.999	602DE_Trip225	1
11/04/2026 14:40:36	52.368890	4.884055	291	Sudden braking	2.20	2.20	6.2	5.3	1.00	2	1.0	1.001	602DE_Trip225	1
11/04/2026 14:40:37	52.368895	4.884042	286	Sudden braking	2.40	2.40	4.6	2.9	1.00	2	0.2	1.000	602DE_Trip225	1
11/04/2026 14:40:58	52.368929	4.883357	276	Sudden braking	2.10	2.10	8.5	9.0	1.00	2	1.9	1.000	602DE_Trip225	1
11/04/2026 14:40:59	52.368930	4.883329	274	Sudden braking	2.40	2.40	7.4	6.6	1.00	3	1.4	0.999	602DE_Trip225	1
11/04/2026 14:41:00	52.368930	4.883309	272	Sudden braking	2.00	2.00	6.7	4.6	1.00	3	1.3	1.000	602DE_Trip225	1
11/04/2026 14:42:35	52.367171	4.879519	244	Sudden braking	2.00	2.00	9.6	9.3	1.00	2	4.0	1.000	602DE_Trip225	1
11/04/2026 14:42:36	52.367157	4.879464	242	Sudden braking	2.10	2.10	7.5	7.2	1.00	2	2.1	1.000	602DE_Trip225	1
11/04/2026 14:49:04	52.360618	4.877239	259	Sudden braking	2.30	2.30	23.8	25.2	1.00	2	7.9	0.999	602DE_Trip225	1
11/04/2026 14:49:05	52.360587	4.877134	248	Sudden braking	2.30	2.30	23.8	22.9	1.00	2	5.4	1.000	602DE_Trip225	1
11/04/2026 14:49:07	52.360558	4.877027	260	Sudden braking	2.20	2.20	21.3	18.9	1.00	2	5.7	0.999	602DE_Trip225	1
11/04/2026 14:50:50	52.357240	4.872076	66	Sudden braking	2.20	2.20	8.9	11.6	1.00	2	4.0	1.000	602DE_Trip225	1
11/04/2026 14:50:51	52.357250	4.872133	78	Sudden braking	3.20	3.20	7.8	8.4	1.00	2	2.3	1.000	602DE_Trip225	1
11/04/2026 14:50:52	52.357261	4.872162	68	Sudden braking	3.10	3.10	6.6	5.3	1.00	2	1.4	1.000	602DE_Trip225	1
11/04/2026 14:50:53	52.357260	4.872182	68	Sudden braking	2.70	2.70	4.5	2.6	1.00	3	0.5	1.000	602DE_Trip225	1
11/04/2026 14:57:59	52.357985	4.878583	164	Sudden braking	2.30	2.30	6.4	7.0	1.00	2	2.5	1.000	602DE_Trip225	1
11/04/2026 14:58:00	52.357963	4.878581	182	Sudden braking	2.30	2.30	5.5	4.7	1.00	3	1.5	1.000	602DE_Trip225	1
11/04/2026 14:58:24	52.357531	4.878842	159	Sudden braking	2.00	2.00	10.2	10.5	1.00	3	3.3	1.000	602DE_Trip225	1
11/04/2026 14:58:25	52.357510	4.878877	129	Sudden braking	2.00	2.00	9.5	8.5	1.00	2	2.4	1.000	602DE_Trip225	1
11/04/2026 14:58:52	52.357937	4.878943	335	Sudden braking	2.00	2.00	6.6	6.7	1.00	2	1.7	1.000	602DE_Trip225	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
11/04/2026 14:58:53	52.357951	4.878930	337	Sudden braking	2.10	2.10	5.4	4.6	1.00	2	1.1	1.000	602DE_Trip225	1
11/04/2026 15:00:09	52.359212	4.877883	315	Sudden braking	2.20	2.20	8.1	7.9	1.00	1	2.0	1.000	602DE_Trip225	1
11/04/2026 15:01:48	52.362155	4.875812	335	Sudden braking	2.40	2.40	10.3	10.6	1.00	2	2.8	1.001	602DE_Trip225	1
11/04/2026 15:01:49	52.362177	4.875792	340	Sudden braking	2.90	2.90	7.8	7.7	1.00	2	0.7	1.000	602DE_Trip225	1
11/04/2026 15:01:50	52.362181	4.875785	327	Sudden braking	2.90	2.90	6.4	4.8	1.00	2	0.8	1.000	602DE_Trip225	1
11/04/2026 15:01:51	52.362181	4.875797	0	Sudden braking	2.40	2.40	5.0	2.4	1.00	2	0.1	1.000	602DE_Trip225	1
11/04/2026 15:02:55	52.361942	4.876086	276	Sudden braking	2.10	2.10	4.3	4.0	1.00	3	2.6	1.000	602DE_Trip225	1
11/04/2026 15:08:21	52.370757	4.870425	5	Sudden braking	2.00	2.00	10.1	10.1	1.00	2	2.9	1.000	602DE_Trip225	1
13/04/2026 05:37:59	52.365141	4.928577	300	Sudden braking	2.50	2.50	14.5	10.8	1.00	3	6.6	1.000	602D3_Trip226	1
13/04/2026 05:41:00	52.369330	4.920503	302	Sudden braking	2.90	2.90	17.8	16.0	1.00	2	8.4	1.000	602D3_Trip226	1
13/04/2026 05:41:50	52.370562	4.916728	299	Sudden braking	3.20	3.20	18.3	16.6	1.00	2	5.7	1.000	602D3_Trip226	1
13/04/2026 05:42:30	52.371615	4.916672	53	Sudden braking	2.30	2.30	11.0	9.5	1.00	2	2.8	1.000	602D3_Trip226	1
13/04/2026 05:42:31	52.371640	4.916678	29	Sudden braking	2.30	2.30	10.2	7.2	1.00	2	1.4	1.000	602D3_Trip226	1
13/04/2026 06:58:28	52.377645	4.895170	55	Sudden braking	2.10	2.10	17.0	17.1	1.00	2	4.9	1.000	602DE_Trip227	1
13/04/2026 06:58:29	52.377666	4.895232	56	Sudden braking	2.10	2.10	15.6	15.0	1.00	2	2.2	1.001	602DE_Trip227	1
13/04/2026 07:00:27	52.376224	4.902776	108	Sudden braking	2.30	2.30	7.8	8.8	1.00	2	2.7	1.000	602DE_Trip227	1
13/04/2026 07:00:28	52.376221	4.902815	94	Sudden braking	2.40	2.40	7.0	6.4	1.00	2	1.2	1.000	602DE_Trip227	1
13/04/2026 07:00:29	52.376225	4.902832	99	Sudden braking	2.20	2.20	4.7	4.2	1.00	2	0.6	1.000	602DE_Trip227	1
13/04/2026 07:00:30	52.376229	4.902837	105	Sudden braking	2.00	2.00	4.2	2.2	1.00	2	0.4	0.999	602DE_Trip227	1
13/04/2026 07:03:43	52.375197	4.914129	212	Sudden braking	2.30	2.30	17.1	15.8	1.00	3	5.4	1.000	602DE_Trip227	1
13/04/2026 12:58:51	52.396913	4.939699	235	Sudden braking	2.50	2.50	11.1	11.3	1.00	2	3.2	1.000	602DE_Trip228	1
13/04/2026 12:58:52	52.396904	4.939654	255	Sudden braking	2.50	2.50	10.7	8.8	1.00	2	3.1	0.999	602DE_Trip228	1
13/04/2026 13:00:31	52.397074	4.933206	234	Sudden braking	2.10	2.10	18.9	17.8	1.00	2	5.6	0.999	602DE_Trip228	1
13/04/2026 13:03:00	52.394047	4.924424	198	Sudden braking	2.00	2.00	16.8	18.6	1.00	3	6.2	1.000	602DE_Trip228	1
13/04/2026 13:03:01	52.393993	4.924408	195	Sudden braking	2.00	2.00	16.0	16.6	1.00	3	4.0	1.000	602DE_Trip228	1
13/04/2026 13:03:02	52.393958	4.924391	197	Sudden braking	2.10	2.10	14.8	14.5	1.00	2	3.6	0.999	602DE_Trip228	1
13/04/2026 13:03:03	52.393928	4.924373	204	Sudden braking	2.40	2.40	14.0	12.1	1.00	2	3.0	1.001	602DE_Trip228	1
13/04/2026 13:03:16	52.394009	4.924729	50	Sudden braking	2.20	2.20	5.3	5.4	1.00	1	1.8	1.000	602DE_Trip228	1
13/04/2026 13:03:17	52.394025	4.924737	21	Sudden braking	2.00	2.00	4.3	3.4	1.00	1	1.0	1.000	602DE_Trip228	1
13/04/2026 13:08:15	52.388742	4.919722	233	Sudden braking	2.30	2.30	18.9	20.7	1.00	3	7.2	1.000	602DE_Trip228	1
13/04/2026 13:08:16	52.388686	4.919667	236	Sudden braking	2.71	2.71	18.4	18.0	1.00	3	5.5	0.998	602DE_Trip228	1
13/04/2026 13:08:17	52.388657	4.919600	237	Sudden braking	2.20	2.20	18.4	15.8	1.00	3	4.6	1.002	602DE_Trip228	1
13/04/2026 13:09:46	52.386951	4.913723	327	Sudden braking	2.20	2.20	12.2	15.2	1.00	1	4.7	1.000	602DE_Trip228	1
13/04/2026 13:09:47	52.386987	4.913688	338	Sudden braking	2.70	2.70	11.1	12.5	1.00	1	3.5	1.000	602DE_Trip228	1
13/04/2026 13:09:48	52.387016	4.913669	349	Sudden braking	3.30	3.30	8.5	9.2	1.00	2	2.1	0.999	602DE_Trip228	1
13/04/2026 13:09:49	52.387035	4.913661	354	Sudden braking	3.40	3.40	8.5	5.8	1.00	2	1.0	1.001	602DE_Trip228	1
13/04/2026 13:09:50	52.387044	4.913659	346	Sudden braking	2.50	2.50	6.3	3.3	1.00	2	0.4	1.000	602DE_Trip228	1
13/04/2026 13:11:54	52.382090	4.908607	197	Sudden braking	2.00	2.00	17.2	17.7	1.00	2	4.2	0.999	602DE_Trip228	1
13/04/2026 13:18:43	52.376771	4.910137	150	Sudden braking	2.10	2.10	18.5	17.1	1.00	3	6.6	1.000	602DE_Trip228	1
13/04/2026 13:21:00	52.374193	4.914251	244	Sudden braking	2.70	2.70	15.5	14.6	1.00	2	4.1	1.000	602DE_Trip228	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
13/04/2026 13:21:06	52.374063	4.914322	130	Sudden braking	2.10	2.10	10.8	10.3	1.00	2	2.0	1.000	602DE_Trip228	1
13/04/2026 13:21:07	52.374056	4.914349	118	Sudden braking	2.10	2.10	10.6	8.2	1.00	3	2.7	1.000	602DE_Trip228	1
13/04/2026 14:17:40	52.374451	4.914595	325	Sudden braking	2.50	2.50	12.0	12.4	1.00	3	8.2	1.000	602D6_Trip230	1
13/04/2026 14:17:41	52.374523	4.914566	332	Sudden braking	2.20	2.20	11.0	10.2	1.00	3	0.8	1.000	602D6_Trip230	1
13/04/2026 14:18:56	52.376549	4.911827	254	Sudden braking	2.10	2.10	11.3	18.3	1.00	2	4.2	1.000	602D6_Trip230	1
13/04/2026 14:18:57	52.376534	4.911770	252	Sudden braking	3.60	3.60	10.6	14.7	1.00	2	5.4	1.000	602D6_Trip230	1
13/04/2026 14:18:58	52.376521	4.911693	255	Sudden braking	3.10	3.10	10.2	11.6	1.00	2	4.5	1.000	602D6_Trip230	1
13/04/2026 14:18:59	52.376525	4.911759	255	Sudden braking	2.10	2.10	9.7	9.5	1.00	2	2.5	1.000	602D6_Trip230	1
13/04/2026 14:19:00	52.376528	4.911722	277	Sudden braking	2.10	2.10	9.4	7.4	1.00	2	2.0	1.000	602D6_Trip230	1
13/04/2026 14:19:58	52.377034	4.910268	354	Sudden braking	2.20	2.20	17.4	20.8	1.00	2	5.7	1.000	602D6_Trip230	1
13/04/2026 14:19:59	52.377083	4.910242	352	Sudden braking	3.80	3.80	15.7	17.0	1.00	2	10.6	1.000	602D6_Trip230	1
13/04/2026 14:20:00	52.377056	4.910093	339	Sudden braking	3.70	3.70	14.0	13.3	1.00	2	5.7	1.000	602D6_Trip230	1
13/04/2026 14:20:01	52.377024	4.910158	7	Sudden braking	3.50	3.50	12.4	9.8	1.00	3	3.9	1.000	602D6_Trip230	1
13/04/2026 14:20:02	52.377006	4.910208	20	Sudden braking	3.20	3.20	10.8	6.6	1.00	3	8.5	1.000	602D6_Trip230	1
13/04/2026 14:20:41	52.378109	4.908488	283	Sudden braking	2.00	2.00	18.8	20.7	1.00	2	6.0	1.000	602D6_Trip230	1
13/04/2026 14:20:42	52.378121	4.908402	283	Sudden braking	3.60	3.60	18.1	17.1	1.00	2	5.8	1.000	602D6_Trip230	1
13/04/2026 14:20:43	52.378133	4.908319	283	Sudden braking	3.60	3.60	15.9	13.5	1.00	2	11.8	1.000	602D6_Trip230	1
13/04/2026 14:21:48	52.379095	4.903371	304	Sudden braking	2.10	2.10	17.6	20.3	1.00	2	14.2	1.000	602D6_Trip230	1
13/04/2026 14:21:49	52.379032	4.903189	300	Sudden braking	3.00	3.00	16.1	17.3	1.00	2	5.4	1.000	602D6_Trip230	1
13/04/2026 14:21:50	52.379056	4.903119	300	Sudden braking	2.60	2.60	14.5	14.7	1.00	2	2.2	1.000	602D6_Trip230	1
13/04/2026 14:21:51	52.379046	4.903148	300	Sudden braking	3.10	3.10	12.9	11.6	1.00	2	6.5	1.000	602D6_Trip230	1
13/04/2026 14:21:52	52.379073	4.903063	303	Sudden braking	3.40	3.40	11.9	8.2	1.00	2	2.0	1.000	602D6_Trip230	1
13/04/2026 14:22:41	52.380433	4.899576	301	Sudden braking	3.30	3.30	20.1	24.9	1.00	2	6.6	1.000	602D6_Trip230	1
13/04/2026 14:22:42	52.380450	4.899482	301	Sudden braking	3.20	3.20	19.1	21.7	1.00	2	5.4	1.000	602D6_Trip230	1
13/04/2026 14:22:43	52.380481	4.899421	301	Sudden braking	3.50	3.50	18.3	18.2	1.00	2	3.5	1.000	602D6_Trip230	1
13/04/2026 14:22:44	52.380491	4.899373	301	Sudden braking	3.70	3.70	17.2	14.5	1.00	2	2.1	1.000	602D6_Trip230	1
13/04/2026 14:22:45	52.380475	4.899390	285	Sudden braking	3.20	3.20	15.7	11.3	1.00	2	1.1	1.000	602D6_Trip230	1
13/04/2026 14:22:52	52.380646	4.899431	28	Sudden braking	2.50	2.50	7.7	8.0	1.00	2	3.1	1.000	602D6_Trip230	1
13/04/2026 14:22:53	52.380665	4.899465	33	Sudden braking	2.80	2.80	7.5	5.2	1.00	2	8.3	1.000	602D6_Trip230	1
13/04/2026 14:25:36	52.381997	4.902675	47	Sudden braking	2.60	2.60	9.7	9.0	1.00	2	3.4	1.000	602D6_Trip230	1
13/04/2026 14:28:42	52.384677	4.906496	28	Sudden braking	2.00	2.00	10.8	15.1	1.00	2	8.9	1.000	602D6_Trip230	1
13/04/2026 14:28:43	52.384747	4.906561	36	Sudden braking	2.00	2.00	10.1	13.1	1.00	2	2.2	1.000	602D6_Trip230	1
13/04/2026 14:28:44	52.384763	4.906579	38	Sudden braking	2.40	2.40	9.6	10.7	1.00	2	5.0	1.000	602D6_Trip230	1
13/04/2026 14:28:45	52.384799	4.906624	38	Sudden braking	2.50	2.50	9.2	8.2	1.00	2	2.9	1.001	602D6_Trip230	1
13/04/2026 14:31:00	52.390617	4.911056	21	Sudden braking	2.10	2.10	15.0	18.2	1.00	2	5.0	1.000	602D6_Trip230	1
13/04/2026 14:31:01	52.390659	4.911083	21	Sudden braking	3.40	3.40	13.9	14.8	1.00	2	3.7	1.000	602D6_Trip230	1
13/04/2026 14:31:02	52.390690	4.911102	21	Sudden braking	3.30	3.30	13.0	11.5	1.00	2	1.3	1.000	602D6_Trip230	1
13/04/2026 14:31:03	52.390678	4.911095	21	Sudden braking	3.00	3.00	12.0	8.5	1.00	3	2.4	1.000	602D6_Trip230	1
13/04/2026 14:31:04	52.390699	4.911108	21	Sudden braking	2.30	2.30	11.2	6.2	1.00	2	2.4	1.000	602D6_Trip230	1
13/04/2026 15:31:12	52.369147	4.921049	123	Sudden braking	2.60	2.60	18.1	16.4	1.00	2	15.6	1.000	602D3_Trip233	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
13/04/2026 15:33:03	52.366001	4.926613	146	Sudden braking	2.20	2.20	11.0	8.6	1.00	1	2.3	1.000	602D3_Trip233	1
13/04/2026 15:33:04	52.365983	4.926628	150	Sudden braking	2.00	2.00	10.3	6.6	1.00	1	1.5	1.000	602D3_Trip233	1
13/04/2026 15:34:40	52.363488	4.930476	179	Sudden braking	2.10	2.10	19.8	18.3	1.00	2	5.5	1.000	602D3_Trip233	1
13/04/2026 15:35:15	52.361473	4.930457	188	Sudden braking	2.20	2.20	17.2	18.6	1.00	2	5.5	1.000	602D3_Trip233	1
13/04/2026 15:35:16	52.361426	4.930435	188	Sudden braking	3.20	3.20	16.5	15.4	1.00	2	4.4	1.000	602D3_Trip233	1
13/04/2026 15:35:19	52.361378	4.930396	201	Sudden braking	3.30	3.30	11.0	8.8	1.00	2	1.3	1.000	602D3_Trip233	1
13/04/2026 15:49:51	52.433758	4.816163	259	Sudden braking	3.20	3.20	31.8	34.8	1.00	3	9.4	1.000	604F0_Trip234	1
13/04/2026 15:49:52	52.433741	4.816026	259	Sudden braking	4.50	4.50	30.1	30.3	1.00	3	7.1	1.000	604F0_Trip234	1
13/04/2026 15:49:53	52.433734	4.815922	261	Sudden braking	4.70	4.70	28.5	25.6	1.00	3	4.8	1.000	604F0_Trip234	1
13/04/2026 15:49:54	52.433746	4.815854	275	Sudden braking	3.70	3.70	27.2	21.9	1.00	3	4.6	1.000	604F0_Trip234	1
13/04/2026 15:49:55	52.433782	4.815821	308	Sudden braking	2.10	2.10	26.0	19.8	1.00	3	6.1	1.000	604F0_Trip234	1
13/04/2026 15:58:21	52.484874	4.806214	324	Sudden braking	2.10	2.10	30.9	34.6	1.00	2	9.7	1.000	604F0_Trip234	1
13/04/2026 15:58:22	52.484944	4.806128	323	Sudden braking	3.20	3.20	28.1	31.4	1.00	2	8.1	0.999	604F0_Trip234	1
13/04/2026 15:58:23	52.485002	4.806055	322	Sudden braking	4.30	4.30	27.0	27.1	1.00	2	6.6	1.000	604F0_Trip234	1
13/04/2026 15:58:24	52.485049	4.805996	322	Sudden braking	4.70	4.70	23.7	22.4	1.00	2	3.7	1.000	604F0_Trip234	1
13/04/2026 15:58:25	52.485076	4.805962	322	Sudden braking	4.80	4.80	20.4	17.6	1.00	2	4.2	1.000	604F0_Trip234	1
13/04/2026 15:58:26	52.485104	4.805923	320	Sudden braking	4.40	4.40	17.2	13.2	1.00	2	2.3	1.001	604F0_Trip234	1
13/04/2026 15:58:27	52.485120	4.805901	320	Sudden braking	3.60	3.60	15.2	9.6	1.00	2	3.3	1.000	604F0_Trip234	1
13/04/2026 15:58:28	52.485125	4.805854	3	Sudden braking	3.00	3.00	11.2	6.6	1.00	2	0.9	1.000	604F0_Trip234	1
13/04/2026 16:00:15	52.488505	4.796451	302	Sudden braking	3.00	3.00	32.7	34.4	1.00	2	9.1	1.000	604F0_Trip234	1
13/04/2026 16:00:16	52.488549	4.796339	301	Sudden braking	4.00	4.00	30.6	30.4	1.00	3	7.1	1.000	604F0_Trip234	1
13/04/2026 16:00:17	52.488571	4.796239	301	Sudden braking	4.80	4.80	28.5	25.6	1.00	3	4.9	1.000	604F0_Trip234	1
13/04/2026 16:00:18	52.488600	4.796185	299	Sudden braking	4.20	4.20	26.7	21.4	1.00	3	2.4	1.000	604F0_Trip234	1
13/04/2026 16:11:14	52.519600	4.706989	335	Sudden braking	2.10	2.10	37.1	35.5	1.00	2	9.5	1.000	604F0_Trip234	1
13/04/2026 16:11:55	52.521948	4.702424	312	Sudden braking	3.50	3.50	25.6	30.5	1.00	3	7.5	1.000	604F0_Trip234	1
13/04/2026 16:11:56	52.521993	4.702341	311	Sudden braking	4.60	4.60	25.0	25.9	1.00	3	4.5	1.000	604F0_Trip234	1
13/04/2026 16:11:57	52.522020	4.702291	314	Sudden braking	4.70	4.70	24.8	21.2	1.00	3	2.0	1.000	604F0_Trip234	1
13/04/2026 16:11:58	52.522032	4.702269	314	Sudden braking	3.60	3.60	23.8	17.6	1.00	3	0.5	1.000	604F0_Trip234	1
13/04/2026 16:14:30	52.535731	4.695534	354	Sudden braking	2.40	2.40	33.7	33.9	1.00	3	9.4	1.000	604F0_Trip234	1
13/04/2026 16:14:31	52.535815	4.695520	354	Sudden braking	2.60	2.60	32.7	31.3	1.00	3	7.9	1.000	604F0_Trip234	1
13/04/2026 16:14:32	52.535885	4.695510	355	Sudden braking	2.20	2.20	31.8	29.1	1.00	3	6.1	1.000	604F0_Trip234	1
14/04/2026 05:05:53	52.536419	4.694453	79	Sudden braking	2.40	2.40	32.7	33.0	1.00	2	8.9	1.000	604F0_Trip236	1
14/04/2026 05:05:54	52.536432	4.694583	83	Sudden braking	2.80	2.80	31.4	30.2	1.00	2	7.4	1.000	604F0_Trip236	1
14/04/2026 05:05:55	52.536430	4.694692	94	Sudden braking	2.70	2.70	30.1	27.5	1.00	2	6.7	1.001	604F0_Trip236	1
14/04/2026 05:05:56	52.536402	4.694780	116	Sudden braking	2.10	2.10	28.1	25.4	1.00	2	6.8	1.000	604F0_Trip236	1
14/04/2026 05:08:37	52.522490	4.702453	131	Sudden braking	2.20	2.20	32.4	34.2	1.00	2	9.2	1.000	604F0_Trip236	1
14/04/2026 05:08:38	52.522435	4.702555	132	Sudden braking	2.60	2.60	30.7	31.6	1.00	2	8.2	1.000	604F0_Trip236	1
14/04/2026 05:08:39	52.522386	4.702645	132	Sudden braking	3.20	3.20	29.0	28.4	1.00	2	7.1	1.000	604F0_Trip236	1
14/04/2026 05:08:40	52.522343	4.702723	133	Sudden braking	3.20	3.20	27.4	25.2	1.00	2	4.3	1.000	604F0_Trip236	1
14/04/2026 05:08:41	52.522317	4.702770	133	Sudden braking	2.20	2.20	25.8	23.0	1.00	2	1.9	1.000	604F0_Trip236	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
14/04/2026 05:09:26	52.519865	4.706293	138	Sudden braking	2.30	2.30	31.9	32.7	1.00	3	8.9	1.000	604F0_Trip236	1
14/04/2026 05:09:27	52.519803	4.706378	140	Sudden braking	2.60	2.60	30.5	30.1	1.00	3	8.0	1.000	604F0_Trip236	1
14/04/2026 05:09:28	52.519746	4.706449	143	Sudden braking	2.40	2.40	29.2	27.7	1.00	3	5.8	1.000	604F0_Trip236	1
14/04/2026 05:09:29	52.519697	4.706476	145	Sudden braking	2.00	2.00	28.1	25.7	1.00	2	6.7	1.000	604F0_Trip236	1
14/04/2026 05:16:19	52.495007	4.760421	102	Sudden braking	2.00	2.00	33.1	36.2	1.00	2	9.4	1.000	604F0_Trip236	1
14/04/2026 05:16:20	52.494989	4.760557	102	Sudden braking	2.80	2.80	30.8	33.4	1.00	2	8.1	1.000	604F0_Trip236	1
14/04/2026 05:16:21	52.494973	4.760673	102	Sudden braking	3.50	3.50	28.3	29.9	1.00	1	6.8	1.000	604F0_Trip236	1
14/04/2026 05:16:22	52.494960	4.760771	102	Sudden braking	3.80	3.80	25.6	26.1	1.00	1	5.7	1.000	604F0_Trip236	1
14/04/2026 05:16:23	52.494950	4.760852	102	Sudden braking	3.90	3.90	22.9	22.2	1.00	1	4.6	1.000	604F0_Trip236	1
14/04/2026 05:16:24	52.494941	4.760919	102	Sudden braking	3.80	3.80	20.3	18.4	1.00	1	3.7	1.000	604F0_Trip236	1
14/04/2026 05:16:25	52.494934	4.760972	102	Sudden braking	3.30	3.30	17.9	15.1	1.00	1	2.8	1.000	604F0_Trip236	1
14/04/2026 05:16:26	52.494928	4.761013	102	Sudden braking	2.60	2.60	15.9	12.5	1.00	1	2.5	1.000	604F0_Trip236	1
14/04/2026 05:16:57	52.494212	4.764314	102	Sudden braking	2.50	2.50	30.5	33.5	1.00	2	8.5	1.000	604F0_Trip236	1
14/04/2026 05:16:58	52.494199	4.764437	99	Sudden braking	3.40	3.40	28.7	30.1	1.00	2	6.6	1.000	604F0_Trip236	1
14/04/2026 05:16:59	52.494189	4.764534	99	Sudden braking	3.90	3.90	26.8	26.2	1.00	2	4.8	1.000	604F0_Trip236	1
14/04/2026 05:17:00	52.494183	4.764604	97	Sudden braking	3.70	3.70	24.8	22.5	1.00	2	4.4	1.000	604F0_Trip236	1
14/04/2026 05:17:01	52.494178	4.764668	97	Sudden braking	2.80	2.80	22.7	19.7	1.00	3	4.0	1.000	604F0_Trip236	1
14/04/2026 05:17:55	52.493822	4.768215	94	Sudden braking	3.30	3.30	33.0	32.8	1.00	2	9.8	1.000	604F0_Trip236	1
14/04/2026 05:17:59	52.494015	4.768692	92	Sudden braking	2.80	2.80	27.8	26.7	1.00	2	3.3	1.000	604F0_Trip236	1
14/04/2026 05:18:00	52.494014	4.768740	92	Sudden braking	2.40	2.40	27.0	24.3	1.00	2	5.7	1.000	604F0_Trip236	1
14/04/2026 05:31:09	52.433845	4.815845	169	Sudden braking	3.00	3.00	29.3	29.2	1.00	2	8.5	1.000	604F0_Trip236	1
14/04/2026 05:31:10	52.433769	4.815822	173	Sudden braking	3.00	3.00	28.1	26.2	1.00	2	4.0	1.000	604F0_Trip236	1
14/04/2026 05:35:09	52.421402	4.826634	184	Sudden braking	2.30	2.30	9.4	6.3	1.00	1	1.6	1.000	604F0_Trip236	1
14/04/2026 06:07:34	52.391293	4.880454	101	Sudden braking	2.10	2.10	32.0	33.5	1.00	2	9.1	1.000	604F0_Trip236	1
14/04/2026 06:07:35	52.391274	4.880584	103	Sudden braking	2.80	2.80	30.8	30.7	1.00	2	8.4	1.000	604F0_Trip236	1
14/04/2026 06:07:36	52.391266	4.880707	105	Sudden braking	2.70	2.70	29.7	28.0	1.00	2	6.7	1.000	604F0_Trip236	1
14/04/2026 06:07:37	52.391270	4.880804	102	Sudden braking	2.20	2.20	28.7	25.8	1.00	2	5.4	1.000	604F0_Trip236	1
14/04/2026 06:08:02	52.390917	4.884128	81	Sudden braking	2.10	2.10	29.6	29.7	1.00	3	6.8	1.000	604F0_Trip236	1
14/04/2026 06:08:03	52.390921	4.884228	83	Sudden braking	2.20	2.20	27.9	27.5	1.00	3	11.4	1.000	604F0_Trip236	1
14/04/2026 06:08:08	52.390782	4.884703	128	Sudden braking	2.00	2.00	18.3	19.3	1.00	3	5.9	1.000	604F0_Trip236	1
14/04/2026 06:08:09	52.390748	4.884771	132	Sudden braking	2.30	2.30	16.4	17.0	1.00	3	3.5	1.000	604F0_Trip236	1
14/04/2026 06:08:10	52.390727	4.884809	132	Sudden braking	2.50	2.50	15.5	14.5	1.00	2	2.8	1.000	604F0_Trip236	1
14/04/2026 06:08:11	52.390710	4.884839	132	Sudden braking	2.50	2.50	14.6	12.0	1.00	3	2.5	1.000	604F0_Trip236	1
14/04/2026 06:08:12	52.390695	4.884866	134	Sudden braking	2.40	2.40	13.5	9.6	1.00	3	2.0	1.000	604F0_Trip236	1
14/04/2026 06:09:06	52.369627	4.919594	295	Sudden braking	2.40	2.40	15.3	16.2	1.00	2	4.4	1.000	602D3_Trip235	1
14/04/2026 06:09:07	52.369650	4.919541	299	Sudden braking	2.60	2.60	14.3	13.6	1.00	2	2.1	1.000	602D3_Trip235	1
14/04/2026 06:09:08	52.369658	4.919514	299	Sudden braking	2.40	2.40	13.4	11.2	1.00	2	1.1	1.000	602D3_Trip235	1
14/04/2026 06:09:09	52.369661	4.919497	297	Sudden braking	2.00	2.00	12.6	9.2	1.00	2	1.7	1.000	602D3_Trip235	1
14/04/2026 06:09:13	52.389710	4.890532	107	Sudden braking	3.10	3.10	29.4	33.5	1.00	2	8.5	1.000	604F0_Trip236	1
14/04/2026 06:09:14	52.389679	4.890647	109	Sudden braking	4.40	4.40	26.5	29.1	1.00	2	7.5	1.000	604F0_Trip236	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
14/04/2026 06:09:15	52.389666	4.890756	111	Sudden braking	5.10	5.10	23.4	24.0	1.00	2	5.6	1.000	604F0_Trip236	1
14/04/2026 06:09:16	52.389642	4.890828	113	Sudden braking	5.30	5.30	20.3	18.7	1.00	2	4.1	1.000	604F0_Trip236	1
14/04/2026 06:09:17	52.389622	4.890879	116	Sudden braking	4.90	4.90	17.2	13.8	1.00	2	2.7	1.000	604F0_Trip236	1
14/04/2026 06:09:18	52.389610	4.890914	119	Sudden braking	3.80	3.80	14.3	10.0	1.00	2	1.5	1.000	604F0_Trip236	1
14/04/2026 06:09:19	52.389600	4.890926	119	Sudden braking	2.60	2.60	11.8	7.4	1.00	3	1.8	1.000	604F0_Trip236	1
14/04/2026 06:10:03	52.371086	4.915428	314	Sudden braking	3.10	3.10	16.8	15.1	1.00	2	5.2	1.000	602D3_Trip235	1
14/04/2026 06:10:41	52.384024	4.892857	183	Sudden braking	2.70	2.70	31.3	34.3	1.00	2	8.0	1.000	604F0_Trip236	1
14/04/2026 06:10:42	52.383952	4.892861	180	Sudden braking	3.50	3.50	28.8	30.8	1.00	2	6.8	1.000	604F0_Trip236	1
14/04/2026 06:10:43	52.383891	4.892863	178	Sudden braking	4.20	4.20	26.2	26.6	1.00	2	6.1	1.000	604F0_Trip236	1
14/04/2026 06:10:44	52.383836	4.892871	178	Sudden braking	4.20	4.20	23.5	22.4	1.00	2	4.5	1.000	604F0_Trip236	1
14/04/2026 06:10:45	52.383795	4.892873	174	Sudden braking	3.70	3.70	20.8	18.7	1.00	2	3.2	1.000	604F0_Trip236	1
14/04/2026 06:10:46	52.383767	4.892881	174	Sudden braking	3.20	3.20	18.2	15.5	1.00	2	2.8	1.000	604F0_Trip236	1
14/04/2026 06:10:47	52.383742	4.892889	171	Sudden braking	2.40	2.40	15.7	13.1	1.00	3	2.5	1.000	604F0_Trip236	1
14/04/2026 06:12:05	52.381116	4.897688	120	Sudden braking	2.40	2.40	28.7	28.2	1.00	2	9.6	1.000	604F0_Trip236	1
14/04/2026 06:12:17	52.380687	4.898836	119	Sudden braking	3.10	3.10	18.8	22.2	1.00	3	4.3	1.000	604F0_Trip236	1
14/04/2026 06:12:18	52.380668	4.898892	119	Sudden braking	3.30	3.30	19.0	18.9	1.00	3	4.9	1.000	604F0_Trip236	1
14/04/2026 06:12:49	52.379544	4.901765	120	Sudden braking	2.00	2.00	29.0	29.9	1.00	3	7.5	1.000	604F0_Trip236	1
14/04/2026 06:12:50	52.379516	4.901866	121	Sudden braking	2.20	2.20	28.1	27.7	1.00	3	6.6	1.000	604F0_Trip236	1
14/04/2026 06:12:51	52.379492	4.901954	121	Sudden braking	2.00	2.00	27.1	25.7	1.00	3	6.6	1.000	604F0_Trip236	1
14/04/2026 06:13:58	52.377921	4.909414	103	Sudden braking	2.30	2.30	27.5	28.3	1.00	2	7.5	1.000	604F0_Trip236	1
14/04/2026 06:13:59	52.377903	4.909520	102	Sudden braking	2.50	2.50	25.9	25.8	1.00	2	6.2	1.000	604F0_Trip236	1
14/04/2026 06:14:00	52.377892	4.909610	102	Sudden braking	2.50	2.50	24.3	23.3	1.00	2	5.5	1.000	604F0_Trip236	1
14/04/2026 06:14:01	52.377882	4.909689	104	Sudden braking	2.20	2.20	22.5	21.1	1.00	2	5.6	1.000	604F0_Trip236	1
14/04/2026 06:14:07	52.377748	4.909987	177	Sudden braking	2.20	2.20	13.0	12.1	1.00	2	2.8	1.000	604F0_Trip236	1
14/04/2026 06:14:08	52.377725	4.910002	188	Sudden braking	2.00	2.00	12.1	10.1	1.00	2	1.9	1.000	604F0_Trip236	1
14/04/2026 06:14:32	52.376658	4.910186	156	Sudden braking	2.30	2.30	20.8	23.7	1.00	3	7.4	1.000	604F0_Trip236	1
14/04/2026 06:14:33	52.376595	4.910223	155	Sudden braking	2.70	2.70	19.1	21.0	1.00	3	1.5	1.000	604F0_Trip236	1
14/04/2026 06:14:34	52.376581	4.910221	155	Sudden braking	3.10	3.10	17.3	17.9	1.00	3	4.4	1.000	604F0_Trip236	1
14/04/2026 06:14:35	52.376555	4.910268	155	Sudden braking	3.70	3.70	15.5	14.2	1.00	3	4.3	1.000	604F0_Trip236	1
14/04/2026 06:14:36	52.376516	4.910276	155	Sudden braking	3.30	3.30	13.9	10.9	1.00	3	1.6	1.000	604F0_Trip236	1
14/04/2026 06:14:37	52.376502	4.910280	155	Sudden braking	2.30	2.30	12.5	8.6	1.00	3	1.0	1.000	604F0_Trip236	1
14/04/2026 06:14:54	52.375825	4.910519	185	Sudden braking	2.50	2.50	17.8	19.2	1.00	2	4.6	1.000	604F0_Trip236	1
14/04/2026 06:14:55	52.375785	4.910530	187	Sudden braking	3.00	3.00	16.9	16.2	1.00	2	1.7	1.000	604F0_Trip236	1
14/04/2026 06:14:56	52.375772	4.910544	191	Sudden braking	2.90	2.90	16.0	13.3	1.00	3	3.1	1.000	604F0_Trip236	1
14/04/2026 06:14:57	52.375799	4.910553	191	Sudden braking	2.10	2.10	15.2	11.2	1.00	3	2.9	1.000	604F0_Trip236	1
14/04/2026 06:16:20	52.374850	4.915071	159	Sudden braking	2.50	2.50	17.5	18.1	1.00	2	3.9	1.000	604F0_Trip236	1
14/04/2026 06:16:21	52.374821	4.915102	154	Sudden braking	2.80	2.80	16.2	15.3	1.00	2	3.1	1.000	604F0_Trip236	1
14/04/2026 06:16:22	52.374796	4.915121	152	Sudden braking	2.60	2.60	14.9	12.7	1.00	2	2.0	1.000	604F0_Trip236	1
14/04/2026 06:16:23	52.374785	4.915143	140	Sudden braking	2.00	2.00	13.7	10.7	1.00	2	3.3	1.000	604F0_Trip236	1
14/04/2026 06:16:31	52.374819	4.915432	115	Sudden braking	2.10	2.10	7.5	5.6	1.00	2	2.1	1.000	604F0_Trip236	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
14/04/2026 16:39:14	52.371331	4.915302	239	Sudden braking	2.50	2.50	13.9	15.3	1.00	2	3.1	1.000	602CA_Trip239	1
14/04/2026 16:39:15	52.371316	4.915264	239	Sudden braking	3.40	3.40	12.1	11.9	1.00	2	1.6	1.000	602CA_Trip239	1
14/04/2026 16:39:16	52.371309	4.915244	239	Sudden braking	3.50	3.50	11.2	8.4	1.00	2	1.6	1.000	602CA_Trip239	1
14/04/2026 16:39:17	52.371316	4.915264	239	Sudden braking	3.30	3.30	10.1	5.1	1.00	2	0.1	1.000	602CA_Trip239	1
14/04/2026 16:44:22	52.366029	4.933658	89	Sudden braking	2.40	2.40	16.1	14.9	1.00	3	5.7	1.000	602CA_Trip239	1
14/04/2026 16:47:35	52.364739	4.947387	108	Sudden braking	2.10	2.10	9.1	6.5	1.00	2	1.1	1.000	602CA_Trip239	1
14/04/2026 16:48:39	52.365888	4.947221	3	Sudden braking	2.00	2.00	12.3	11.3	1.00	2	3.5	1.000	602CA_Trip239	1
14/04/2026 16:48:40	52.365918	4.947236	2	Sudden braking	2.80	2.80	10.9	8.5	1.00	2	2.7	1.000	602CA_Trip239	1
14/04/2026 16:49:09	52.366196	4.947560	48	Sudden braking	2.00	2.00	9.8	8.9	1.00	2	2.3	1.000	602CA_Trip239	1
14/04/2026 16:49:16	52.366224	4.947539	335	Sudden braking	2.10	2.10	2.3	2.1	1.00	2	1.4	1.000	602CA_Trip239	1
14/04/2026 16:50:22	52.365518	4.948604	107	Sudden braking	2.10	2.10	10.0	7.4	1.00	2	2.7	1.000	602CA_Trip239	1
14/04/2026 16:50:23	52.365511	4.948642	106	Sudden braking	2.10	2.10	9.2	5.3	1.00	2	1.3	1.000	602CA_Trip239	1
14/04/2026 16:51:33	52.365483	4.949363	89	Sudden braking	2.00	2.00	8.6	8.9	1.00	2	2.7	1.000	602CA_Trip239	1
14/04/2026 16:51:34	52.365468	4.949395	112	Sudden braking	2.40	2.40	7.3	6.5	1.00	2	1.9	1.000	602CA_Trip239	1
14/04/2026 16:51:35	52.365475	4.949420	103	Sudden braking	2.40	2.40	6.6	4.1	1.00	2	1.0	1.000	602CA_Trip239	1
15/04/2026 06:05:39	52.361123	4.930482	5	Sudden braking	2.48	2.48	10.7	12.7	1.00	2	1.5	1.000	602D3_Trip240	1
15/04/2026 06:05:40	52.361134	4.930491	5	Sudden braking	3.60	3.60	10.7	9.1	1.00	2	1.6	1.000	602D3_Trip240	1
15/04/2026 06:06:21	52.362765	4.930566	357	Sudden braking	2.90	2.90	18.6	17.0	1.00	2	5.6	1.000	602D3_Trip240	1
15/04/2026 07:12:31	52.389976	4.922874	233	Sudden braking	2.00	2.00	15.7	18.4	1.00	2	5.3	1.000	602D6_Trip241	1
15/04/2026 07:12:32	52.389952	4.922807	232	Sudden braking	3.10	3.10	15.0	15.3	1.00	3	3.8	1.000	602D6_Trip241	1
15/04/2026 07:12:33	52.389953	4.922751	232	Sudden braking	3.00	3.00	13.4	12.3	1.00	3	6.5	1.000	602D6_Trip241	1
15/04/2026 07:12:34	52.389977	4.922837	232	Sudden braking	2.90	2.90	12.1	9.4	1.00	3	2.4	1.000	602D6_Trip241	1
15/04/2026 07:12:35	52.389979	4.922802	232	Sudden braking	2.50	2.50	10.9	6.9	1.00	2	1.5	1.000	602D6_Trip241	1
15/04/2026 07:13:11	52.389162	4.920730	232	Sudden braking	2.90	2.90	15.2	16.4	1.00	2	9.5	1.000	602D6_Trip241	1
15/04/2026 07:13:12	52.389076	4.920730	235	Sudden braking	3.40	3.40	14.5	13.0	1.00	2	10.3	1.000	602D6_Trip241	1
15/04/2026 07:13:13	52.389164	4.920781	223	Sudden braking	3.60	3.60	13.5	9.4	1.00	2	1.6	1.000	602D6_Trip241	1
15/04/2026 07:13:25	52.388731	4.919748	220	Sudden braking	2.60	2.60	18.5	20.7	1.00	2	4.7	1.000	602D6_Trip241	1
15/04/2026 07:13:26	52.388732	4.919678	236	Sudden braking	2.50	2.50	18.4	18.2	1.00	2	3.2	1.000	602D6_Trip241	1
15/04/2026 07:13:27	52.388717	4.919637	240	Sudden braking	2.20	2.20	18.4	16.0	1.00	2	4.2	1.000	602D6_Trip241	1
15/04/2026 07:16:00	52.383387	4.911711	200	Sudden braking	3.00	3.00	20.0	19.6	1.00	3	4.2	1.000	602D6_Trip241	1
15/04/2026 07:16:01	52.383352	4.911692	200	Sudden braking	2.00	2.00	19.3	17.6	1.00	3	3.9	1.000	602D6_Trip241	1
15/04/2026 07:16:27	52.383084	4.909830	241	Sudden braking	3.30	3.30	20.1	17.7	1.00	2	8.0	1.000	602D6_Trip241	1
15/04/2026 07:17:03	52.381921	4.908368	218	Sudden braking	4.10	4.10	4.3	10.0	1.00	2	1.3	1.000	602D6_Trip241	1
15/04/2026 07:17:04	52.381916	4.908350	218	Sudden braking	4.50	4.50	4.3	5.5	1.00	2	2.2	1.000	602D6_Trip241	1
15/04/2026 07:17:05	52.381934	4.908359	218	Sudden braking	2.70	2.70	4.3	2.8	1.00	2	1.3	1.000	602D6_Trip241	1
15/04/2026 07:28:17	52.374542	4.914617	152	Sudden braking	2.70	2.70	10.5	11.1	1.00	3	2.1	1.000	602D6_Trip241	1
15/04/2026 07:28:18	52.374560	4.914625	144	Sudden braking	2.60	2.60	9.9	8.5	1.00	3	1.8	1.000	602D6_Trip241	1
15/04/2026 07:28:19	52.374566	4.914650	82	Sudden braking	2.60	2.60	9.4	5.9	1.00	3	1.7	1.000	602D6_Trip241	1
15/04/2026 07:28:31	52.374105	4.914187	228	Sudden braking	2.00	2.00	14.8	15.7	1.00	2	2.3	1.000	602D6_Trip241	1
15/04/2026 07:28:32	52.374111	4.914155	234	Sudden braking	2.60	2.60	14.0	13.1	1.00	2	2.0	1.000	602D6_Trip241	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
15/04/2026 07:56:26	52.371066	4.913223	283	Sudden braking	2.20	2.20	14.3	12.5	1.00	2	3.1	1.000	602D3_Trip242	1
15/04/2026 07:56:27	52.371066	4.913178	276	Sudden braking	2.30	2.30	13.8	10.2	1.00	2	1.3	0.999	602D3_Trip242	1
15/04/2026 08:59:52	52.380079	4.892228	26	Sudden braking	2.40	2.40	9.9	9.4	1.00	2	3.8	1.000	602D3_Trip243	1
15/04/2026 08:59:53	52.380112	4.892241	18	Sudden braking	2.10	2.10	9.1	7.3	1.00	2	1.2	1.000	602D3_Trip243	1
15/04/2026 09:03:20	52.376196	4.902659	148	Sudden braking	2.10	2.10	14.3	15.4	1.00	2	5.0	1.000	602D3_Trip243	1
15/04/2026 09:03:21	52.376160	4.902703	143	Sudden braking	2.70	2.70	13.6	12.7	1.00	2	2.3	1.000	602D3_Trip243	1
15/04/2026 09:03:23	52.376161	4.902752	72	Sudden braking	3.40	3.40	8.5	6.3	1.00	2	1.5	1.000	602D3_Trip243	1
15/04/2026 09:08:55	52.376646	4.913866	96	Sudden braking	2.90	2.90	15.0	15.2	1.00	3	5.5	1.000	602D3_Trip243	1
15/04/2026 09:08:56	52.376641	4.913946	96	Sudden braking	2.80	2.80	14.2	12.4	1.00	2	1.1	1.000	602D3_Trip243	1
15/04/2026 09:08:57	52.376640	4.913962	97	Sudden braking	2.69	2.69	13.6	9.7	1.00	3	4.2	1.002	602D3_Trip243	1
15/04/2026 15:01:08	52.371390	4.916012	243	Sudden braking	2.03	2.03	13.4	13.2	1.00	2	4.7	1.000	602D3_Trip244	1
15/04/2026 15:02:06	52.370134	4.918034	129	Sudden braking	2.30	2.30	10.6	10.1	1.00	2	3.0	1.000	602D3_Trip244	1
15/04/2026 15:10:00	52.363442	4.930467	179	Sudden braking	2.00	2.00	14.8	14.0	1.00	2	2.4	1.000	602D3_Trip244	1
15/04/2026 15:22:43	52.376599	4.912101	265	Sudden braking	2.50	2.50	14.4	15.5	1.00	2	7.9	1.000	602D6_Trip245	1
15/04/2026 15:22:44	52.376579	4.911990	263	Sudden braking	2.50	2.50	13.3	13.0	1.00	2	4.7	1.000	602D6_Trip245	1
15/04/2026 15:22:45	52.376597	4.912052	285	Sudden braking	2.20	2.20	12.1	10.8	1.00	2	8.5	1.000	602D6_Trip245	1
15/04/2026 15:22:46	52.376554	4.911948	258	Sudden braking	2.30	2.30	11.0	8.5	1.00	2	2.9	1.000	602D6_Trip245	1
15/04/2026 15:25:04	52.378472	4.906026	339	Sudden braking	2.00	2.00	8.6	5.3	1.00	2	1.3	1.000	602D6_Trip245	1
15/04/2026 17:10:53	52.378772	4.874348	74	Sudden braking	2.00	2.00	16.5	15.1	1.00	2	3.0	1.000	602CA_Trip246	1
15/04/2026 17:12:27	52.375760	4.875347	111	Sudden braking	2.50	2.50	15.5	15.4	1.00	2	5.4	1.000	602CA_Trip246	1
15/04/2026 17:12:28	52.375743	4.875421	111	Sudden braking	2.50	2.50	15.0	12.9	1.00	2	1.6	1.000	602CA_Trip246	1
15/04/2026 17:12:29	52.375740	4.875444	111	Sudden braking	2.00	2.00	14.7	10.9	1.00	2	3.3	1.000	602CA_Trip246	1
15/04/2026 17:13:02	52.374344	4.874997	191	Sudden braking	2.40	2.40	14.1	13.6	1.00	2	4.5	1.000	602CA_Trip246	1
15/04/2026 17:13:03	52.374304	4.874985	190	Sudden braking	2.40	2.40	13.4	11.2	1.00	2	1.2	1.000	602CA_Trip246	1
15/04/2026 17:13:11	52.374087	4.874848	187	Sudden braking	2.20	2.20	7.3	7.9	1.00	2	1.4	1.000	602CA_Trip246	1
15/04/2026 17:13:12	52.374075	4.874856	173	Sudden braking	2.30	2.30	6.9	5.6	1.00	2	1.2	1.000	602CA_Trip246	1
15/04/2026 17:14:18	52.372291	4.875664	198	Sudden braking	2.00	2.00	12.2	11.6	1.00	2	2.3	1.000	602CA_Trip246	1
15/04/2026 17:14:19	52.372271	4.875651	199	Sudden braking	2.20	2.20	10.7	9.4	1.00	2	2.0	1.000	602CA_Trip246	1
15/04/2026 17:14:20	52.372257	4.875634	204	Sudden braking	2.00	2.00	9.9	7.4	1.00	2	2.0	1.000	602CA_Trip246	1
15/04/2026 17:15:28	52.372095	4.878128	64	Sudden braking	2.00	2.00	14.5	14.8	1.00	2	5.2	1.000	602CA_Trip246	1
15/04/2026 17:15:30	52.372123	4.878203	59	Sudden braking	2.20	2.20	13.7	10.7	1.00	2	4.1	1.000	602CA_Trip246	1
17/04/2026 08:46:46	52.406534	4.924796	1	Sudden braking	3.17	3.17	14.3	17.1	1.00	2	6.0	1.000	602D6_Trip271	1
17/04/2026 08:46:49	52.406624	4.924821	11	Sudden braking	2.90	2.90	14.3	11.0	1.00	2	3.0	1.000	602D6_Trip271	1
17/04/2026 08:46:50	52.406650	4.924836	18	Sudden braking	2.90	2.90	14.2	8.1	1.00	2	3.4	1.000	602D6_Trip271	1
17/04/2026 08:47:55	52.409668	4.928146	27	Sudden braking	2.40	2.40	16.2	16.2	1.00	2	6.7	1.000	602D6_Trip271	1
17/04/2026 08:48:34	52.411299	4.929662	75	Sudden braking	3.00	3.00	9.7	8.4	1.00	2	9.0	1.000	602D6_Trip271	1
17/04/2026 08:50:05	52.413076	4.928349	305	Sudden braking	2.10	2.10	13.8	15.6	1.00	2	5.8	1.000	602D6_Trip271	1
17/04/2026 08:50:06	52.413104	4.928277	304	Sudden braking	2.50	2.50	12.9	13.1	1.00	2	2.2	1.000	602D6_Trip271	1
17/04/2026 08:50:07	52.413118	4.928256	310	Sudden braking	2.40	2.40	12.1	10.7	1.00	2	2.4	1.000	602D6_Trip271	1
17/04/2026 08:50:08	52.413135	4.928233	320	Sudden braking	2.40	2.40	11.5	8.3	1.00	2	3.8	1.000	602D6_Trip271	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
17/04/2026 08:50:29	52.413719	4.926891	311	Sudden braking	2.00	2.00	13.5	12.2	1.00	2	4.0	1.000	602D6_Trip271	1
17/04/2026 08:52:37	52.417711	4.924388	28	Sudden braking	2.20	2.20	15.9	15.7	1.00	2	5.1	1.000	602D6_Trip271	1
17/04/2026 08:52:38	52.417749	4.924429	30	Sudden braking	2.10	2.10	15.6	13.6	1.00	2	1.7	1.000	602D6_Trip271	1
17/04/2026 08:53:17	52.418800	4.922244	304	Sudden braking	2.60	2.60	14.3	15.8	1.00	2	5.4	1.000	602D6_Trip271	1
17/04/2026 08:53:18	52.418826	4.922177	304	Sudden braking	2.40	2.40	12.9	13.4	1.00	2	1.3	1.000	602D6_Trip271	1
17/04/2026 08:53:19	52.418815	4.922173	294	Sudden braking	2.80	2.80	11.6	10.6	1.00	2	5.2	1.000	602D6_Trip271	1
17/04/2026 08:53:20	52.418843	4.922112	302	Sudden braking	2.40	2.40	10.3	8.2	1.00	2	2.5	1.000	602D6_Trip271	1
17/04/2026 08:53:37	52.419161	4.920719	288	Sudden braking	2.50	2.50	14.2	16.5	1.00	2	2.4	1.000	602D6_Trip271	1
17/04/2026 08:53:38	52.419177	4.920695	293	Sudden braking	2.40	2.40	14.5	14.1	1.00	2	1.4	0.999	602D6_Trip271	1
17/04/2026 08:55:32	52.420860	4.913151	295	Sudden braking	2.10	2.10	14.8	16.4	1.00	2	4.4	1.000	602D6_Trip271	1
17/04/2026 08:55:33	52.420872	4.913088	292	Sudden braking	2.50	2.50	13.8	13.9	1.00	2	2.6	1.000	602D6_Trip271	1
17/04/2026 08:55:34	52.420894	4.913081	306	Sudden braking	2.80	2.80	12.8	11.1	1.00	2	3.0	1.000	602D6_Trip271	1
17/04/2026 08:55:35	52.420892	4.913037	295	Sudden braking	2.00	2.00	11.7	9.1	1.00	2	4.4	1.000	602D6_Trip271	1
17/04/2026 08:58:54	52.425426	4.903984	300	Sudden braking	2.10	2.10	14.3	11.8	1.00	2	3.9	1.000	602D6_Trip271	1
17/04/2026 08:58:55	52.425445	4.903937	309	Sudden braking	2.00	2.00	14.2	9.8	1.00	2	5.0	1.000	602D6_Trip271	1
17/04/2026 09:00:57	52.429220	4.899844	4	Sudden braking	2.10	2.10	16.7	18.4	1.00	2	5.4	1.000	602D6_Trip271	1
17/04/2026 09:00:58	52.429269	4.899844	2	Sudden braking	2.50	2.50	15.5	15.9	1.00	2	2.7	1.000	602D6_Trip271	1
17/04/2026 09:00:59	52.429293	4.899836	360	Sudden braking	2.50	2.50	14.4	13.4	1.00	2	3.3	1.000	602D6_Trip271	1
17/04/2026 09:01:00	52.429323	4.899834	357	Sudden braking	2.40	2.40	13.5	11.0	1.00	2	4.2	1.000	602D6_Trip271	1
17/04/2026 09:01:37	52.431373	4.899984	352	Sudden braking	2.00	2.00	18.5	19.0	1.00	2	6.0	1.000	602D6_Trip271	1
17/04/2026 09:01:40	52.431508	4.899981	353	Sudden braking	2.70	2.70	13.2	13.2	1.00	2	1.4	1.000	602D6_Trip271	1
17/04/2026 09:01:41	52.431520	4.899980	356	Sudden braking	2.70	2.70	12.2	10.5	1.00	2	4.1	1.000	602D6_Trip271	1
17/04/2026 09:01:42	52.431555	4.899964	351	Sudden braking	2.80	2.80	11.3	7.7	1.00	2	5.2	1.000	602D6_Trip271	1
17/04/2026 09:02:10	52.432885	4.900148	14	Sudden braking	2.80	2.80	12.4	10.6	1.00	2	4.1	1.000	602D6_Trip271	1
17/04/2026 09:02:11	52.432921	4.900154	14	Sudden braking	2.80	2.80	12.1	7.8	1.00	2	3.2	1.000	602D6_Trip271	1
17/04/2026 09:02:37	52.434092	4.899840	295	Sudden braking	2.40	2.40	12.1	11.1	1.00	2	3.4	1.000	602D6_Trip271	1
17/04/2026 09:02:38	52.434105	4.899795	295	Sudden braking	2.00	2.00	12.4	9.1	1.00	2	2.6	1.000	602D6_Trip271	1
17/04/2026 09:03:32	52.434910	4.896389	271	Sudden braking	2.00	2.00	12.6	12.6	1.00	2	1.5	1.000	602D6_Trip271	1
17/04/2026 09:06:10	52.439937	4.892327	358	Sudden braking	2.00	2.00	15.1	17.5	1.00	2	5.8	1.000	602D6_Trip271	1
17/04/2026 09:06:11	52.439989	4.892322	357	Sudden braking	2.20	2.20	14.4	15.3	1.00	2	2.1	1.000	602D6_Trip271	1
17/04/2026 09:06:12	52.440007	4.892321	355	Sudden braking	2.40	2.40	13.2	12.9	1.00	2	2.6	1.000	602D6_Trip271	1
17/04/2026 09:06:13	52.440030	4.892318	355	Sudden braking	2.70	2.70	12.0	10.2	1.00	2	3.8	1.000	602D6_Trip271	1
17/04/2026 09:06:28	52.440797	4.892137	1	Sudden braking	2.00	2.00	17.7	20.1	1.00	2	7.0	1.000	602D6_Trip271	1
17/04/2026 09:06:29	52.440860	4.892135	357	Sudden braking	3.10	3.10	16.5	17.0	1.00	2	5.5	1.000	602D6_Trip271	1
17/04/2026 09:06:32	52.440932	4.892090	338	Sudden braking	3.20	3.20	11.6	10.8	1.00	2	4.1	1.000	602D6_Trip271	1
17/04/2026 09:06:33	52.440966	4.892068	338	Sudden braking	3.20	3.20	9.9	7.6	1.00	2	3.8	1.000	602D6_Trip271	1
17/04/2026 10:31:50	52.432375	4.899773	226	Sudden braking	2.20	2.20	10.2	14.7	1.00	2	4.7	1.000	602D6_Trip272	1
17/04/2026 10:31:53	52.432301	4.899712	205	Sudden braking	2.20	2.20	8.6	10.0	1.00	2	1.6	1.000	602D6_Trip272	1
17/04/2026 10:31:54	52.432287	4.899706	193	Sudden braking	2.20	2.20	8.3	7.8	1.00	2	4.0	1.000	602D6_Trip272	1
17/04/2026 10:41:51	52.413671	4.911038	84	Sudden braking	2.00	2.00	11.3	10.3	1.00	2	3.5	1.000	602D6_Trip272	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
17/04/2026 10:42:31	52.412554	4.910875	192	Sudden braking	2.30	2.30	8.5	8.5	1.00	2	3.4	1.000	602D6_Trip272	1
17/04/2026 10:44:10	52.409636	4.914937	134	Sudden braking	2.50	2.50	7.4	7.3	1.00	2	3.2	1.000	602D6_Trip272	1
17/04/2026 10:47:29	52.403215	4.912705	197	Sudden braking	2.10	2.10	10.4	10.4	1.00	2	3.8	1.000	602D6_Trip272	1
17/04/2026 10:47:30	52.403185	4.912678	199	Sudden braking	2.00	2.00	10.0	8.4	1.00	2	3.0	1.000	602D6_Trip272	1
17/04/2026 10:48:30	52.400974	4.911389	181	Sudden braking	2.20	2.20	9.3	12.8	1.00	2	3.9	1.000	602D6_Trip272	1
17/04/2026 10:48:31	52.400939	4.911394	179	Sudden braking	2.10	2.10	8.9	10.7	1.00	2	1.2	1.000	602D6_Trip272	1
17/04/2026 10:48:32	52.400930	4.911386	180	Sudden braking	2.00	2.00	8.5	8.7	1.00	2	2.4	1.000	602D6_Trip272	1
17/04/2026 10:48:33	52.400910	4.911372	190	Sudden braking	2.00	2.00	8.3	6.7	1.00	2	2.9	1.000	602D6_Trip272	1
17/04/2026 10:49:04	52.400867	4.912891	84	Sudden braking	2.00	2.00	9.6	9.0	1.00	2	1.7	1.000	602D6_Trip272	1
17/04/2026 10:49:32	52.400914	4.914999	75	Sudden braking	2.50	2.50	15.4	16.2	1.00	2	15.0	1.000	602D6_Trip272	1
17/04/2026 10:49:35	52.401051	4.915112	84	Sudden braking	2.60	2.60	11.7	11.1	1.00	2	3.8	1.000	602D6_Trip272	1
17/04/2026 10:49:36	52.401054	4.915167	84	Sudden braking	2.70	2.70	10.4	8.4	1.00	2	2.9	1.000	602D6_Trip272	1
17/04/2026 10:50:31	52.400061	4.919431	109	Sudden braking	2.50	2.50	13.9	14.8	1.00	2	5.7	1.000	602D6_Trip272	1
17/04/2026 10:50:32	52.400036	4.919505	112	Sudden braking	2.20	2.20	12.7	12.6	1.00	2	1.9	1.000	602D6_Trip272	1
17/04/2026 10:50:33	52.400052	4.919498	106	Sudden braking	2.30	2.30	11.6	10.3	1.00	2	2.9	1.000	602D6_Trip272	1
17/04/2026 10:50:34	52.400063	4.919537	90	Sudden braking	2.60	2.60	10.6	7.7	1.00	2	3.5	1.000	602D6_Trip272	1
17/04/2026 10:51:45	52.397992	4.922571	151	Sudden braking	2.60	2.60	12.8	13.6	1.00	3	5.0	1.000	602D6_Trip272	1
17/04/2026 10:51:46	52.397950	4.922602	153	Sudden braking	2.20	2.20	11.8	11.4	1.00	3	2.7	1.000	602D6_Trip272	1
17/04/2026 10:51:47	52.397969	4.922576	156	Sudden braking	2.40	2.40	10.8	9.0	1.00	3	1.7	1.000	602D6_Trip272	1
17/04/2026 10:51:48	52.397954	4.922586	163	Sudden braking	2.20	2.20	9.8	6.8	1.00	3	2.6	1.000	602D6_Trip272	1
17/04/2026 10:52:11	52.396965	4.923197	162	Sudden braking	2.80	2.80	10.6	14.3	1.00	2	5.1	1.000	602D6_Trip272	1
17/04/2026 10:52:12	52.396925	4.923231	160	Sudden braking	2.80	2.80	10.0	11.5	1.00	2	2.5	1.000	602D6_Trip272	1
17/04/2026 10:52:13	52.396942	4.923208	161	Sudden braking	2.90	2.90	9.5	8.6	1.00	3	3.3	1.000	602D6_Trip272	1
17/04/2026 10:52:14	52.396912	4.923208	170	Sudden braking	2.80	2.80	9.1	5.8	1.00	3	2.0	1.000	602D6_Trip272	1
17/04/2026 10:54:54	52.391074	4.924826	160	Sudden braking	2.30	2.30	10.0	7.1	1.00	2	3.5	1.000	602D6_Trip272	1
20/04/2026 06:41:34	52.389945	4.922609	232	Sudden braking	2.80	2.80	14.3	15.0	1.00	3	6.0	1.000	602D6_Trip300	1
20/04/2026 06:41:35	52.389909	4.922541	233	Sudden braking	2.60	2.60	13.4	12.4	1.00	3	3.0	1.000	602D6_Trip300	1
20/04/2026 06:41:37	52.389899	4.922551	232	Sudden braking	2.00	2.00	11.5	8.6	1.00	2	5.9	1.000	602D6_Trip300	1
20/04/2026 06:42:05	52.389443	4.921182	277	Sudden braking	2.10	2.10	12.5	16.8	1.00	2	13.6	1.000	602D6_Trip300	1
20/04/2026 06:42:06	52.389341	4.921073	251	Sudden braking	2.80	2.80	12.9	14.0	1.00	2	8.7	1.000	602D6_Trip300	1
20/04/2026 06:42:07	52.389350	4.921200	224	Sudden braking	3.60	3.60	12.1	10.4	1.00	2	3.7	1.000	602D6_Trip300	1
20/04/2026 06:42:08	52.389325	4.921164	222	Sudden braking	4.00	4.00	11.3	6.4	1.00	2	5.0	1.000	602D6_Trip300	1
20/04/2026 06:42:24	52.388995	4.919993	256	Sudden braking	2.20	2.20	8.4	8.5	1.00	2	6.1	1.000	602D6_Trip300	1
20/04/2026 06:42:33	52.373343	4.938614	2	Sudden braking	2.00	2.00	10.2	9.4	1.00	2	1.6	1.000	602D3_Trip298	1
20/04/2026 06:44:34	52.385381	4.874812	89	Sudden braking	2.90	2.90	17.3	17.6	1.00	2	4.5	1.000	602CA_Trip301	1
20/04/2026 06:44:35	52.385380	4.874879	89	Sudden braking	3.30	3.30	16.0	14.3	1.00	2	2.1	1.000	602CA_Trip301	1
20/04/2026 06:44:38	52.385377	4.874936	89	Sudden braking	2.00	2.00	13.2	9.5	1.00	2	2.2	1.000	602CA_Trip301	1
20/04/2026 06:44:38	52.383743	4.911968	220	Sudden braking	2.90	2.90	9.8	8.9	1.00	3	3.5	1.000	602D6_Trip300	1
20/04/2026 06:44:39	52.383714	4.911947	220	Sudden braking	2.10	2.10	9.6	6.8	1.00	2	1.2	1.000	602D6_Trip300	1
20/04/2026 06:45:22	52.382835	4.909438	221	Sudden braking	3.40	3.40	15.5	17.3	1.00	2	3.7	1.000	602D6_Trip300	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
20/04/2026 06:45:23	52.382804	4.909420	221	Sudden braking	3.40	3.40	14.1	13.9	1.00	2	3.4	1.000	602D6_Trip300	1
20/04/2026 06:45:24	52.382825	4.909456	221	Sudden braking	3.30	3.30	12.6	10.6	1.00	2	4.7	1.000	602D6_Trip300	1
20/04/2026 06:45:25	52.382800	4.909401	221	Sudden braking	3.00	3.00	11.1	7.6	1.00	2	2.8	1.000	602D6_Trip300	1
20/04/2026 06:45:45	52.385126	4.880510	158	Sudden braking	2.60	2.60	14.3	13.9	1.00	2	1.5	1.000	602CA_Trip301	1
20/04/2026 06:45:46	52.385116	4.880525	158	Sudden braking	3.00	3.00	14.7	10.9	1.00	2	5.3	1.000	602CA_Trip301	1
20/04/2026 06:45:53	52.381785	4.908632	222	Sudden braking	2.20	2.20	5.6	5.2	1.00	2	2.3	1.000	602D6_Trip300	1
20/04/2026 06:48:29	52.382440	4.890649	58	Sudden braking	2.60	2.60	16.0	14.7	1.00	2	1.1	1.000	602CA_Trip301	1
20/04/2026 06:48:58	52.382822	4.893106	72	Sudden braking	2.00	2.00	13.4	13.1	1.00	2	3.7	1.000	602CA_Trip301	1
20/04/2026 06:48:59	52.382834	4.893156	70	Sudden braking	2.60	2.60	11.8	10.5	1.00	2	2.3	1.000	602CA_Trip301	1
20/04/2026 06:52:04	52.378406	4.905175	128	Sudden braking	2.00	2.00	13.7	14.1	1.00	2	2.9	1.000	602CA_Trip301	1
20/04/2026 06:52:05	52.378382	4.905192	140	Sudden braking	2.50	2.50	13.1	11.6	1.00	2	2.1	1.000	602CA_Trip301	1
20/04/2026 06:52:06	52.378364	4.905188	160	Sudden braking	2.70	2.70	12.4	8.9	1.00	1	1.5	1.000	602CA_Trip301	1
20/04/2026 06:53:02	52.377166	4.903956	195	Sudden braking	2.00	2.00	14.5	13.1	1.00	2	2.9	1.000	602CA_Trip301	1
20/04/2026 06:53:48	52.376522	4.907142	100	Sudden braking	2.10	2.10	14.0	11.6	1.00	2	4.1	1.000	602CA_Trip301	1
20/04/2026 06:54:03	52.378073	4.908475	103	Sudden braking	3.10	3.10	14.8	16.2	1.00	2	5.9	1.000	602D6_Trip300	1
20/04/2026 06:54:04	52.378061	4.908559	103	Sudden braking	3.20	3.20	13.5	13.0	1.00	2	3.7	1.000	602D6_Trip300	1
20/04/2026 06:54:05	52.378055	4.908506	103	Sudden braking	3.30	3.30	12.8	9.7	1.00	2	3.5	1.000	602D6_Trip300	1
20/04/2026 06:54:06	52.378048	4.908556	103	Sudden braking	2.40	2.40	11.4	7.3	1.00	2	2.0	1.000	602D6_Trip300	1
20/04/2026 06:54:14	52.376479	4.909393	88	Sudden braking	2.80	2.80	15.8	15.9	1.00	2	2.8	1.000	602CA_Trip301	1
20/04/2026 06:54:15	52.376496	4.909423	88	Sudden braking	2.70	2.70	14.4	13.2	1.00	2	2.1	1.000	602CA_Trip301	1
20/04/2026 06:54:16	52.376477	4.909430	88	Sudden braking	2.50	2.50	13.2	10.7	1.00	2	3.4	1.000	602CA_Trip301	1
20/04/2026 06:54:27	52.376378	4.910170	124	Sudden braking	2.30	2.30	12.5	15.0	1.00	2	1.7	1.000	602CA_Trip301	1
20/04/2026 06:54:28	52.376365	4.910154	141	Sudden braking	2.90	2.90	12.3	12.1	1.00	2	5.2	1.000	602CA_Trip301	1
20/04/2026 06:54:29	52.376323	4.910186	187	Sudden braking	3.10	3.10	12.1	9.0	1.00	2	1.9	1.000	602CA_Trip301	1
20/04/2026 06:54:46	52.376490	4.910311	155	Sudden braking	2.40	2.40	23.4	24.4	1.00	2	2.6	1.000	602D6_Trip300	1
20/04/2026 06:54:47	52.376486	4.910348	159	Sudden braking	2.70	2.70	22.1	21.7	1.00	2	3.9	1.000	602D6_Trip300	1
20/04/2026 06:54:48	52.376451	4.910340	159	Sudden braking	2.60	2.60	20.4	19.1	1.00	2	4.8	1.000	602D6_Trip300	1
20/04/2026 06:54:52	52.376293	4.910424	164	Sudden braking	2.40	2.40	13.0	13.3	1.00	2	4.9	1.000	602D6_Trip300	1
20/04/2026 06:54:53	52.376251	4.910443	165	Sudden braking	2.20	2.20	11.6	11.1	1.00	2	1.7	1.000	602D6_Trip300	1
20/04/2026 06:54:54	52.376266	4.910436	164	Sudden braking	2.00	2.00	10.4	9.1	1.00	2	3.8	1.000	602D6_Trip300	1
20/04/2026 06:54:55	52.376232	4.910451	165	Sudden braking	2.20	2.20	9.3	6.9	1.00	2	2.4	1.000	602D6_Trip300	1
20/04/2026 06:56:01	52.376642	4.913913	99	Sudden braking	3.00	3.00	16.1	15.0	1.00	2	4.8	1.000	602D6_Trip300	1
20/04/2026 06:56:04	52.376646	4.914006	129	Sudden braking	2.10	2.10	11.6	10.5	1.00	2	2.8	1.000	602D6_Trip300	1
20/04/2026 06:56:36	52.375336	4.914263	204	Sudden braking	2.00	2.00	23.8	25.6	1.00	2	5.3	1.000	602D6_Trip300	1
20/04/2026 06:56:37	52.375292	4.914238	203	Sudden braking	2.10	2.10	22.9	23.5	1.00	2	3.3	1.000	602D6_Trip300	1
20/04/2026 06:56:38	52.375311	4.914201	209	Sudden braking	2.30	2.30	21.9	21.2	1.00	2	5.3	1.000	602D6_Trip300	1
20/04/2026 06:56:39	52.375269	4.914166	209	Sudden braking	2.20	2.20	20.8	19.0	1.00	2	4.4	1.000	602D6_Trip300	1
20/04/2026 06:56:44	52.374804	4.915162	149	Sudden braking	2.10	2.10	13.0	12.5	1.00	2	5.0	1.000	602CA_Trip301	1
20/04/2026 06:56:45	52.374762	4.915192	152	Sudden braking	2.00	2.00	12.6	10.5	1.00	2	1.1	1.000	602CA_Trip301	1
20/04/2026 06:56:47	52.374731	4.915215	146	Sudden braking	2.20	2.20	11.4	6.4	1.00	2	4.0	1.000	602CA_Trip301	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
20/04/2026 06:57:06	52.374128	4.914263	239	Sudden braking	2.70	2.70	14.8	16.2	1.00	2	4.2	1.000	602D6_Trip300	1
20/04/2026 06:57:07	52.374115	4.914206	243	Sudden braking	4.20	4.20	13.8	12.0	1.00	2	2.4	1.000	602D6_Trip300	1
20/04/2026 07:42:47	52.353752	4.807258	141	Sudden braking	2.20	2.20	13.8	14.4	0.91	2	4.1	0.910	63C0A_Trip303	1
20/04/2026 07:42:47	52.353724	4.807297	140	Sudden braking	2.18	2.18	13.3	12.2	1.01	2	2.9	1.011	63C0A_Trip303	1
20/04/2026 07:45:30	52.351205	4.815639	91	Sudden braking	2.11	2.11	16.1	17.9	1.00	2	4.6	0.997	63C0A_Trip303	1
20/04/2026 07:45:31	52.351199	4.815707	98	Sudden braking	2.76	2.76	14.8	15.1	1.01	2	4.0	1.015	63C0A_Trip303	1
20/04/2026 07:45:32	52.351189	4.815763	103	Sudden braking	3.39	3.39	13.0	11.7	1.00	2	2.8	1.004	63C0A_Trip303	1
20/04/2026 07:45:33	52.351181	4.815802	108	Sudden braking	3.41	3.41	9.8	8.3	1.00	2	1.1	0.998	63C0A_Trip303	1
20/04/2026 07:45:34	52.351181	4.815818	94	Sudden braking	3.03	3.03	8.7	5.3	0.99	2	0.8	0.989	63C0A_Trip303	1
20/04/2026 07:46:38	52.351266	4.820794	87	Sudden braking	2.52	2.52	16.1	14.7	1.11	2	5.0	1.111	63C0A_Trip303	1
20/04/2026 07:48:03	52.351514	4.827117	87	Sudden braking	2.27	2.27	6.0	6.3	1.01	2	1.1	1.012	63C0A_Trip303	1
20/04/2026 07:48:05	52.351516	4.827133	89	Sudden braking	2.15	2.15	4.9	4.2	0.98	2	0.7	0.976	63C0A_Trip303	1
20/04/2026 07:48:21	52.351280	4.827179	109	Sudden braking	2.28	2.28	4.3	4.0	1.01	2	0.4	1.007	63C0A_Trip303	1
20/04/2026 07:48:22	52.351284	4.827177	0	Sudden braking	2.04	2.04	3.5	2.0	0.98	2	0.1	0.978	63C0A_Trip303	1
20/04/2026 07:49:14	52.351337	4.829044	89	Sudden braking	2.43	2.43	18.3	17.6	0.95	3	5.5	0.947	63C0A_Trip303	1
20/04/2026 07:54:00	52.351448	4.842776	93	Sudden braking	2.50	2.50	24.0	28.6	0.92	2	6.7	0.921	604F9_Trip304	1
20/04/2026 07:54:01	52.351443	4.842873	94	Sudden braking	4.07	4.07	24.3	24.5	1.01	3	6.0	1.008	604F9_Trip304	1
20/04/2026 07:54:02	52.351438	4.842961	93	Sudden braking	3.69	3.69	24.0	20.9	0.97	3	3.5	0.975	604F9_Trip304	1
20/04/2026 08:05:17	52.360501	4.876830	63	Sudden braking	2.24	2.24	15.1	16.8	0.98	2	4.9	0.982	602EF_Trip305	1
20/04/2026 08:05:18	52.360513	4.876900	74	Sudden braking	3.37	3.37	14.6	13.4	1.01	2	4.4	1.010	602EF_Trip305	1
20/04/2026 08:05:19	52.360529	4.876959	68	Sudden braking	2.55	2.55	14.6	10.9	0.98	2	1.7	0.979	602EF_Trip305	1
20/04/2026 08:07:58	52.360694	4.885560	131	Sudden braking	2.01	2.01	10.9	11.7	1.04	2	3.7	1.045	602EF_Trip305	1
20/04/2026 08:08:00	52.360673	4.885603	128	Sudden braking	2.62	2.62	9.4	9.1	0.99	2	2.5	0.992	602EF_Trip305	1
20/04/2026 08:08:01	52.360660	4.885632	127	Sudden braking	2.65	2.65	8.2	6.5	0.98	2	1.0	0.980	602EF_Trip305	1
20/04/2026 08:08:21	52.360241	4.886443	131	Sudden braking	2.02	2.02	13.9	15.3	1.04	2	4.6	1.040	602EF_Trip305	1
20/04/2026 08:08:23	52.360214	4.886493	130	Sudden braking	3.09	3.09	10.3	12.3	0.97	2	2.9	0.971	602EF_Trip305	1
20/04/2026 08:08:23	52.360195	4.886523	130	Sudden braking	3.34	3.34	9.3	8.9	1.02	2	2.2	1.018	602EF_Trip305	1
20/04/2026 08:08:25	52.360182	4.886548	130	Sudden braking	3.15	3.15	7.3	5.8	0.98	1	1.0	0.984	602EF_Trip305	1
20/04/2026 08:08:25	52.360175	4.886558	0	Sudden braking	2.52	2.52	5.3	3.3	0.99	1	0.6	0.994	602EF_Trip305	1
20/04/2026 08:10:08	52.358065	4.890423	112	Sudden braking	2.35	2.35	13.5	14.8	1.02	2	4.4	1.022	602EF_Trip305	1
20/04/2026 08:10:09	52.358052	4.890485	105	Sudden braking	3.13	3.13	12.5	11.6	1.02	2	3.3	1.023	602EF_Trip305	1
20/04/2026 08:10:11	52.358043	4.890531	105	Sudden braking	3.56	3.56	9.3	8.1	0.98	2	2.1	0.982	602EF_Trip305	1
20/04/2026 08:10:11	52.358038	4.890561	105	Sudden braking	2.78	2.78	7.9	5.3	1.01	2	1.2	1.009	602EF_Trip305	1
20/04/2026 08:16:52	52.348850	4.904190	116	Sudden braking	2.09	2.09	10.6	11.2	1.00	2	2.5	1.005	602B1_Trip306	1
20/04/2026 08:16:53	52.348852	4.904227	100	Sudden braking	2.72	2.72	9.6	8.6	0.96	2	2.0	0.956	602B1_Trip306	1
20/04/2026 08:16:53	52.348852	4.904256	93	Sudden braking	2.34	2.34	8.9	6.1	1.07	2	1.2	1.068	602B1_Trip306	1
20/04/2026 08:17:41	52.349266	4.907021	74	Sudden braking	2.48	2.48	12.6	13.5	1.01	3	4.9	1.008	602B1_Trip306	1
20/04/2026 08:17:42	52.349280	4.907138	0	Sudden braking	2.18	2.18	10.5	9.6	1.01	3	4.1	1.010	602B1_Trip306	1
20/04/2026 08:17:44	52.349286	4.907196	77	Sudden braking	2.25	2.25	9.7	7.4	0.98	4	4.6	0.977	602B1_Trip306	1
20/04/2026 17:21:23	52.358661	4.904077	43	Sudden braking	2.10	2.10	8.2	9.1	1.05	2	2.8	1.046	602ED_Trip316	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
20/04/2026 17:21:24	52.358680	4.904105	37	Sudden braking	2.58	2.58	6.1	6.6	0.97	2	1.4	0.968	602ED_Trip316	1
20/04/2026 17:21:25	52.358692	4.904109	354	Sudden braking	2.29	2.29	5.3	4.3	1.00	2	0.7	1.003	602ED_Trip316	1
20/04/2026 17:21:26	52.358697	4.904103	0	Sudden braking	2.03	2.03	3.5	2.3	0.98	2	0.4	0.983	602ED_Trip316	1
20/04/2026 17:24:56	52.358456	4.889408	299	Sudden braking	2.23	2.23	12.4	11.0	0.99	2	4.7	0.987	602ED_Trip316	1
20/04/2026 17:27:41	52.362830	4.880547	296	Sudden braking	2.53	2.53	7.1	8.2	0.99	2	2.1	0.989	602ED_Trip316	1
20/04/2026 17:27:42	52.362846	4.880530	325	Sudden braking	2.52	2.52	5.7	5.7	0.99	2	0.8	0.992	602ED_Trip316	1
20/04/2026 17:27:43	52.362850	4.880540	0	Sudden braking	2.50	2.50	5.2	3.3	0.96	1	0.3	0.960	602ED_Trip316	1
20/04/2026 17:28:53	52.364406	4.878660	349	Sudden braking	2.15	2.15	15.5	12.5	0.93	3	3.1	0.932	602ED_Trip316	1
20/04/2026 17:30:26	52.368258	4.876624	330	Sudden braking	2.10	2.10	9.7	10.0	1.00	2	2.8	0.998	602ED_Trip316	1
20/04/2026 17:30:27	52.368282	4.876608	331	Sudden braking	2.10	2.10	7.2	7.9	1.00	2	1.5	0.999	602ED_Trip316	1
20/04/2026 17:30:28	52.368295	4.876600	331	Sudden braking	2.06	2.06	5.7	5.9	0.97	2	1.6	0.970	602ED_Trip316	1
20/04/2026 17:34:22	52.375101	4.877511	23	Sudden braking	2.03	2.03	16.4	14.9	0.99	3	5.1	0.987	602ED_Trip316	1
20/04/2026 19:42:51	52.360344	4.885706	228	Sudden braking	2.14	2.14	9.6	7.7	1.03	3	1.7	1.030	602B1_Trip320	1
20/04/2026 19:44:36	52.357599	4.886189	99	Sudden braking	2.32	2.32	9.5	9.1	0.99	2	3.0	0.993	602B1_Trip320	1
20/04/2026 19:44:37	52.357595	4.886232	104	Sudden braking	2.30	2.30	8.3	6.7	1.04	2	1.3	1.042	602B1_Trip320	1
20/04/2026 19:44:38	52.357593	4.886251	96	Sudden braking	2.14	2.14	6.7	4.6	0.98	2	0.5	0.983	602B1_Trip320	1
20/04/2026 19:45:44	52.354818	4.886325	177	Sudden braking	2.02	2.02	12.3	12.0	1.04	2	3.6	1.041	602B1_Trip320	1
20/04/2026 19:46:30	52.353822	4.886381	181	Sudden braking	2.27	2.27	16.9	14.9	0.97	2	4.7	0.970	602B1_Trip320	1
20/04/2026 19:47:14	52.352161	4.885837	198	Sudden braking	2.16	2.16	5.8	5.7	1.02	1	1.2	1.020	602B1_Trip320	1
20/04/2026 19:47:15	52.352151	4.885841	0	Sudden braking	2.15	2.15	4.0	3.6	0.98	1	0.5	0.978	602B1_Trip320	1
20/04/2026 19:54:29	52.348853	4.904287	98	Sudden braking	2.26	2.26	13.3	13.2	1.02	3	5.0	1.017	602B1_Trip320	1
21/04/2026 08:42:30	52.385510	4.874905	88	Sudden braking	2.70	2.70	16.5	17.5	1.00	2	6.9	1.000	602CA_Trip326	1
21/04/2026 08:42:35	52.385514	4.875075	88	Sudden braking	2.90	2.90	8.7	7.3	1.00	2	2.1	1.000	602CA_Trip326	1
21/04/2026 08:43:36	52.385106	4.880623	98	Sudden braking	2.60	2.60	13.7	14.0	1.00	2	6.6	1.000	602CA_Trip326	1
21/04/2026 08:43:39	52.385073	4.880735	131	Sudden braking	2.10	2.10	9.8	9.4	1.00	2	2.3	1.000	602CA_Trip326	1
21/04/2026 08:43:40	52.385066	4.880766	121	Sudden braking	2.40	2.40	8.6	7.0	1.00	2	1.9	1.000	602CA_Trip326	1
21/04/2026 08:44:43	52.384265	4.884395	131	Sudden braking	2.30	2.30	8.7	9.2	1.00	2	6.0	1.000	602CA_Trip326	1
21/04/2026 08:46:13	52.381831	4.889961	28	Sudden braking	3.00	3.00	14.6	15.9	1.00	2	6.0	1.000	602CA_Trip326	1
21/04/2026 08:46:14	52.381880	4.889995	28	Sudden braking	2.90	2.90	13.2	13.0	1.00	3	7.4	1.000	602CA_Trip326	1
21/04/2026 08:46:15	52.381814	4.890004	28	Sudden braking	2.90	2.90	11.8	10.1	1.00	3	4.3	1.000	602CA_Trip326	1
21/04/2026 08:46:16	52.381846	4.890039	28	Sudden braking	2.90	2.90	10.3	7.2	1.00	3	2.5	1.000	602CA_Trip326	1
21/04/2026 08:46:46	52.382661	4.891874	81	Sudden braking	3.00	3.00	15.7	15.5	1.00	2	9.2	1.000	602CA_Trip326	1
21/04/2026 08:46:47	52.382672	4.892008	83	Sudden braking	2.40	2.40	15.8	13.1	1.00	2	2.1	1.000	602CA_Trip326	1
21/04/2026 08:46:56	52.382803	4.892951	87	Sudden braking	2.30	2.30	13.0	12.9	1.00	2	5.9	1.000	602CA_Trip326	1
21/04/2026 08:46:57	52.382807	4.893038	75	Sudden braking	2.20	2.20	12.2	10.7	1.00	2	3.5	1.000	602CA_Trip326	1
21/04/2026 08:48:51	52.380343	4.899524	121	Sudden braking	2.30	2.30	14.5	16.1	1.00	2	5.9	1.000	602CA_Trip326	1
21/04/2026 08:48:52	52.380316	4.899598	121	Sudden braking	2.30	2.30	13.8	13.8	1.00	2	1.3	1.000	602CA_Trip326	1
21/04/2026 08:49:58	52.378501	4.904942	111	Sudden braking	2.20	2.20	17.1	17.7	1.00	2	5.6	1.000	602CA_Trip326	1
21/04/2026 08:50:01	52.378454	4.905119	115	Sudden braking	2.10	2.10	12.6	13.2	1.00	2	1.7	1.000	602CA_Trip326	1
21/04/2026 08:50:02	52.378444	4.905136	129	Sudden braking	2.40	2.40	11.7	10.8	1.00	2	5.8	1.000	602CA_Trip326	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
21/04/2026 08:50:03	52.378406	4.905195	135	Sudden braking	2.10	2.10	10.7	8.7	1.00	2	1.0	1.000	602CA_Trip326	1
21/04/2026 08:52:14	52.376768	4.906912	89	Sudden braking	2.30	2.30	8.0	6.5	1.00	2	6.7	1.000	602CA_Trip326	1
21/04/2026 08:52:51	52.376056	4.909818	179	Sudden braking	2.20	2.20	11.2	12.4	1.00	2	7.0	1.000	602CA_Trip326	1
21/04/2026 08:52:52	52.376030	4.909912	190	Sudden braking	3.40	3.40	10.4	9.0	1.00	2	6.7	1.000	602CA_Trip326	1
21/04/2026 08:52:53	52.375980	4.909967	190	Sudden braking	3.30	3.30	9.6	5.7	1.00	2	1.8	1.000	602CA_Trip326	1
21/04/2026 08:53:45	52.376702	4.913465	94	Sudden braking	2.90	2.90	17.9	18.9	1.00	2	8.2	1.001	602CA_Trip326	1
21/04/2026 08:53:46	52.376695	4.913585	96	Sudden braking	4.20	4.20	14.5	14.7	1.00	2	5.8	1.000	602CA_Trip326	1
21/04/2026 08:53:47	52.376690	4.913671	96	Sudden braking	2.80	2.80	13.3	11.9	1.00	2	1.7	1.000	602CA_Trip326	1
21/04/2026 08:53:48	52.376688	4.913696	96	Sudden braking	2.30	2.30	12.3	9.6	1.00	2	4.3	1.000	602CA_Trip326	1
21/04/2026 08:53:49	52.376684	4.913758	97	Sudden braking	2.70	2.70	11.7	6.9	1.00	2	5.4	1.000	602CA_Trip326	1
21/04/2026 08:54:29	52.375188	4.914120	205	Sudden braking	2.40	2.40	14.2	13.0	1.00	2	4.2	1.000	602CA_Trip326	1
21/04/2026 11:46:50	52.376856	4.898654	309	Sudden braking	2.30	2.30	7.2	6.7	1.00	2	2.8	1.001	602DE_Trip327	1
21/04/2026 11:46:51	52.376869	4.898618	297	Sudden braking	2.10	2.10	6.5	4.6	1.00	2	0.3	0.999	602DE_Trip327	1
21/04/2026 11:52:08	52.364506	4.892639	179	Sudden braking	2.00	2.00	14.6	15.6	1.00	2	4.8	1.001	602DE_Trip327	1
21/04/2026 11:52:09	52.364468	4.892670	163	Sudden braking	2.10	2.10	12.6	13.5	1.00	2	2.7	0.999	602DE_Trip327	1
21/04/2026 11:52:10	52.364447	4.892691	156	Sudden braking	2.70	2.70	11.3	10.8	1.00	2	2.2	1.001	602DE_Trip327	1
21/04/2026 11:52:11	52.364429	4.892700	169	Sudden braking	3.10	3.10	10.1	7.7	1.00	2	1.6	1.000	602DE_Trip327	1
21/04/2026 13:17:05	52.367774	4.903157	51	Sudden braking	2.00	2.00	13.3	15.3	1.00	2	4.5	0.999	602DE_Trip328	1
21/04/2026 13:17:06	52.367796	4.903212	59	Sudden braking	2.50	2.50	13.3	12.8	1.00	3	4.0	1.000	602DE_Trip328	1
21/04/2026 13:17:07	52.367808	4.903267	75	Sudden braking	2.40	2.40	11.2	10.4	1.00	3	2.2	1.000	602DE_Trip328	1
21/04/2026 13:17:08	52.367817	4.903296	76	Sudden braking	2.50	2.50	10.3	7.9	1.00	2	1.8	1.000	602DE_Trip328	1
21/04/2026 13:17:09	52.367822	4.903321	92	Sudden braking	2.10	2.10	9.1	5.8	1.00	3	1.3	1.000	602DE_Trip328	1
21/04/2026 13:17:39	52.368598	4.903956	85	Sudden braking	2.40	2.40	8.5	7.0	1.00	2	1.5	1.001	602DE_Trip328	1
21/04/2026 13:17:40	52.368597	4.903978	96	Sudden braking	2.60	2.60	6.2	4.4	1.00	2	1.2	0.999	602DE_Trip328	1
21/04/2026 13:18:15	52.368414	4.904368	123	Sudden braking	2.00	2.00	8.1	7.3	1.00	2	2.4	1.000	602DE_Trip328	1
21/04/2026 13:21:35	52.370869	4.915941	127	Sudden braking	2.10	2.10	11.5	13.1	1.00	1	3.3	0.999	602DE_Trip328	1
21/04/2026 13:21:36	52.370858	4.915986	108	Sudden braking	2.60	2.60	10.9	10.5	1.00	2	2.7	1.000	602DE_Trip328	1
21/04/2026 13:21:37	52.370851	4.916023	98	Sudden braking	2.40	2.40	9.8	8.1	1.00	2	1.1	1.000	602DE_Trip328	1
21/04/2026 13:23:28	52.372126	4.917798	48	Sudden braking	2.00	2.00	14.9	15.5	1.00	3	4.6	1.000	602DE_Trip328	1
21/04/2026 15:08:58	52.377736	4.897287	321	Sudden braking	2.10	2.10	5.9	4.7	1.00	2	1.1	1.001	602DE_Trip332	1
21/04/2026 15:47:35	52.368889	4.888754	159	Sudden braking	2.00	2.00	19.6	20.0	1.00	2	7.7	1.000	602DE_Trip334	1
21/04/2026 15:47:36	52.368825	4.888798	164	Sudden braking	2.20	2.20	19.0	17.8	1.00	2	6.5	1.001	602DE_Trip334	1
21/04/2026 15:47:41	52.368612	4.888953	113	Sudden braking	2.20	2.20	9.7	9.4	1.00	2	0.4	0.999	602DE_Trip334	1
21/04/2026 15:47:42	52.368608	4.888954	130	Sudden braking	2.00	2.00	9.4	7.4	1.00	2	3.8	1.000	602DE_Trip334	1
21/04/2026 15:48:25	52.369059	4.891783	91	Sudden braking	2.30	2.30	14.2	13.1	1.00	2	4.4	0.999	602DE_Trip334	1
21/04/2026 15:49:39	52.366961	4.895331	88	Sudden braking	2.20	2.20	10.9	12.8	1.00	2	2.3	1.000	602DE_Trip334	1
21/04/2026 15:49:40	52.366971	4.895360	78	Sudden braking	2.80	2.80	9.8	10.0	1.00	2	2.1	1.000	602DE_Trip334	1
21/04/2026 15:49:41	52.366968	4.895390	85	Sudden braking	3.40	3.40	9.2	6.6	1.00	2	1.7	1.000	602DE_Trip334	1
21/04/2026 15:49:42	52.366962	4.895414	93	Sudden braking	2.80	2.80	8.2	3.8	1.00	2	1.2	1.000	602DE_Trip334	1
21/04/2026 20:23:28	52.346604	4.908163	79	Sudden braking	2.38	2.38	12.8	12.6	0.97	2	3.5	0.967	604F9_Trip341	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
21/04/2026 20:23:29	52.346606	4.908215	80	Sudden braking	2.06	2.06	11.4	10.5	1.02	2	2.9	1.019	604F9_Trip341	1
21/04/2026 20:23:32	52.346615	4.908263	0	Sudden braking	2.03	2.03	8.0	7.1	0.98	2	2.8	0.983	604F9_Trip341	1
22/04/2026 06:52:50	52.385402	4.875722	95	Sudden braking	3.30	3.30	13.7	15.1	1.00	2	7.0	1.000	602CA_Trip353	1
22/04/2026 06:52:51	52.385405	4.875824	89	Sudden braking	3.20	3.20	12.5	11.9	1.00	2	9.9	1.000	602CA_Trip353	1
22/04/2026 06:52:52	52.385427	4.875683	89	Sudden braking	2.60	2.60	11.2	9.3	1.00	2	1.1	1.000	602CA_Trip353	1
22/04/2026 06:52:53	52.385428	4.875700	89	Sudden braking	2.80	2.80	9.8	6.5	1.00	2	2.7	1.000	602CA_Trip353	1
22/04/2026 06:54:47	52.384255	4.884467	131	Sudden braking	2.30	2.30	13.4	13.4	1.00	2	4.4	1.000	602CA_Trip353	1
22/04/2026 06:56:23	52.382101	4.890221	41	Sudden braking	3.10	3.10	15.9	16.6	1.00	2	7.7	1.000	602CA_Trip353	1
22/04/2026 06:56:24	52.382160	4.890282	34	Sudden braking	3.00	3.00	15.2	13.6	1.00	2	12.8	1.000	602CA_Trip353	1
22/04/2026 06:56:25	52.382062	4.890181	34	Sudden braking	3.30	3.30	14.3	10.3	1.00	2	5.8	1.000	602CA_Trip353	1
22/04/2026 06:56:58	52.379415	4.898250	20	Sudden braking	2.70	2.70	10.7	10.2	1.00	3	1.9	1.000	602DE_Trip350	1
22/04/2026 06:56:59	52.379432	4.898258	20	Sudden braking	2.50	2.50	10.0	7.7	1.00	3	0.7	1.002	602DE_Trip350	1
22/04/2026 06:57:23	52.382797	4.894450	113	Sudden braking	3.10	3.10	16.2	16.3	1.00	2	4.8	1.000	602CA_Trip353	1
22/04/2026 06:57:24	52.382777	4.894513	117	Sudden braking	3.10	3.10	15.7	13.2	1.00	3	5.5	1.000	602CA_Trip353	1
22/04/2026 06:57:25	52.382804	4.894445	122	Sudden braking	2.60	2.60	15.5	10.6	1.00	2	1.9	1.000	602CA_Trip353	1
22/04/2026 07:00:31	52.377027	4.904492	122	Sudden braking	2.10	2.10	8.1	8.3	1.00	2	4.3	1.000	602CA_Trip353	1
22/04/2026 07:06:26	52.385211	4.909761	67	Sudden braking	2.00	2.00	19.5	18.4	1.00	3	6.6	1.001	602DE_Trip350	1
22/04/2026 07:06:38	52.374513	4.915348	161	Sudden braking	2.10	2.10	12.8	12.8	1.00	2	3.2	1.000	602CA_Trip353	1
22/04/2026 07:06:39	52.374486	4.915362	159	Sudden braking	2.50	2.50	11.3	10.3	1.00	2	2.2	1.000	602CA_Trip353	1
22/04/2026 07:06:40	52.374470	4.915382	150	Sudden braking	2.20	2.20	10.5	8.1	1.00	2	1.9	1.000	602CA_Trip353	1
22/04/2026 07:14:22	52.397451	4.931665	34	Sudden braking	2.90	2.90	12.7	12.2	1.00	2	6.5	1.000	602DE_Trip350	1
22/04/2026 07:14:23	52.397501	4.931718	31	Sudden braking	3.10	3.10	12.1	9.1	1.00	2	3.4	1.001	602DE_Trip350	1
22/04/2026 07:14:24	52.397526	4.931746	0	Sudden braking	2.00	2.00	11.9	7.1	1.00	2	1.8	1.000	602DE_Trip350	1
22/04/2026 07:14:41	52.397243	4.932797	128	Sudden braking	2.50	2.50	16.9	15.9	1.00	2	4.1	1.000	602DE_Trip350	1
22/04/2026 07:14:42	52.397220	4.932845	128	Sudden braking	2.00	2.00	16.4	13.9	1.00	2	5.9	1.001	602DE_Trip350	1
22/04/2026 07:17:39	52.397552	4.940914	103	Sudden braking	2.20	2.20	6.6	6.1	1.00	2	2.2	1.001	602DE_Trip350	1
22/04/2026 07:17:40	52.397572	4.940918	103	Sudden braking	2.20	2.20	4.3	3.9	1.00	2	0.7	0.999	602DE_Trip350	1
22/04/2026 07:17:41	52.397578	4.940921	97	Sudden braking	2.00	2.00	3.9	1.9	1.00	2	0.2	1.001	602DE_Trip350	1
22/04/2026 07:50:52	52.361036	4.886736	41	Sudden braking	2.11	2.11	11.8	13.7	0.95	3	3.5	0.950	604F9_Trip352	1
22/04/2026 07:50:53	52.361059	4.886771	41	Sudden braking	2.36	2.36	11.8	11.3	1.02	2	3.4	1.018	604F9_Trip352	1
22/04/2026 07:50:54	52.361082	4.886805	43	Sudden braking	2.06	2.06	9.1	9.2	1.02	2	2.1	1.020	604F9_Trip352	1
22/04/2026 07:52:44	52.364499	4.889704	35	Sudden braking	2.55	2.55	8.9	6.8	0.94	3	0.6	0.943	604F9_Trip352	1
22/04/2026 07:54:41	52.363062	4.895639	106	Sudden braking	2.11	2.11	15.1	15.2	1.00	3	5.2	0.996	604F9_Trip352	1
22/04/2026 07:54:42	52.363053	4.895714	108	Sudden braking	2.03	2.03	14.3	13.1	1.03	3	3.4	1.035	604F9_Trip352	1
22/04/2026 07:56:06	52.364068	4.901120	75	Sudden braking	2.03	2.03	11.6	11.6	1.03	3	3.3	1.033	604F9_Trip352	1
22/04/2026 07:58:09	52.367575	4.903851	133	Sudden braking	2.72	2.72	10.4	12.0	0.99	2	4.0	0.991	604F9_Trip352	1
22/04/2026 07:58:10	52.367551	4.903895	132	Sudden braking	3.06	3.06	8.9	8.9	1.01	2	2.3	1.012	604F9_Trip352	1
22/04/2026 07:58:11	52.367538	4.903921	121	Sudden braking	3.00	3.00	7.1	6.0	0.97	2	0.7	0.968	604F9_Trip352	1
22/04/2026 07:58:12	52.367541	4.903931	0	Sudden braking	2.49	2.49	6.4	3.4	1.04	2	1.0	1.044	604F9_Trip352	1
22/04/2026 08:00:25	52.370005	4.908340	55	Sudden braking	2.41	2.41	9.1	10.5	0.95	2	2.8	0.954	604F9_Trip352	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
22/04/2026 08:00:26	52.370019	4.908374	53	Sudden braking	2.38	2.38	9.1	8.1	1.01	2	2.1	1.009	604F9_Trip352	1
22/04/2026 08:00:27	52.370028	4.908400	58	Sudden braking	2.19	2.19	7.5	5.9	1.00	2	1.1	1.005	604F9_Trip352	1
22/04/2026 08:00:28	52.370032	4.908415	0	Sudden braking	2.03	2.03	5.0	3.8	1.03	3	0.3	1.035	604F9_Trip352	1
22/04/2026 08:01:02	52.370512	4.909831	64	Sudden braking	2.09	2.09	9.5	9.2	1.00	3	2.2	1.004	604F9_Trip352	1
22/04/2026 08:01:03	52.370520	4.909860	64	Sudden braking	2.36	2.36	7.9	6.8	1.02	3	2.0	1.019	604F9_Trip352	1
22/04/2026 08:01:04	52.370529	4.909886	62	Sudden braking	2.23	2.23	6.4	4.6	0.99	3	1.1	0.986	604F9_Trip352	1
22/04/2026 09:33:08	52.396414	4.930573	214	Sudden braking	2.50	2.50	14.5	13.7	1.00	3	5.3	1.001	602DE_Trip354	1
22/04/2026 09:33:39	52.396831	4.928801	316	Sudden braking	2.00	2.00	14.8	15.0	1.00	2	5.1	1.000	602DE_Trip354	1
22/04/2026 09:33:40	52.396866	4.928751	321	Sudden braking	2.70	2.70	14.5	12.3	1.00	2	4.5	1.000	602DE_Trip354	1
22/04/2026 09:37:43	52.388802	4.919833	246	Sudden braking	2.60	2.60	18.0	20.2	1.00	2	5.4	0.999	602DE_Trip354	1
22/04/2026 09:37:44	52.388779	4.919762	241	Sudden braking	2.10	2.10	17.6	18.1	1.00	2	4.5	1.000	602DE_Trip354	1
22/04/2026 09:40:07	52.385463	4.913050	42	Sudden braking	2.70	2.70	3.7	3.4	1.00	2	0.7	1.000	602DE_Trip354	1
22/04/2026 09:40:08	52.385469	4.913055	93	Sudden braking	2.00	2.00	3.3	1.4	1.00	2	1.4	1.001	602DE_Trip354	1
22/04/2026 09:42:47	52.381877	4.908337	201	Sudden braking	2.10	2.10	13.1	12.9	1.00	2	3.8	1.000	602DE_Trip354	1
22/04/2026 09:42:48	52.381845	4.908318	199	Sudden braking	2.00	2.00	12.0	10.9	1.00	2	3.3	1.000	602DE_Trip354	1
22/04/2026 09:50:57	52.377910	4.909352	104	Sudden braking	2.40	2.40	9.0	8.5	1.00	2	2.3	1.000	602DE_Trip354	1
22/04/2026 09:50:58	52.377904	4.909384	104	Sudden braking	2.60	2.60	6.9	5.9	1.00	1	0.6	1.001	602DE_Trip354	1
22/04/2026 09:50:59	52.377903	4.909393	105	Sudden braking	2.60	2.60	5.0	3.3	1.00	1	0.2	0.999	602DE_Trip354	1
22/04/2026 09:51:00	52.377903	4.909390	0	Sudden braking	2.10	2.10	4.8	1.2	1.00	1	0.1	1.001	602DE_Trip354	1
23/04/2026 15:23:39	52.375596	4.915075	13	Sudden braking	2.30	2.30	21.8	20.5	1.00	3	5.1	1.000	63C0A_Trip377	1
23/04/2026 15:24:39	52.376140	4.910785	241	Sudden braking	2.10	2.10	19.1	20.2	1.00	3	4.8	1.000	63C0A_Trip377	1
23/04/2026 15:24:40	52.376118	4.910723	241	Sudden braking	2.60	2.60	18.1	17.6	1.00	3	3.8	1.000	63C0A_Trip377	1
23/04/2026 15:24:41	52.376104	4.910673	242	Sudden braking	2.60	2.60	17.1	15.0	1.00	3	2.4	1.000	63C0A_Trip377	1
23/04/2026 15:24:50	52.375837	4.910644	177	Sudden braking	2.20	2.20	10.5	8.5	1.00	2	1.4	1.000	63C0A_Trip377	1
23/04/2026 15:25:15	52.377109	4.910118	0	Sudden braking	2.00	2.00	25.1	23.8	1.00	2	6.3	1.000	63C0A_Trip377	1
23/04/2026 15:25:46	52.378166	4.907739	281	Sudden braking	2.30	2.30	28.1	30.1	1.00	3	8.1	1.000	63C0A_Trip377	1
23/04/2026 15:25:47	52.378181	4.907622	281	Sudden braking	2.90	2.90	26.5	27.2	1.00	2	5.5	1.000	63C0A_Trip377	1
23/04/2026 15:25:48	52.378194	4.907544	284	Sudden braking	3.20	3.20	24.8	24.0	1.00	3	5.2	1.000	63C0A_Trip377	1
23/04/2026 15:25:49	52.378208	4.907471	285	Sudden braking	2.70	2.70	22.8	21.3	1.00	3	4.7	1.000	63C0A_Trip377	1
23/04/2026 15:25:53	52.378241	4.907178	282	Sudden braking	2.10	2.10	15.0	14.7	1.00	4	3.6	1.000	63C0A_Trip377	1
23/04/2026 15:25:54	52.378250	4.907128	285	Sudden braking	2.30	2.30	13.7	12.4	1.00	4	1.5	1.000	63C0A_Trip377	1
23/04/2026 15:25:55	52.378258	4.907110	292	Sudden braking	2.20	2.20	12.7	10.2	1.00	3	1.8	1.000	63C0A_Trip377	1
23/04/2026 15:26:44	52.379193	4.902584	301	Sudden braking	2.00	2.00	28.3	30.9	1.00	2	8.8	1.000	63C0A_Trip377	1
23/04/2026 15:26:45	52.379234	4.902472	301	Sudden braking	2.90	2.90	26.7	28.0	1.00	2	7.8	1.000	63C0A_Trip377	1
23/04/2026 15:26:46	52.379270	4.902374	301	Sudden braking	3.40	3.40	25.2	24.6	1.00	2	5.7	1.000	63C0A_Trip377	1
23/04/2026 15:26:47	52.379296	4.902302	301	Sudden braking	3.40	3.40	24.0	21.2	1.00	2	4.0	1.000	63C0A_Trip377	1
23/04/2026 15:26:48	52.379314	4.902251	301	Sudden braking	2.70	2.70	23.0	18.5	1.00	2	3.7	1.000	63C0A_Trip377	1
23/04/2026 15:27:08	52.379982	4.900423	301	Sudden braking	2.20	2.20	24.6	25.3	1.00	2	6.8	1.000	63C0A_Trip377	1
23/04/2026 15:27:09	52.380013	4.900336	301	Sudden braking	2.50	2.50	24.0	22.8	1.00	2	5.4	1.000	63C0A_Trip377	1
23/04/2026 15:27:10	52.380037	4.900269	301	Sudden braking	2.10	2.10	23.3	20.7	1.00	2	3.5	1.000	63C0A_Trip377	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
23/04/2026 15:28:27	52.382925	4.893562	275	Sudden braking	2.30	2.30	17.2	15.9	1.00	3	5.4	1.000	63C0A_Trip377	1
23/04/2026 15:28:28	52.382937	4.893485	285	Sudden braking	2.00	2.00	16.8	13.9	1.00	3	1.4	1.000	63C0A_Trip377	1
23/04/2026 15:28:55	52.384856	4.893262	11	Sudden braking	2.20	2.20	27.2	28.3	1.00	2	8.1	1.000	63C0A_Trip377	1
23/04/2026 15:28:56	52.384928	4.893286	7	Sudden braking	2.60	2.60	25.9	25.7	1.00	3	6.5	1.000	63C0A_Trip377	1
23/04/2026 15:28:57	52.384985	4.893306	7	Sudden braking	2.70	2.70	24.8	23.0	1.00	3	5.7	1.000	63C0A_Trip377	1
23/04/2026 15:28:58	52.385036	4.893313	4	Sudden braking	2.40	2.40	23.9	20.6	1.00	3	6.0	1.000	63C0A_Trip377	1
23/04/2026 15:29:34	52.387988	4.892188	345	Sudden braking	2.30	2.30	29.3	30.1	1.00	2	8.1	1.000	63C0A_Trip377	1
23/04/2026 15:29:35	52.388059	4.892158	345	Sudden braking	2.70	2.70	27.8	27.4	1.00	2	7.2	1.000	63C0A_Trip377	1
23/04/2026 15:29:36	52.388122	4.892132	345	Sudden braking	2.60	2.60	26.5	24.8	1.00	2	5.9	1.000	63C0A_Trip377	1
23/04/2026 15:29:37	52.388174	4.892111	345	Sudden braking	2.10	2.10	25.4	22.7	1.00	2	5.5	1.000	63C0A_Trip377	1
23/04/2026 15:29:59	52.389612	4.891178	304	Sudden braking	2.00	2.00	27.7	27.4	1.00	2	7.3	1.000	63C0A_Trip377	1
23/04/2026 15:30:21	52.389896	4.889397	282	Sudden braking	2.20	2.20	17.6	18.2	1.00	2	4.7	1.000	63C0A_Trip377	1
23/04/2026 15:30:22	52.389906	4.889330	282	Sudden braking	2.30	2.30	16.1	15.9	1.00	2	4.1	1.000	63C0A_Trip377	1
23/04/2026 15:30:23	52.389914	4.889271	282	Sudden braking	2.10	2.10	15.3	13.8	1.00	2	3.6	0.999	63C0A_Trip377	1
23/04/2026 15:31:52	52.390609	4.885317	310	Sudden braking	2.30	2.30	16.0	16.2	1.00	3	4.1	1.000	63C0A_Trip377	1
23/04/2026 15:31:53	52.390632	4.885270	314	Sudden braking	2.20	2.20	15.2	14.0	1.00	3	3.0	1.000	63C0A_Trip377	1
23/04/2026 15:31:54	52.390650	4.885237	314	Sudden braking	2.20	2.20	14.3	11.8	1.00	4	2.1	1.000	63C0A_Trip377	1
23/04/2026 15:31:55	52.390663	4.885214	314	Sudden braking	2.20	2.20	13.4	9.6	1.00	4	2.0	1.000	63C0A_Trip377	1
23/04/2026 15:33:00	52.391585	4.878619	283	Sudden braking	2.50	2.50	30.7	33.1	1.00	2	9.1	1.000	63C0A_Trip377	1
23/04/2026 15:33:01	52.391607	4.878490	283	Sudden braking	3.30	3.30	28.7	29.8	1.00	2	7.6	1.000	63C0A_Trip377	1
23/04/2026 15:33:02	52.391622	4.878380	287	Sudden braking	3.60	3.60	26.6	26.2	1.00	2	5.9	1.000	63C0A_Trip377	1
23/04/2026 15:33:03	52.391649	4.878306	295	Sudden braking	3.40	3.40	24.5	22.8	1.00	2	4.7	1.000	63C0A_Trip377	1
23/04/2026 15:33:04	52.391671	4.878247	306	Sudden braking	2.90	2.90	22.2	19.9	1.00	3	5.2	1.000	63C0A_Trip377	1
23/04/2026 15:33:05	52.391702	4.878189	306	Sudden braking	2.00	2.00	20.0	17.9	1.00	2	5.0	1.000	63C0A_Trip377	1
23/04/2026 15:34:03	52.392853	4.876152	279	Sudden braking	2.70	2.70	23.7	25.8	1.00	2	6.9	1.000	63C0A_Trip377	1
23/04/2026 15:34:04	52.392858	4.876050	271	Sudden braking	4.20	4.20	21.1	21.6	1.00	3	6.0	1.000	63C0A_Trip377	1
23/04/2026 15:34:05	52.392854	4.875962	271	Sudden braking	4.90	4.90	19.9	16.7	1.00	2	2.9	1.000	63C0A_Trip377	1
23/04/2026 15:34:06	52.392853	4.875920	272	Sudden braking	4.80	4.80	17.2	11.9	1.00	3	1.1	1.000	63C0A_Trip377	1
23/04/2026 15:34:07	52.392851	4.875904	272	Sudden braking	2.00	2.00	14.7	7.9	2.00	3	1.7	2.000	63C0A_Trip377	1
23/04/2026 15:34:31	52.392886	4.873401	272	Sudden braking	2.40	2.40	31.6	36.2	1.00	2	9.8	1.000	63C0A_Trip377	1
23/04/2026 15:34:32	52.392889	4.873257	272	Sudden braking	4.10	4.10	29.5	32.1	1.00	2	8.5	1.000	63C0A_Trip377	1
23/04/2026 15:34:33	52.392893	4.873132	272	Sudden braking	5.20	5.20	27.6	26.9	1.00	2	5.7	1.000	63C0A_Trip377	1
23/04/2026 15:34:34	52.392891	4.873048	272	Sudden braking	5.00	5.00	25.8	21.9	1.00	2	3.1	1.000	63C0A_Trip377	1
23/04/2026 15:34:35	52.392892	4.873002	272	Sudden braking	3.90	3.90	24.5	18.0	1.00	2	3.3	0.999	63C0A_Trip377	1
23/04/2026 15:34:36	52.392893	4.872953	272	Sudden braking	2.10	2.10	23.0	15.9	1.00	2	3.9	1.000	63C0A_Trip377	1
23/04/2026 15:35:06	52.392926	4.868777	264	Sudden braking	2.00	2.00	32.4	36.4	1.00	3	9.9	1.000	63C0A_Trip377	1
23/04/2026 15:35:07	52.392912	4.868632	259	Sudden braking	3.20	3.20	29.9	33.2	1.00	3	8.8	1.000	63C0A_Trip377	1
23/04/2026 15:35:08	52.392880	4.868514	245	Sudden braking	3.80	3.80	27.3	29.4	1.00	3	6.6	1.000	63C0A_Trip377	1
23/04/2026 15:35:09	52.392849	4.868431	242	Sudden braking	4.40	4.40	24.7	25.0	1.00	3	6.4	1.000	63C0A_Trip377	1
23/04/2026 15:35:10	52.392805	4.868370	235	Sudden braking	5.10	5.10	22.3	19.9	1.00	3	4.9	1.000	63C0A_Trip377	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
23/04/2026 15:35:11	52.392778	4.868313	235	Sudden braking	4.50	4.50	20.3	15.4	1.00	3	3.6	1.000	63C0A_Trip377	1
23/04/2026 15:35:12	52.392775	4.868260	236	Sudden braking	3.00	3.00	18.7	12.4	1.00	3	1.2	1.000	63C0A_Trip377	1
23/04/2026 15:41:36	52.417654	4.826894	20	Sudden braking	3.10	3.10	27.5	33.7	1.00	1	9.5	1.000	63C0A_Trip377	1
23/04/2026 15:41:37	52.417735	4.826936	17	Sudden braking	4.20	4.20	24.1	29.5	1.00	1	8.3	1.000	63C0A_Trip377	1
23/04/2026 15:41:38	52.417810	4.826947	9	Sudden braking	5.00	5.00	20.5	24.5	1.00	1	12.5	1.000	63C0A_Trip377	1
23/04/2026 15:41:39	52.417859	4.826781	32	Sudden braking	5.20	5.20	17.0	19.3	1.00	1	3.0	1.000	63C0A_Trip377	1
23/04/2026 15:41:40	52.417879	4.826811	35	Sudden braking	4.60	4.60	15.8	14.7	1.00	2	2.1	1.000	63C0A_Trip377	1
23/04/2026 15:41:41	52.417895	4.826828	35	Sudden braking	3.60	3.60	15.8	11.1	1.00	2	1.8	1.000	63C0A_Trip377	1
23/04/2026 15:41:42	52.417910	4.826836	28	Sudden braking	2.50	2.50	13.8	8.6	1.00	1	1.9	1.000	63C0A_Trip377	1
23/04/2026 15:47:50	52.423898	4.827672	6	Sudden braking	2.50	2.50	29.3	30.8	1.00	4	8.5	1.000	63C0A_Trip377	1
23/04/2026 15:47:51	52.423973	4.827697	6	Sudden braking	3.20	3.20	28.5	27.6	1.00	2	7.4	1.000	63C0A_Trip377	1
23/04/2026 15:47:52	52.424039	4.827715	6	Sudden braking	3.40	3.40	26.8	24.2	1.00	3	5.7	1.000	63C0A_Trip377	1
23/04/2026 15:47:53	52.424090	4.827708	6	Sudden braking	2.80	2.80	25.4	21.4	1.00	3	4.3	1.000	63C0A_Trip377	1
23/04/2026 15:48:33	52.426900	4.827430	345	Sudden braking	2.55	2.55	36.8	34.4	0.98	3	9.8	0.981	63C0A_Trip377	1
23/04/2026 15:50:22	52.434133	4.818632	318	Sudden braking	2.20	2.20	26.4	29.9	1.00	2	6.8	1.000	63C0A_Trip377	1
23/04/2026 15:50:23	52.434179	4.818567	320	Sudden braking	2.10	2.10	26.4	27.8	1.00	2	7.3	1.000	63C0A_Trip377	1
23/04/2026 16:03:39	52.485087	4.805947	320	Sudden braking	2.40	2.40	14.7	14.2	1.00	3	4.8	1.000	63C0A_Trip377	1
23/04/2026 16:03:40	52.485118	4.805898	315	Sudden braking	2.90	2.90	13.8	11.3	1.00	3	3.5	1.000	63C0A_Trip377	1
23/04/2026 16:03:41	52.485139	4.805860	312	Sudden braking	2.90	2.90	12.8	8.4	1.00	3	0.2	1.000	63C0A_Trip377	1
23/04/2026 16:13:10	52.495456	4.757428	280	Sudden braking	2.80	2.80	26.6	23.2	1.00	2	7.3	1.000	63C0A_Trip377	1
23/04/2026 16:21:33	52.519618	4.706978	336	Sudden braking	2.20	2.20	33.6	31.2	1.00	3	8.0	1.000	63C0A_Trip377	1
23/04/2026 16:22:18	52.521951	4.702419	312	Sudden braking	3.00	3.00	25.5	26.6	1.00	3	6.7	1.000	63C0A_Trip377	1
23/04/2026 16:22:19	52.521991	4.702345	311	Sudden braking	3.60	3.60	24.3	23.0	1.00	3	4.3	1.000	63C0A_Trip377	1
23/04/2026 16:22:20	52.522016	4.702297	314	Sudden braking	3.10	3.10	23.3	19.9	1.00	3	1.6	1.000	63C0A_Trip377	1
23/04/2026 16:22:21	52.522026	4.702280	314	Sudden braking	2.20	2.20	22.4	17.7	1.00	3	0.4	1.000	63C0A_Trip377	1
23/04/2026 16:25:12	52.535738	4.695533	354	Sudden braking	2.10	2.10	29.1	27.7	1.00	2	7.4	1.000	63C0A_Trip377	1
23/04/2026 16:26:48	52.539559	4.685861	311	Sudden braking	3.10	3.10	30.9	31.0	1.00	3	9.4	1.000	63C0A_Trip377	1
23/04/2026 16:26:49	52.539615	4.685757	311	Sudden braking	2.90	2.90	30.1	28.1	1.00	3	5.9	1.000	63C0A_Trip377	1
23/04/2026 16:26:50	52.539653	4.685695	311	Sudden braking	2.40	2.40	29.4	25.7	1.00	3	5.5	1.000	63C0A_Trip377	1
23/04/2026 16:40:41	52.368857	4.913882	119	Sudden braking	2.30	2.30	16.8	17.3	1.00	2	3.9	1.000	604F0_Trip382	1
23/04/2026 16:40:42	52.368837	4.913929	119	Sudden braking	2.60	2.60	15.7	14.7	1.00	2	3.1	1.000	604F0_Trip382	1
23/04/2026 16:40:43	52.368816	4.913960	119	Sudden braking	2.30	2.30	14.6	12.4	1.00	2	2.7	1.000	604F0_Trip382	1
23/04/2026 16:41:30	52.366693	4.911985	210	Sudden braking	2.70	2.70	16.5	17.2	1.00	2	4.1	1.000	604F0_Trip382	1
23/04/2026 16:41:31	52.366661	4.911956	209	Sudden braking	3.00	3.00	15.7	14.2	1.00	2	1.3	1.000	604F0_Trip382	1
23/04/2026 16:41:32	52.366651	4.911947	209	Sudden braking	3.60	3.60	14.7	10.6	1.00	2	2.8	1.000	604F0_Trip382	1
23/04/2026 16:41:33	52.366629	4.911927	209	Sudden braking	3.70	3.70	13.6	6.9	1.00	2	1.7	1.000	604F0_Trip382	1
23/04/2026 16:41:57	52.366222	4.911348	203	Sudden braking	2.10	2.10	17.3	16.9	1.00	2	10.5	1.000	604F0_Trip382	1
23/04/2026 16:41:58	52.366274	4.911219	224	Sudden braking	2.20	2.20	17.0	14.7	1.00	2	4.1	1.000	604F0_Trip382	1
23/04/2026 16:43:08	52.364403	4.906206	260	Sudden braking	2.70	2.70	13.4	13.4	1.00	2	1.3	1.000	604F0_Trip382	1
23/04/2026 16:44:29	52.363802	4.903180	254	Sudden braking	2.40	2.40	17.6	18.0	1.00	2	4.4	1.000	604F0_Trip382	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
23/04/2026 16:44:30	52.363796	4.903116	258	Sudden braking	2.60	2.60	16.8	15.4	1.00	2	2.7	1.000	604F0_Trip382	1
23/04/2026 16:44:31	52.363785	4.903082	254	Sudden braking	2.00	2.00	16.2	13.4	1.00	2	1.9	1.000	604F0_Trip382	1
23/04/2026 16:44:42	52.363634	4.902427	253	Sudden braking	2.20	2.20	14.4	13.8	1.00	2	3.4	1.000	604F0_Trip382	1
23/04/2026 16:44:43	52.363622	4.902382	250	Sudden braking	2.10	2.10	13.9	11.7	1.00	2	2.1	1.000	604F0_Trip382	1
23/04/2026 16:45:27	52.362998	4.898854	252	Sudden braking	2.10	2.10	14.5	15.0	1.00	2	3.0	1.000	604F0_Trip382	1
23/04/2026 16:45:28	52.362989	4.898813	252	Sudden braking	2.30	2.30	13.8	12.7	1.00	2	2.5	1.000	604F0_Trip382	1
23/04/2026 16:45:29	52.362982	4.898778	252	Sudden braking	2.40	2.40	13.0	10.3	1.00	2	2.3	1.000	604F0_Trip382	1
23/04/2026 16:45:30	52.362976	4.898746	250	Sudden braking	2.00	2.00	12.1	8.3	1.00	2	1.4	1.000	604F0_Trip382	1
23/04/2026 16:46:33	52.359854	4.898769	203	Sudden braking	2.00	2.00	17.9	18.2	1.00	2	4.1	1.000	604F0_Trip382	1
23/04/2026 16:46:34	52.359820	4.898750	203	Sudden braking	2.10	2.10	16.6	16.1	1.00	2	2.9	1.000	604F0_Trip382	1
23/04/2026 16:46:35	52.359795	4.898736	203	Sudden braking	2.00	2.00	15.5	14.1	1.00	2	3.5	1.000	604F0_Trip382	1
23/04/2026 16:49:42	52.362635	4.883963	312	Sudden braking	2.20	2.20	12.9	12.9	1.00	2	2.5	1.000	604F0_Trip382	1
23/04/2026 16:49:43	52.362644	4.883929	302	Sudden braking	2.10	2.10	12.1	10.8	1.00	2	1.4	1.000	604F0_Trip382	1
23/04/2026 16:55:38	52.355025	4.855969	253	Sudden braking	2.20	2.20	18.7	20.1	1.00	2	5.2	1.000	604F0_Trip382	1
23/04/2026 16:55:39	52.355003	4.855901	249	Sudden braking	2.50	2.50	17.4	17.6	1.00	2	3.3	1.000	604F0_Trip382	1
23/04/2026 16:55:40	52.354998	4.855853	252	Sudden braking	2.50	2.50	15.9	15.1	1.00	2	2.2	1.000	604F0_Trip382	1
23/04/2026 16:55:41	52.354989	4.855824	247	Sudden braking	2.30	2.30	14.4	12.8	1.00	2	3.9	1.000	604F0_Trip382	1
23/04/2026 16:58:07	52.355725	4.844507	269	Sudden braking	2.00	2.00	17.7	17.0	1.00	2	3.8	1.000	604F0_Trip382	1
23/04/2026 17:01:21	52.356348	4.827716	272	Sudden braking	2.30	2.30	14.7	14.9	1.00	2	3.6	1.000	604F0_Trip382	1
23/04/2026 17:01:22	52.356354	4.827665	275	Sudden braking	3.10	3.10	13.9	11.8	1.00	2	2.3	1.000	604F0_Trip382	1
23/04/2026 17:01:23	52.356360	4.827633	277	Sudden braking	3.10	3.10	12.9	8.7	1.00	2	1.2	1.000	604F0_Trip382	1
24/04/2026 09:00:02	52.344974	4.944844	315	Sudden braking	2.00	2.00	11.7	12.9	1.00	2	3.4	1.000	602DE_Trip390	1
24/04/2026 09:00:04	52.345002	4.944798	315	Sudden braking	2.40	2.40	10.0	8.6	1.00	2	3.7	1.000	602DE_Trip390	1
24/04/2026 09:00:05	52.345026	4.944758	315	Sudden braking	2.10	2.10	9.1	6.5	1.00	2	1.7	1.000	602DE_Trip390	1
24/04/2026 09:01:35	52.347791	4.940494	322	Sudden braking	2.00	2.00	9.2	7.4	1.00	1	1.5	1.000	602DE_Trip390	1
24/04/2026 09:01:36	52.347803	4.940483	323	Sudden braking	2.30	2.30	7.7	5.1	1.00	1	1.0	1.000	602DE_Trip390	1
24/04/2026 09:02:43	52.348342	4.939489	316	Sudden braking	2.00	2.00	14.6	16.0	1.00	2	5.2	1.000	602DE_Trip390	1
24/04/2026 09:02:46	52.348398	4.939391	310	Sudden braking	2.60	2.60	12.5	11.0	1.00	2	1.2	1.000	602DE_Trip390	1
24/04/2026 09:09:45	52.359854	4.925548	338	Sudden braking	2.40	2.40	10.3	9.0	1.00	1	1.5	1.000	602DE_Trip390	1
24/04/2026 09:09:46	52.359868	4.925545	338	Sudden braking	2.60	2.60	8.7	6.4	1.00	1	1.1	1.000	602DE_Trip390	1
24/04/2026 09:12:13	52.362278	4.923978	344	Sudden braking	2.40	2.40	11.0	10.7	1.00	2	2.8	1.000	602DE_Trip390	1
24/04/2026 09:15:23	52.367320	4.925653	44	Sudden braking	2.10	2.10	9.3	8.8	1.00	2	5.1	1.000	602DE_Trip390	1
24/04/2026 09:15:59	52.368164	4.923933	299	Sudden braking	2.00	2.00	11.4	11.9	1.00	2	2.6	1.000	602DE_Trip390	1
24/04/2026 09:16:00	52.368172	4.923897	294	Sudden braking	2.00	2.00	10.7	9.9	1.00	2	3.7	1.000	602DE_Trip390	1
24/04/2026 09:18:12	52.371043	4.915492	305	Sudden braking	2.60	2.60	12.4	11.7	1.00	2	4.2	1.000	602DE_Trip390	1
24/04/2026 09:18:13	52.371069	4.915446	319	Sudden braking	2.60	2.60	11.7	9.1	1.00	3	2.5	1.000	602DE_Trip390	1
24/04/2026 09:18:35	52.371493	4.916436	65	Sudden braking	2.20	2.20	11.7	7.9	1.00	2	4.1	1.000	602DE_Trip390	1
24/04/2026 09:18:43	52.371641	4.916827	69	Sudden braking	2.40	2.40	8.4	7.8	1.00	2	3.1	1.000	602DE_Trip390	1
24/04/2026 09:19:42	52.372985	4.917212	303	Sudden braking	2.10	2.10	10.3	9.7	1.00	2	5.1	1.000	602DE_Trip390	1
24/04/2026 09:19:43	52.373022	4.917168	316	Sudden braking	2.20	2.20	9.4	7.5	1.00	2	1.2	1.000	602DE_Trip390	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_h_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
24/04/2026 14:52:09	52.375941	4.921629	12	Sudden braking	2.10	2.10	19.2	20.0	1.00	2	9.9	1.000	602B1_Trip396	1
24/04/2026 14:52:10	52.376013	4.921715	27	Sudden braking	2.40	2.40	17.9	17.6	1.00	3	5.7	1.000	602B1_Trip396	1
24/04/2026 14:54:50	52.379253	4.925757	107	Sudden braking	2.00	2.00	23.3	23.1	1.00	3	4.7	1.000	602B1_Trip396	1
24/04/2026 16:19:32	52.371676	4.916327	254	Sudden braking	2.20	2.20	10.3	10.1	1.00	2	5.9	1.000	602DE_Trip398	1
24/04/2026 16:19:33	52.371652	4.916250	246	Sudden braking	2.00	2.00	9.6	8.1	1.00	2	1.7	1.000	602DE_Trip398	1
24/04/2026 16:22:50	52.367642	4.925395	120	Sudden braking	2.20	2.20	11.5	10.0	1.00	2	2.5	1.000	602DE_Trip398	1
24/04/2026 16:22:51	52.367621	4.925408	141	Sudden braking	2.10	2.10	10.4	7.9	1.00	2	1.3	1.000	602DE_Trip398	1
24/04/2026 16:25:56	52.363465	4.930459	179	Sudden braking	2.00	2.00	14.9	14.9	1.00	2	3.3	1.000	602DE_Trip398	1
24/04/2026 16:25:57	52.363435	4.930463	179	Sudden braking	2.10	2.10	14.0	12.8	1.00	2	2.3	1.000	602DE_Trip398	1
24/04/2026 16:31:07	52.353830	4.930286	136	Sudden braking	2.10	2.10	16.3	16.7	1.00	2	4.1	1.000	602DE_Trip398	1
24/04/2026 16:31:08	52.353803	4.930328	136	Sudden braking	2.10	2.10	15.2	14.6	1.00	2	3.0	1.000	602DE_Trip398	1
24/04/2026 16:31:09	52.353787	4.930363	137	Sudden braking	2.10	2.10	14.2	12.5	1.00	2	2.7	1.000	602DE_Trip398	1
24/04/2026 16:32:17	52.351627	4.933793	139	Sudden braking	2.10	2.10	13.6	12.1	1.00	2	4.5	1.000	602DE_Trip398	1
24/04/2026 16:32:41	52.350779	4.934936	184	Sudden braking	2.20	2.20	8.9	7.3	1.00	2	2.6	1.000	602DE_Trip398	1
24/04/2026 16:34:15	52.348194	4.939260	138	Sudden braking	2.10	2.10	14.2	12.7	1.00	2	4.1	1.000	602DE_Trip398	1
24/04/2026 16:34:16	52.348165	4.939297	143	Sudden braking	2.00	2.00	13.3	10.7	1.00	2	2.4	0.999	602DE_Trip398	1
24/04/2026 16:36:39	52.343435	4.946863	135	Sudden braking	2.10	2.10	16.5	15.5	1.00	2	5.0	1.000	602DE_Trip398	1
24/04/2026 16:36:54	52.342952	4.947654	134	Sudden braking	2.00	2.00	15.3	15.9	1.00	2	5.3	1.000	602DE_Trip398	1
24/04/2026 16:36:55	52.342915	4.947705	136	Sudden braking	2.10	2.10	15.0	13.8	1.00	2	1.8	1.000	602DE_Trip398	1
25/04/2026 07:40:49	52.338898	4.950190	245	Sudden braking	2.00	2.00	13.5	11.3	1.00	2	1.1	1.000	602DE_Trip399	1
25/04/2026 07:43:43	52.339092	4.939526	318	Sudden braking	3.00	3.00	18.8	16.8	1.00	2	6.1	1.000	602DE_Trip399	1
25/04/2026 07:48:19	52.348412	4.928003	314	Sudden braking	2.30	2.30	13.7	14.4	1.00	2	6.2	1.002	602DE_Trip399	1
25/04/2026 07:48:21	52.348447	4.927932	313	Sudden braking	2.40	2.40	11.8	12.0	1.00	2	1.7	1.000	602DE_Trip399	1
25/04/2026 07:48:22	52.348458	4.927915	315	Sudden braking	2.20	2.20	10.9	9.8	1.00	2	3.5	1.000	602DE_Trip399	1
25/04/2026 07:48:23	52.348479	4.927877	315	Sudden braking	2.00	2.00	9.9	7.8	1.00	2	3.0	1.000	602DE_Trip399	1
25/04/2026 07:49:10	52.350075	4.925261	318	Sudden braking	2.20	2.20	12.2	11.5	1.00	2	2.8	1.000	602DE_Trip399	1
25/04/2026 07:49:11	52.350094	4.925235	320	Sudden braking	2.60	2.60	11.7	8.9	1.00	2	1.8	1.000	602DE_Trip399	1
25/04/2026 14:51:29	52.358598	4.917177	338	Sudden braking	2.30	2.30	10.8	8.6	1.00	2	1.8	1.000	602DE_Trip432	1
25/04/2026 14:52:32	52.359797	4.917086	16	Sudden braking	2.00	2.00	12.4	9.5	1.00	2	5.1	1.000	602DE_Trip432	1
25/04/2026 14:56:45	52.365774	4.927079	39	Sudden braking	2.10	2.10	9.1	6.1	1.00	2	1.4	1.000	602DE_Trip432	1
25/04/2026 14:58:22	52.368087	4.924151	305	Sudden braking	2.20	2.20	10.7	10.5	1.00	2	2.4	1.000	602DE_Trip432	1
25/04/2026 14:58:23	52.368103	4.924128	314	Sudden braking	2.40	2.40	9.6	8.1	1.00	2	4.4	1.000	602DE_Trip432	1
25/04/2026 18:07:14	52.371379	4.915189	239	Sudden braking	2.00	2.00	9.3	7.6	1.00	2	1.2	1.000	602DE_Trip437	1
25/04/2026 18:07:15	52.371369	4.915183	222	Sudden braking	2.10	2.10	8.6	5.5	1.00	2	1.4	1.000	602DE_Trip437	1
25/04/2026 18:17:03	52.366576	4.925629	136	Sudden braking	2.00	2.00	10.6	10.2	1.00	2	4.4	1.000	602DE_Trip438	1
25/04/2026 18:27:54	52.347960	4.939680	137	Sudden braking	2.20	2.20	14.7	13.6	1.00	2	4.1	1.000	602DE_Trip438	1
25/04/2026 19:27:41	52.371221	4.934459	246	Sudden braking	2.50	2.50	9.5	9.6	1.00	2	5.0	1.000	602B1_Trip439	1
25/04/2026 19:27:44	52.371175	4.934452	180	Sudden braking	2.20	2.20	7.2	4.9	1.00	2	1.2	1.000	602B1_Trip439	1
25/04/2026 19:27:45	52.371179	4.934436	195	Sudden braking	2.30	2.30	5.4	2.6	1.00	2	1.0	1.000	602B1_Trip439	1
25/04/2026 19:30:49	52.366172	4.932866	272	Sudden braking	3.10	3.10	16.1	16.0	1.00	2	3.8	1.000	602B1_Trip439	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
25/04/2026 19:30:50	52.366159	4.932815	260	Sudden braking	4.20	4.20	14.1	11.8	1.00	2	2.9	1.000	602B1_Trip439	1
25/04/2026 19:30:51	52.366133	4.932810	228	Sudden braking	3.90	3.90	12.2	7.9	1.00	3	1.4	1.000	602B1_Trip439	1
26/04/2026 11:11:22	52.353188	4.970985	343	Sudden braking	2.50	2.50	10.5	11.6	1.00	3	4.4	1.000	602DE_Trip441	1
27/04/2026 05:18:07	52.348662	4.927564	313	Sudden braking	2.20	2.20	13.8	14.7	1.00	2	5.3	1.000	602DE_Trip444	1
27/04/2026 05:18:10	52.348721	4.927463	316	Sudden braking	2.20	2.20	11.3	10.3	1.00	2	3.6	1.000	602DE_Trip444	1
27/04/2026 05:18:11	52.348741	4.927422	314	Sudden braking	2.20	2.20	10.7	8.1	1.00	2	3.3	1.000	602DE_Trip444	1
27/04/2026 05:19:20	52.350738	4.924203	315	Sudden braking	2.10	2.10	13.8	13.8	1.00	2	4.6	1.000	602DE_Trip444	1
27/04/2026 05:19:23	52.350797	4.924105	317	Sudden braking	2.00	2.00	12.7	9.8	1.00	3	3.7	1.000	602DE_Trip444	1
27/04/2026 05:21:20	52.354615	4.920173	334	Sudden braking	2.40	2.40	14.4	12.9	1.00	2	7.1	1.000	602DE_Trip444	1
28/04/2026 05:09:41	52.340412	4.937192	317	Sudden braking	2.30	2.30	14.0	13.9	1.00	2	4.9	1.000	602DE_Trip448	1
28/04/2026 05:10:26	52.341936	4.934899	318	Sudden braking	2.20	2.20	13.1	14.2	1.00	2	4.4	1.000	602DE_Trip448	1
28/04/2026 05:10:27	52.341963	4.934851	313	Sudden braking	2.10	2.10	12.3	12.1	1.00	2	1.0	1.000	602DE_Trip448	1
28/04/2026 05:10:28	52.341964	4.934836	304	Sudden braking	2.30	2.30	11.6	9.8	1.00	2	2.6	1.000	602DE_Trip448	1
28/04/2026 05:10:29	52.341981	4.934810	314	Sudden braking	2.10	2.10	10.9	7.7	1.00	2	3.5	1.000	602DE_Trip448	1
28/04/2026 05:15:40	52.350949	4.923842	315	Sudden braking	2.20	2.20	10.1	6.5	1.00	2	4.4	1.000	602DE_Trip448	1
28/04/2026 08:06:16	52.353812	4.809239	73	Sudden braking	2.10	2.10	16.6	16.4	1.00	2	4.0	1.000	604F0_Trip450	1
28/04/2026 08:06:17	52.353820	4.809296	74	Sudden braking	2.90	2.90	16.1	13.5	1.00	2	2.8	1.000	604F0_Trip450	1
28/04/2026 08:06:18	52.353828	4.809336	73	Sudden braking	3.00	3.00	15.4	10.5	1.00	2	1.9	1.000	604F0_Trip450	1
28/04/2026 08:10:21	52.356106	4.826960	90	Sudden braking	2.10	2.10	16.3	16.7	1.00	2	3.6	1.000	604F0_Trip450	1
28/04/2026 08:10:22	52.356102	4.827013	94	Sudden braking	2.20	2.20	14.8	14.5	1.00	2	3.3	1.000	604F0_Trip450	1
28/04/2026 08:10:23	52.356093	4.827058	104	Sudden braking	2.10	2.10	13.9	12.4	1.00	2	2.8	1.000	604F0_Trip450	1
28/04/2026 08:21:14	52.361575	4.881631	56	Sudden braking	2.50	2.50	15.8	18.6	1.00	2	4.5	1.000	604F0_Trip450	1
28/04/2026 08:21:15	52.361605	4.881677	50	Sudden braking	3.10	3.10	14.8	15.5	1.00	2	3.1	1.000	604F0_Trip450	1
28/04/2026 08:21:16	52.361624	4.881710	49	Sudden braking	3.30	3.30	13.6	12.2	1.00	2	2.1	1.000	604F0_Trip450	1
28/04/2026 08:21:17	52.361640	4.881729	44	Sudden braking	3.20	3.20	11.1	9.0	1.00	2	1.1	1.000	604F0_Trip450	1
28/04/2026 08:21:18	52.361647	4.881741	43	Sudden braking	3.00	3.00	9.7	6.0	1.00	2	1.2	1.000	604F0_Trip450	1
28/04/2026 08:27:35	52.362174	4.907005	72	Sudden braking	2.00	2.00	15.3	17.6	1.00	2	4.5	1.000	604F0_Trip450	1
28/04/2026 08:27:36	52.362187	4.907067	72	Sudden braking	2.60	2.60	14.4	15.0	1.00	2	3.3	1.000	604F0_Trip450	1
28/04/2026 08:27:37	52.362200	4.907111	72	Sudden braking	2.50	2.50	13.6	12.5	1.00	2	2.2	1.000	604F0_Trip450	1
28/04/2026 08:27:38	52.362212	4.907138	71	Sudden braking	2.20	2.20	12.7	10.3	1.00	2	2.1	1.000	604F0_Trip450	1
28/04/2026 08:27:39	52.362221	4.907165	74	Sudden braking	2.50	2.50	11.7	7.8	1.00	2	2.0	1.000	604F0_Trip450	1
28/04/2026 08:27:40	52.362228	4.907192	74	Sudden braking	2.10	2.10	10.5	5.7	1.00	2	1.2	1.000	604F0_Trip450	1
28/04/2026 08:29:07	52.364210	4.906238	340	Sudden braking	2.10	2.10	17.3	17.1	1.00	2	4.2	1.000	604F0_Trip450	1
28/04/2026 08:29:08	52.364245	4.906217	340	Sudden braking	2.20	2.20	16.3	14.9	1.00	2	1.9	1.000	604F0_Trip450	1
28/04/2026 08:29:09	52.364261	4.906207	340	Sudden braking	2.10	2.10	15.6	12.8	1.00	2	1.9	1.000	604F0_Trip450	1
28/04/2026 08:30:23	52.366098	4.911577	30	Sudden braking	2.40	2.40	15.3	15.9	1.00	2	3.3	1.000	604F0_Trip450	1
28/04/2026 08:30:24	52.366121	4.911609	30	Sudden braking	2.60	2.60	14.6	13.3	1.00	2	2.4	1.000	604F0_Trip450	1
28/04/2026 08:30:25	52.366135	4.911636	30	Sudden braking	3.10	3.10	13.8	10.2	1.00	2	2.4	1.000	604F0_Trip450	1
28/04/2026 08:30:26	52.366147	4.911666	30	Sudden braking	3.30	3.30	11.4	6.9	1.00	2	2.4	1.000	604F0_Trip450	1
28/04/2026 08:31:25	52.368376	4.913600	26	Sudden braking	2.20	2.20	19.4	20.6	1.00	2	5.0	1.000	604F0_Trip450	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
28/04/2026 08:31:26	52.368418	4.913625	24	Sudden braking	2.30	2.30	18.7	18.3	1.00	2	2.4	1.000	604F0_Trip450	1
28/04/2026 08:31:27	52.368433	4.913649	29	Sudden braking	2.20	2.20	18.0	16.1	1.00	2	3.0	1.000	604F0_Trip450	1
28/04/2026 08:32:55	52.371033	4.913258	93	Sudden braking	2.10	2.10	9.9	8.8	1.00	2	1.9	1.000	604F0_Trip450	1
28/04/2026 08:33:17	52.371089	4.914713	56	Sudden braking	2.10	2.10	19.3	17.3	1.00	2	3.7	1.000	604F0_Trip450	1
28/04/2026 08:33:38	52.371689	4.916307	65	Sudden braking	2.90	2.90	18.8	16.6	1.00	2	4.7	1.000	604F0_Trip450	1
28/04/2026 08:33:39	52.371716	4.916359	58	Sudden braking	3.40	3.40	16.6	13.2	1.00	2	1.6	1.000	604F0_Trip450	1
28/04/2026 08:33:44	52.371737	4.916395	33	Sudden braking	3.00	3.00	6.6	7.0	1.00	2	1.9	1.000	604F0_Trip450	1
28/04/2026 08:33:45	52.371745	4.916418	43	Sudden braking	2.20	2.20	5.2	4.8	1.00	2	1.3	1.000	604F0_Trip450	1
28/04/2026 17:21:14	52.376094	4.921857	38	Sudden braking	2.60	2.60	18.1	19.0	1.00	2	4.2	1.000	602B1_Trip451	1
28/04/2026 17:21:15	52.376118	4.921906	44	Sudden braking	3.10	3.10	17.4	15.9	1.00	2	3.5	1.000	602B1_Trip451	1
28/04/2026 17:21:16	52.376143	4.921936	48	Sudden braking	3.70	3.70	15.3	12.2	1.00	2	2.4	1.000	602B1_Trip451	1
28/04/2026 17:21:17	52.376157	4.921962	52	Sudden braking	3.40	3.40	14.1	8.8	1.00	2	1.0	1.000	602B1_Trip451	1
29/04/2026 08:59:21	52.340928	4.951704	315	Sudden braking	2.20	2.20	9.4	7.4	1.00	2	2.9	1.000	602DE_Trip459	1
29/04/2026 09:07:22	52.353720	4.930880	314	Sudden braking	2.00	2.00	8.7	7.6	1.00	2	1.8	1.000	602DE_Trip459	1
29/04/2026 09:07:23	52.353735	4.930869	319	Sudden braking	2.30	2.30	8.1	5.3	1.00	2	1.3	1.000	602DE_Trip459	1
29/04/2026 09:15:59	52.363676	4.930592	6	Sudden braking	2.00	2.00	11.2	9.5	1.00	2	5.7	1.000	602DE_Trip459	1
29/04/2026 09:16:00	52.363727	4.930585	5	Sudden braking	2.00	2.00	11.3	7.5	1.00	2	2.8	1.000	602DE_Trip459	1
29/04/2026 09:20:28	52.370075	4.918366	300	Sudden braking	2.10	2.10	14.6	13.4	1.00	2	5.2	1.000	602DE_Trip459	1
29/04/2026 09:20:51	52.370574	4.916957	297	Sudden braking	2.70	2.70	12.7	13.5	1.00	2	5.1	1.000	602DE_Trip459	1
29/04/2026 09:20:52	52.370601	4.916895	299	Sudden braking	2.50	2.50	11.8	11.0	1.00	2	1.5	1.000	602DE_Trip459	1
29/04/2026 09:20:53	52.370607	4.916915	320	Sudden braking	2.50	2.50	10.9	8.5	1.00	2	2.8	1.000	602DE_Trip459	1
29/04/2026 10:11:02	52.353797	4.809224	72	Sudden braking	2.00	2.00	16.6	16.9	1.00	2	4.3	1.000	604F0_Trip463	1
29/04/2026 10:11:03	52.353810	4.809284	71	Sudden braking	2.40	2.40	15.9	14.5	1.00	2	3.0	1.000	604F0_Trip463	1
29/04/2026 10:11:04	52.353817	4.809327	72	Sudden braking	2.80	2.80	15.0	11.7	1.00	2	2.1	1.001	604F0_Trip463	1
29/04/2026 10:11:06	52.353824	4.809355	71	Sudden braking	2.70	2.70	13.0	9.0	1.00	2	1.2	1.000	604F0_Trip463	1
29/04/2026 10:19:00	52.354950	4.850042	89	Sudden braking	2.20	2.20	14.0	15.2	1.00	2	3.2	1.000	604F0_Trip463	1
29/04/2026 10:19:01	52.354951	4.850089	89	Sudden braking	2.50	2.50	13.4	12.7	1.00	2	2.1	1.000	604F0_Trip463	1
29/04/2026 10:19:02	52.354951	4.850121	89	Sudden braking	2.50	2.50	12.7	10.2	1.00	2	1.7	1.000	604F0_Trip463	1
29/04/2026 10:19:03	52.354951	4.850146	89	Sudden braking	2.30	2.30	11.9	7.9	1.00	2	2.0	1.000	604F0_Trip463	1
29/04/2026 10:19:46	52.354834	4.852786	94	Sudden braking	2.10	2.10	17.4	17.3	1.00	2	3.8	1.000	604F0_Trip463	1
29/04/2026 10:19:47	52.354831	4.852841	94	Sudden braking	2.10	2.10	16.5	15.2	1.00	2	3.2	1.000	604F0_Trip463	1
29/04/2026 10:20:12	52.354739	4.854909	78	Sudden braking	2.00	2.00	19.4	20.8	1.00	2	5.6	1.000	604F0_Trip463	1
29/04/2026 10:20:13	52.354751	4.854988	75	Sudden braking	2.40	2.40	17.9	18.4	1.00	2	4.0	1.000	604F0_Trip463	1
29/04/2026 10:20:14	52.354761	4.855045	75	Sudden braking	2.60	2.60	16.3	15.8	1.00	2	2.5	1.000	604F0_Trip463	1
29/04/2026 10:20:15	52.354769	4.855080	72	Sudden braking	2.60	2.60	14.9	13.2	1.00	2	2.6	1.000	604F0_Trip463	1
29/04/2026 10:20:16	52.354776	4.855116	72	Sudden braking	2.00	2.00	13.5	11.2	1.00	2	2.3	1.000	604F0_Trip463	1
29/04/2026 10:23:51	52.358797	4.875322	66	Sudden braking	2.20	2.20	19.2	19.1	1.00	2	4.3	1.000	604F0_Trip463	1
29/04/2026 10:23:52	52.358802	4.875384	67	Sudden braking	2.50	2.50	18.7	16.6	1.00	2	4.0	1.000	604F0_Trip463	1
29/04/2026 10:24:13	52.359297	4.877124	67	Sudden braking	2.10	2.10	19.4	20.0	1.00	2	4.9	1.000	604F0_Trip463	1
29/04/2026 10:24:14	52.359318	4.877187	66	Sudden braking	2.40	2.40	18.5	17.6	1.00	2	4.1	1.000	604F0_Trip463	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
29/04/2026 10:24:15	52.359336	4.877240	66	Sudden braking	2.30	2.30	17.8	15.3	1.00	2	3.2	1.000	604F0_Trip463	1
29/04/2026 10:25:26	52.359223	4.881862	157	Sudden braking	2.10	2.10	18.0	17.6	1.00	2	4.4	1.000	604F0_Trip463	1
29/04/2026 10:26:41	52.360395	4.885814	37	Sudden braking	2.10	2.10	13.7	14.4	1.00	2	3.6	1.000	604F0_Trip463	1
29/04/2026 10:26:42	52.360416	4.885856	47	Sudden braking	2.00	2.00	13.2	12.4	1.00	2	3.9	1.000	604F0_Trip463	1
29/04/2026 10:26:43	52.360441	4.885895	45	Sudden braking	2.10	2.10	12.5	10.3	1.00	2	3.2	1.000	604F0_Trip463	1
29/04/2026 10:28:32	52.363301	4.888648	29	Sudden braking	2.40	2.40	15.4	16.3	1.00	2	3.4	1.000	604F0_Trip463	1
29/04/2026 10:28:33	52.363328	4.888672	28	Sudden braking	2.70	2.70	14.2	13.6	1.00	2	2.0	0.999	604F0_Trip463	1
29/04/2026 10:28:33	52.363342	4.888692	28	Sudden braking	2.70	2.70	13.3	10.9	1.00	2	2.0	1.000	604F0_Trip463	1
29/04/2026 10:28:34	52.363354	4.888713	28	Sudden braking	2.20	2.20	12.7	8.7	1.00	2	1.4	1.000	604F0_Trip463	1
29/04/2026 10:29:27	52.362799	4.893115	103	Sudden braking	2.30	2.30	20.2	19.7	1.00	2	3.9	1.000	604F0_Trip463	1
29/04/2026 10:29:28	52.362790	4.893171	103	Sudden braking	2.50	2.50	19.9	17.2	1.00	2	3.5	1.000	604F0_Trip463	1
29/04/2026 10:32:16	52.364296	4.906463	72	Sudden braking	2.00	2.00	19.4	17.9	1.00	2	5.8	1.000	604F0_Trip463	1
29/04/2026 10:32:40	52.364765	4.908598	74	Sudden braking	2.50	2.50	19.7	20.2	1.00	2	5.8	1.000	604F0_Trip463	1
29/04/2026 10:32:41	52.364776	4.908681	74	Sudden braking	3.30	3.30	19.4	16.9	1.00	2	3.5	1.000	604F0_Trip463	1
29/04/2026 10:32:42	52.364778	4.908733	74	Sudden braking	3.20	3.20	18.9	13.7	1.00	2	1.1	1.000	604F0_Trip463	1
29/04/2026 10:33:05	52.365054	4.910286	72	Sudden braking	2.60	2.60	19.6	19.6	1.00	2	4.6	1.000	604F0_Trip463	1
29/04/2026 10:33:06	52.365067	4.910349	72	Sudden braking	2.60	2.60	18.9	17.0	1.00	2	3.3	1.000	604F0_Trip463	1
29/04/2026 10:33:25	52.365881	4.911404	29	Sudden braking	2.20	2.20	21.4	21.3	1.00	2	5.5	1.000	604F0_Trip463	1
29/04/2026 10:33:26	52.365929	4.911421	29	Sudden braking	2.10	2.10	20.1	19.2	1.00	2	4.0	1.000	604F0_Trip463	1
29/04/2026 10:34:27	52.368456	4.913753	25	Sudden braking	2.40	2.40	18.2	18.7	1.00	2	4.4	1.000	604F0_Trip463	1
29/04/2026 10:34:28	52.368490	4.913785	28	Sudden braking	2.60	2.60	17.3	16.1	1.00	2	3.4	1.000	604F0_Trip463	1
29/04/2026 10:34:29	52.368519	4.913806	29	Sudden braking	2.30	2.30	16.4	13.8	1.00	2	2.5	1.000	604F0_Trip463	1
29/04/2026 10:35:01	52.369498	4.912329	304	Sudden braking	2.10	2.10	15.7	13.6	1.00	2	2.6	1.000	604F0_Trip463	1
29/04/2026 11:10:04	52.379472	4.923227	251	Sudden braking	2.70	2.70	9.8	10.5	1.00	2	3.7	1.000	602B1_Trip467	1
29/04/2026 11:10:05	52.379439	4.923231	233	Sudden braking	2.70	2.70	8.5	7.8	1.00	2	5.3	1.000	602B1_Trip467	1
29/04/2026 11:10:06	52.379399	4.923275	176	Sudden braking	2.10	2.10	7.8	5.7	1.00	2	2.4	1.000	602B1_Trip467	1
29/04/2026 11:11:27	52.376603	4.921776	201	Sudden braking	2.20	2.20	19.6	22.5	1.00	2	7.0	1.000	602B1_Trip467	1
29/04/2026 11:11:28	52.376541	4.921788	187	Sudden braking	3.60	3.60	17.8	18.9	1.00	2	3.2	1.000	602B1_Trip467	1
29/04/2026 11:11:29	52.376513	4.921772	186	Sudden braking	3.80	3.80	16.1	15.1	1.00	2	1.4	1.000	602B1_Trip467	1
29/04/2026 11:11:30	52.376511	4.921751	190	Sudden braking	3.20	3.20	14.4	11.9	1.00	2	5.7	1.000	602B1_Trip467	1
29/04/2026 11:11:31	52.376544	4.921688	233	Sudden braking	2.60	2.60	12.7	9.3	1.00	2	5.4	1.000	602B1_Trip467	1
29/04/2026 11:18:25	52.373367	4.916579	312	Sudden braking	2.60	2.60	17.5	16.3	1.00	3	5.9	1.001	602B1_Trip467	1
29/04/2026 11:18:27	52.373390	4.916502	312	Sudden braking	2.50	2.50	17.2	13.8	1.00	3	1.1	1.000	602B1_Trip467	1
29/04/2026 17:21:07	52.371376	4.915169	213	Sudden braking	2.01	2.01	7.0	5.9	0.99	2	1.5	0.993	602DE_Trip469	1
29/04/2026 17:27:40	52.362611	4.930467	185	Sudden braking	2.00	2.00	11.7	10.6	1.00	2	7.9	1.000	602DE_Trip469	1
29/04/2026 17:29:29	52.359113	4.931147	251	Sudden braking	2.00	2.00	10.5	9.7	1.00	3	6.5	1.000	602DE_Trip469	1
29/04/2026 17:31:35	52.356515	4.927339	180	Sudden braking	2.00	2.00	9.9	9.2	1.00	2	5.2	1.000	602DE_Trip469	1
29/04/2026 17:32:36	52.354354	4.929539	136	Sudden braking	2.90	2.90	15.6	17.7	1.00	2	5.7	1.000	602DE_Trip469	1
29/04/2026 17:32:39	52.354282	4.929669	129	Sudden braking	3.40	3.40	12.1	10.6	1.00	2	1.8	1.000	602DE_Trip469	1
29/04/2026 17:32:40	52.354288	4.929645	139	Sudden braking	2.10	2.10	10.7	8.5	1.00	2	1.1	1.000	602DE_Trip469	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
29/04/2026 17:35:14	52.349942	4.936454	135	Sudden braking	2.60	2.60	9.9	13.4	1.00	2	6.1	1.000	602DE_Trip469	1
29/04/2026 17:35:15	52.349902	4.936515	134	Sudden braking	2.50	2.50	9.7	10.9	1.00	2	1.8	1.000	602DE_Trip469	1
29/04/2026 17:35:27	52.349534	4.937074	137	Sudden braking	2.90	2.90	13.7	13.8	1.00	3	6.2	1.000	602DE_Trip469	1
29/04/2026 17:35:28	52.349494	4.937137	136	Sudden braking	2.10	2.10	13.3	11.7	1.00	3	2.0	1.000	602DE_Trip469	1
29/04/2026 17:36:41	52.347519	4.940375	135	Sudden braking	2.40	2.40	13.9	14.9	1.00	3	1.5	1.000	602DE_Trip469	1
29/04/2026 17:36:42	52.347509	4.940390	136	Sudden braking	2.70	2.70	13.9	12.2	1.00	2	1.5	1.000	602DE_Trip469	1
29/04/2026 17:36:43	52.347500	4.940406	135	Sudden braking	2.20	2.20	13.8	10.0	1.00	2	2.0	1.000	602DE_Trip469	1
29/04/2026 17:41:55	52.339377	4.954889	107	Sudden braking	2.00	2.00	10.5	8.8	1.00	2	1.8	1.000	602DE_Trip469	1
29/04/2026 17:41:56	52.339368	4.954912	112	Sudden braking	2.10	2.10	10.0	6.7	1.00	2	1.1	1.000	602DE_Trip469	1
29/04/2026 18:28:26	52.364425	4.906422	252	Sudden braking	2.00	2.00	14.0	14.0	1.00	2	2.3	1.000	604F0_Trip471	1
29/04/2026 18:28:27	52.364423	4.906388	252	Sudden braking	2.10	2.10	12.7	11.9	1.00	2	3.0	1.000	604F0_Trip471	1
29/04/2026 18:30:17	52.361993	4.898907	158	Sudden braking	2.20	2.20	17.7	18.4	1.00	2	3.5	1.000	604F0_Trip471	1
29/04/2026 18:30:18	52.361964	4.898928	155	Sudden braking	2.40	2.40	16.8	16.0	1.00	2	3.6	1.000	604F0_Trip471	1
29/04/2026 18:30:19	52.361936	4.898953	153	Sudden braking	2.10	2.10	15.9	13.9	1.00	2	3.2	1.000	604F0_Trip471	1
29/04/2026 18:32:12	52.359631	4.891747	279	Sudden braking	2.00	2.00	15.1	15.0	1.00	2	3.7	1.000	604F0_Trip471	1
29/04/2026 18:33:12	52.361130	4.887054	309	Sudden braking	2.50	2.50	21.3	21.3	1.00	2	4.9	1.000	604F0_Trip471	1
29/04/2026 18:33:13	52.361153	4.886993	306	Sudden braking	2.60	2.60	20.9	18.7	1.00	2	3.2	1.000	604F0_Trip471	1
29/04/2026 18:33:14	52.361167	4.886951	303	Sudden braking	2.20	2.20	20.6	16.5	1.00	2	2.9	1.000	604F0_Trip471	1
29/04/2026 18:33:52	52.362562	4.883924	308	Sudden braking	2.20	2.20	18.2	17.7	1.00	2	4.2	1.001	604F0_Trip471	1
29/04/2026 18:33:53	52.362589	4.883881	311	Sudden braking	3.40	3.40	16.4	14.3	1.00	2	3.5	1.000	604F0_Trip471	1
29/04/2026 18:33:54	52.362612	4.883846	313	Sudden braking	3.70	3.70	15.3	10.6	1.00	2	2.1	1.000	604F0_Trip471	1
29/04/2026 18:34:48	52.361957	4.881980	231	Sudden braking	2.00	2.00	13.2	12.8	1.00	2	2.8	1.000	604F0_Trip471	1
29/04/2026 18:34:49	52.361946	4.881943	239	Sudden braking	2.60	2.60	12.4	10.2	1.00	2	2.1	1.000	604F0_Trip471	1
29/04/2026 18:34:50	52.361944	4.881912	251	Sudden braking	2.50	2.50	11.5	7.7	1.00	2	1.9	1.000	604F0_Trip471	1
29/04/2026 18:36:31	52.360842	4.874015	311	Sudden braking	2.20	2.20	17.6	17.7	1.00	2	4.5	1.000	604F0_Trip471	1
29/04/2026 18:36:32	52.360882	4.874006	332	Sudden braking	2.20	2.20	16.6	15.5	1.00	2	22.4	1.000	604F0_Trip471	1
29/04/2026 18:36:33	52.361073	4.873906	336	Sudden braking	2.00	2.00	15.8	13.5	1.00	2	3.1	1.000	604F0_Trip471	1
30/04/2026 09:22:21	52.356102	4.827092	112	Sudden braking	2.00	2.00	12.5	11.0	1.00	2	2.5	1.000	604F0_Trip475	1
30/04/2026 09:22:22	52.356090	4.827122	112	Sudden braking	2.40	2.40	11.6	8.6	1.00	2	1.6	1.000	604F0_Trip475	1
30/04/2026 09:22:23	52.356082	4.827141	112	Sudden braking	2.50	2.50	10.7	6.1	1.00	2	2.0	1.000	604F0_Trip475	1
30/04/2026 09:27:02	52.354950	4.849943	89	Sudden braking	2.20	2.20	19.4	19.9	1.00	2	4.8	1.000	604F0_Trip475	1
30/04/2026 09:27:03	52.354950	4.850014	89	Sudden braking	2.70	2.70	17.6	17.2	1.00	2	3.8	1.000	604F0_Trip475	1
30/04/2026 09:27:04	52.354950	4.850070	89	Sudden braking	2.90	2.90	16.7	14.3	1.00	2	2.9	1.000	604F0_Trip475	1
30/04/2026 09:27:05	52.354951	4.850114	89	Sudden braking	3.00	3.00	14.9	11.3	1.00	2	2.1	1.000	604F0_Trip475	1
30/04/2026 09:31:45	52.358832	4.875321	65	Sudden braking	2.50	2.50	17.5	16.7	1.00	2	3.7	1.000	604F0_Trip475	1
30/04/2026 09:31:46	52.358845	4.875371	66	Sudden braking	2.20	2.20	17.2	14.5	1.00	2	2.2	1.000	604F0_Trip475	1
30/04/2026 09:32:56	52.360351	4.880946	66	Sudden braking	2.10	2.10	19.6	19.6	1.00	2	4.8	1.000	604F0_Trip475	1
30/04/2026 09:32:57	52.360371	4.881008	66	Sudden braking	2.20	2.20	19.3	17.4	1.00	2	4.4	1.000	604F0_Trip475	1
30/04/2026 09:33:19	52.359266	4.881854	156	Sudden braking	2.40	2.40	16.1	16.5	1.00	2	3.8	1.000	604F0_Trip475	1
30/04/2026 09:33:20	52.359237	4.881882	157	Sudden braking	2.70	2.70	15.4	13.8	1.00	2	2.7	1.000	604F0_Trip475	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
30/04/2026 09:33:21	52.359214	4.881899	156	Sudden braking	3.00	3.00	14.6	10.8	1.00	2	2.3	1.000	604F0_Trip475	1
30/04/2026 09:33:22	52.359195	4.881911	156	Sudden braking	2.70	2.70	13.6	8.1	1.00	2	2.1	1.000	604F0_Trip475	1
30/04/2026 09:34:36	52.360451	4.885938	46	Sudden braking	3.50	3.50	14.7	17.3	1.00	2	11.5	1.001	604F0_Trip475	1
30/04/2026 09:34:37	52.360388	4.885804	42	Sudden braking	3.74	3.74	14.6	13.6	0.99	2	10.4	0.990	604F0_Trip475	1
30/04/2026 09:34:38	52.360333	4.885679	49	Sudden braking	2.60	2.60	14.6	11.0	1.00	2	4.9	1.000	604F0_Trip475	1
30/04/2026 09:34:47	52.360506	4.885968	46	Sudden braking	2.10	2.10	9.8	8.3	1.00	2	2.0	1.000	604F0_Trip475	1
30/04/2026 09:34:48	52.360510	4.885998	67	Sudden braking	2.30	2.30	9.1	6.0	1.00	2	1.9	1.000	604F0_Trip475	1
30/04/2026 09:35:43	52.361002	4.886690	40	Sudden braking	2.10	2.10	16.8	17.5	1.00	2	5.3	1.000	604F0_Trip475	1
30/04/2026 09:35:44	52.361042	4.886733	36	Sudden braking	2.90	2.90	15.7	14.6	1.00	2	3.1	1.000	604F0_Trip475	1
30/04/2026 09:36:02	52.361674	4.887165	33	Sudden braking	2.20	2.20	15.5	15.4	1.00	2	3.9	1.000	604F0_Trip475	1
30/04/2026 09:36:03	52.361706	4.887189	31	Sudden braking	2.60	2.60	14.3	12.8	1.00	2	2.7	1.000	604F0_Trip475	1
30/04/2026 09:36:04	52.361729	4.887204	30	Sudden braking	2.50	2.50	13.3	10.3	1.00	2	1.5	1.000	604F0_Trip475	1
30/04/2026 09:36:26	52.362399	4.887797	32	Sudden braking	2.20	2.20	12.3	13.4	1.00	2	3.5	1.000	604F0_Trip475	1
30/04/2026 09:36:27	52.362429	4.887815	27	Sudden braking	2.40	2.40	11.2	11.0	1.00	2	1.6	1.000	604F0_Trip475	1
30/04/2026 09:36:28	52.362441	4.887825	27	Sudden braking	2.30	2.30	10.1	8.7	1.00	2	1.3	1.000	604F0_Trip475	1
30/04/2026 09:36:29	52.362453	4.887831	23	Sudden braking	2.00	2.00	9.1	6.7	1.00	2	1.1	1.000	604F0_Trip475	1
30/04/2026 09:37:45	52.362889	4.892499	102	Sudden braking	2.00	2.00	8.7	8.0	1.00	2	2.7	1.000	604F0_Trip475	1
30/04/2026 09:40:42	52.364273	4.905668	71	Sudden braking	2.40	2.40	18.9	19.3	1.00	2	4.6	1.000	604F0_Trip475	1
30/04/2026 09:40:43	52.364284	4.905733	72	Sudden braking	2.50	2.50	17.6	16.8	1.00	2	3.7	1.000	604F0_Trip475	1
30/04/2026 09:40:44	52.364300	4.905783	71	Sudden braking	2.00	2.00	16.3	14.8	1.00	2	3.5	1.000	604F0_Trip475	1
30/04/2026 09:40:51	52.364271	4.906083	134	Sudden braking	2.20	2.20	7.6	6.2	1.00	2	2.0	1.000	604F0_Trip475	1
30/04/2026 09:44:06	52.369463	4.912287	304	Sudden braking	2.00	2.00	16.8	16.9	1.00	2	4.1	1.000	604F0_Trip475	1
30/04/2026 09:44:07	52.369495	4.912255	317	Sudden braking	2.20	2.20	16.1	14.7	1.00	2	4.2	1.000	604F0_Trip475	1
30/04/2026 09:44:08	52.369532	4.912267	347	Sudden braking	2.00	2.00	15.5	12.7	1.00	2	3.3	1.000	604F0_Trip475	1
30/04/2026 15:32:30	52.346968	4.941207	139	Sudden braking	2.00	2.00	14.0	12.1	1.00	2	2.4	1.000	602DE_Trip476	1
30/04/2026 15:36:27	52.340153	4.952293	161	Sudden braking	2.00	2.00	9.7	7.0	1.00	1	1.6	1.000	602DE_Trip476	1
01/05/2026 05:50:15	52.356118	4.826959	88	Sudden braking	2.00	2.00	17.6	20.8	1.00	2	5.7	1.000	604F0_Trip478	1
01/05/2026 05:50:16	52.356109	4.827042	96	Sudden braking	2.80	2.80	16.8	18.0	1.00	2	4.1	1.000	604F0_Trip478	1
01/05/2026 05:50:17	52.356094	4.827097	105	Sudden braking	3.30	3.30	14.8	14.7	1.00	2	2.8	1.000	604F0_Trip478	1
01/05/2026 05:50:18	52.356080	4.827130	115	Sudden braking	3.50	3.50	13.6	11.2	1.00	2	1.4	1.000	604F0_Trip478	1
01/05/2026 05:50:19	52.356070	4.827143	124	Sudden braking	2.90	2.90	11.8	8.3	1.00	2	1.1	1.000	604F0_Trip478	1
01/05/2026 05:54:51	52.354950	4.850084	89	Sudden braking	2.20	2.20	14.6	14.2	1.00	2	3.2	1.000	604F0_Trip478	1
01/05/2026 05:54:52	52.354951	4.850131	89	Sudden braking	2.60	2.60	13.9	11.6	1.00	2	2.2	1.000	604F0_Trip478	1
01/05/2026 05:54:53	52.354951	4.850163	89	Sudden braking	2.40	2.40	12.6	9.2	1.00	2	1.3	1.000	604F0_Trip478	1
01/05/2026 06:00:13	52.359352	4.877253	66	Sudden braking	2.00	2.00	15.9	18.6	1.00	1	4.5	1.000	604F0_Trip478	1
01/05/2026 06:00:14	52.359363	4.877316	67	Sudden braking	2.70	2.70	15.4	15.9	1.00	1	3.2	1.000	604F0_Trip478	1
01/05/2026 06:00:15	52.359375	4.877359	67	Sudden braking	3.10	3.10	13.6	12.8	1.00	1	2.3	1.000	604F0_Trip478	1
01/05/2026 06:00:16	52.359382	4.877390	67	Sudden braking	3.30	3.30	12.7	9.5	1.00	1	1.9	1.000	604F0_Trip478	1
01/05/2026 06:00:17	52.359382	4.877418	67	Sudden braking	3.00	3.00	11.5	6.5	1.00	1	1.4	1.000	604F0_Trip478	1
01/05/2026 06:02:49	52.359756	4.884959	42	Sudden braking	2.00	2.00	20.3	19.1	1.00	2	4.6	1.001	604F0_Trip478	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
01/05/2026 06:03:12	52.360532	4.885970	49	Sudden braking	2.90	2.90	9.1	6.9	1.00	2	1.0	1.000	604F0_Trip478	1
01/05/2026 06:03:13	52.360536	4.885983	53	Sudden braking	2.50	2.50	8.3	4.4	1.00	2	1.9	1.000	604F0_Trip478	1
01/05/2026 06:03:58	52.361604	4.887047	30	Sudden braking	2.60	2.60	16.4	17.5	1.00	2	3.8	1.000	604F0_Trip478	1
01/05/2026 06:03:59	52.361629	4.887086	40	Sudden braking	2.70	2.70	15.7	14.8	1.00	2	3.4	1.000	604F0_Trip478	1
01/05/2026 06:04:00	52.361647	4.887127	50	Sudden braking	2.20	2.20	15.0	12.6	1.00	2	3.0	1.000	604F0_Trip478	1
01/05/2026 06:04:41	52.363294	4.888610	29	Sudden braking	2.10	2.10	16.9	18.3	1.00	2	4.6	1.000	604F0_Trip478	1
01/05/2026 06:04:42	52.363330	4.888642	28	Sudden braking	2.50	2.50	16.1	15.8	1.00	2	3.6	1.000	604F0_Trip478	1
01/05/2026 06:04:43	52.363358	4.888668	28	Sudden braking	2.20	2.20	15.4	13.6	1.00	2	2.9	1.000	604F0_Trip478	1
01/05/2026 06:06:08	52.364922	4.892794	11	Sudden braking	2.00	2.00	22.6	24.1	1.00	2	7.6	1.000	604F0_Trip478	1
01/05/2026 06:06:09	52.364986	4.892829	11	Sudden braking	2.20	2.20	21.8	21.9	1.00	2	5.9	1.000	604F0_Trip478	1
01/05/2026 06:10:25	52.376104	4.902809	71	Sudden braking	2.10	2.10	14.3	13.8	1.00	2	3.7	1.000	604F0_Trip478	1
01/05/2026 06:10:26	52.376138	4.902818	71	Sudden braking	2.10	2.10	13.5	11.7	1.00	1	2.2	1.000	604F0_Trip478	1
01/05/2026 06:10:27	52.376156	4.902831	36	Sudden braking	2.30	2.30	11.8	9.4	1.00	1	2.6	1.000	604F0_Trip478	1
01/05/2026 08:12:43	52.340652	4.952157	313	Sudden braking	2.40	2.40	26.3	27.7	1.00	2	7.1	1.000	602DE_Trip479	1
01/05/2026 08:12:44	52.340690	4.952073	311	Sudden braking	3.10	3.10	25.9	24.6	1.00	2	7.5	1.000	602DE_Trip479	1
01/05/2026 08:12:45	52.340724	4.951977	307	Sudden braking	2.30	2.30	25.6	22.3	1.00	2	6.1	1.000	602DE_Trip479	1
01/05/2026 08:12:57	52.341059	4.951441	313	Sudden braking	2.10	2.10	14.3	14.6	1.00	2	3.2	1.000	602DE_Trip479	1
01/05/2026 08:12:58	52.341078	4.951406	313	Sudden braking	2.10	2.10	12.9	12.5	1.00	2	2.6	1.000	602DE_Trip479	1
01/05/2026 08:16:53	52.347174	4.941352	317	Sudden braking	2.00	2.00	14.0	14.5	1.00	2	5.6	1.000	602DE_Trip479	1
01/05/2026 08:18:52	52.350188	4.936525	316	Sudden braking	2.00	2.00	12.8	9.4	1.00	2	7.1	1.000	602DE_Trip479	1
01/05/2026 08:19:11	52.350819	4.935514	315	Sudden braking	2.20	2.20	9.7	9.9	1.00	2	2.8	1.000	602DE_Trip479	1
01/05/2026 08:19:40	52.351211	4.934626	316	Sudden braking	2.30	2.30	14.7	12.3	1.00	2	2.7	1.000	602DE_Trip479	1
01/05/2026 08:20:04	52.352077	4.933219	316	Sudden braking	2.90	2.90	17.1	16.3	1.00	2	4.4	1.000	602DE_Trip479	1
01/05/2026 08:20:05	52.352103	4.933170	298	Sudden braking	2.60	2.60	16.9	13.7	1.00	2	3.5	1.000	602DE_Trip479	1
01/05/2026 08:20:51	52.353794	4.930744	311	Sudden braking	2.20	2.20	15.3	15.6	1.00	2	6.5	1.000	602DE_Trip479	1
01/05/2026 08:24:15	52.360012	4.927481	49	Sudden braking	2.00	2.00	8.8	7.4	1.00	2	5.2	1.000	602DE_Trip479	1
01/05/2026 08:24:52	52.360560	4.929694	71	Sudden braking	2.50	2.50	9.8	9.6	1.00	2	5.4	1.000	602DE_Trip479	1
01/05/2026 08:25:36	52.362163	4.930629	0	Sudden braking	2.40	2.40	12.0	8.7	1.00	2	1.2	1.000	602DE_Trip479	1
01/05/2026 08:26:48	52.364793	4.929340	312	Sudden braking	2.00	2.00	11.3	11.6	1.00	2	3.2	1.000	602DE_Trip479	1
01/05/2026 08:27:24	52.365710	4.926999	335	Sudden braking	3.20	3.20	10.4	9.9	1.00	2	3.0	1.000	602DE_Trip479	1
01/05/2026 08:29:01	52.368229	4.923400	299	Sudden braking	2.40	2.40	17.7	17.8	1.00	2	5.6	1.000	602DE_Trip479	1
01/05/2026 08:29:04	52.368284	4.923242	300	Sudden braking	2.10	2.10	14.6	13.0	1.00	2	7.4	1.000	602DE_Trip479	1
01/05/2026 08:29:33	52.369082	4.921048	299	Sudden braking	2.20	2.20	21.7	20.9	1.00	2	5.8	1.000	602DE_Trip479	1
01/05/2026 08:29:41	52.369243	4.920579	299	Sudden braking	2.60	2.60	16.2	14.6	1.00	2	2.3	1.000	602DE_Trip479	1
01/05/2026 08:32:39	52.373431	4.916397	306	Sudden braking	2.20	2.20	13.6	14.8	1.00	2	4.4	1.000	602DE_Trip479	1
01/05/2026 08:32:40	52.373462	4.916357	313	Sudden braking	2.40	2.40	12.9	12.4	1.00	2	1.6	1.000	602DE_Trip479	1
01/05/2026 08:32:41	52.373449	4.916367	312	Sudden braking	2.40	2.40	12.2	10.0	1.00	2	3.1	1.000	602DE_Trip479	1
01/05/2026 15:36:58	52.376125	4.921930	46	Sudden braking	2.70	2.70	13.1	15.6	1.00	1	3.9	1.000	602B1_Trip487	1
01/05/2026 15:36:59	52.376145	4.921977	50	Sudden braking	3.50	3.50	11.9	12.1	1.00	1	2.6	1.000	602B1_Trip487	1
01/05/2026 15:37:00	52.376164	4.921999	47	Sudden braking	3.50	3.50	9.1	8.6	1.00	1	1.2	1.000	602B1_Trip487	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
01/05/2026 15:39:31	52.379360	4.923332	44	Sudden braking	2.00	2.00	19.4	16.6	1.00	2	6.2	1.000	602B1_Trip487	1
01/05/2026 17:56:59	52.376403	4.911542	245	Sudden braking	2.00	2.00	13.7	14.5	1.00	2	2.7	1.000	63C0A_Trip488	1
01/05/2026 17:57:00	52.376391	4.911507	244	Sudden braking	2.40	2.40	12.3	12.1	1.00	2	3.2	1.000	63C0A_Trip488	1
01/05/2026 17:57:01	52.376373	4.911470	242	Sudden braking	2.10	2.10	11.3	10.0	1.00	2	1.9	1.000	63C0A_Trip488	1
01/05/2026 17:57:15	52.376130	4.910767	242	Sudden braking	2.30	2.30	14.2	15.0	1.00	2	3.1	1.000	63C0A_Trip488	1
01/05/2026 17:57:16	52.376118	4.910727	242	Sudden braking	2.80	2.80	13.0	12.2	1.00	2	2.3	1.000	63C0A_Trip488	1
01/05/2026 17:57:17	52.376107	4.910698	242	Sudden braking	3.20	3.20	11.7	9.0	1.00	2	2.0	1.000	63C0A_Trip488	1
01/05/2026 17:58:34	52.378290	4.906875	282	Sudden braking	2.00	2.00	22.1	24.6	1.00	2	6.7	1.000	63C0A_Trip488	1
01/05/2026 17:58:35	52.378299	4.906777	282	Sudden braking	2.20	2.20	20.7	22.4	1.00	3	5.4	1.000	63C0A_Trip488	1
01/05/2026 17:58:36	52.378324	4.906708	279	Sudden braking	2.50	2.50	19.9	19.9	1.00	2	5.3	1.000	63C0A_Trip488	1
01/05/2026 17:58:37	52.378332	4.906631	273	Sudden braking	2.80	2.80	19.9	17.1	1.00	3	4.7	1.000	63C0A_Trip488	1
01/05/2026 17:58:38	52.378334	4.906563	273	Sudden braking	2.40	2.40	18.3	14.7	1.00	3	3.5	1.000	63C0A_Trip488	1
01/05/2026 17:59:10	52.378988	4.903600	305	Sudden braking	2.00	2.00	27.2	27.7	1.00	2	6.4	1.000	63C0A_Trip488	1
01/05/2026 17:59:11	52.379021	4.903524	305	Sudden braking	2.20	2.20	26.0	25.5	1.00	2	6.3	1.000	63C0A_Trip488	1
01/05/2026 17:59:12	52.379051	4.903444	303	Sudden braking	2.00	2.00	24.8	23.5	1.00	2	5.9	1.000	63C0A_Trip488	1
01/05/2026 17:59:45	52.379991	4.900396	301	Sudden braking	2.40	2.40	24.4	23.8	1.00	2	5.3	1.000	63C0A_Trip488	1
01/05/2026 17:59:46	52.380016	4.900329	301	Sudden braking	2.20	2.20	22.9	21.6	1.00	2	4.1	1.000	63C0A_Trip488	1
01/05/2026 18:00:51	52.382928	4.893819	269	Sudden braking	2.70	2.70	30.2	31.9	1.00	3	8.4	1.000	63C0A_Trip488	1
01/05/2026 18:00:52	52.382925	4.893696	267	Sudden braking	3.20	3.20	28.5	28.7	1.00	2	7.8	1.000	63C0A_Trip488	1
01/05/2026 18:00:53	52.382924	4.893581	275	Sudden braking	3.40	3.40	26.9	25.3	1.00	2	7.1	1.000	63C0A_Trip488	1
01/05/2026 18:00:54	52.382938	4.893479	285	Sudden braking	3.10	3.10	25.5	22.2	1.00	2	6.2	1.000	63C0A_Trip488	1
01/05/2026 18:00:55	52.382962	4.893397	293	Sudden braking	2.10	2.10	24.4	20.1	1.00	2	7.1	1.000	63C0A_Trip488	1
01/05/2026 18:01:21	52.384997	4.893335	7	Sudden braking	2.10	2.10	29.7	33.5	1.00	2	8.1	1.000	63C0A_Trip488	1
01/05/2026 18:01:22	52.385070	4.893343	4	Sudden braking	3.00	3.00	28.9	30.5	1.00	2	7.8	1.000	63C0A_Trip488	1
01/05/2026 18:01:23	52.385140	4.893350	2	Sudden braking	4.00	4.00	26.1	26.5	1.00	2	6.6	1.000	63C0A_Trip488	1
01/05/2026 18:01:24	52.385199	4.893353	2	Sudden braking	5.00	5.00	23.1	21.5	1.00	2	4.4	1.000	63C0A_Trip488	1
01/05/2026 18:01:25	52.385237	4.893370	2	Sudden braking	4.90	4.90	20.0	16.6	1.00	2	1.1	1.000	63C0A_Trip488	1
01/05/2026 18:01:26	52.385246	4.893362	0	Sudden braking	2.00	2.00	17.0	12.6	2.00	2	2.4	2.000	63C0A_Trip488	1
01/05/2026 18:01:28	52.385267	4.893356	0	Sudden braking	3.10	3.10	11.4	9.5	1.00	2	2.2	1.000	63C0A_Trip488	1
01/05/2026 18:01:29	52.385286	4.893366	358	Sudden braking	2.10	2.10	9.1	7.4	1.00	2	2.2	1.000	63C0A_Trip488	1
01/05/2026 18:02:31	52.389493	4.891477	323	Sudden braking	2.30	2.30	24.1	23.4	1.00	3	5.8	1.000	63C0A_Trip488	1
01/05/2026 18:02:32	52.389530	4.891417	314	Sudden braking	2.20	2.20	23.2	21.2	1.00	3	5.3	1.000	63C0A_Trip488	1
01/05/2026 18:05:28	52.392918	4.868566	259	Sudden braking	2.50	2.50	32.5	32.1	1.00	2	8.2	1.000	63C0A_Trip488	1
01/05/2026 18:05:29	52.392891	4.868454	253	Sudden braking	3.50	3.50	30.1	28.6	1.00	2	5.2	1.000	63C0A_Trip488	1
01/05/2026 18:05:30	52.392861	4.868395	245	Sudden braking	3.90	3.90	27.3	24.7	1.00	2	3.5	1.000	63C0A_Trip488	1
01/05/2026 18:05:34	52.392780	4.868222	236	Sudden braking	3.70	3.70	16.1	17.3	1.00	2	16.6	1.000	63C0A_Trip488	1
01/05/2026 18:05:35	52.392880	4.868041	217	Sudden braking	4.00	4.00	14.3	13.3	1.00	1	4.2	1.000	63C0A_Trip488	1
01/05/2026 18:05:36	52.392863	4.867985	232	Sudden braking	3.30	3.30	12.6	10.0	1.00	1	1.8	1.000	63C0A_Trip488	1
01/05/2026 18:12:01	52.417415	4.826403	22	Sudden braking	2.50	2.50	33.6	32.1	1.00	2	9.3	1.000	63C0A_Trip488	1
01/05/2026 18:12:06	52.417770	4.826670	26	Sudden braking	3.00	3.00	20.2	26.4	1.00	2	6.9	1.000	63C0A_Trip488	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
01/05/2026 18:12:07	52.417821	4.826728	32	Sudden braking	3.70	3.70	18.5	22.7	1.00	2	6.0	1.000	63C0A_Trip488	1
01/05/2026 18:12:08	52.417858	4.826793	43	Sudden braking	3.80	3.80	16.7	18.9	1.00	2	4.8	1.000	63C0A_Trip488	1
01/05/2026 18:12:09	52.417893	4.826834	37	Sudden braking	4.00	4.00	16.7	14.9	1.00	2	3.4	1.000	63C0A_Trip488	1
01/05/2026 18:12:10	52.417924	4.826834	17	Sudden braking	4.40	4.40	16.7	10.5	1.00	2	2.1	1.000	63C0A_Trip488	1
01/05/2026 18:12:20	52.417930	4.826846	4	Sudden braking	2.60	2.60	2.7	4.2	1.00	2	1.0	1.000	63C0A_Trip488	1
01/05/2026 18:29:52	52.433767	4.816305	256	Sudden braking	2.30	2.30	32.9	35.8	1.00	2	9.6	1.000	63C0A_Trip488	1
01/05/2026 18:29:53	52.433751	4.816166	258	Sudden braking	3.30	3.30	31.3	32.5	1.00	2	8.3	1.000	63C0A_Trip488	1
01/05/2026 18:29:54	52.433735	4.816046	259	Sudden braking	4.00	4.00	29.9	28.5	1.00	2	6.7	1.000	63C0A_Trip488	1
01/05/2026 18:29:55	52.433726	4.815949	260	Sudden braking	3.70	3.70	28.6	24.8	1.00	3	5.4	1.000	63C0A_Trip488	1
01/05/2026 18:29:56	52.433734	4.815870	273	Sudden braking	2.40	2.40	27.6	22.4	1.00	3	5.3	1.000	63C0A_Trip488	1
01/05/2026 18:35:41	52.470137	4.805493	357	Sudden braking	2.10	2.10	32.6	36.1	1.00	2	9.3	1.000	63C0A_Trip488	1
01/05/2026 18:35:42	52.470221	4.805488	358	Sudden braking	3.00	3.00	30.0	33.1	1.00	2	7.9	1.000	63C0A_Trip488	1
01/05/2026 18:35:43	52.470292	4.805483	358	Sudden braking	3.70	3.70	27.2	29.4	1.00	1	6.6	1.000	63C0A_Trip488	1
01/05/2026 18:35:44	52.470351	4.805480	358	Sudden braking	4.20	4.20	25.9	25.2	1.00	1	5.5	1.000	63C0A_Trip488	1
01/05/2026 18:35:45	52.470400	4.805477	358	Sudden braking	4.40	4.40	22.6	20.8	1.00	1	4.2	1.000	63C0A_Trip488	1
01/05/2026 18:35:46	52.470438	4.805475	358	Sudden braking	4.60	4.60	20.9	16.2	1.00	1	3.0	1.000	63C0A_Trip488	1
01/05/2026 18:35:47	52.470465	4.805473	358	Sudden braking	4.40	4.40	19.0	11.8	1.00	1	2.0	1.000	63C0A_Trip488	1
01/05/2026 18:38:26	52.484898	4.806185	324	Sudden braking	2.40	2.40	30.9	36.4	1.00	2	10.6	1.000	63C0A_Trip488	1
01/05/2026 18:38:27	52.484974	4.806091	323	Sudden braking	3.90	3.90	27.9	32.5	1.00	2	8.7	1.000	63C0A_Trip488	1
01/05/2026 18:38:28	52.485036	4.806013	322	Sudden braking	5.40	5.40	24.9	27.1	1.00	2	7.1	1.000	63C0A_Trip488	1
01/05/2026 18:38:29	52.485086	4.805948	320	Sudden braking	6.40	6.40	23.4	20.7	1.00	2	5.6	1.000	63C0A_Trip488	1
01/05/2026 18:38:30	52.485122	4.805891	315	Sudden braking	6.10	6.10	21.6	14.6	1.00	2	1.4	1.000	63C0A_Trip488	1
01/05/2026 18:38:31	52.485131	4.805876	315	Sudden braking	4.60	4.60	19.4	10.0	1.00	2	1.5	1.000	63C0A_Trip488	1
01/05/2026 18:38:32	52.485124	4.805857	12	Sudden braking	2.60	2.60	17.0	7.4	1.00	2	1.3	1.000	63C0A_Trip488	1
01/05/2026 18:39:51	52.488379	4.796771	301	Sudden braking	2.10	2.10	33.4	36.8	1.00	2	10.5	1.000	63C0A_Trip488	1
01/05/2026 18:39:52	52.488428	4.796639	302	Sudden braking	2.80	2.80	31.3	34.0	1.00	2	7.6	1.000	63C0A_Trip488	1
01/05/2026 18:39:53	52.488466	4.796545	302	Sudden braking	3.60	3.60	29.1	30.4	1.00	2	8.0	1.000	63C0A_Trip488	1
01/05/2026 18:39:54	52.488508	4.796448	302	Sudden braking	4.30	4.30	26.7	26.1	1.00	2	6.2	1.000	63C0A_Trip488	1
01/05/2026 18:39:55	52.488538	4.796372	301	Sudden braking	4.00	4.00	24.4	22.1	1.00	2	5.3	1.000	63C0A_Trip488	1
01/05/2026 18:39:56	52.488561	4.796304	301	Sudden braking	2.90	2.90	22.2	19.2	1.00	2	4.3	0.999	63C0A_Trip488	1
01/05/2026 18:39:56	52.488580	4.796247	301	Sudden braking	2.10	2.10	20.2	17.1	1.00	2	4.0	1.000	63C0A_Trip488	1
01/05/2026 18:50:59	52.519559	4.707013	323	Sudden braking	2.00	2.00	36.7	36.6	1.00	2	8.4	1.000	63C0A_Trip488	1
01/05/2026 18:51:00	52.519630	4.706969	336	Sudden braking	2.80	2.80	36.3	33.8	1.00	2	8.3	1.000	63C0A_Trip488	1
01/05/2026 18:51:40	52.521934	4.702449	314	Sudden braking	3.60	3.60	31.4	33.7	1.00	2	9.5	1.000	63C0A_Trip488	1
01/05/2026 18:51:41	52.521991	4.702344	311	Sudden braking	4.70	4.70	29.9	29.0	1.00	2	5.4	1.000	63C0A_Trip488	1
01/05/2026 18:51:42	52.522023	4.702284	314	Sudden braking	4.30	4.30	28.9	24.7	1.00	2	1.6	1.000	63C0A_Trip488	1
01/05/2026 18:51:43	52.522033	4.702268	314	Sudden braking	3.20	3.20	27.7	21.5	1.00	2	0.4	1.000	63C0A_Trip488	1
01/05/2026 18:54:08	52.535817	4.695520	354	Sudden braking	2.30	2.30	34.2	33.7	1.00	2	9.4	1.000	63C0A_Trip488	1
01/05/2026 18:54:09	52.535902	4.695508	355	Sudden braking	2.10	2.10	33.3	31.6	1.00	2	6.6	1.000	63C0A_Trip488	1
01/05/2026 18:55:37	52.540099	4.684760	307	Sudden braking	2.80	2.80	32.1	34.5	1.00	2	8.5	1.000	63C0A_Trip488	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
01/05/2026 18:55:38	52.540146	4.684662	310	Sudden braking	3.80	3.80	30.5	30.7	1.00	2	6.9	1.000	63C0A_Trip488	1
01/05/2026 18:55:39	52.540187	4.684585	311	Sudden braking	4.10	4.10	29.0	26.6	1.00	2	4.9	1.000	63C0A_Trip488	1
01/05/2026 18:55:40	52.540218	4.684534	311	Sudden braking	3.30	3.30	27.7	23.3	1.00	2	4.3	1.000	63C0A_Trip488	1
01/05/2026 18:55:41	52.540245	4.684488	314	Sudden braking	2.00	2.00	26.7	21.3	1.00	2	5.0	1.000	63C0A_Trip488	1
01/05/2026 18:56:52	52.541460	4.677203	281	Sudden braking	2.50	2.50	29.3	30.8	1.00	2	7.8	1.000	63C0A_Trip488	1
01/05/2026 18:56:53	52.541471	4.677089	280	Sudden braking	3.10	3.10	27.6	27.7	1.00	2	6.1	1.000	63C0A_Trip488	1
01/05/2026 18:56:54	52.541480	4.677000	280	Sudden braking	3.50	3.50	26.0	24.2	1.00	2	5.0	1.000	63C0A_Trip488	1
01/05/2026 18:56:55	52.541488	4.676926	280	Sudden braking	3.10	3.10	24.8	21.1	1.00	2	4.1	1.000	63C0A_Trip488	1
01/05/2026 18:56:56	52.541495	4.676868	280	Sudden braking	2.00	2.00	23.9	19.1	1.00	2	4.3	1.000	63C0A_Trip488	1
01/05/2026 18:57:14	52.542677	4.675971	311	Sudden braking	2.30	2.30	31.9	32.9	1.00	2	9.0	1.000	63C0A_Trip488	1
01/05/2026 18:57:15	52.542719	4.675857	303	Sudden braking	2.70	2.70	31.0	30.2	1.00	2	7.3	1.000	63C0A_Trip488	1
01/05/2026 18:57:16	52.542759	4.675772	300	Sudden braking	2.60	2.60	30.2	27.6	1.00	2	5.7	1.000	63C0A_Trip488	1
04/05/2026 05:09:36	52.339077	4.950790	239	Sudden braking	2.30	2.30	10.9	10.5	1.00	2	2.0	1.000	602DE_Trip498	1
04/05/2026 05:10:13	52.338504	4.948885	251	Sudden braking	2.60	2.60	11.0	9.7	1.00	2	8.5	1.000	602DE_Trip498	1
04/05/2026 05:17:17	52.347585	4.929561	343	Sudden braking	2.30	2.30	10.6	9.3	1.00	2	2.7	1.000	602DE_Trip498	1
04/05/2026 05:17:18	52.347609	4.929553	345	Sudden braking	2.70	2.70	9.9	6.6	1.00	2	2.4	1.000	602DE_Trip498	1
04/05/2026 05:18:34	52.349168	4.926623	314	Sudden braking	2.60	2.60	14.1	13.1	1.00	2	7.8	1.000	602DE_Trip498	1
04/05/2026 05:18:35	52.349223	4.926552	315	Sudden braking	2.20	2.20	14.2	10.9	1.00	2	3.0	1.000	602DE_Trip498	1
04/05/2026 05:20:56	52.353166	4.920653	324	Sudden braking	3.10	3.10	14.9	17.2	1.00	2	7.3	1.000	602DE_Trip498	1
04/05/2026 05:20:59	52.353246	4.920556	324	Sudden braking	3.50	3.50	12.4	10.1	1.00	2	4.0	1.000	602DE_Trip498	1
04/05/2026 05:21:00	52.353275	4.920521	323	Sudden braking	2.20	2.20	11.2	7.9	1.00	2	2.4	1.000	602DE_Trip498	1
04/05/2026 07:59:40	52.356119	4.807036	343	Sudden braking	2.70	2.70	21.9	20.6	1.00	2	5.9	1.000	604F0_Trip502	1
04/05/2026 07:59:47	52.356415	4.806873	342	Sudden braking	2.40	2.40	16.2	15.4	1.00	2	2.2	1.000	604F0_Trip502	1
04/05/2026 08:00:06	52.356876	4.808523	71	Sudden braking	2.00	2.00	20.4	17.3	1.00	2	5.1	1.000	604F0_Trip502	1
04/05/2026 08:00:14	52.356560	4.808913	153	Sudden braking	2.10	2.10	9.6	11.8	1.00	1	3.3	1.000	604F0_Trip502	1
04/05/2026 08:00:15	52.356533	4.808933	151	Sudden braking	2.50	2.50	9.6	9.3	1.00	1	2.0	1.000	604F0_Trip502	1
04/05/2026 08:00:16	52.356525	4.808960	135	Sudden braking	2.10	2.10	8.9	7.2	1.00	1	1.1	1.000	604F0_Trip502	1
04/05/2026 08:08:39	52.364125	4.852808	90	Sudden braking	2.00	2.00	16.8	17.6	1.00	2	4.3	1.000	604F0_Trip502	1
04/05/2026 08:08:40	52.364124	4.852871	92	Sudden braking	2.00	2.00	16.1	15.6	1.00	2	3.2	1.000	604F0_Trip502	1
04/05/2026 08:08:41	52.364124	4.852919	91	Sudden braking	2.10	2.10	14.4	13.5	1.00	2	2.9	1.000	604F0_Trip502	1
04/05/2026 08:08:42	52.364121	4.852961	95	Sudden braking	2.50	2.50	13.5	11.0	1.00	2	2.8	1.000	604F0_Trip502	1
04/05/2026 08:08:43	52.364111	4.852999	106	Sudden braking	2.40	2.40	12.5	8.6	1.00	2	1.6	1.000	604F0_Trip502	1
04/05/2026 08:11:57	52.366827	4.870975	64	Sudden braking	2.00	2.00	19.9	20.4	1.00	2	6.3	1.000	604F0_Trip502	1
04/05/2026 08:11:58	52.366847	4.871063	64	Sudden braking	2.10	2.10	19.8	18.3	1.00	2	3.2	1.000	604F0_Trip502	1
04/05/2026 08:12:08	52.367080	4.871742	64	Sudden braking	3.00	3.00	16.4	17.9	1.00	2	3.7	1.000	604F0_Trip502	1
04/05/2026 08:12:09	52.367090	4.871795	68	Sudden braking	3.40	3.40	15.3	14.5	1.00	2	2.5	1.000	604F0_Trip502	1
04/05/2026 08:12:10	52.367095	4.871830	74	Sudden braking	2.90	2.90	13.9	11.6	1.00	2	1.5	1.000	604F0_Trip502	1
04/05/2026 08:13:25	52.368205	4.875886	71	Sudden braking	2.10	2.10	13.1	14.1	1.00	2	3.0	1.000	604F0_Trip502	1
04/05/2026 08:13:26	52.368214	4.875929	72	Sudden braking	2.30	2.30	11.5	11.8	1.00	2	2.7	1.000	604F0_Trip502	1
04/05/2026 08:13:27	52.368224	4.875965	69	Sudden braking	2.40	2.40	10.1	9.4	1.00	1	1.8	1.000	604F0_Trip502	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
04/05/2026 08:13:28	52.368232	4.875987	65	Sudden braking	2.40	2.40	9.2	7.0	1.00	2	1.2	1.000	604F0_Trip502	1
04/05/2026 08:13:29	52.368240	4.876000	56	Sudden braking	2.10	2.10	8.2	4.9	1.00	2	2.2	1.000	604F0_Trip502	1
04/05/2026 08:13:59	52.368649	4.877728	70	Sudden braking	2.00	2.00	20.7	22.9	1.00	2	7.1	1.000	604F0_Trip502	1
04/05/2026 08:14:00	52.368664	4.877830	73	Sudden braking	3.40	3.40	18.9	19.5	1.00	2	5.5	1.000	604F0_Trip502	1
04/05/2026 08:14:01	52.368677	4.877908	72	Sudden braking	3.90	3.90	17.2	15.6	1.00	2	2.0	1.000	604F0_Trip502	1
04/05/2026 08:14:02	52.368676	4.877938	79	Sudden braking	3.70	3.70	15.8	11.9	1.00	2	1.3	1.000	604F0_Trip502	1
04/05/2026 08:16:18	52.370156	4.888387	96	Sudden braking	2.10	2.10	11.3	10.1	1.00	2	1.6	1.000	604F0_Trip502	1
04/05/2026 08:18:06	52.372761	4.892528	97	Sudden braking	2.10	2.10	13.7	15.6	1.00	2	3.1	1.000	604F0_Trip502	1
04/05/2026 08:18:07	52.372752	4.892573	101	Sudden braking	2.40	2.40	13.3	13.2	1.00	2	2.8	1.000	604F0_Trip502	1
04/05/2026 08:18:08	52.372747	4.892612	98	Sudden braking	2.30	2.30	12.7	10.9	1.00	2	3.1	1.000	604F0_Trip502	1
04/05/2026 08:18:09	52.372735	4.892652	100	Sudden braking	2.50	2.50	10.8	8.4	1.00	2	1.8	1.000	604F0_Trip502	1
04/05/2026 08:18:10	52.372729	4.892678	102	Sudden braking	2.50	2.50	9.7	5.9	1.00	2	1.6	1.000	604F0_Trip502	1
04/05/2026 08:21:11	52.368515	4.903745	95	Sudden braking	2.00	2.00	10.4	8.6	1.00	2	2.8	1.000	604F0_Trip502	1
04/05/2026 08:22:42	52.368341	4.908166	47	Sudden braking	2.60	2.60	19.1	19.1	1.00	2	4.0	1.000	604F0_Trip502	1
04/05/2026 08:22:43	52.368367	4.908207	44	Sudden braking	3.30	3.30	18.1	15.8	1.00	2	3.9	1.000	604F0_Trip502	1
04/05/2026 08:23:04	52.369159	4.909433	44	Sudden braking	2.00	2.00	19.3	20.4	1.00	2	5.2	1.000	604F0_Trip502	1
04/05/2026 08:23:05	52.369194	4.909485	46	Sudden braking	2.40	2.40	18.1	18.0	1.00	2	4.9	1.000	604F0_Trip502	1
04/05/2026 08:23:06	52.369227	4.909532	46	Sudden braking	2.30	2.30	16.9	15.7	1.00	2	3.0	1.000	604F0_Trip502	1
04/05/2026 08:23:07	52.369242	4.909567	46	Sudden braking	2.00	2.00	15.8	13.7	1.00	2	3.3	1.000	604F0_Trip502	1
04/05/2026 08:23:54	52.370989	4.912339	40	Sudden braking	2.30	2.30	19.1	19.8	1.00	2	5.6	1.000	604F0_Trip502	1
04/05/2026 08:23:55	52.371023	4.912399	40	Sudden braking	2.70	2.70	18.5	17.1	1.00	2	3.5	1.000	604F0_Trip502	1
04/05/2026 14:17:32	52.351243	4.923071	135	Sudden braking	2.30	2.30	16.3	17.2	1.00	2	5.0	1.000	602DE_Trip503	1
04/05/2026 14:17:35	52.351161	4.923169	135	Sudden braking	2.50	2.50	13.2	12.1	1.00	1	2.5	1.000	602DE_Trip503	1
04/05/2026 14:17:42	52.350964	4.923522	135	Sudden braking	2.10	2.10	9.2	9.0	1.00	1	4.8	1.000	602DE_Trip503	1
04/05/2026 14:22:04	52.347621	4.928937	155	Sudden braking	2.10	2.10	8.6	6.5	1.00	2	1.5	1.000	602DE_Trip503	1
04/05/2026 14:30:55	52.340324	4.952179	124	Sudden braking	3.60	3.60	16.4	15.0	1.00	1	5.7	0.999	602DE_Trip503	1
04/05/2026 14:30:59	52.340312	4.952031	140	Sudden braking	3.30	3.30	7.2	8.5	1.00	1	8.7	1.000	602DE_Trip503	1
04/05/2026 14:31:00	52.340273	4.952142	142	Sudden braking	3.20	3.20	5.3	5.3	1.00	1	15.3	1.000	602DE_Trip503	1
04/05/2026 16:59:18	52.359525	4.883754	307	Sudden braking	2.50	2.50	13.9	14.8	1.00	2	3.3	1.000	604F0_Trip504	1
04/05/2026 16:59:19	52.359533	4.883708	299	Sudden braking	2.80	2.80	13.5	12.0	1.00	2	2.0	1.000	604F0_Trip504	1
04/05/2026 16:59:20	52.359540	4.883681	297	Sudden braking	3.00	3.00	12.1	9.0	1.00	2	1.6	1.000	604F0_Trip504	1
04/05/2026 16:59:21	52.359547	4.883661	299	Sudden braking	2.40	2.40	11.2	6.6	1.00	2	1.1	1.000	604F0_Trip504	1
04/05/2026 17:00:54	52.359532	4.877926	246	Sudden braking	2.50	2.50	17.2	18.0	1.00	2	3.9	1.000	604F0_Trip504	1
04/05/2026 17:00:55	52.359518	4.877873	246	Sudden braking	3.10	3.10	15.0	14.9	1.00	2	2.9	1.000	604F0_Trip504	1
04/05/2026 17:00:56	52.359504	4.877839	246	Sudden braking	3.80	3.80	13.9	11.1	1.00	2	1.8	1.000	604F0_Trip504	1
04/05/2026 17:00:57	52.359496	4.877817	246	Sudden braking	3.80	3.80	12.7	7.3	1.00	2	1.4	1.000	604F0_Trip504	1
04/05/2026 17:05:18	52.354987	4.855982	252	Sudden braking	2.60	2.60	17.6	18.6	1.00	2	4.1	1.000	604F0_Trip504	1
04/05/2026 17:05:19	52.354976	4.855925	253	Sudden braking	3.00	3.00	16.8	15.6	1.00	2	2.7	1.000	604F0_Trip504	1
04/05/2026 17:05:20	52.354969	4.855887	253	Sudden braking	3.80	3.80	15.9	11.8	1.00	2	1.9	1.000	604F0_Trip504	1
04/05/2026 17:05:21	52.354964	4.855861	253	Sudden braking	4.00	4.00	14.7	7.8	1.00	2	1.5	1.000	604F0_Trip504	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
04/05/2026 17:08:31	52.355715	4.844583	269	Sudden braking	2.00	2.00	20.1	19.7	1.00	2	4.9	1.000	604F0_Trip504	1
04/05/2026 17:08:32	52.355715	4.844510	270	Sudden braking	2.10	2.10	19.4	17.6	1.00	2	4.0	1.000	604F0_Trip504	1
04/05/2026 17:11:35	52.356339	4.827644	274	Sudden braking	2.30	2.30	16.8	17.5	1.00	2	4.0	1.000	604F0_Trip504	1
04/05/2026 17:11:36	52.356353	4.827589	283	Sudden braking	2.70	2.70	14.9	14.8	1.00	2	3.5	1.000	604F0_Trip504	1
04/05/2026 17:11:37	52.356371	4.827548	294	Sudden braking	3.20	3.20	14.0	11.6	1.00	2	2.0	1.000	604F0_Trip504	1
04/05/2026 17:11:38	52.356381	4.827522	297	Sudden braking	3.40	3.40	13.0	8.2	1.00	2	1.9	1.000	604F0_Trip504	1
04/05/2026 17:14:49	52.354351	4.810777	256	Sudden braking	2.00	2.00	17.1	16.8	1.00	2	3.9	1.000	604F0_Trip504	1
04/05/2026 17:14:50	52.354347	4.810720	261	Sudden braking	2.10	2.10	16.3	14.7	1.00	2	3.6	1.000	604F0_Trip504	1
04/05/2026 17:14:51	52.354352	4.810668	270	Sudden braking	2.60	2.60	15.4	12.1	1.00	2	2.9	1.000	604F0_Trip504	1
04/05/2026 17:14:52	52.354366	4.810631	284	Sudden braking	2.60	2.60	14.3	9.5	1.00	2	2.0	1.000	604F0_Trip504	1
04/05/2026 17:15:35	52.353718	4.807449	248	Sudden braking	2.00	2.00	19.0	19.2	1.00	2	4.3	1.000	604F0_Trip504	1
04/05/2026 17:15:36	52.353702	4.807392	248	Sudden braking	2.00	2.00	17.6	17.2	1.00	2	3.9	1.000	604F0_Trip504	1
04/05/2026 17:16:14	52.354788	4.806285	263	Sudden braking	2.00	2.00	9.3	9.5	1.00	2	2.7	1.000	604F0_Trip504	1
04/05/2026 17:16:15	52.354784	4.806246	259	Sudden braking	2.30	2.30	9.1	7.2	1.00	2	1.7	1.000	604F0_Trip504	1
04/05/2026 17:17:15	52.354466	4.805797	225	Sudden braking	3.20	3.20	9.6	15.2	1.00	2	3.8	1.000	604F0_Trip504	1
04/05/2026 17:17:16	52.354495	4.805827	213	Sudden braking	5.60	5.60	7.5	9.6	1.00	2	15.5	1.000	604F0_Trip504	1
04/05/2026 17:17:17	52.354625	4.805910	336	Sudden braking	3.90	3.90	6.0	5.7	1.00	2	4.2	1.000	604F0_Trip504	1
05/05/2026 05:04:51	52.542555	4.675478	63	Sudden braking	2.09	2.09	26.3	26.7	1.00	3	8.6	1.004	63C0A_Trip506	1
05/05/2026 05:04:52	52.542616	4.675557	45	Sudden braking	2.40	2.40	23.3	24.3	1.00	3	6.4	1.001	63C0A_Trip506	1
05/05/2026 05:04:53	52.542666	4.675603	34	Sudden braking	2.60	2.60	22.8	21.7	1.00	3	5.3	0.999	63C0A_Trip506	1
05/05/2026 05:04:54	52.542707	4.675642	31	Sudden braking	2.51	2.51	20.8	19.2	1.00	3	4.3	0.997	63C0A_Trip506	1
05/05/2026 05:07:41	52.536429	4.694515	83	Sudden braking	2.30	2.30	32.6	33.5	1.00	3	8.8	1.000	63C0A_Trip506	1
05/05/2026 05:07:42	52.536432	4.694645	89	Sudden braking	2.60	2.60	31.4	30.9	1.00	3	7.7	1.000	63C0A_Trip506	1
05/05/2026 05:07:43	52.536405	4.694749	110	Sudden braking	2.30	2.30	30.1	28.6	1.00	3	7.3	1.000	63C0A_Trip506	1
05/05/2026 05:10:13	52.522465	4.702500	131	Sudden braking	2.20	2.20	31.9	33.6	1.00	3	9.7	1.000	63C0A_Trip506	1
05/05/2026 05:10:14	52.522407	4.702607	132	Sudden braking	2.90	2.90	30.2	30.7	1.00	3	7.5	1.000	63C0A_Trip506	1
05/05/2026 05:10:15	52.522362	4.702689	132	Sudden braking	3.00	3.00	28.7	27.7	1.00	3	5.0	1.000	63C0A_Trip506	1
05/05/2026 05:10:16	52.522332	4.702744	133	Sudden braking	2.80	2.80	27.1	24.9	1.00	3	2.5	1.000	63C0A_Trip506	1
05/05/2026 05:10:17	52.522310	4.702748	183	Sudden braking	2.10	2.10	25.6	22.8	1.00	3	21.2	1.000	63C0A_Trip506	1
05/05/2026 05:10:59	52.519900	4.706241	134	Sudden braking	2.40	2.40	33.7	34.9	1.00	2	10.1	1.000	63C0A_Trip506	1
05/05/2026 05:11:00	52.519831	4.706340	140	Sudden braking	2.80	2.80	32.4	32.1	1.00	3	8.0	1.000	63C0A_Trip506	1
05/05/2026 05:11:01	52.519775	4.706414	143	Sudden braking	2.80	2.80	31.1	29.3	1.00	3	6.3	1.000	63C0A_Trip506	1
05/05/2026 05:11:02	52.519730	4.706470	143	Sudden braking	2.20	2.20	30.0	27.1	1.00	3	3.6	1.000	63C0A_Trip506	1
05/05/2026 05:16:05	52.339036	4.939607	318	Sudden braking	2.50	2.50	18.1	16.7	1.00	2	5.1	1.000	602DE_Trip505	1
05/05/2026 05:17:55	52.343069	4.933594	321	Sudden braking	3.00	3.00	15.5	14.5	1.00	3	4.8	1.000	602DE_Trip505	1
05/05/2026 05:17:56	52.343103	4.933549	322	Sudden braking	2.70	2.70	15.1	11.8	1.00	3	4.5	1.000	602DE_Trip505	1
05/05/2026 05:18:11	52.494201	4.764408	99	Sudden braking	2.40	2.40	32.8	35.0	1.00	2	8.6	1.000	63C0A_Trip506	1
05/05/2026 05:18:12	52.494189	4.764534	99	Sudden braking	3.10	3.10	30.9	31.9	1.00	2	7.4	1.000	63C0A_Trip506	1
05/05/2026 05:18:13	52.494180	4.764642	97	Sudden braking	3.40	3.40	28.8	28.5	1.00	2	6.4	1.000	63C0A_Trip506	1
05/05/2026 05:18:14	52.494173	4.764735	97	Sudden braking	3.10	3.10	26.5	25.4	1.00	2	5.3	1.000	63C0A_Trip506	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
05/05/2026 05:18:15	52.494167	4.764812	97	Sudden braking	2.50	2.50	24.1	22.9	1.00	2	5.3	1.000	63C0A_Trip506	1
05/05/2026 05:18:16	52.494162	4.764890	96	Sudden braking	2.10	2.10	21.6	20.8	1.00	2	5.5	1.000	63C0A_Trip506	1
05/05/2026 05:18:17	52.494157	4.764971	96	Sudden braking	2.00	2.00	19.3	18.8	1.00	2	5.0	1.000	63C0A_Trip506	1
05/05/2026 05:18:18	52.494153	4.765045	96	Sudden braking	2.00	2.00	17.1	16.8	1.00	3	3.8	1.000	63C0A_Trip506	1
05/05/2026 05:18:19	52.494149	4.765101	96	Sudden braking	2.10	2.10	15.2	14.7	1.00	3	3.1	1.000	63C0A_Trip506	1
05/05/2026 05:18:20	52.494146	4.765147	96	Sudden braking	2.20	2.20	13.4	12.5	1.00	3	2.5	1.000	63C0A_Trip506	1
05/05/2026 05:19:06	52.493825	4.768212	94	Sudden braking	2.20	2.20	32.5	31.9	1.00	3	8.9	1.000	63C0A_Trip506	1
05/05/2026 05:21:40	52.349504	4.926158	313	Sudden braking	2.10	2.10	12.9	13.9	1.00	2	5.4	1.000	602DE_Trip505	1
05/05/2026 05:21:41	52.349537	4.926099	313	Sudden braking	2.30	2.30	12.0	11.6	1.00	2	1.3	1.000	602DE_Trip505	1
05/05/2026 05:21:42	52.349538	4.926080	306	Sudden braking	2.00	2.00	11.2	9.6	1.00	2	4.0	1.000	602DE_Trip505	1
05/05/2026 05:21:43	52.349570	4.926055	325	Sudden braking	2.00	2.00	10.3	7.6	1.00	2	2.9	1.000	602DE_Trip505	1
05/05/2026 05:22:23	52.350696	4.924308	336	Sudden braking	2.20	2.20	9.0	7.8	1.00	2	6.7	1.000	602DE_Trip505	1
05/05/2026 05:25:37	52.471603	4.805242	178	Sudden braking	2.30	2.30	33.1	35.1	1.00	2	8.6	1.000	63C0A_Trip506	1
05/05/2026 05:25:38	52.471526	4.805248	178	Sudden braking	2.80	2.80	31.3	32.3	1.00	2	7.4	1.000	63C0A_Trip506	1
05/05/2026 05:25:39	52.471459	4.805252	178	Sudden braking	3.20	3.20	29.4	29.1	1.00	2	6.9	1.000	63C0A_Trip506	1
05/05/2026 05:25:40	52.471397	4.805256	178	Sudden braking	3.10	3.10	27.4	26.0	1.00	2	6.2	1.000	63C0A_Trip506	1
05/05/2026 05:25:41	52.471341	4.805259	178	Sudden braking	2.40	2.40	25.3	23.6	1.00	2	5.2	1.000	63C0A_Trip506	1
05/05/2026 05:32:09	52.434047	4.815777	172	Sudden braking	2.00	2.00	34.0	36.7	1.00	3	10.1	1.000	63C0A_Trip506	1
05/05/2026 05:32:10	52.433957	4.815793	173	Sudden braking	3.00	3.00	32.6	33.7	1.00	3	9.0	1.000	63C0A_Trip506	1
05/05/2026 05:32:11	52.433876	4.815804	175	Sudden braking	3.60	3.60	31.3	30.1	1.00	3	7.5	1.000	63C0A_Trip506	1
05/05/2026 05:32:12	52.433809	4.815815	173	Sudden braking	3.30	3.30	30.2	26.8	1.00	3	6.3	1.000	63C0A_Trip506	1
05/05/2026 05:32:13	52.433753	4.815826	173	Sudden braking	2.20	2.20	29.3	24.6	1.00	3	4.4	1.000	63C0A_Trip506	1
05/05/2026 06:04:12	52.392800	4.875239	91	Sudden braking	2.10	2.10	32.0	30.7	1.00	2	7.8	1.000	63C0A_Trip506	1
05/05/2026 06:04:23	52.392702	4.876563	117	Sudden braking	2.60	2.60	25.4	27.6	1.00	3	7.5	1.000	63C0A_Trip506	1
05/05/2026 06:04:24	52.392671	4.876662	120	Sudden braking	2.70	2.70	23.8	24.9	1.00	2	5.3	1.000	63C0A_Trip506	1
05/05/2026 06:04:25	52.392648	4.876730	125	Sudden braking	2.80	2.80	22.0	22.1	1.00	2	5.3	1.000	63C0A_Trip506	1
05/05/2026 06:04:26	52.392624	4.876797	125	Sudden braking	3.00	3.00	20.1	19.1	1.00	2	5.2	1.000	63C0A_Trip506	1
05/05/2026 06:04:27	52.392601	4.876863	129	Sudden braking	2.60	2.60	18.2	16.5	1.00	2	5.0	1.000	63C0A_Trip506	1
05/05/2026 06:04:28	52.392578	4.876926	133	Sudden braking	2.10	2.10	16.7	14.4	1.00	3	3.3	1.000	63C0A_Trip506	1
05/05/2026 06:05:09	52.391268	4.880708	105	Sudden braking	2.20	2.20	32.7	32.1	1.00	2	7.5	1.000	63C0A_Trip506	1
05/05/2026 06:05:10	52.391276	4.880818	102	Sudden braking	2.00	2.00	32.1	30.1	1.00	2	6.9	1.000	63C0A_Trip506	1
05/05/2026 06:05:41	52.390775	4.884717	128	Sudden braking	2.10	2.10	20.2	22.8	1.00	2	6.2	1.000	63C0A_Trip506	1
05/05/2026 06:05:42	52.390739	4.884787	132	Sudden braking	2.80	2.80	18.3	20.0	1.00	2	4.7	1.000	63C0A_Trip506	1
05/05/2026 06:05:43	52.390711	4.884839	132	Sudden braking	3.20	3.20	16.2	16.8	1.00	2	3.9	1.000	63C0A_Trip506	1
05/05/2026 06:05:44	52.390686	4.884881	134	Sudden braking	3.10	3.10	15.2	13.7	1.00	2	2.7	1.000	63C0A_Trip506	1
05/05/2026 06:05:45	52.390669	4.884910	134	Sudden braking	3.20	3.20	13.9	10.5	1.00	2	2.5	1.000	63C0A_Trip506	1
05/05/2026 06:05:46	52.390653	4.884937	134	Sudden braking	3.20	3.20	12.6	7.3	1.00	2	1.8	1.000	63C0A_Trip506	1
05/05/2026 06:05:47	52.390642	4.884956	134	Sudden braking	2.20	2.20	11.1	5.1	1.00	2	0.2	1.000	63C0A_Trip506	1
05/05/2026 06:08:39	52.382313	4.895171	141	Sudden braking	2.40	2.40	30.6	32.0	1.00	3	8.8	1.000	63C0A_Trip506	1
05/05/2026 06:08:40	52.382251	4.895251	140	Sudden braking	2.70	2.70	28.5	29.3	1.00	2	7.6	1.000	63C0A_Trip506	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
05/05/2026 06:08:41	52.382201	4.895328	140	Sudden braking	2.90	2.90	26.3	26.4	1.00	2	7.2	1.000	63C0A_Trip506	1
05/05/2026 06:08:42	52.382151	4.895396	140	Sudden braking	2.80	2.80	23.9	23.6	1.00	3	5.4	1.000	63C0A_Trip506	1
05/05/2026 06:08:43	52.382114	4.895449	139	Sudden braking	2.60	2.60	21.4	21.0	1.00	3	5.4	1.000	63C0A_Trip506	1
05/05/2026 06:08:44	52.382078	4.895501	139	Sudden braking	2.50	2.50	18.9	18.5	1.00	3	4.9	1.000	63C0A_Trip506	1
05/05/2026 06:08:45	52.382045	4.895549	139	Sudden braking	2.40	2.40	16.6	16.1	1.00	3	4.0	1.000	63C0A_Trip506	1
05/05/2026 06:08:46	52.382017	4.895585	140	Sudden braking	2.40	2.40	14.4	13.7	1.00	3	3.0	1.000	63C0A_Trip506	1
05/05/2026 06:08:47	52.381996	4.895614	140	Sudden braking	2.50	2.50	12.4	11.2	1.00	3	2.5	1.000	63C0A_Trip506	1
05/05/2026 06:08:48	52.381978	4.895637	142	Sudden braking	2.20	2.20	10.6	9.0	1.00	3	2.1	1.000	63C0A_Trip506	1
05/05/2026 06:09:28	52.380364	4.898569	123	Sudden braking	2.30	2.30	26.5	26.9	1.00	2	7.5	1.000	63C0A_Trip506	1
05/05/2026 06:09:29	52.380324	4.898658	124	Sudden braking	2.40	2.40	25.0	24.5	1.00	2	6.1	1.000	63C0A_Trip506	1
05/05/2026 06:09:30	52.380304	4.898741	113	Sudden braking	2.10	2.10	23.5	22.4	1.00	2	5.2	1.000	63C0A_Trip506	1
05/05/2026 06:11:19	52.377883	4.909660	102	Sudden braking	2.20	2.20	31.1	33.2	1.00	2	8.8	1.000	63C0A_Trip506	1
05/05/2026 06:11:20	52.377870	4.909788	104	Sudden braking	3.10	3.10	29.6	30.1	1.00	2	7.7	1.000	63C0A_Trip506	1
05/05/2026 06:11:21	52.377854	4.909899	106	Sudden braking	3.30	3.30	28.3	26.8	1.00	3	5.7	1.000	63C0A_Trip506	1
05/05/2026 06:11:22	52.377827	4.909970	118	Sudden braking	2.90	2.90	27.2	23.9	1.00	2	5.3	1.000	63C0A_Trip506	1
05/05/2026 06:11:23	52.377783	4.909997	131	Sudden braking	2.10	2.10	26.3	21.8	1.00	2	5.7	1.000	63C0A_Trip506	1
05/05/2026 06:11:48	52.375894	4.910546	180	Sudden braking	2.70	2.70	24.4	25.6	1.00	3	5.6	1.000	63C0A_Trip506	1
05/05/2026 06:11:49	52.375843	4.910536	185	Sudden braking	3.80	3.80	22.4	21.8	1.00	3	4.7	1.000	63C0A_Trip506	1
05/05/2026 06:11:50	52.375802	4.910525	187	Sudden braking	4.20	4.20	20.4	17.6	1.00	3	3.6	1.000	63C0A_Trip506	1
05/05/2026 06:11:53	52.375770	4.910555	119	Sudden braking	2.30	2.30	15.8	11.9	1.00	3	2.4	1.000	63C0A_Trip506	1
05/05/2026 06:12:37	52.376678	4.913929	99	Sudden braking	2.40	2.40	25.0	24.1	1.00	3	6.0	1.000	63C0A_Trip506	1
05/05/2026 06:12:38	52.376665	4.914014	97	Sudden braking	2.00	2.00	24.3	22.1	1.00	3	5.3	1.000	63C0A_Trip506	1
05/05/2026 06:13:20	52.374834	4.915051	158	Sudden braking	2.20	2.20	16.3	17.1	1.00	1	3.9	1.000	63C0A_Trip506	1
05/05/2026 06:13:21	52.374801	4.915071	161	Sudden braking	2.80	2.80	15.0	14.3	1.00	1	2.5	1.000	63C0A_Trip506	1
05/05/2026 06:13:22	52.374784	4.915094	155	Sudden braking	2.70	2.70	13.9	11.6	1.00	1	2.6	1.000	63C0A_Trip506	1
06/05/2026 08:11:43	52.334784	4.954701	221	Sudden braking	2.50	2.50	14.1	15.5	1.00	2	5.2	1.000	602DE_Trip512	1
06/05/2026 08:11:44	52.334739	4.954683	212	Sudden braking	2.70	2.70	13.2	12.8	1.00	2	1.1	1.000	602DE_Trip512	1
06/05/2026 08:11:45	52.334735	4.954698	200	Sudden braking	2.70	2.70	12.6	10.1	1.00	2	3.1	1.000	602DE_Trip512	1
06/05/2026 08:11:46	52.334709	4.954681	197	Sudden braking	2.60	2.60	12.2	7.5	1.00	2	3.1	1.000	602DE_Trip512	1
06/05/2026 08:14:09	52.331099	4.945854	246	Sudden braking	2.20	2.20	11.2	10.7	1.00	2	4.9	1.000	602DE_Trip512	1
06/05/2026 08:14:49	52.330209	4.943374	243	Sudden braking	2.10	2.10	13.9	12.9	1.00	2	3.9	1.000	602DE_Trip512	1
06/05/2026 08:15:03	52.329946	4.942532	254	Sudden braking	2.00	2.00	9.6	7.9	1.00	2	3.9	1.000	602DE_Trip512	1
06/05/2026 08:15:44	52.329578	4.939619	260	Sudden braking	2.00	2.00	12.9	13.4	1.00	2	6.1	1.000	602DE_Trip512	1
06/05/2026 08:15:45	52.329607	4.939542	275	Sudden braking	2.10	2.10	13.1	11.3	1.00	2	2.1	1.000	602DE_Trip512	1
06/05/2026 08:16:08	52.329821	4.937768	289	Sudden braking	2.40	2.40	12.1	12.3	1.00	2	2.8	1.000	602DE_Trip512	1
06/05/2026 08:16:09	52.329836	4.937734	293	Sudden braking	2.50	2.50	11.5	9.8	1.00	2	2.6	1.000	602DE_Trip512	1
06/05/2026 08:16:10	52.329848	4.937702	301	Sudden braking	2.00	2.00	10.7	7.8	1.00	2	2.8	1.000	602DE_Trip512	1
06/05/2026 08:16:29	52.330036	4.936087	270	Sudden braking	2.40	2.40	16.4	16.8	1.00	2	7.2	1.000	602DE_Trip512	1
06/05/2026 08:16:30	52.330029	4.935981	270	Sudden braking	2.50	2.50	15.7	14.3	1.00	2	1.4	1.000	602DE_Trip512	1
06/05/2026 08:16:56	52.330246	4.934196	282	Sudden braking	2.00	2.00	16.6	18.1	1.00	2	5.5	1.000	602DE_Trip512	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
06/05/2026 08:16:57	52.330259	4.934118	286	Sudden braking	2.30	2.30	16.6	15.8	1.00	2	8.4	1.000	602DE_Trip512	1
07/05/2026 09:00:04	52.317869	4.885779	72	Sudden braking	2.60	2.60	12.4	13.1	1.00	3	4.0	1.001	602CA_Trip523	1
07/05/2026 09:00:05	52.317873	4.885837	90	Sudden braking	2.90	2.90	11.8	10.3	0.96	3	2.7	0.965	602CA_Trip523	1
07/05/2026 09:00:06	52.317869	4.885877	110	Sudden braking	2.14	2.14	11.8	8.1	1.03	3	1.5	1.027	602CA_Trip523	1
07/05/2026 09:04:42	52.324630	4.894770	18	Sudden braking	2.10	2.10	14.4	15.7	1.00	2	4.9	0.998	602CA_Trip523	1
07/05/2026 09:04:43	52.324673	4.894789	17	Sudden braking	2.97	2.97	12.6	12.8	0.98	2	3.8	0.978	602CA_Trip523	1
07/05/2026 09:04:44	52.324706	4.894803	16	Sudden braking	3.18	3.18	11.8	9.6	1.01	2	2.6	1.006	602CA_Trip523	1
07/05/2026 09:04:45	52.324728	4.894817	14	Sudden braking	3.17	3.17	9.7	6.4	1.01	2	1.3	1.009	602CA_Trip523	1
07/05/2026 09:04:46	52.324738	4.894826	21	Sudden braking	2.76	2.76	7.6	3.6	1.01	2	0.8	1.013	602CA_Trip523	1
07/05/2026 09:09:46	52.332369	4.897595	351	Sudden braking	2.27	2.27	10.9	10.5	1.01	2	3.2	1.013	602CA_Trip523	1
07/05/2026 09:09:47	52.332397	4.897589	349	Sudden braking	2.54	2.54	9.5	8.0	0.98	2	2.4	0.983	602CA_Trip523	1
07/05/2026 09:09:48	52.332418	4.897577	350	Sudden braking	2.14	2.14	8.3	5.8	1.03	2	1.3	1.029	602CA_Trip523	1
07/05/2026 09:17:25	52.347018	4.912004	344	Sudden braking	2.13	2.13	8.8	8.9	1.03	1	2.6	1.032	602CA_Trip523	1
07/05/2026 09:17:26	52.347041	4.911995	348	Sudden braking	2.52	2.52	6.9	6.4	0.99	1	1.7	0.992	602CA_Trip523	1
07/05/2026 09:17:27	52.347056	4.911998	352	Sudden braking	2.32	2.32	4.8	4.1	0.99	1	1.0	0.993	602CA_Trip523	1
07/05/2026 09:23:50	52.359849	4.908535	76	Sudden braking	2.19	2.19	7.2	8.7	1.01	2	3.5	1.006	602CA_Trip523	1
07/05/2026 09:23:51	52.359867	4.908577	79	Sudden braking	2.40	2.40	5.9	6.3	1.00	2	1.6	0.998	602CA_Trip523	1
07/05/2026 09:23:52	52.359880	4.908589	82	Sudden braking	2.53	2.53	4.7	3.8	0.99	2	0.8	0.990	602CA_Trip523	1
07/05/2026 09:24:42	52.360218	4.908836	338	Sudden braking	2.21	2.21	9.3	11.1	0.99	2	3.4	0.994	602CA_Trip523	1
07/05/2026 09:24:43	52.360245	4.908813	336	Sudden braking	2.48	2.48	9.3	8.6	1.01	2	2.4	1.009	602CA_Trip523	1
07/05/2026 09:24:44	52.360264	4.908795	326	Sudden braking	2.74	2.74	7.0	5.9	0.98	2	1.8	0.984	602CA_Trip523	1
07/05/2026 09:24:45	52.360278	4.908782	322	Sudden braking	2.09	2.09	7.0	3.8	1.01	2	0.4	1.006	602CA_Trip523	1
07/05/2026 09:26:14	52.364143	4.906457	342	Sudden braking	2.35	2.35	9.9	10.2	1.02	2	3.0	1.023	602CA_Trip523	1
07/05/2026 09:26:15	52.364168	4.906444	339	Sudden braking	2.87	2.87	7.7	7.5	0.94	2	2.6	0.941	602CA_Trip523	1
07/05/2026 09:26:16	52.364190	4.906430	342	Sudden braking	2.18	2.18	7.7	5.3	1.01	2	1.9	1.008	602CA_Trip523	1
07/05/2026 09:27:12	52.366080	4.905136	342	Sudden braking	2.24	2.24	15.8	15.6	0.94	2	6.3	0.936	602CA_Trip523	1
07/05/2026 09:27:13	52.366137	4.905143	345	Sudden braking	2.00	2.00	15.8	13.5	1.05	2	5.1	1.049	602CA_Trip523	1
07/05/2026 09:31:10	52.371023	4.914921	70	Sudden braking	2.37	2.37	15.0	15.6	1.01	1	4.4	1.011	602CA_Trip523	1
07/05/2026 09:31:11	52.371041	4.914979	81	Sudden braking	3.01	3.01	11.9	12.6	1.00	1	4.4	0.996	602CA_Trip523	1
07/05/2026 09:31:12	52.371049	4.915043	86	Sudden braking	3.24	3.24	9.8	9.4	0.99	1	2.3	0.988	602CA_Trip523	1
07/05/2026 09:31:13	52.371049	4.915076	89	Sudden braking	3.08	3.08	8.9	6.3	1.00	1	0.9	1.005	602CA_Trip523	1
07/05/2026 09:31:14	52.371049	4.915090	99	Sudden braking	2.47	2.47	7.7	3.8	1.01	1	0.2	1.013	602CA_Trip523	1
07/05/2026 09:47:47	52.354300	4.810069	164	Sudden braking	2.30	2.30	14.2	13.2	1.00	2	2.4	1.000	604F0_Trip524	1
07/05/2026 09:47:48	52.354279	4.810075	165	Sudden braking	2.80	2.80	13.4	10.4	1.00	2	1.8	1.000	604F0_Trip524	1
07/05/2026 09:47:49	52.354264	4.810085	167	Sudden braking	3.10	3.10	11.3	7.3	1.00	1	1.4	1.000	604F0_Trip524	1
07/05/2026 09:52:40	52.356209	4.836421	82	Sudden braking	2.40	2.40	13.8	13.6	1.00	1	4.4	1.000	604F0_Trip524	1
07/05/2026 09:52:41	52.356196	4.836482	96	Sudden braking	3.10	3.10	13.3	10.5	1.00	1	2.3	1.000	604F0_Trip524	1
07/05/2026 09:55:09	52.355704	4.847624	91	Sudden braking	2.00	2.00	21.2	20.2	1.00	2	4.8	1.000	604F0_Trip524	1
07/05/2026 09:56:23	52.354811	4.853251	99	Sudden braking	2.10	2.10	17.2	15.8	1.00	2	3.7	1.000	604F0_Trip524	1
07/05/2026 09:56:45	52.354776	4.855118	72	Sudden braking	2.10	2.10	15.1	16.0	1.00	2	3.4	1.000	604F0_Trip524	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
07/05/2026 09:56:46	52.354787	4.855165	69	Sudden braking	2.20	2.20	14.3	13.8	1.00	2	2.4	1.000	604F0_Trip524	1
07/05/2026 09:56:47	52.354796	4.855196	62	Sudden braking	2.30	2.30	13.4	11.5	1.00	2	2.6	1.000	604F0_Trip524	1
07/05/2026 09:56:48	52.354807	4.855230	62	Sudden braking	2.50	2.50	12.3	9.0	1.00	2	1.7	1.000	604F0_Trip524	1
07/05/2026 09:56:49	52.354814	4.855251	62	Sudden braking	2.60	2.60	11.3	6.4	1.00	2	1.2	1.000	604F0_Trip524	1
07/05/2026 10:02:18	52.361590	4.881635	59	Sudden braking	2.40	2.40	17.9	16.9	1.00	2	4.2	1.000	604F0_Trip524	1
07/05/2026 10:02:19	52.361615	4.881683	54	Sudden braking	2.70	2.70	17.1	14.2	1.00	2	3.0	1.000	604F0_Trip524	1
07/05/2026 10:02:20	52.361637	4.881708	45	Sudden braking	3.20	3.20	16.1	11.0	1.00	2	2.0	1.000	604F0_Trip524	1
07/05/2026 10:04:54	52.359628	4.890037	113	Sudden braking	2.10	2.10	16.9	17.8	1.00	2	3.9	1.000	604F0_Trip524	1
07/05/2026 10:04:55	52.359616	4.890092	113	Sudden braking	2.30	2.30	15.3	15.5	1.00	2	3.6	1.000	604F0_Trip524	1
07/05/2026 10:04:56	52.359603	4.890141	113	Sudden braking	2.20	2.20	13.7	13.3	1.00	2	2.5	1.000	604F0_Trip524	1
07/05/2026 10:04:57	52.359600	4.890177	109	Sudden braking	2.20	2.20	12.2	11.1	1.00	2	2.4	1.000	604F0_Trip524	1
07/05/2026 10:04:58	52.359593	4.890210	112	Sudden braking	2.00	2.00	10.7	9.1	1.00	2	1.6	1.000	604F0_Trip524	1
07/05/2026 10:10:25	52.366146	4.911648	32	Sudden braking	2.20	2.20	18.2	20.3	1.00	2	4.4	1.000	604F0_Trip524	1
07/05/2026 10:10:26	52.366178	4.911689	34	Sudden braking	2.60	2.60	16.5	17.7	1.00	2	3.3	1.000	604F0_Trip524	1
07/05/2026 10:10:27	52.366198	4.911724	30	Sudden braking	2.60	2.60	14.6	15.1	1.00	2	3.3	1.000	604F0_Trip524	1
07/05/2026 10:10:28	52.366214	4.911765	30	Sudden braking	2.60	2.60	13.6	12.5	1.00	2	3.4	1.000	604F0_Trip524	1
07/05/2026 10:10:29	52.366243	4.911779	30	Sudden braking	2.70	2.70	12.5	9.8	1.00	2	1.2	1.000	604F0_Trip524	1
07/05/2026 10:10:30	52.366253	4.911780	30	Sudden braking	2.70	2.70	11.2	7.1	1.00	2	1.1	1.000	604F0_Trip524	1
07/05/2026 10:10:31	52.366250	4.911765	30	Sudden braking	2.40	2.40	8.8	4.7	1.00	2	2.0	1.000	604F0_Trip524	1
07/05/2026 10:11:48	52.367831	4.913216	30	Sudden braking	2.20	2.20	11.9	11.7	1.00	2	2.9	1.000	604F0_Trip524	1
07/05/2026 10:11:49	52.367856	4.913231	30	Sudden braking	2.10	2.10	10.7	9.6	1.00	2	1.5	1.000	604F0_Trip524	1
07/05/2026 10:13:55	52.371002	4.915056	76	Sudden braking	2.30	2.30	14.5	12.6	1.00	2	2.7	1.000	604F0_Trip524	1
07/05/2026 10:13:56	52.371001	4.915095	84	Sudden braking	2.20	2.20	13.8	10.4	1.00	2	2.0	1.000	604F0_Trip524	1
07/05/2026 13:26:16	52.355451	4.919267	154	Sudden braking	2.30	2.30	16.1	15.4	1.00	2	5.6	1.000	602DE_Trip527	1
07/05/2026 13:29:00	52.350112	4.924792	141	Sudden braking	2.10	2.10	12.3	11.9	1.00	2	2.3	1.000	602DE_Trip527	1
07/05/2026 13:29:01	52.350096	4.924814	146	Sudden braking	2.80	2.80	11.8	9.1	1.00	2	2.0	1.000	602DE_Trip527	1
07/05/2026 13:30:16	52.348392	4.927805	135	Sudden braking	2.20	2.20	14.5	14.1	1.00	2	4.7	1.000	602DE_Trip527	1
07/05/2026 13:30:17	52.348363	4.927856	134	Sudden braking	2.30	2.30	14.5	11.8	1.00	2	1.0	1.000	602DE_Trip527	1
07/05/2026 13:38:03	52.341541	4.949775	147	Sudden braking	2.40	2.40	14.8	14.4	1.00	2	6.8	1.000	602DE_Trip527	1
07/05/2026 13:38:47	52.340228	4.952310	131	Sudden braking	2.10	2.10	21.9	22.9	1.00	2	7.3	1.000	602DE_Trip527	1
07/05/2026 13:38:51	52.340180	4.952396	133	Sudden braking	3.90	3.90	14.4	16.2	1.00	2	3.6	1.000	602DE_Trip527	1
07/05/2026 13:38:52	52.340159	4.952434	133	Sudden braking	4.60	4.60	12.3	11.6	1.00	2	2.1	1.000	602DE_Trip527	1
07/05/2026 15:21:28	52.375596	4.915096	13	Sudden braking	2.80	2.80	23.8	23.2	1.00	3	6.3	1.000	63C0A_Trip537	1
07/05/2026 15:21:29	52.375653	4.915096	13	Sudden braking	2.00	2.00	23.6	21.2	1.00	3	1.1	1.000	63C0A_Trip537	1
07/05/2026 15:21:49	52.376548	4.914024	347	Sudden braking	2.20	2.20	22.4	24.2	1.00	3	6.5	1.000	63C0A_Trip537	1
07/05/2026 15:21:50	52.376607	4.914017	352	Sudden braking	3.00	3.00	21.8	21.2	1.00	3	4.0	1.000	63C0A_Trip537	1
07/05/2026 15:21:51	52.376642	4.914027	359	Sudden braking	2.80	2.80	21.4	18.4	1.00	3	3.1	1.000	63C0A_Trip537	1
07/05/2026 15:22:22	52.376184	4.910972	242	Sudden braking	2.50	2.50	18.0	21.4	1.00	2	5.6	1.000	63C0A_Trip537	1
07/05/2026 15:22:23	52.376156	4.910905	239	Sudden braking	3.70	3.70	16.6	17.7	1.00	3	3.1	1.000	63C0A_Trip537	1
07/05/2026 15:22:24	52.376144	4.910863	240	Sudden braking	4.10	4.10	15.5	13.6	1.00	3	1.6	1.000	63C0A_Trip537	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
07/05/2026 15:22:27	52.376129	4.910818	240	Sudden braking	2.80	2.80	10.2	7.1	1.00	3	1.9	1.000	63C0A_Trip537	1
07/05/2026 15:22:55	52.375338	4.909917	246	Sudden braking	2.90	2.90	21.0	20.6	1.00	2	4.7	1.000	63C0A_Trip537	1
07/05/2026 15:22:56	52.375323	4.909853	250	Sudden braking	2.90	2.90	19.2	17.7	1.00	2	3.0	1.000	63C0A_Trip537	1
07/05/2026 15:22:57	52.375331	4.909811	256	Sudden braking	3.20	3.20	18.4	14.5	1.00	2	1.6	1.000	63C0A_Trip537	1
07/05/2026 15:23:47	52.375636	4.908027	296	Sudden braking	2.40	2.40	25.0	26.5	1.00	3	5.8	1.000	63C0A_Trip537	1
07/05/2026 15:23:48	52.375660	4.907952	296	Sudden braking	3.00	3.00	24.3	23.5	1.00	3	5.4	1.000	63C0A_Trip537	1
07/05/2026 15:23:49	52.375674	4.907876	296	Sudden braking	2.70	2.70	23.6	20.8	1.00	3	2.3	1.000	63C0A_Trip537	1
07/05/2026 15:24:01	52.376399	4.907705	348	Sudden braking	3.20	3.20	21.9	22.5	1.00	4	6.3	1.000	63C0A_Trip537	1
07/05/2026 15:24:02	52.376455	4.907708	348	Sudden braking	3.40	3.40	21.4	19.1	1.00	4	2.8	1.000	63C0A_Trip537	1
07/05/2026 15:24:03	52.376480	4.907699	348	Sudden braking	2.40	2.40	21.0	16.7	1.00	3	2.7	1.000	63C0A_Trip537	1
07/05/2026 15:24:24	52.376513	4.910100	88	Sudden braking	2.30	2.30	24.0	25.2	1.00	3	5.3	1.000	63C0A_Trip537	1
07/05/2026 15:24:25	52.376510	4.910179	88	Sudden braking	2.90	2.90	22.5	22.3	1.00	2	5.9	1.000	63C0A_Trip537	1
07/05/2026 15:24:26	52.376512	4.910265	88	Sudden braking	2.80	2.80	21.1	19.5	1.00	2	2.3	1.000	63C0A_Trip537	1
07/05/2026 15:24:27	52.376513	4.910300	45	Sudden braking	2.30	2.30	19.9	17.2	1.00	3	1.6	1.000	63C0A_Trip537	1
07/05/2026 15:26:31	52.379940	4.900538	301	Sudden braking	2.20	2.20	21.4	26.1	1.00	2	8.1	1.000	63C0A_Trip537	1
07/05/2026 15:26:32	52.379977	4.900435	301	Sudden braking	3.70	3.70	19.9	22.4	1.00	3	5.2	1.000	63C0A_Trip537	1
07/05/2026 15:26:33	52.380001	4.900369	301	Sudden braking	4.60	4.60	18.6	17.8	1.00	3	3.5	1.000	63C0A_Trip537	1
07/05/2026 15:26:34	52.380017	4.900325	301	Sudden braking	4.60	4.60	17.3	13.2	1.00	4	1.3	1.000	63C0A_Trip537	1
07/05/2026 15:26:35	52.380023	4.900308	301	Sudden braking	3.30	3.30	16.2	9.9	1.00	4	1.0	1.000	63C0A_Trip537	1
07/05/2026 15:27:43	52.382931	4.893991	275	Sudden braking	2.10	2.10	31.5	33.6	1.00	2	7.8	1.000	63C0A_Trip537	1
07/05/2026 15:27:44	52.382929	4.893876	269	Sudden braking	2.70	2.70	29.5	30.9	1.00	2	7.7	1.000	63C0A_Trip537	1
07/05/2026 15:27:45	52.382927	4.893762	267	Sudden braking	3.20	3.20	27.4	27.7	1.00	2	7.0	1.000	63C0A_Trip537	1
07/05/2026 15:27:46	52.382923	4.893659	269	Sudden braking	3.10	3.10	25.2	24.6	1.00	2	5.8	1.000	63C0A_Trip537	1
07/05/2026 15:27:47	52.382924	4.893573	275	Sudden braking	2.90	2.90	23.1	21.7	1.00	2	4.8	1.000	63C0A_Trip537	1
07/05/2026 15:27:48	52.382932	4.893503	282	Sudden braking	2.80	2.80	21.1	18.9	1.00	2	6.3	1.000	63C0A_Trip537	1
07/05/2026 15:27:49	52.382956	4.893419	293	Sudden braking	2.10	2.10	19.2	16.8	1.00	2	5.2	1.000	63C0A_Trip537	1
07/05/2026 15:27:56	52.383198	4.893265	324	Sudden braking	2.00	2.00	10.7	8.8	1.00	3	1.8	1.000	63C0A_Trip537	1
07/05/2026 15:28:22	52.384821	4.893254	13	Sudden braking	2.10	2.10	28.9	31.0	1.00	2	7.8	1.000	63C0A_Trip537	1
07/05/2026 15:28:23	52.384889	4.893277	11	Sudden braking	2.70	2.70	26.7	28.3	1.00	2	7.6	1.000	63C0A_Trip537	1
07/05/2026 15:28:24	52.384957	4.893290	7	Sudden braking	3.10	3.10	24.4	25.2	1.00	2	6.6	1.000	63C0A_Trip537	1
07/05/2026 15:28:25	52.385017	4.893298	4	Sudden braking	3.20	3.20	21.9	22.0	1.00	2	5.1	1.000	63C0A_Trip537	1
07/05/2026 15:28:26	52.385062	4.893304	4	Sudden braking	3.30	3.30	19.5	18.7	1.00	2	4.1	1.000	63C0A_Trip537	1
07/05/2026 15:28:27	52.385099	4.893310	4	Sudden braking	3.30	3.30	17.1	15.4	1.00	2	3.7	1.000	63C0A_Trip537	1
07/05/2026 15:28:28	52.385132	4.893311	2	Sudden braking	2.70	2.70	14.8	12.7	1.00	2	2.9	1.000	63C0A_Trip537	1
07/05/2026 15:29:27	52.388902	4.891797	345	Sudden braking	2.50	2.50	31.5	36.0	1.00	1	10.4	1.000	63C0A_Trip537	1
07/05/2026 15:29:28	52.388994	4.891762	345	Sudden braking	3.60	3.60	28.8	32.4	1.00	2	8.6	1.000	63C0A_Trip537	1
07/05/2026 15:29:29	52.389069	4.891731	344	Sudden braking	4.20	4.20	25.9	28.2	1.00	2	6.5	1.000	63C0A_Trip537	1
07/05/2026 15:29:30	52.389125	4.891704	344	Sudden braking	4.30	4.30	22.8	23.9	1.00	2	5.3	1.000	63C0A_Trip537	1
07/05/2026 15:29:31	52.389170	4.891684	344	Sudden braking	4.00	4.00	19.5	19.9	1.00	2	5.3	1.000	63C0A_Trip537	1
07/05/2026 15:29:32	52.389216	4.891664	344	Sudden braking	3.50	3.50	18.2	16.4	1.00	2	4.8	1.000	63C0A_Trip537	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
07/05/2026 15:29:33	52.389258	4.891646	343	Sudden braking	3.00	3.00	15.5	13.4	1.00	3	3.4	1.000	63C0A_Trip537	1
07/05/2026 15:29:34	52.389286	4.891627	338	Sudden braking	2.70	2.70	13.8	10.7	1.00	3	2.4	1.000	63C0A_Trip537	1
07/05/2026 15:29:35	52.389306	4.891612	338	Sudden braking	2.50	2.50	12.2	8.2	1.00	3	1.8	1.000	63C0A_Trip537	1
07/05/2026 15:29:36	52.389321	4.891599	338	Sudden braking	2.00	2.00	10.7	6.2	1.00	3	1.6	1.000	63C0A_Trip537	1
07/05/2026 15:30:25	52.390266	4.886482	284	Sudden braking	2.70	2.70	32.0	34.3	1.00	2	8.3	1.000	63C0A_Trip537	1
07/05/2026 15:30:26	52.390285	4.886364	284	Sudden braking	3.30	3.30	30.0	31.0	1.00	3	6.7	1.000	63C0A_Trip537	1
07/05/2026 15:30:27	52.390299	4.886268	285	Sudden braking	3.70	3.70	27.7	27.3	1.00	3	6.1	1.000	63C0A_Trip537	1
07/05/2026 15:30:28	52.390310	4.886181	285	Sudden braking	3.40	3.40	25.2	23.9	1.00	3	5.5	1.000	63C0A_Trip537	1
07/05/2026 15:30:29	52.390320	4.886102	285	Sudden braking	2.70	2.70	22.6	21.2	1.00	3	4.8	1.000	63C0A_Trip537	1
07/05/2026 15:30:30	52.390336	4.886036	289	Sudden braking	2.20	2.20	20.1	19.0	1.00	3	4.7	1.000	63C0A_Trip537	1
07/05/2026 15:30:32	52.390375	4.885919	291	Sudden braking	2.00	2.00	16.4	15.1	1.00	3	4.3	1.000	63C0A_Trip537	1
07/05/2026 15:30:33	52.390393	4.885862	291	Sudden braking	2.40	2.40	14.4	12.7	1.00	3	3.6	1.000	63C0A_Trip537	1
07/05/2026 15:30:34	52.390408	4.885815	294	Sudden braking	2.30	2.30	13.1	10.4	1.00	3	2.0	1.000	63C0A_Trip537	1
07/05/2026 15:31:14	52.391520	4.881295	270	Sudden braking	2.00	2.00	31.0	36.5	1.00	2	9.7	1.000	63C0A_Trip537	1
07/05/2026 15:31:15	52.391487	4.881164	254	Sudden braking	4.20	4.20	28.4	32.3	1.00	2	9.8	1.000	63C0A_Trip537	1
07/05/2026 15:31:16	52.391437	4.881045	241	Sudden braking	5.90	5.90	26.0	26.4	1.00	3	6.2	1.000	63C0A_Trip537	1
07/05/2026 15:31:17	52.391404	4.880971	238	Sudden braking	6.00	6.00	23.8	20.4	1.00	3	2.6	1.000	63C0A_Trip537	1
07/05/2026 15:31:18	52.391391	4.880939	238	Sudden braking	5.10	5.10	22.0	15.3	1.00	3	1.3	1.000	63C0A_Trip537	1
07/05/2026 15:31:19	52.391385	4.880922	239	Sudden braking	3.30	3.30	20.6	12.0	1.00	3	2.5	1.000	63C0A_Trip537	1
07/05/2026 15:32:46	52.392786	4.868287	235	Sudden braking	2.00	2.00	31.9	30.5	1.00	2	8.6	1.000	63C0A_Trip537	1
07/05/2026 15:33:01	52.392478	4.866586	268	Sudden braking	2.00	2.00	29.5	33.4	1.00	3	6.4	1.000	63C0A_Trip537	1
07/05/2026 15:33:02	52.392496	4.866497	279	Sudden braking	3.40	3.40	28.3	30.0	1.00	3	6.6	1.000	63C0A_Trip537	1
07/05/2026 15:33:03	52.392507	4.866401	281	Sudden braking	4.00	4.00	27.1	26.0	1.00	3	4.0	1.000	63C0A_Trip537	1
07/05/2026 15:33:04	52.392515	4.866344	283	Sudden braking	3.70	3.70	26.0	22.3	1.00	3	3.1	1.000	63C0A_Trip537	1
07/05/2026 15:33:05	52.392522	4.866300	285	Sudden braking	2.70	2.70	25.1	19.6	1.00	3	4.2	1.000	63C0A_Trip537	1
07/05/2026 15:38:51	52.417481	4.826757	29	Sudden braking	2.10	2.10	30.2	32.8	1.00	2	11.5	1.000	63C0A_Trip537	1
07/05/2026 15:38:52	52.417572	4.826837	26	Sudden braking	2.80	2.80	27.5	30.0	1.00	2	9.6	1.000	63C0A_Trip537	1
07/05/2026 15:38:53	52.417651	4.826893	20	Sudden braking	3.50	3.50	24.7	26.5	1.00	2	6.6	1.000	63C0A_Trip537	1
07/05/2026 15:38:54	52.417708	4.826922	17	Sudden braking	4.00	4.00	21.7	22.5	1.00	2	5.2	1.000	63C0A_Trip537	1
07/05/2026 15:38:55	52.417754	4.826936	13	Sudden braking	4.10	4.10	20.2	18.4	1.00	2	1.6	1.000	63C0A_Trip537	1
07/05/2026 15:38:56	52.417766	4.826951	17	Sudden braking	3.90	3.90	18.6	14.5	1.00	2	2.0	1.000	63C0A_Trip537	1
07/05/2026 15:38:57	52.417783	4.826943	64	Sudden braking	3.80	3.80	16.8	10.7	1.00	2	8.3	1.000	63C0A_Trip537	1
07/05/2026 15:38:58	52.417817	4.826834	64	Sudden braking	3.30	3.30	15.0	7.4	1.00	2	1.1	1.000	63C0A_Trip537	1
07/05/2026 15:45:55	52.419434	4.826953	3	Sudden braking	3.20	3.20	17.1	15.1	1.00	1	4.8	1.000	63C0A_Trip537	1
07/05/2026 15:45:56	52.419477	4.826949	3	Sudden braking	4.30	4.30	16.6	10.8	1.00	1	4.8	1.000	63C0A_Trip537	1
07/05/2026 15:46:50	52.420664	4.826738	327	Sudden braking	2.20	2.20	9.8	9.8	1.00	1	1.5	1.000	63C0A_Trip537	1
07/05/2026 15:46:51	52.420677	4.826745	331	Sudden braking	2.20	2.20	8.5	7.6	1.00	1	2.0	1.000	63C0A_Trip537	1
07/05/2026 15:46:52	52.420695	4.826743	342	Sudden braking	2.10	2.10	7.4	5.5	1.00	1	2.6	1.000	63C0A_Trip537	1
07/05/2026 15:50:29	52.424017	4.827679	6	Sudden braking	2.10	2.10	30.1	28.0	1.00	3	7.1	1.000	63C0A_Trip537	1
07/05/2026 15:52:57	52.433736	4.816132	255	Sudden braking	3.10	3.10	32.7	34.3	1.00	2	8.7	1.000	63C0A_Trip537	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
07/05/2026 15:52:58	52.433719	4.816006	256	Sudden braking	3.90	3.90	31.4	30.4	1.00	2	6.9	1.000	63C0A_Trip537	1
07/05/2026 15:52:59	52.433721	4.815905	265	Sudden braking	3.60	3.60	30.2	26.8	1.00	3	5.6	1.000	63C0A_Trip537	1
07/05/2026 15:53:00	52.433752	4.815840	291	Sudden braking	2.50	2.50	29.2	24.3	1.00	3	6.2	1.000	63C0A_Trip537	1
07/05/2026 15:56:58	52.456853	4.806240	358	Sudden braking	2.40	2.40	31.4	33.5	1.00	3	7.9	0.999	63C0A_Trip537	1
07/05/2026 15:56:58	52.456924	4.806236	359	Sudden braking	2.80	2.80	30.3	30.7	1.00	2	7.4	1.000	63C0A_Trip537	1
07/05/2026 15:56:59	52.456991	4.806233	359	Sudden braking	3.10	3.10	27.5	27.6	1.00	2	7.2	1.000	63C0A_Trip537	1
07/05/2026 15:57:00	52.457056	4.806231	359	Sudden braking	3.00	3.00	24.5	24.6	1.00	2	6.6	1.000	63C0A_Trip537	1
07/05/2026 15:57:04	52.457254	4.806220	358	Sudden braking	3.20	3.20	19.6	18.4	1.00	3	4.1	1.000	63C0A_Trip537	1
07/05/2026 15:57:05	52.457291	4.806218	358	Sudden braking	3.10	3.10	18.5	15.3	1.00	3	3.0	1.000	63C0A_Trip537	1
07/05/2026 15:59:19	52.470122	4.805494	357	Sudden braking	2.10	2.10	32.6	32.5	1.00	3	7.9	1.000	63C0A_Trip537	1
07/05/2026 15:59:20	52.470193	4.805489	358	Sudden braking	2.00	2.00	31.5	30.5	1.00	3	6.9	1.000	63C0A_Trip537	1
07/05/2026 16:01:55	52.484789	4.806299	334	Sudden braking	2.70	2.70	31.4	34.4	1.00	3	12.7	1.000	63C0A_Trip537	1
07/05/2026 16:01:56	52.484896	4.806200	324	Sudden braking	3.50	3.50	28.9	30.9	1.00	3	8.6	1.000	63C0A_Trip537	1
07/05/2026 16:01:57	52.484947	4.806124	323	Sudden braking	3.80	3.80	26.2	27.1	1.00	2	6.3	1.000	63C0A_Trip537	1
07/05/2026 16:01:58	52.484993	4.806067	322	Sudden braking	4.00	4.00	23.2	23.1	1.00	2	5.4	1.000	63C0A_Trip537	1
07/05/2026 16:01:59	52.485031	4.806019	322	Sudden braking	3.90	3.90	20.1	19.2	1.00	2	4.7	1.000	63C0A_Trip537	1
07/05/2026 16:02:00	52.485064	4.805976	322	Sudden braking	3.40	3.40	18.4	15.8	1.00	2	6.0	1.000	63C0A_Trip537	1
07/05/2026 16:02:01	52.485105	4.805918	315	Sudden braking	3.10	3.10	15.4	12.7	1.00	3	2.6	1.000	63C0A_Trip537	1
07/05/2026 16:02:02	52.485122	4.805891	315	Sudden braking	3.20	3.20	13.7	9.5	1.00	3	2.8	1.000	63C0A_Trip537	1
07/05/2026 16:02:03	52.485138	4.805861	312	Sudden braking	2.90	2.90	12.0	6.6	1.00	3	0.4	1.000	63C0A_Trip537	1
07/05/2026 16:02:53	52.486921	4.801246	299	Sudden braking	2.20	2.20	34.7	35.2	1.00	3	9.7	1.000	63C0A_Trip537	1
07/05/2026 16:02:54	52.486964	4.801121	299	Sudden braking	2.30	2.30	33.8	32.9	1.00	3	8.1	1.000	63C0A_Trip537	1
07/05/2026 16:02:55	52.486999	4.801016	299	Sudden braking	2.10	2.10	33.1	30.8	1.00	3	7.5	1.000	63C0A_Trip537	1
07/05/2026 16:03:26	52.488419	4.796662	302	Sudden braking	2.10	2.10	33.1	35.3	1.00	2	8.9	1.000	63C0A_Trip537	1
07/05/2026 16:03:27	52.488463	4.796552	302	Sudden braking	2.50	2.50	31.2	32.8	1.00	3	8.1	1.000	63C0A_Trip537	1
07/05/2026 16:03:28	52.488505	4.796454	302	Sudden braking	3.20	3.20	30.4	29.6	1.00	3	8.2	1.000	63C0A_Trip537	1
07/05/2026 16:03:29	52.488545	4.796351	301	Sudden braking	3.30	3.30	28.2	26.3	1.00	2	7.3	1.000	63C0A_Trip537	1
07/05/2026 16:03:30	52.488564	4.796249	301	Sudden braking	3.00	3.00	26.3	23.3	1.00	3	5.2	1.000	63C0A_Trip537	1
07/05/2026 16:03:31	52.488597	4.796194	299	Sudden braking	2.60	2.60	24.7	20.7	1.00	3	2.5	1.000	63C0A_Trip537	1
07/05/2026 16:07:12	52.494741	4.762530	295	Sudden braking	3.80	3.80	34.8	33.1	1.00	3	10.0	1.001	63C0A_Trip537	1
07/05/2026 16:07:13	52.494778	4.762395	294	Sudden braking	5.90	5.90	33.2	27.2	1.00	3	7.8	1.000	63C0A_Trip537	1
07/05/2026 16:14:56	52.521868	4.702563	313	Sudden braking	2.10	2.10	32.2	34.9	1.00	3	9.4	1.000	63C0A_Trip537	1
07/05/2026 16:14:57	52.521926	4.702462	314	Sudden braking	3.20	3.20	30.5	31.7	1.00	3	8.4	1.000	63C0A_Trip537	1
07/05/2026 16:14:58	52.521977	4.702370	312	Sudden braking	4.00	4.00	29.0	27.7	1.00	3	6.3	1.000	63C0A_Trip537	1
07/05/2026 16:14:59	52.522015	4.702300	311	Sudden braking	3.70	3.70	28.0	24.0	1.00	3	2.7	1.000	63C0A_Trip537	1
07/05/2026 16:15:00	52.522031	4.702271	314	Sudden braking	2.70	2.70	26.9	21.3	1.00	3	0.7	1.000	63C0A_Trip537	1
07/05/2026 16:20:20	52.542695	4.675931	305	Sudden braking	2.00	2.00	33.4	33.1	1.00	4	8.9	1.000	63C0A_Trip537	1
07/05/2026 16:20:21	52.542735	4.675817	303	Sudden braking	2.00	2.00	32.8	31.1	1.00	4	7.0	1.000	63C0A_Trip537	1
07/05/2026 20:26:51	52.371063	4.913221	280	Sudden braking	2.30	2.30	9.6	8.5	1.00	2	2.6	1.000	602CA_Trip538	1
07/05/2026 20:26:52	52.371064	4.913183	270	Sudden braking	2.04	2.04	8.7	6.4	1.03	2	1.9	1.030	602CA_Trip538	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
07/05/2026 20:32:07	52.361324	4.908158	248	Sudden braking	2.09	2.09	8.1	6.1	1.01	2	2.4	1.006	602CA_Trip538	1
07/05/2026 20:32:08	52.361311	4.908130	242	Sudden braking	2.01	2.01	6.3	4.1	1.00	2	0.6	0.996	602CA_Trip538	1
07/05/2026 20:35:34	52.356066	4.904911	182	Sudden braking	2.31	2.31	7.6	8.7	0.99	2	2.4	0.994	602CA_Trip538	1
07/05/2026 20:35:35	52.356044	4.904910	200	Sudden braking	2.45	2.45	6.1	6.4	0.94	2	1.5	0.937	602CA_Trip538	1
07/05/2026 20:35:36	52.356032	4.904902	214	Sudden braking	2.31	2.31	6.1	4.0	1.04	2	0.6	1.040	602CA_Trip538	1
07/05/2026 20:35:37	52.356027	4.904897	227	Sudden braking	2.00	2.00	3.7	2.0	1.00	2	0.6	1.001	602CA_Trip538	1
08/05/2026 05:01:07	52.542590	4.675532	53	Sudden braking	2.00	2.00	29.6	28.6	1.00	3	9.7	1.000	63C0A_Trip539	1
08/05/2026 05:03:53	52.536414	4.694428	79	Sudden braking	2.00	2.00	33.0	34.3	1.00	3	9.2	1.000	63C0A_Trip539	1
08/05/2026 05:03:54	52.536431	4.694561	83	Sudden braking	2.30	2.30	31.6	32.0	1.00	3	8.2	1.000	63C0A_Trip539	1
08/05/2026 05:03:55	52.536424	4.694681	94	Sudden braking	2.50	2.50	30.3	29.5	1.00	3	7.4	1.000	63C0A_Trip539	1
08/05/2026 05:03:56	52.536394	4.694778	110	Sudden braking	2.50	2.50	29.2	27.0	1.00	3	7.5	1.000	63C0A_Trip539	1
08/05/2026 05:03:57	52.536335	4.694834	141	Sudden braking	2.00	2.00	28.3	25.0	1.00	3	8.2	1.000	63C0A_Trip539	1
08/05/2026 05:06:34	52.522442	4.702544	132	Sudden braking	2.40	2.40	32.0	32.8	1.00	2	9.0	1.000	63C0A_Trip539	1
08/05/2026 05:06:35	52.522388	4.702642	132	Sudden braking	2.70	2.70	30.4	30.1	1.00	2	7.0	1.000	63C0A_Trip539	1
08/05/2026 05:06:36	52.522346	4.702719	133	Sudden braking	2.50	2.50	28.9	27.6	1.00	2	4.3	1.000	63C0A_Trip539	1
08/05/2026 05:06:37	52.522320	4.702765	133	Sudden braking	2.20	2.20	27.4	25.4	1.00	3	2.3	1.000	63C0A_Trip539	1
08/05/2026 05:07:19	52.519896	4.706247	134	Sudden braking	2.40	2.40	33.7	35.0	1.00	3	11.0	1.000	63C0A_Trip539	1
08/05/2026 05:07:20	52.519821	4.706354	140	Sudden braking	2.80	2.80	32.4	32.2	1.00	3	8.7	1.000	63C0A_Trip539	1
08/05/2026 05:07:21	52.519760	4.706432	143	Sudden braking	2.70	2.70	31.1	29.5	1.00	3	6.4	1.000	63C0A_Trip539	1
08/05/2026 05:07:22	52.519713	4.706488	145	Sudden braking	2.30	2.30	30.0	27.2	1.00	3	3.3	1.000	63C0A_Trip539	1
08/05/2026 05:11:48	52.502768	4.738514	131	Sudden braking	2.10	2.10	32.4	35.7	1.00	3	9.9	1.000	63C0A_Trip539	1
08/05/2026 05:11:49	52.502710	4.738624	131	Sudden braking	3.10	3.10	30.1	32.6	1.00	3	8.1	1.000	63C0A_Trip539	1
08/05/2026 05:11:50	52.502662	4.738714	131	Sudden braking	3.80	3.80	27.7	28.8	1.00	3	6.4	1.000	63C0A_Trip539	1
08/05/2026 05:11:51	52.502624	4.738785	131	Sudden braking	4.10	4.10	25.0	24.7	1.00	3	4.3	1.000	63C0A_Trip539	1
08/05/2026 05:11:52	52.502599	4.738834	131	Sudden braking	3.90	3.90	22.2	20.8	1.00	3	4.3	1.000	63C0A_Trip539	1
08/05/2026 05:11:53	52.502574	4.738881	131	Sudden braking	3.30	3.30	19.5	17.5	1.00	3	3.7	1.000	63C0A_Trip539	1
08/05/2026 05:11:54	52.502552	4.738923	131	Sudden braking	2.50	2.50	17.9	15.0	1.00	3	3.3	1.000	63C0A_Trip539	1
08/05/2026 05:11:55	52.502532	4.738960	131	Sudden braking	2.00	2.00	16.2	13.0	1.00	4	3.0	1.000	63C0A_Trip539	1
08/05/2026 05:11:56	52.502515	4.738993	131	Sudden braking	2.50	2.50	14.6	10.5	1.00	4	2.7	1.000	63C0A_Trip539	1
08/05/2026 05:11:57	52.502499	4.739023	131	Sudden braking	2.20	2.20	13.2	8.3	1.00	3	1.6	1.000	63C0A_Trip539	1
08/05/2026 05:16:03	52.493812	4.768300	93	Sudden braking	2.60	2.60	34.2	33.6	1.00	3	9.3	1.000	63C0A_Trip539	1
08/05/2026 05:22:39	52.471371	4.805257	178	Sudden braking	2.20	2.20	33.5	36.5	1.00	2	9.4	1.000	63C0A_Trip539	1
08/05/2026 05:22:40	52.471287	4.805263	178	Sudden braking	2.80	2.80	31.3	33.7	1.00	3	7.3	1.000	63C0A_Trip539	1
08/05/2026 05:22:41	52.471221	4.805267	178	Sudden braking	3.30	3.30	28.7	30.4	1.00	3	6.7	1.000	63C0A_Trip539	1
08/05/2026 05:22:42	52.471160	4.805271	178	Sudden braking	3.70	3.70	25.9	26.7	1.00	3	6.5	1.000	63C0A_Trip539	1
08/05/2026 05:22:43	52.471102	4.805274	178	Sudden braking	3.60	3.60	22.8	23.1	1.00	3	5.7	1.000	63C0A_Trip539	1
08/05/2026 05:22:44	52.471050	4.805278	178	Sudden braking	3.70	3.70	19.7	19.4	1.00	3	4.6	1.000	63C0A_Trip539	1
08/05/2026 05:22:45	52.471009	4.805280	178	Sudden braking	3.90	3.90	18.1	15.5	1.00	3	2.9	1.000	63C0A_Trip539	1
08/05/2026 05:22:46	52.470983	4.805282	178	Sudden braking	3.40	3.40	15.2	12.1	1.00	3	1.1	1.000	63C0A_Trip539	1
08/05/2026 05:22:47	52.470973	4.805282	178	Sudden braking	3.10	3.10	13.5	9.0	1.00	3	1.5	1.000	63C0A_Trip539	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_seg ment_kmh	duration_flagged_inte rval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_repr esented
08/05/2026 05:22:48	52.470960	4.805283	178	Sudden braking	2.90	2.90	11.8	6.1	1.00	3	2.3	1.000	63C0A_Trip539	1
08/05/2026 05:29:15	52.433866	4.815810	174	Sudden braking	2.90	2.90	33.6	34.5	1.00	4	9.5	1.000	63C0A_Trip539	1
08/05/2026 05:29:16	52.433782	4.815823	173	Sudden braking	3.40	3.40	33.0	31.1	1.00	3	7.5	1.000	63C0A_Trip539	1
08/05/2026 05:29:17	52.433717	4.815858	173	Sudden braking	3.00	3.00	32.0	28.1	1.00	2	4.9	1.000	63C0A_Trip539	1
08/05/2026 08:19:05	52.336709	4.906176	1	Sudden braking	2.20	2.20	11.6	13.7	1.00	2	4.5	1.000	602CA_Trip540	1
08/05/2026 08:19:06	52.336747	4.906160	0	Sudden braking	2.78	2.78	9.9	11.0	0.97	2	3.2	0.970	602CA_Trip540	1
08/05/2026 08:19:07	52.336775	4.906144	357	Sudden braking	3.09	3.09	9.9	7.8	1.03	2	1.6	1.034	602CA_Trip540	1
08/05/2026 08:19:08	52.336788	4.906152	357	Sudden braking	3.18	3.18	8.0	4.6	1.01	2	0.6	1.006	602CA_Trip540	1
08/05/2026 08:19:09	52.336791	4.906145	356	Sudden braking	2.24	2.24	6.9	2.3	1.03	2	0.1	1.027	602CA_Trip540	1
08/05/2026 08:20:10	52.338605	4.907141	45	Sudden braking	2.58	2.58	9.9	11.1	1.01	2	3.6	1.006	602CA_Trip540	1
08/05/2026 08:20:11	52.338630	4.907176	41	Sudden braking	3.00	3.00	7.5	8.1	1.00	2	2.9	1.001	602CA_Trip540	1
08/05/2026 08:20:12	52.338652	4.907197	27	Sudden braking	2.93	2.93	6.0	5.2	0.99	2	0.5	0.989	602CA_Trip540	1
08/05/2026 08:20:13	52.338657	4.907197	20	Sudden braking	2.53	2.53	4.6	2.7	0.99	2	0.7	0.990	602CA_Trip540	1
08/05/2026 08:20:58	52.339382	4.908833	36	Sudden braking	2.21	2.21	13.3	12.6	0.95	3	2.8	0.950	602CA_Trip540	1
08/05/2026 08:29:44	52.359968	4.908472	81	Sudden braking	2.34	2.34	9.2	10.9	0.98	1	3.4	0.983	602CA_Trip540	1
08/05/2026 08:29:45	52.359975	4.908520	87	Sudden braking	2.75	2.75	9.2	8.1	1.02	1	2.6	1.018	602CA_Trip540	1
08/05/2026 08:29:46	52.359979	4.908557	88	Sudden braking	2.76	2.76	7.2	5.4	0.98	1	1.6	0.979	602CA_Trip540	1
08/05/2026 08:29:47	52.359975	4.908580	80	Sudden braking	2.28	2.28	7.2	3.1	1.01	1	0.5	1.009	602CA_Trip540	1
08/05/2026 08:30:45	52.360204	4.908845	329	Sudden braking	2.04	2.04	11.8	13.1	1.03	2	5.7	1.027	602CA_Trip540	1
08/05/2026 08:30:46	52.360249	4.908803	330	Sudden braking	2.80	2.80	11.3	10.4	0.97	2	4.1	0.966	602CA_Trip540	1
08/05/2026 08:30:47	52.360283	4.908779	328	Sudden braking	2.89	2.89	10.7	7.5	1.00	2	2.2	1.002	602CA_Trip540	1
08/05/2026 08:30:48	52.360301	4.908764	325	Sudden braking	3.00	3.00	9.0	4.5	1.00	3	0.7	1.000	602CA_Trip540	1
08/05/2026 08:30:49	52.360306	4.908759	328	Sudden braking	2.51	2.51	7.5	2.0	1.00	3	0.1	0.997	602CA_Trip540	1
08/05/2026 08:32:10	52.364160	4.906503	344	Sudden braking	2.04	2.04	13.9	15.4	0.98	1	5.1	0.981	602CA_Trip540	1
08/05/2026 08:32:11	52.364206	4.906495	341	Sudden braking	2.70	2.70	12.7	12.7	1.00	1	4.6	1.000	602CA_Trip540	1
08/05/2026 08:32:12	52.364245	4.906471	339	Sudden braking	2.89	2.89	9.9	9.8	1.00	1	3.5	1.005	602CA_Trip540	1
08/05/2026 08:32:13	52.364268	4.906437	334	Sudden braking	2.87	2.87	8.9	6.9	1.01	1	3.3	1.010	602CA_Trip540	1
08/05/2026 08:32:14	52.364298	4.906435	336	Sudden braking	2.59	2.59	6.7	4.3	1.00	2	3.1	1.005	602CA_Trip540	1
08/05/2026 08:33:41	52.367640	4.904355	342	Sudden braking	2.10	2.10	11.2	9.6	1.00	2	3.2	1.000	602CA_Trip540	1
08/05/2026 08:34:00	52.368088	4.904977	82	Sudden braking	2.60	2.60	15.2	15.3	1.00	2	5.6	0.999	602CA_Trip540	1
08/05/2026 08:34:01	52.368109	4.905052	77	Sudden braking	2.21	2.21	14.6	13.1	1.00	2	4.2	0.997	602CA_Trip540	1
08/05/2026 08:37:01	52.371036	4.914940	72	Sudden braking	2.34	2.34	12.3	13.4	0.98	1	4.7	0.982	602CA_Trip540	1
08/05/2026 08:37:02	52.371051	4.915006	78	Sudden braking	3.07	3.07	10.6	10.3	1.01	1	3.3	1.010	602CA_Trip540	1
08/05/2026 08:37:03	52.371059	4.915052	77	Sudden braking	3.04	3.04	9.8	7.2	1.02	1	2.0	1.020	602CA_Trip540	1
08/05/2026 08:37:04	52.371066	4.915079	75	Sudden braking	2.93	2.93	6.0	4.3	0.99	1	0.2	0.989	602CA_Trip540	1
08/05/2026 08:37:05	52.371068	4.915078	0	Sudden braking	2.37	2.37	6.0	1.9	1.01	1	0.7	1.014	602CA_Trip540	1
08/05/2026 08:38:19	52.372377	4.918242	55	Sudden braking	2.03	2.03	7.6	7.5	0.99	3	2.4	0.987	602CA_Trip540	1
08/05/2026 08:38:20	52.372396	4.918258	61	Sudden braking	2.03	2.03	7.8	5.5	0.99	3	1.9	0.987	602CA_Trip540	1
08/05/2026 08:39:14	52.374172	4.915506	342	Sudden braking	2.09	2.09	7.9	9.1	0.96	2	3.1	0.957	602CA_Trip540	1
08/05/2026 08:39:15	52.374196	4.915486	344	Sudden braking	2.10	2.10	7.9	7.0	1.00	2	2.8	0.998	602CA_Trip540	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
08/05/2026 08:39:16	52.374220	4.915471	355	Sudden braking	2.00	2.00	5.9	5.0	1.00	2	1.9	1.002	602CA_Trip540	1
08/05/2026 13:14:54	52.337376	4.938840	278	Sudden braking	2.30	2.30	14.6	12.9	1.00	2	1.9	1.000	602DE_Trip541	1
08/05/2026 13:14:55	52.337389	4.938859	287	Sudden braking	2.60	2.60	14.5	10.3	1.00	2	4.8	1.000	602DE_Trip541	1
08/05/2026 13:16:26	52.338639	4.932007	284	Sudden braking	2.60	2.60	16.3	15.6	1.00	2	5.4	1.000	602DE_Trip541	1
08/05/2026 13:16:27	52.338654	4.931931	286	Sudden braking	2.50	2.50	16.0	13.1	1.00	2	1.0	1.000	602DE_Trip541	1
08/05/2026 13:16:54	52.339027	4.929913	286	Sudden braking	2.30	2.30	16.6	15.4	1.00	2	5.5	1.000	602DE_Trip541	1
08/05/2026 13:17:53	52.340598	4.925962	307	Sudden braking	2.00	2.00	17.2	17.5	1.00	2	4.8	1.000	602DE_Trip541	1
08/05/2026 13:17:56	52.340675	4.925818	314	Sudden braking	2.00	2.00	14.1	13.2	1.00	2	1.5	1.000	602DE_Trip541	1
08/05/2026 13:19:37	52.343820	4.919600	340	Sudden braking	2.40	2.40	13.7	11.6	1.00	2	9.1	1.000	602DE_Trip541	1
08/05/2026 13:19:47	52.344308	4.919342	348	Sudden braking	2.80	2.80	15.8	15.2	1.00	2	5.4	1.001	602DE_Trip541	1
08/05/2026 13:19:49	52.344356	4.919337	348	Sudden braking	2.00	2.00	16.0	13.2	1.00	2	1.1	1.000	602DE_Trip541	1
08/05/2026 13:19:56	52.344681	4.919211	341	Sudden braking	2.60	2.60	14.0	14.3	1.00	2	1.0	1.000	602DE_Trip541	1
08/05/2026 13:19:57	52.344690	4.919208	340	Sudden braking	3.30	3.30	14.3	11.0	1.00	2	6.3	1.000	602DE_Trip541	1
08/05/2026 16:03:28	52.376541	4.914208	348	Sudden braking	2.70	2.70	15.1	16.1	1.00	2	3.6	1.000	63C0A_Trip544	1
08/05/2026 16:03:29	52.376572	4.914196	348	Sudden braking	3.60	3.60	14.8	12.5	1.00	2	1.0	1.000	63C0A_Trip544	1
08/05/2026 16:03:30	52.376567	4.914185	359	Sudden braking	4.00	4.00	14.3	8.5	1.00	2	1.6	1.000	63C0A_Trip544	1
08/05/2026 16:03:42	52.376590	4.914190	348	Sudden braking	2.50	2.50	1.6	2.3	1.00	2	1.7	1.000	63C0A_Trip544	1
08/05/2026 16:05:06	52.376569	4.912146	272	Sudden braking	2.20	2.20	19.2	20.2	1.00	2	4.1	1.000	63C0A_Trip544	1
08/05/2026 16:05:07	52.376571	4.912086	280	Sudden braking	2.40	2.40	18.6	17.8	1.00	3	3.2	1.000	63C0A_Trip544	1
08/05/2026 16:05:08	52.376562	4.912040	272	Sudden braking	2.30	2.30	17.1	15.5	1.00	3	4.4	1.000	63C0A_Trip544	1
08/05/2026 16:05:09	52.376592	4.911998	280	Sudden braking	2.00	2.00	15.6	13.5	1.00	2	3.0	1.000	63C0A_Trip544	1
08/05/2026 16:05:33	52.376135	4.910778	243	Sudden braking	2.10	2.10	13.7	14.9	1.00	3	3.1	1.000	63C0A_Trip544	1
08/05/2026 16:05:34	52.376122	4.910737	243	Sudden braking	2.10	2.10	13.0	12.8	1.00	3	1.7	1.000	63C0A_Trip544	1
08/05/2026 16:06:07	52.376702	4.910189	336	Sudden braking	4.20	4.20	20.1	21.1	1.00	3	7.9	1.000	63C0A_Trip544	1
08/05/2026 16:06:08	52.376764	4.910134	337	Sudden braking	5.00	5.00	18.6	16.1	1.00	3	5.0	1.000	63C0A_Trip544	1
08/05/2026 16:06:09	52.376806	4.910103	338	Sudden braking	2.70	2.70	17.0	13.4	1.00	2	4.2	1.000	63C0A_Trip544	1
08/05/2026 16:07:15	52.378297	4.906865	282	Sudden braking	2.00	2.00	14.2	12.5	1.00	3	2.5	1.000	63C0A_Trip544	1
08/05/2026 16:07:43	52.378741	4.904194	301	Sudden braking	2.00	2.00	26.2	27.2	1.00	2	6.7	1.000	63C0A_Trip544	1
08/05/2026 16:07:44	52.378778	4.904117	305	Sudden braking	2.40	2.40	25.9	24.8	1.00	2	4.3	1.000	63C0A_Trip544	1
08/05/2026 16:07:45	52.378800	4.904065	304	Sudden braking	2.10	2.10	25.8	22.7	1.00	2	4.6	1.000	63C0A_Trip544	1
08/05/2026 16:10:09	52.384865	4.893252	11	Sudden braking	2.10	2.10	31.7	33.1	1.00	3	8.9	1.000	63C0A_Trip544	1
08/05/2026 16:10:10	52.384944	4.893274	7	Sudden braking	2.30	2.30	29.9	30.8	1.00	2	8.4	1.000	63C0A_Trip544	1
08/05/2026 16:10:11	52.385019	4.893288	4	Sudden braking	2.80	2.80	28.3	28.0	1.00	2	7.4	1.000	63C0A_Trip544	1
08/05/2026 16:10:12	52.385085	4.893299	4	Sudden braking	3.10	3.10	26.9	24.9	1.00	2	6.4	1.000	63C0A_Trip544	1
08/05/2026 16:10:13	52.385142	4.893299	2	Sudden braking	2.60	2.60	25.8	22.3	1.00	2	4.7	1.000	63C0A_Trip544	1
08/05/2026 16:10:54	52.388931	4.891772	345	Sudden braking	3.30	3.30	31.2	34.2	1.00	2	9.3	1.000	63C0A_Trip544	1
08/05/2026 16:10:55	52.389012	4.891735	345	Sudden braking	4.00	4.00	28.8	30.2	1.00	2	7.2	1.000	63C0A_Trip544	1
08/05/2026 16:10:56	52.389075	4.891715	344	Sudden braking	4.20	4.20	26.3	26.0	1.00	2	5.4	1.000	63C0A_Trip544	1
08/05/2026 16:10:57	52.389123	4.891699	344	Sudden braking	4.30	4.30	23.6	21.7	1.00	2	5.5	1.000	63C0A_Trip544	1
08/05/2026 16:10:58	52.389171	4.891680	344	Sudden braking	3.60	3.60	20.9	18.1	1.00	2	4.9	1.000	63C0A_Trip544	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
08/05/2026 16:10:59	52.389212	4.891656	344	Sudden braking	2.30	2.30	18.2	15.8	1.00	2	3.3	1.000	63C0A_Trip544	1
08/05/2026 16:14:24	52.392934	4.868661	264	Sudden braking	2.10	2.10	34.5	36.3	1.00	2	9.2	1.000	63C0A_Trip544	1
08/05/2026 16:14:25	52.392906	4.868533	253	Sudden braking	3.00	3.00	32.4	33.3	1.00	3	8.2	1.000	63C0A_Trip544	1
08/05/2026 16:14:26	52.392884	4.868418	253	Sudden braking	3.70	3.70	29.9	29.6	1.00	3	4.5	1.000	63C0A_Trip544	1
08/05/2026 16:14:27	52.392851	4.868381	242	Sudden braking	3.90	3.90	27.2	25.7	1.00	2	5.6	1.000	63C0A_Trip544	1
08/05/2026 16:14:30	52.392778	4.868217	236	Sudden braking	3.30	3.30	19.6	18.8	1.00	3	3.8	1.000	63C0A_Trip544	1
08/05/2026 16:14:31	52.392759	4.868171	236	Sudden braking	3.30	3.30	17.8	15.5	1.00	3	6.8	1.000	63C0A_Trip544	1
08/05/2026 16:14:32	52.392735	4.868079	249	Sudden braking	3.10	3.10	16.2	12.4	1.00	3	10.1	1.000	63C0A_Trip544	1
08/05/2026 16:14:33	52.392772	4.867943	234	Sudden braking	2.40	2.40	14.6	10.0	1.00	3	1.2	1.000	63C0A_Trip544	1
08/05/2026 16:20:42	52.417761	4.826939	13	Sudden braking	2.40	2.40	28.9	33.1	1.00	2	7.8	1.000	63C0A_Trip544	1
08/05/2026 16:20:43	52.417830	4.826952	9	Sudden braking	3.70	3.70	25.6	29.4	1.00	2	4.5	1.000	63C0A_Trip544	1
08/05/2026 16:20:44	52.417870	4.826962	8	Sudden braking	5.00	5.00	24.3	24.4	1.00	2	3.3	1.000	63C0A_Trip544	1
08/05/2026 16:20:45	52.417894	4.826989	59	Sudden braking	5.50	5.50	22.7	18.9	1.00	2	3.0	1.000	63C0A_Trip544	1
08/05/2026 16:20:46	52.417918	4.827010	49	Sudden braking	5.50	5.50	20.8	13.4	1.00	2	1.6	1.000	63C0A_Trip544	1
08/05/2026 16:20:47	52.417926	4.826990	28	Sudden braking	5.30	5.30	18.7	8.1	1.00	2	1.4	1.000	63C0A_Trip544	1
08/05/2026 16:48:49	52.434198	4.818542	320	Sudden braking	3.00	3.00	37.8	34.8	1.00	2	10.0	1.000	63C0A_Trip544	1
08/05/2026 16:49:06	52.433759	4.816290	257	Sudden braking	2.20	2.20	32.0	35.6	1.00	3	9.7	1.000	63C0A_Trip544	1
08/05/2026 16:49:07	52.433742	4.816150	258	Sudden braking	3.50	3.50	30.2	32.1	1.00	3	8.4	1.000	63C0A_Trip544	1
08/05/2026 16:49:08	52.433724	4.816029	257	Sudden braking	4.50	4.50	28.5	27.6	1.00	3	6.7	1.000	63C0A_Trip544	1
08/05/2026 16:49:09	52.433721	4.815931	264	Sudden braking	4.20	4.20	27.0	23.4	1.00	3	5.1	1.000	63C0A_Trip544	1
08/05/2026 16:49:10	52.433738	4.815860	280	Sudden braking	2.90	2.90	25.8	20.5	1.00	2	4.3	1.000	63C0A_Trip544	1
08/05/2026 16:53:14	52.457678	4.806203	359	Sudden braking	2.80	2.80	32.2	32.1	1.00	3	6.7	1.000	63C0A_Trip544	1
08/05/2026 16:53:15	52.457739	4.806201	359	Sudden braking	2.50	2.50	31.4	29.6	1.00	3	6.8	1.000	63C0A_Trip544	1
08/05/2026 16:57:41	52.484755	4.806325	334	Sudden braking	2.20	2.20	34.2	36.0	1.00	3	12.1	1.002	63C0A_Trip544	1
08/05/2026 16:57:43	52.484851	4.806240	327	Sudden braking	3.20	3.20	29.6	32.8	1.00	3	9.4	1.000	63C0A_Trip544	1
08/05/2026 16:57:44	52.484920	4.806159	323	Sudden braking	3.70	3.70	27.2	29.1	1.00	3	5.6	1.000	63C0A_Trip544	1
08/05/2026 16:57:45	52.484960	4.806109	323	Sudden braking	4.00	4.00	24.8	25.1	1.00	3	5.5	1.000	63C0A_Trip544	1
08/05/2026 16:57:46	52.484999	4.806059	322	Sudden braking	3.70	3.70	22.5	21.4	1.00	3	4.6	1.000	63C0A_Trip544	1
08/05/2026 16:57:47	52.485032	4.806018	322	Sudden braking	2.90	2.90	20.6	18.5	1.00	2	4.0	1.000	63C0A_Trip544	1
08/05/2026 16:57:48	52.485060	4.805982	322	Sudden braking	2.20	2.20	20.3	16.3	1.00	3	4.6	1.000	63C0A_Trip544	1
08/05/2026 16:58:56	52.488477	4.796508	302	Sudden braking	2.20	2.20	32.6	35.9	1.00	2	9.4	1.000	63C0A_Trip544	1
08/05/2026 16:58:57	52.488524	4.796393	302	Sudden braking	3.20	3.20	30.7	32.7	1.00	3	8.2	1.000	63C0A_Trip544	1
08/05/2026 16:58:58	52.488557	4.796283	301	Sudden braking	4.30	4.30	29.0	28.4	1.00	3	6.8	1.000	63C0A_Trip544	1
08/05/2026 16:58:59	52.488595	4.796205	301	Sudden braking	4.30	4.30	27.4	24.1	1.00	3	3.8	1.000	63C0A_Trip544	1
08/05/2026 16:59:00	52.488610	4.796156	299	Sudden braking	3.10	3.10	26.1	21.0	1.00	3	1.4	1.000	63C0A_Trip544	1
08/05/2026 17:10:20	52.521927	4.702460	314	Sudden braking	3.50	3.50	31.5	33.6	1.00	3	9.2	1.000	63C0A_Trip544	1
08/05/2026 17:10:21	52.521983	4.702360	311	Sudden braking	4.80	4.80	30.6	28.8	1.00	3	5.9	1.000	63C0A_Trip544	1
08/05/2026 17:10:22	52.522018	4.702294	311	Sudden braking	4.40	4.40	29.2	24.4	1.00	3	2.0	1.000	63C0A_Trip544	1
08/05/2026 17:10:23	52.522030	4.702273	314	Sudden braking	2.90	2.90	27.6	21.5	1.00	3	0.3	1.000	63C0A_Trip544	1
08/05/2026 17:12:51	52.535762	4.695529	354	Sudden braking	2.00	2.00	34.9	34.5	1.00	3	9.3	1.000	63C0A_Trip544	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
08/05/2026 17:14:50	52.542503	4.681533	282	Sudden braking	2.50	2.50	33.0	35.3	1.00	3	10.6	1.000	63C0A_Trip544	1
08/05/2026 17:14:51	52.542523	4.681379	280	Sudden braking	3.50	3.50	31.6	31.8	1.00	3	7.7	1.000	63C0A_Trip544	1
08/05/2026 17:14:52	52.542535	4.681268	280	Sudden braking	3.70	3.70	30.4	28.1	1.00	3	6.0	1.000	63C0A_Trip544	1
08/05/2026 17:14:53	52.542546	4.681180	281	Sudden braking	3.00	3.00	29.3	25.1	1.00	3	5.1	1.000	63C0A_Trip544	1
08/05/2026 17:15:27	52.541499	4.676926	280	Sudden braking	2.00	2.00	30.2	29.2	1.00	3	7.4	1.000	63C0A_Trip544	1
08/05/2026 20:16:44	52.358614	4.941158	274	Sudden braking	2.39	2.39	10.7	10.8	1.00	2	3.0	1.003	602CA_Trip546	1
08/05/2026 20:16:45	52.358619	4.941114	280	Sudden braking	2.64	2.64	9.2	8.1	1.02	2	2.6	1.022	602CA_Trip546	1
08/05/2026 20:16:46	52.358627	4.941078	292	Sudden braking	2.44	2.44	7.1	5.7	0.98	2	1.1	0.982	602CA_Trip546	1
08/05/2026 20:17:47	52.356815	4.939980	234	Sudden braking	2.54	2.54	20.8	22.2	0.98	3	6.7	0.984	602CA_Trip546	1
08/05/2026 20:17:48	52.356754	4.939974	226	Sudden braking	2.18	2.18	20.4	20.0	1.01	3	5.7	1.008	602CA_Trip546	1
08/05/2026 20:17:49	52.356713	4.939925	226	Sudden braking	3.24	3.24	19.8	16.7	1.02	3	3.4	1.018	602CA_Trip546	1
08/05/2026 20:17:50	52.356682	4.939916	208	Sudden braking	2.54	2.54	18.6	14.2	0.98	3	5.4	0.984	602CA_Trip546	1
08/05/2026 20:20:57	52.350987	4.935153	258	Sudden braking	2.81	2.81	6.5	7.0	1.00	2	1.7	0.998	602CA_Trip546	1
08/05/2026 20:20:58	52.350983	4.935128	245	Sudden braking	2.67	2.67	4.8	4.3	1.01	2	1.4	1.010	602CA_Trip546	1
08/05/2026 20:20:59	52.350973	4.935116	241	Sudden braking	2.01	2.01	3.0	2.3	0.99	1	0.5	0.994	602CA_Trip546	1
08/05/2026 20:22:59	52.347716	4.929342	228	Sudden braking	2.09	2.09	8.0	7.3	0.96	1	1.9	0.957	602CA_Trip546	1
08/05/2026 20:23:00	52.347702	4.929326	238	Sudden braking	2.32	2.32	8.0	5.0	0.99	1	0.6	0.991	602CA_Trip546	1
08/05/2026 20:23:01	52.347698	4.929320	239	Sudden braking	2.08	2.08	7.1	2.9	1.01	2	0.4	1.009	602CA_Trip546	1
08/05/2026 20:26:30	52.345939	4.920176	267	Sudden braking	2.39	2.39	8.3	7.0	1.00	2	2.2	1.004	602CA_Trip546	1
08/05/2026 20:26:31	52.345935	4.920145	267	Sudden braking	2.44	2.44	6.8	4.6	0.98	2	0.9	0.983	602CA_Trip546	1
08/05/2026 20:26:32	52.345937	4.920132	274	Sudden braking	2.16	2.16	6.8	2.4	1.02	2	0.4	1.019	602CA_Trip546	1
08/05/2026 20:30:08	52.338246	4.921342	157	Sudden braking	2.93	2.93	13.1	13.7	0.99	2	4.7	0.989	602CA_Trip546	1
08/05/2026 20:30:09	52.338216	4.921390	155	Sudden braking	3.46	3.46	11.2	10.2	1.01	2	2.9	1.013	602CA_Trip546	1
08/05/2026 20:30:10	52.338191	4.921405	155	Sudden braking	3.31	3.31	9.1	6.9	1.00	2	1.8	0.997	602CA_Trip546	1
08/05/2026 20:30:11	52.338176	4.921414	154	Sudden braking	2.83	2.83	7.8	4.1	0.99	2	0.9	0.988	602CA_Trip546	1
08/05/2026 20:32:15	52.332930	4.922971	144	Sudden braking	2.01	2.01	13.2	14.6	1.00	2	4.3	0.997	602CA_Trip546	1
08/05/2026 20:32:16	52.332896	4.923000	145	Sudden braking	2.10	2.10	12.2	12.5	1.00	2	3.6	0.999	602CA_Trip546	1
08/05/2026 20:32:17	52.332872	4.923035	139	Sudden braking	2.72	2.72	8.8	9.8	0.99	2	2.3	0.992	602CA_Trip546	1
08/05/2026 20:32:18	52.332853	4.923050	137	Sudden braking	2.91	2.91	8.8	6.8	1.03	2	2.2	1.030	602CA_Trip546	1
08/05/2026 20:32:19	52.332840	4.923074	139	Sudden braking	2.32	2.32	5.9	4.5	0.99	2	0.9	0.993	602CA_Trip546	1
08/05/2026 20:53:27	52.300710	4.883859	286	Sudden braking	2.11	2.11	21.2	20.4	0.99	2	6.6	0.993	602CA_Trip546	1
08/05/2026 20:53:28	52.300727	4.883767	288	Sudden braking	2.71	2.71	21.0	17.7	0.99	2	6.8	0.987	602CA_Trip546	1
09/05/2026 12:54:24	52.367435	4.889640	180	Sudden braking	2.00	2.00	12.1	11.6	1.00	2	2.5	1.000	604F0_Trip547	1
09/05/2026 12:54:25	52.367412	4.889640	180	Sudden braking	2.00	2.00	11.4	9.6	1.00	2	1.3	1.000	604F0_Trip547	1
09/05/2026 12:54:46	52.366953	4.888744	242	Sudden braking	2.20	2.20	19.9	21.8	1.00	3	4.9	1.000	604F0_Trip547	1
09/05/2026 12:54:47	52.366932	4.888681	242	Sudden braking	2.80	2.80	18.9	19.0	1.00	3	4.0	1.000	604F0_Trip547	1
09/05/2026 12:54:48	52.366915	4.888629	242	Sudden braking	3.10	3.10	17.7	15.9	1.00	2	3.2	1.000	604F0_Trip547	1
09/05/2026 12:54:49	52.366902	4.888587	242	Sudden braking	2.30	2.30	16.5	13.6	1.00	2	1.7	1.000	604F0_Trip547	1
09/05/2026 12:55:57	52.368685	4.887012	2	Sudden braking	2.30	2.30	17.1	17.5	1.00	2	4.4	1.000	604F0_Trip547	1
09/05/2026 12:55:58	52.368724	4.887009	2	Sudden braking	2.70	2.70	16.2	14.8	1.00	2	2.7	1.000	604F0_Trip547	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
09/05/2026 12:55:59	52.368748	4.886999	2	Sudden braking	2.40	2.40	15.5	12.4	1.00	2	2.0	1.000	604F0_Trip547	1
09/05/2026 12:57:08	52.368952	4.882537	281	Sudden braking	2.30	2.30	12.2	11.5	1.00	3	2.7	1.000	604F0_Trip547	1
09/05/2026 12:57:09	52.368955	4.882497	280	Sudden braking	2.30	2.30	11.1	9.2	1.00	2	1.6	1.000	604F0_Trip547	1
09/05/2026 12:58:17	52.366849	4.880219	243	Sudden braking	2.00	2.00	18.6	18.9	1.00	2	4.6	1.000	604F0_Trip547	1
09/05/2026 12:58:18	52.366830	4.880159	243	Sudden braking	2.20	2.20	17.3	16.7	1.00	2	4.0	1.000	604F0_Trip547	1
09/05/2026 12:58:19	52.366813	4.880106	243	Sudden braking	2.00	2.00	16.1	14.7	1.00	2	3.0	1.000	604F0_Trip547	1
09/05/2026 12:59:42	52.363790	4.881902	158	Sudden braking	2.00	2.00	17.7	17.5	1.00	2	4.6	1.000	604F0_Trip547	1
09/05/2026 12:59:43	52.363750	4.881921	169	Sudden braking	2.10	2.10	16.7	15.4	1.00	2	5.0	1.000	604F0_Trip547	1
09/05/2026 13:00:01	52.363157	4.880881	235	Sudden braking	2.40	2.40	16.8	16.9	1.00	2	4.4	1.000	604F0_Trip547	1
09/05/2026 13:00:02	52.363133	4.880830	236	Sudden braking	2.50	2.50	15.4	14.4	1.00	2	3.6	1.000	604F0_Trip547	1
09/05/2026 13:00:03	52.363113	4.880790	236	Sudden braking	2.00	2.00	13.9	12.4	1.00	2	2.8	1.000	604F0_Trip547	1
09/05/2026 13:06:21	52.354984	4.855942	254	Sudden braking	2.50	2.50	17.6	18.7	1.00	3	4.9	1.000	604F0_Trip547	1
09/05/2026 13:06:22	52.354973	4.855873	255	Sudden braking	3.00	3.00	15.9	15.7	1.00	2	4.3	1.000	604F0_Trip547	1
09/05/2026 13:06:23	52.354960	4.855814	252	Sudden braking	2.70	2.70	14.2	13.0	1.00	2	2.4	1.000	604F0_Trip547	1
09/05/2026 13:06:24	52.354949	4.855783	247	Sudden braking	2.30	2.30	12.6	10.7	1.00	2	2.3	1.000	604F0_Trip547	1
09/05/2026 13:07:34	52.354953	4.850638	268	Sudden braking	2.30	2.30	19.2	20.0	1.00	2	4.9	1.000	604F0_Trip547	1
09/05/2026 13:07:35	52.354950	4.850565	269	Sudden braking	2.50	2.50	18.0	17.5	1.00	2	3.7	1.000	604F0_Trip547	1
09/05/2026 13:07:36	52.354950	4.850510	271	Sudden braking	2.70	2.70	17.1	14.8	1.00	2	3.1	1.000	604F0_Trip547	1
09/05/2026 13:07:37	52.354950	4.850464	273	Sudden braking	2.30	2.30	16.5	12.5	1.00	2	2.2	1.000	604F0_Trip547	1
09/05/2026 13:08:49	52.355704	4.844655	269	Sudden braking	2.00	2.00	20.2	20.5	1.00	2	5.0	1.000	604F0_Trip547	1
09/05/2026 13:08:50	52.355704	4.844581	269	Sudden braking	2.10	2.10	19.2	18.4	1.00	2	4.1	1.000	604F0_Trip547	1
09/05/2026 13:08:51	52.355706	4.844521	271	Sudden braking	2.00	2.00	18.4	16.4	1.00	2	3.6	1.000	604F0_Trip547	1
09/05/2026 13:14:42	52.354373	4.811016	252	Sudden braking	2.10	2.10	19.2	20.1	1.00	2	5.2	1.000	604F0_Trip547	1
09/05/2026 13:14:43	52.354360	4.810942	253	Sudden braking	2.40	2.40	17.7	17.7	1.00	2	4.5	1.000	604F0_Trip547	1
09/05/2026 13:14:44	52.354349	4.810878	254	Sudden braking	2.40	2.40	16.2	15.3	1.00	2	3.9	1.000	604F0_Trip547	1
09/05/2026 13:14:45	52.354338	4.810823	254	Sudden braking	2.00	2.00	14.6	13.3	1.00	2	3.0	1.000	604F0_Trip547	1
10/05/2026 13:03:52	52.296717	4.867170	286	Sudden braking	2.51	2.51	9.8	7.5	1.00	2	2.6	0.998	602CA_Trip548	1
10/05/2026 13:03:53	52.296726	4.867135	293	Sudden braking	2.51	2.51	9.1	5.0	1.00	2	1.8	0.998	602CA_Trip548	1
10/05/2026 13:03:54	52.296734	4.867113	297	Sudden braking	2.24	2.24	6.4	2.8	0.98	2	0.3	0.981	602CA_Trip548	1
10/05/2026 14:05:46	52.356543	4.808904	158	Sudden braking	2.10	2.10	12.9	12.3	1.00	2	3.1	1.000	604F0_Trip550	1
10/05/2026 14:05:47	52.356522	4.808935	146	Sudden braking	2.90	2.90	12.3	9.4	1.00	2	2.2	1.000	604F0_Trip550	1
10/05/2026 14:05:48	52.356520	4.808966	122	Sudden braking	2.40	2.40	10.9	7.0	1.00	2	1.0	1.000	604F0_Trip550	1
10/05/2026 14:10:38	52.363955	4.826562	88	Sudden braking	2.10	2.10	18.4	18.9	1.00	2	4.4	1.000	604F0_Trip550	1
10/05/2026 14:10:39	52.363959	4.826627	87	Sudden braking	2.20	2.20	17.1	16.7	1.00	2	3.5	1.000	604F0_Trip550	1
10/05/2026 14:10:40	52.363959	4.826679	88	Sudden braking	2.10	2.10	16.0	14.6	1.00	2	2.9	1.000	604F0_Trip550	1
10/05/2026 14:10:50	52.363778	4.826909	149	Sudden braking	2.60	2.60	9.8	7.0	1.00	1	1.2	1.000	604F0_Trip550	1
10/05/2026 14:57:38	52.301526	4.867921	208	Sudden braking	2.06	2.06	11.0	11.5	1.02	2	3.4	1.020	602CA_Trip553	1
10/05/2026 14:57:39	52.301501	4.867896	211	Sudden braking	2.88	2.88	8.0	8.6	1.01	2	2.3	1.008	602CA_Trip553	1
10/05/2026 14:57:40	52.301483	4.867879	217	Sudden braking	2.95	2.95	6.5	5.7	0.98	2	2.1	0.983	602CA_Trip553	1
10/05/2026 14:57:41	52.301469	4.867858	227	Sudden braking	2.07	2.07	6.5	3.6	1.01	2	0.6	1.015	602CA_Trip553	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
10/05/2026 14:58:24	52.300651	4.867153	209	Sudden braking	2.07	2.07	6.2	6.5	0.96	2	1.6	0.965	602CA_Trip553	1
10/05/2026 14:59:01	52.299922	4.867370	145	Sudden braking	2.09	2.09	14.5	14.2	0.96	2	4.9	0.959	602CA_Trip553	1
10/05/2026 21:44:23	52.337467	4.945139	65	Sudden braking	2.00	2.00	11.2	12.1	1.00	2	1.9	1.000	602DE_Trip554	1
10/05/2026 21:44:25	52.337474	4.945173	68	Sudden braking	2.10	2.10	9.6	8.1	1.00	2	3.6	1.000	602DE_Trip554	1
10/05/2026 21:44:49	52.337839	4.946608	66	Sudden braking	2.10	2.10	13.0	12.2	1.00	2	4.5	1.000	602DE_Trip554	1
10/05/2026 21:46:36	52.339689	4.952361	92	Sudden braking	2.10	2.10	10.1	9.9	1.00	2	7.8	1.000	602DE_Trip554	1
11/05/2026 05:06:18	52.536431	4.694520	83	Sudden braking	2.20	2.20	34.2	34.8	1.00	3	9.0	1.000	63C0A_Trip556	1
11/05/2026 05:06:19	52.536433	4.694653	89	Sudden braking	2.30	2.30	33.0	32.5	1.00	3	8.0	1.000	63C0A_Trip556	1
11/05/2026 05:06:20	52.536407	4.694763	110	Sudden braking	2.00	2.00	31.8	30.5	1.00	3	8.2	1.000	63C0A_Trip556	1
11/05/2026 05:08:49	52.522515	4.702407	131	Sudden braking	2.00	2.00	33.4	35.5	1.00	3	10.0	1.000	63C0A_Trip556	1
11/05/2026 05:08:50	52.522456	4.702518	131	Sudden braking	2.70	2.70	31.8	32.8	1.00	3	9.3	1.000	63C0A_Trip556	1
11/05/2026 05:08:51	52.522400	4.702621	132	Sudden braking	3.00	3.00	30.2	29.8	1.00	3	6.9	1.000	63C0A_Trip556	1
11/05/2026 05:08:52	52.522358	4.702696	132	Sudden braking	3.10	3.10	28.7	26.7	1.00	3	5.7	1.000	63C0A_Trip556	1
11/05/2026 05:08:53	52.522324	4.702758	133	Sudden braking	2.50	2.50	27.3	24.2	1.00	3	2.7	1.000	63C0A_Trip556	1
11/05/2026 05:09:35	52.519859	4.706302	138	Sudden braking	2.00	2.00	35.5	36.9	1.00	3	10.3	1.000	63C0A_Trip556	1
11/05/2026 05:09:36	52.519788	4.706399	140	Sudden braking	2.80	2.80	34.0	34.1	1.00	3	8.5	1.000	63C0A_Trip556	1
11/05/2026 05:09:37	52.519727	4.706474	143	Sudden braking	3.10	3.10	32.6	31.0	1.00	3	5.2	1.000	63C0A_Trip556	1
11/05/2026 05:09:38	52.519688	4.706517	145	Sudden braking	3.00	3.00	31.5	28.0	1.00	3	2.0	1.000	63C0A_Trip556	1
11/05/2026 05:15:53	52.495281	4.756883	114	Sudden braking	2.20	2.20	34.6	33.5	1.00	2	8.6	1.000	63C0A_Trip556	1
11/05/2026 05:16:18	52.494963	4.760748	102	Sudden braking	2.90	2.90	30.4	34.7	1.00	3	8.4	1.000	63C0A_Trip556	1
11/05/2026 05:16:19	52.494947	4.760870	102	Sudden braking	4.00	4.00	27.5	30.7	1.00	3	6.6	1.000	63C0A_Trip556	1
11/05/2026 05:16:20	52.494935	4.760964	102	Sudden braking	5.30	5.30	24.5	25.4	1.00	3	5.2	1.000	63C0A_Trip556	1
11/05/2026 05:16:21	52.494925	4.761039	102	Sudden braking	5.50	5.50	21.3	19.9	1.00	3	3.4	1.000	63C0A_Trip556	1
11/05/2026 05:16:22	52.494918	4.761088	102	Sudden braking	4.70	4.70	18.1	15.2	1.00	3	1.8	1.000	63C0A_Trip556	1
11/05/2026 05:16:23	52.494915	4.761115	103	Sudden braking	3.90	3.90	16.2	11.3	1.00	3	2.3	1.000	63C0A_Trip556	1
11/05/2026 05:16:24	52.494910	4.761148	103	Sudden braking	2.90	2.90	14.1	8.4	1.00	3	1.5	1.000	63C0A_Trip556	1
11/05/2026 05:16:25	52.494907	4.761169	103	Sudden braking	2.00	2.00	12.0	6.4	1.00	3	1.7	1.000	63C0A_Trip556	1
11/05/2026 05:17:15	52.494163	4.764874	96	Sudden braking	2.30	2.30	26.7	28.3	1.00	3	7.1	1.000	63C0A_Trip556	1
11/05/2026 05:17:16	52.494157	4.764978	96	Sudden braking	2.70	2.70	24.5	25.6	1.00	3	6.2	1.000	63C0A_Trip556	1
11/05/2026 05:17:17	52.494151	4.765069	96	Sudden braking	3.00	3.00	22.3	22.6	1.00	3	5.1	1.000	63C0A_Trip556	1
11/05/2026 05:17:18	52.494146	4.765144	96	Sudden braking	3.10	3.10	20.1	19.5	1.00	3	4.1	1.000	63C0A_Trip556	1
11/05/2026 05:17:19	52.494142	4.765204	96	Sudden braking	2.90	2.90	18.8	16.6	1.00	3	3.1	1.000	63C0A_Trip556	1
11/05/2026 05:17:20	52.494139	4.765249	96	Sudden braking	2.70	2.70	17.5	13.9	1.00	3	2.8	1.000	63C0A_Trip556	1
11/05/2026 05:17:21	52.494137	4.765290	96	Sudden braking	2.40	2.40	16.2	11.5	1.00	3	2.6	1.000	63C0A_Trip556	1
11/05/2026 05:17:57	52.493797	4.768278	93	Sudden braking	2.60	2.60	33.6	32.9	1.00	3	9.8	1.000	63C0A_Trip556	1
11/05/2026 05:18:01	52.494014	4.768730	92	Sudden braking	2.40	2.40	29.1	27.9	1.00	3	4.6	1.000	63C0A_Trip556	1
11/05/2026 05:22:53	52.482469	4.807144	170	Sudden braking	2.10	2.10	33.2	37.2	1.00	3	11.1	1.000	63C0A_Trip556	1
11/05/2026 05:22:54	52.482371	4.807177	168	Sudden braking	3.50	3.50	31.4	33.7	1.00	3	8.6	1.000	63C0A_Trip556	1
11/05/2026 05:22:55	52.482296	4.807205	168	Sudden braking	4.50	4.50	29.7	29.2	1.00	3	6.1	1.000	63C0A_Trip556	1
11/05/2026 05:22:56	52.482241	4.807223	168	Sudden braking	4.60	4.60	28.3	24.6	1.00	3	9.4	1.000	63C0A_Trip556	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
11/05/2026 05:22:57	52.482225	4.807359	169	Sudden braking	3.50	3.50	27.2	21.1	1.00	3	3.3	1.000	63C0A_Trip556	1
11/05/2026 05:25:06	52.469169	4.805510	176	Sudden braking	2.70	2.70	35.0	35.0	1.00	3	8.6	1.000	63C0A_Trip556	1
11/05/2026 05:25:07	52.469092	4.805517	177	Sudden braking	2.50	2.50	34.3	32.5	1.00	3	5.6	1.000	63C0A_Trip556	1
11/05/2026 05:25:08	52.469041	4.805521	177	Sudden braking	2.00	2.00	33.7	30.5	1.00	3	7.3	1.000	63C0A_Trip556	1
11/05/2026 05:30:50	52.433993	4.815805	172	Sudden braking	2.40	2.40	33.3	35.3	1.00	3	9.8	1.000	63C0A_Trip556	1
11/05/2026 05:30:51	52.433905	4.815820	173	Sudden braking	3.40	3.40	32.0	31.9	1.00	3	8.8	1.000	63C0A_Trip556	1
11/05/2026 05:30:52	52.433827	4.815831	173	Sudden braking	3.60	3.60	31.2	28.3	1.00	3	6.8	1.000	63C0A_Trip556	1
11/05/2026 05:30:53	52.433766	4.815823	173	Sudden braking	2.70	2.70	30.1	25.6	1.00	3	5.5	1.000	63C0A_Trip556	1
11/05/2026 06:04:08	52.392501	4.867462	69	Sudden braking	2.10	2.10	33.0	33.4	1.00	3	8.1	1.000	63C0A_Trip556	1
11/05/2026 06:04:09	52.392535	4.867567	62	Sudden braking	2.10	2.10	31.7	31.3	1.00	3	6.6	1.000	63C0A_Trip556	1
11/05/2026 06:04:10	52.392568	4.867647	56	Sudden braking	2.10	2.10	30.5	29.2	1.00	3	7.6	1.000	63C0A_Trip556	1
11/05/2026 06:05:17	52.392600	4.876861	129	Sudden braking	2.80	2.80	24.9	28.9	1.00	2	8.4	1.000	63C0A_Trip556	1
11/05/2026 06:05:18	52.392548	4.876950	137	Sudden braking	4.10	4.10	22.7	24.8	1.00	2	5.1	1.000	63C0A_Trip556	1
11/05/2026 06:05:19	52.392510	4.876993	140	Sudden braking	5.00	5.00	20.6	19.8	1.00	3	4.3	1.000	63C0A_Trip556	1
11/05/2026 06:05:20	52.392480	4.877033	140	Sudden braking	4.90	4.90	18.8	14.9	1.00	3	2.6	1.000	63C0A_Trip556	1
11/05/2026 06:05:21	52.392460	4.877052	141	Sudden braking	3.60	3.60	17.2	11.3	1.00	3	1.8	1.000	63C0A_Trip556	1
11/05/2026 06:05:35	52.391925	4.877780	141	Sudden braking	2.70	2.70	23.7	25.1	1.00	2	7.1	1.001	63C0A_Trip556	1
11/05/2026 06:05:37	52.391875	4.877845	141	Sudden braking	3.40	3.40	22.1	21.7	1.00	2	5.4	0.999	63C0A_Trip556	1
11/05/2026 06:05:37	52.391838	4.877896	141	Sudden braking	3.00	3.00	22.1	18.7	1.00	3	2.9	1.001	63C0A_Trip556	1
11/05/2026 06:05:39	52.391819	4.877925	141	Sudden braking	2.10	2.10	21.1	16.6	1.00	3	3.7	1.000	63C0A_Trip556	1
11/05/2026 06:06:00	52.391286	4.880481	101	Sudden braking	2.00	2.00	32.8	33.3	1.00	3	9.3	1.000	63C0A_Trip556	1
11/05/2026 06:06:01	52.391272	4.880616	105	Sudden braking	2.10	2.10	32.0	31.2	1.00	2	8.3	1.000	63C0A_Trip556	1
11/05/2026 06:07:50	52.386324	4.892788	164	Sudden braking	2.30	2.30	32.4	35.7	1.00	3	9.7	1.000	63C0A_Trip556	1
11/05/2026 06:07:51	52.386239	4.892821	164	Sudden braking	3.20	3.20	30.0	32.5	1.00	3	8.2	1.000	63C0A_Trip556	1
11/05/2026 06:07:52	52.386168	4.892848	165	Sudden braking	4.10	4.10	27.4	28.4	1.00	2	7.5	1.000	63C0A_Trip556	1
11/05/2026 06:07:53	52.386103	4.892881	165	Sudden braking	4.00	4.00	24.5	24.4	1.00	3	5.7	1.000	63C0A_Trip556	1
11/05/2026 06:07:54	52.386054	4.892902	165	Sudden braking	3.60	3.60	21.6	20.8	1.00	3	5.1	1.000	63C0A_Trip556	1
11/05/2026 06:07:55	52.386010	4.892924	165	Sudden braking	3.70	3.70	18.7	17.1	1.00	3	4.9	1.000	63C0A_Trip556	1
11/05/2026 06:07:56	52.385968	4.892945	165	Sudden braking	3.40	3.40	15.9	13.7	1.00	3	3.3	1.000	63C0A_Trip556	1
11/05/2026 06:07:57	52.385939	4.892950	165	Sudden braking	2.70	2.70	13.5	11.0	1.00	3	2.0	1.000	63C0A_Trip556	1
11/05/2026 06:07:58	52.385922	4.892957	165	Sudden braking	2.30	2.30	11.3	8.7	1.00	3	1.8	1.000	63C0A_Trip556	1
11/05/2026 06:09:04	52.382055	4.895492	139	Sudden braking	2.60	2.60	31.4	34.3	1.00	2	9.3	1.000	63C0A_Trip556	1
11/05/2026 06:09:05	52.381990	4.895580	140	Sudden braking	3.40	3.40	29.1	30.9	1.00	2	7.8	1.000	63C0A_Trip556	1
11/05/2026 06:09:06	52.381936	4.895652	142	Sudden braking	4.10	4.10	26.8	26.8	1.00	2	6.6	1.000	63C0A_Trip556	1
11/05/2026 06:09:07	52.381889	4.895710	142	Sudden braking	4.10	4.10	24.3	22.7	1.00	3	5.3	1.000	63C0A_Trip556	1
11/05/2026 06:09:08	52.381851	4.895757	142	Sudden braking	3.40	3.40	21.8	19.3	1.00	3	4.2	1.000	63C0A_Trip556	1
11/05/2026 06:09:09	52.381822	4.895796	142	Sudden braking	2.50	2.50	19.1	16.8	1.00	3	3.9	1.000	63C0A_Trip556	1
11/05/2026 06:09:13	52.381712	4.895923	142	Sudden braking	2.10	2.10	12.6	10.4	1.00	3	2.4	1.000	63C0A_Trip556	1
11/05/2026 06:09:14	52.381697	4.895949	142	Sudden braking	2.80	2.80	11.6	7.6	1.00	3	1.9	1.000	63C0A_Trip556	1
11/05/2026 06:10:11	52.380367	4.898515	122	Sudden braking	2.20	2.20	28.6	29.1	1.00	3	7.9	1.000	63C0A_Trip556	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
11/05/2026 06:10:12	52.380329	4.898613	123	Sudden braking	2.50	2.50	27.0	26.6	1.00	2	6.7	1.000	63C0A_Trip556	1
11/05/2026 06:10:13	52.380298	4.898696	120	Sudden braking	2.10	2.10	25.3	24.5	1.00	2	5.4	1.000	63C0A_Trip556	1
11/05/2026 06:12:00	52.377893	4.909631	102	Sudden braking	2.20	2.20	31.1	32.9	1.00	2	8.7	1.000	63C0A_Trip556	1
11/05/2026 06:12:01	52.377877	4.909756	104	Sudden braking	3.00	3.00	29.6	29.9	1.00	2	7.5	1.000	63C0A_Trip556	1
11/05/2026 06:12:02	52.377856	4.909861	106	Sudden braking	3.30	3.30	28.3	26.6	1.00	2	6.6	1.000	63C0A_Trip556	1
11/05/2026 06:12:03	52.377816	4.909932	125	Sudden braking	2.80	2.80	27.1	23.8	1.00	2	5.7	1.000	63C0A_Trip556	1
11/05/2026 06:12:19	52.376609	4.910173	156	Sudden braking	2.00	2.00	28.1	30.0	1.00	2	8.5	1.000	63C0A_Trip556	1
11/05/2026 06:12:20	52.376535	4.910207	155	Sudden braking	2.50	2.50	27.1	27.5	1.00	2	4.3	1.000	63C0A_Trip556	1
11/05/2026 06:12:21	52.376506	4.910247	155	Sudden braking	2.70	2.70	26.2	24.8	1.00	3	4.7	1.000	63C0A_Trip556	1
11/05/2026 06:12:22	52.376490	4.910311	159	Sudden braking	2.50	2.50	25.3	22.3	1.00	2	6.2	1.000	63C0A_Trip556	1
11/05/2026 06:12:33	52.375843	4.910535	180	Sudden braking	2.80	2.80	20.4	21.9	1.00	3	4.6	1.000	63C0A_Trip556	1
11/05/2026 06:12:34	52.375802	4.910541	185	Sudden braking	3.90	3.90	19.2	18.0	1.00	3	3.9	1.000	63C0A_Trip556	1
11/05/2026 06:12:37	52.375786	4.910548	191	Sudden braking	2.40	2.40	16.0	11.9	1.00	3	3.1	1.000	63C0A_Trip556	1
11/05/2026 06:14:16	52.374806	4.915057	161	Sudden braking	2.20	2.20	15.1	15.5	1.00	2	4.2	1.000	63C0A_Trip556	1
11/05/2026 06:14:17	52.374771	4.915083	160	Sudden braking	2.70	2.70	14.1	12.8	1.00	2	3.2	0.999	63C0A_Trip556	1
11/05/2026 06:14:17	52.374749	4.915113	149	Sudden braking	2.20	2.20	13.2	10.6	1.00	2	2.4	1.000	63C0A_Trip556	1
11/05/2026 07:18:59	52.296410	4.868411	109	Sudden braking	2.73	2.73	10.7	11.7	0.99	1	3.0	0.989	602CA_Trip558	1
11/05/2026 07:19:00	52.296398	4.868451	111	Sudden braking	3.34	3.34	8.7	8.4	0.99	1	2.6	0.987	602CA_Trip558	1
11/05/2026 07:19:01	52.296387	4.868484	115	Sudden braking	3.02	3.02	8.7	5.3	1.03	1	1.3	1.028	602CA_Trip558	1
11/05/2026 07:19:02	52.296382	4.868501	115	Sudden braking	2.34	2.34	6.3	3.0	0.98	1	0.5	0.982	602CA_Trip558	1
11/05/2026 07:21:09	52.298456	4.869407	25	Sudden braking	2.59	2.59	16.7	17.7	1.00	2	4.3	1.005	602CA_Trip558	1
11/05/2026 07:21:10	52.298478	4.869459	40	Sudden braking	4.01	4.01	15.8	13.7	1.00	2	5.8	0.997	602CA_Trip558	1
11/05/2026 07:21:11	52.298529	4.869477	40	Sudden braking	2.68	2.68	14.6	11.0	1.01	2	2.7	1.007	602CA_Trip558	1
11/05/2026 07:30:46	52.327702	4.869144	9	Sudden braking	2.23	2.23	10.2	11.6	0.99	1	3.9	0.988	602CA_Trip558	1
11/05/2026 07:30:47	52.327735	4.869163	16	Sudden braking	3.02	3.02	10.2	8.6	0.99	1	3.0	0.992	602CA_Trip558	1
11/05/2026 07:30:48	52.327761	4.869172	15	Sudden braking	3.00	3.00	9.4	5.6	1.00	1	1.3	1.000	602CA_Trip558	1
11/05/2026 07:30:49	52.327766	4.869191	18	Sudden braking	2.50	2.50	8.4	3.1	1.00	1	1.7	1.002	602CA_Trip558	1
11/05/2026 07:33:07	52.331871	4.869137	8	Sudden braking	2.77	2.77	12.4	14.1	1.01	3	5.8	1.011	602CA_Trip558	1
11/05/2026 07:33:08	52.331923	4.869140	12	Sudden braking	3.60	3.60	11.6	10.5	1.00	3	4.4	0.999	602CA_Trip558	1
11/05/2026 07:33:09	52.331961	4.869156	7	Sudden braking	3.18	3.18	9.7	7.3	1.00	3	2.6	1.005	602CA_Trip558	1
11/05/2026 07:33:10	52.331983	4.869167	7	Sudden braking	2.09	2.09	9.7	5.2	1.00	3	0.9	1.004	602CA_Trip558	1
11/05/2026 07:34:10	52.334864	4.869149	0	Sudden braking	2.61	2.61	9.2	10.8	1.00	1	3.2	0.998	602CA_Trip558	1
11/05/2026 07:34:11	52.334892	4.869153	3	Sudden braking	2.89	2.89	9.2	7.9	1.00	1	2.6	1.003	602CA_Trip558	1
11/05/2026 07:34:12	52.334915	4.869157	14	Sudden braking	2.73	2.73	7.2	5.2	0.99	1	1.8	0.988	602CA_Trip558	1
11/05/2026 07:34:13	52.334930	4.869164	23	Sudden braking	2.22	2.22	6.0	3.0	0.99	1	0.1	0.990	602CA_Trip558	1
11/05/2026 07:35:15	52.336755	4.869103	5	Sudden braking	2.17	2.17	14.1	15.0	1.01	4	5.2	1.013	602CA_Trip558	1
11/05/2026 07:35:16	52.336801	4.869091	357	Sudden braking	2.99	2.99	11.9	12.0	1.00	2	3.3	1.004	602CA_Trip558	1
11/05/2026 07:35:17	52.336830	4.869082	346	Sudden braking	3.55	3.55	10.9	8.5	0.99	2	2.2	0.987	602CA_Trip558	1
11/05/2026 07:35:18	52.336844	4.869059	338	Sudden braking	2.58	2.58	10.1	5.9	1.01	2	0.6	1.007	602CA_Trip558	1
11/05/2026 07:36:06	52.338637	4.868394	338	Sudden braking	2.29	2.29	22.9	26.3	1.00	3	8.3	1.005	602CA_Trip558	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
11/05/2026 07:36:07	52.338700	4.868330	333	Sudden braking	2.81	2.81	22.6	23.5	0.99	3	5.7	0.995	602CA_Trip558	1
11/05/2026 07:36:08	52.338745	4.868289	328	Sudden braking	2.38	2.38	22.1	21.1	1.01	2	5.2	1.010	602CA_Trip558	1
11/05/2026 07:36:09	52.338786	4.868325	330	Sudden braking	2.71	2.71	21.5	18.4	1.00	2	5.3	0.996	602CA_Trip558	1
11/05/2026 07:38:37	52.346184	4.867339	353	Sudden braking	2.45	2.45	11.1	10.8	1.02	2	2.9	1.021	602CA_Trip558	1
11/05/2026 07:38:38	52.346210	4.867332	342	Sudden braking	3.03	3.03	9.2	7.8	0.99	2	3.1	0.989	602CA_Trip558	1
11/05/2026 07:38:39	52.346236	4.867316	339	Sudden braking	2.67	2.67	8.1	5.2	0.97	2	1.9	0.975	602CA_Trip558	1
11/05/2026 07:38:40	52.346253	4.867318	336	Sudden braking	2.10	2.10	8.1	3.1	1.00	2	1.3	0.999	602CA_Trip558	1
11/05/2026 07:39:48	52.346655	4.867826	79	Sudden braking	2.92	2.92	12.1	12.8	0.99	2	4.1	0.994	602CA_Trip558	1
11/05/2026 07:39:49	52.346661	4.867886	82	Sudden braking	3.39	3.39	11.4	9.4	1.00	2	2.0	1.003	602CA_Trip558	1
11/05/2026 07:39:50	52.346667	4.867914	78	Sudden braking	3.44	3.44	9.3	6.0	0.99	2	0.9	0.989	602CA_Trip558	1
11/05/2026 07:39:51	52.346667	4.867928	77	Sudden braking	3.01	3.01	9.3	3.0	1.00	2	0.1	0.997	602CA_Trip558	1
11/05/2026 07:39:52	52.346668	4.867929	76	Sudden braking	2.00	2.00	8.0	1.0	1.00	2	0.1	1.002	602CA_Trip558	1
11/05/2026 07:41:20	52.350140	4.866742	346	Sudden braking	2.33	2.33	11.0	10.1	0.99	3	3.3	0.989	602CA_Trip558	1
11/05/2026 07:42:24	52.350169	4.870913	88	Sudden braking	2.48	2.48	7.6	8.0	1.01	2	2.6	1.007	602CA_Trip558	1
11/05/2026 07:42:25	52.350178	4.870948	57	Sudden braking	2.59	2.59	7.0	5.4	1.00	2	0.7	1.003	602CA_Trip558	1
11/05/2026 07:42:26	52.350183	4.870955	36	Sudden braking	2.24	2.24	4.7	3.2	0.98	3	2.0	0.983	602CA_Trip558	1
11/05/2026 07:43:37	52.352899	4.870165	335	Sudden braking	2.12	2.12	15.8	15.8	0.99	2	5.0	0.991	602CA_Trip558	1
11/05/2026 07:43:38	52.352937	4.870127	332	Sudden braking	2.10	2.10	15.7	13.7	1.00	3	3.8	0.998	602CA_Trip558	1
11/05/2026 07:47:28	52.360469	4.876781	72	Sudden braking	2.10	2.10	21.2	21.4	1.00	2	5.6	0.998	602CA_Trip558	1
11/05/2026 07:49:52	52.360514	4.885821	137	Sudden braking	2.00	2.00	11.3	11.6	1.00	2	2.8	0.998	602CA_Trip558	1
11/05/2026 07:51:31	52.362507	4.887730	27	Sudden braking	2.04	2.04	12.7	13.4	0.98	2	4.9	0.982	602CA_Trip558	1
11/05/2026 07:51:32	52.362541	4.887774	32	Sudden braking	2.31	2.31	12.0	11.1	1.00	3	3.5	0.997	602CA_Trip558	1
11/05/2026 07:51:33	52.362566	4.887805	27	Sudden braking	2.09	2.09	10.7	9.0	1.00	3	2.0	1.005	602CA_Trip558	1
11/05/2026 07:52:17	52.364147	4.889352	19	Sudden braking	2.28	2.28	16.6	15.8	1.01	3	4.3	1.009	602CA_Trip558	1
11/05/2026 07:52:18	52.364183	4.889373	12	Sudden braking	2.22	2.22	15.5	13.6	0.99	3	3.2	0.993	602CA_Trip558	1
11/05/2026 07:52:45	52.365232	4.890310	30	Sudden braking	2.04	2.04	13.0	14.2	0.98	3	3.6	0.979	602CA_Trip558	1
11/05/2026 07:52:46	52.365259	4.890338	31	Sudden braking	2.14	2.14	13.0	12.0	1.03	3	3.4	1.028	602CA_Trip558	1
11/05/2026 07:52:47	52.365285	4.890363	24	Sudden braking	2.19	2.19	10.3	9.8	1.01	2	2.8	1.006	602CA_Trip558	1
11/05/2026 07:53:26	52.365062	4.892413	115	Sudden braking	2.66	2.66	13.8	12.3	0.98	2	4.1	0.978	602CA_Trip558	1
11/05/2026 07:56:35	52.367847	4.903263	69	Sudden braking	2.54	2.54	13.1	15.3	0.98	2	4.5	0.983	602CA_Trip558	1
11/05/2026 07:56:36	52.367851	4.903329	87	Sudden braking	3.30	3.30	12.4	12.0	1.00	2	3.9	1.001	602CA_Trip558	1
11/05/2026 07:56:37	52.367849	4.903387	103	Sudden braking	3.05	3.05	10.5	8.9	1.02	2	2.0	1.016	602CA_Trip558	1
11/05/2026 07:56:38	52.367844	4.903414	110	Sudden braking	2.95	2.95	8.3	6.0	0.98	2	0.6	0.982	602CA_Trip558	1
11/05/2026 07:56:39	52.367839	4.903409	64	Sudden braking	2.56	2.56	8.3	3.4	1.01	2	1.8	1.014	602CA_Trip558	1
11/05/2026 07:57:20	52.368599	4.903906	64	Sudden braking	2.63	2.63	11.5	13.3	1.03	2	4.1	1.026	602CA_Trip558	1
11/05/2026 07:57:21	52.368606	4.903966	64	Sudden braking	3.24	3.24	10.8	10.1	0.99	2	2.2	0.988	602CA_Trip558	1
11/05/2026 07:57:22	52.368611	4.903998	72	Sudden braking	3.40	3.40	10.8	6.7	1.00	2	1.8	0.999	602CA_Trip558	1
11/05/2026 07:57:23	52.368601	4.904018	129	Sudden braking	3.12	3.12	7.8	3.6	0.99	2	1.9	0.992	602CA_Trip558	1
11/05/2026 07:57:24	52.368584	4.904025	157	Sudden braking	2.03	2.03	6.2	1.6	0.98	2	0.1	0.983	602CA_Trip558	1
11/05/2026 07:58:34	52.370035	4.908244	56	Sudden braking	2.22	2.22	14.4	15.5	1.03	1	4.6	1.035	602CA_Trip558	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
11/05/2026 07:58:35	52.370051	4.908307	55	Sudden braking	3.26	3.26	11.5	12.3	0.98	1	2.8	0.983	602CA_Trip558	1
11/05/2026 07:58:36	52.370064	4.908343	59	Sudden braking	3.72	3.72	11.5	8.6	0.99	1	2.7	0.994	602CA_Trip558	1
11/05/2026 07:58:37	52.370072	4.908379	62	Sudden braking	3.26	3.26	10.4	5.4	0.98	1	1.8	0.982	602CA_Trip558	1
11/05/2026 07:58:38	52.370076	4.908406	65	Sudden braking	2.46	2.46	7.6	2.9	1.01	1	1.5	1.015	602CA_Trip558	1
11/05/2026 08:00:51	52.371012	4.914954	68	Sudden braking	2.19	2.19	12.4	13.4	1.00	2	4.2	1.004	602CA_Trip558	1
11/05/2026 08:00:52	52.371025	4.915012	72	Sudden braking	2.39	2.39	11.3	11.0	1.01	2	2.9	1.006	602CA_Trip558	1
11/05/2026 08:00:53	52.371029	4.915054	85	Sudden braking	2.68	2.68	9.5	8.3	1.01	2	2.3	1.006	602CA_Trip558	1
11/05/2026 08:00:54	52.371030	4.915087	75	Sudden braking	2.76	2.76	6.6	5.5	1.02	2	1.2	1.016	602CA_Trip558	1
11/05/2026 08:00:55	52.371038	4.915100	63	Sudden braking	2.32	2.32	5.5	3.2	0.99	2	0.4	0.990	602CA_Trip558	1
11/05/2026 08:10:19	52.353815	4.809169	73	Sudden braking	2.40	2.40	19.8	21.0	1.00	2	4.8	1.000	604F0_Trip559	1
11/05/2026 08:10:20	52.353831	4.809235	74	Sudden braking	3.01	3.01	17.8	18.0	1.00	2	3.3	0.996	604F0_Trip559	1
11/05/2026 08:10:21	52.353842	4.809280	73	Sudden braking	3.70	3.70	16.9	14.3	1.00	2	2.1	1.000	604F0_Trip559	1
11/05/2026 08:10:22	52.353849	4.809308	72	Sudden braking	3.70	3.70	15.8	10.6	1.00	2	1.8	1.000	604F0_Trip559	1
11/05/2026 08:13:56	52.356109	4.826951	91	Sudden braking	2.10	2.10	16.4	15.9	1.00	2	3.4	1.000	604F0_Trip559	1
11/05/2026 08:13:57	52.356105	4.827001	95	Sudden braking	2.20	2.20	14.8	13.7	1.00	2	2.9	1.001	604F0_Trip559	1
11/05/2026 08:13:59	52.356101	4.827044	101	Sudden braking	2.10	2.10	12.3	11.6	1.00	2	2.6	1.000	604F0_Trip559	1
11/05/2026 08:16:18	52.356277	4.840228	91	Sudden braking	2.60	2.60	19.4	19.8	1.00	2	4.6	1.000	604F0_Trip559	1
11/05/2026 08:16:19	52.356277	4.840296	90	Sudden braking	2.80	2.80	18.3	17.0	1.00	2	2.8	1.000	604F0_Trip559	1
11/05/2026 08:16:20	52.356277	4.840338	89	Sudden braking	2.50	2.50	17.4	14.5	1.00	2	2.5	1.000	604F0_Trip559	1
11/05/2026 08:18:30	52.354950	4.850038	89	Sudden braking	2.30	2.30	15.0	15.7	1.00	2	3.7	1.000	604F0_Trip559	1
11/05/2026 08:18:31	52.354951	4.850093	89	Sudden braking	2.90	2.90	14.2	12.8	1.00	2	2.5	1.000	604F0_Trip559	1
11/05/2026 08:18:32	52.354951	4.850129	89	Sudden braking	3.40	3.40	13.3	9.4	1.00	2	1.4	1.000	604F0_Trip559	1
11/05/2026 08:19:29	52.354716	4.854680	83	Sudden braking	2.00	2.00	23.1	25.2	1.00	2	6.5	1.000	604F0_Trip559	1
11/05/2026 08:19:30	52.354724	4.854775	81	Sudden braking	2.70	2.70	21.6	22.5	1.00	2	5.7	1.000	604F0_Trip559	1
11/05/2026 08:19:31	52.354732	4.854857	81	Sudden braking	2.80	2.80	19.9	19.7	1.00	2	4.4	1.000	604F0_Trip559	1
11/05/2026 08:19:32	52.354740	4.854920	78	Sudden braking	2.50	2.50	18.2	17.2	1.00	2	3.0	1.000	604F0_Trip559	1
11/05/2026 08:19:33	52.354746	4.854963	78	Sudden braking	2.30	2.30	16.4	14.9	1.00	2	3.0	1.000	604F0_Trip559	1
11/05/2026 08:19:34	52.354754	4.855004	75	Sudden braking	2.00	2.00	14.6	12.9	1.00	2	3.4	1.000	604F0_Trip559	1
11/05/2026 08:24:48	52.361612	4.881579	52	Sudden braking	2.20	2.20	18.0	19.1	1.00	2	4.5	1.000	604F0_Trip559	1
11/05/2026 08:24:49	52.361639	4.881629	50	Sudden braking	2.80	2.80	17.2	16.3	1.00	2	3.3	1.000	604F0_Trip559	1
11/05/2026 08:24:50	52.361659	4.881663	47	Sudden braking	3.60	3.60	16.3	12.7	1.00	2	1.9	1.000	604F0_Trip559	1
11/05/2026 08:24:51	52.361672	4.881682	40	Sudden braking	4.00	4.00	15.2	8.7	1.00	2	1.3	1.000	604F0_Trip559	1
11/05/2026 08:27:11	52.359633	4.890108	112	Sudden braking	2.30	2.30	17.8	18.4	1.00	2	4.7	1.000	604F0_Trip559	1
11/05/2026 08:27:12	52.359614	4.890169	114	Sudden braking	2.90	2.90	17.0	15.5	1.00	2	3.7	1.000	604F0_Trip559	1
11/05/2026 08:27:13	52.359593	4.890211	118	Sudden braking	3.30	3.30	16.1	12.2	1.00	2	1.8	1.000	604F0_Trip559	1
11/05/2026 08:27:14	52.359585	4.890235	116	Sudden braking	3.10	3.10	13.8	9.1	1.00	2	1.4	1.000	604F0_Trip559	1
11/05/2026 08:28:44	52.359367	4.898154	78	Sudden braking	2.10	2.10	18.3	19.1	1.00	2	5.3	1.000	604F0_Trip559	1
11/05/2026 08:28:45	52.359381	4.898229	78	Sudden braking	2.90	2.90	17.5	16.2	1.00	2	3.6	1.000	604F0_Trip559	1
11/05/2026 08:28:46	52.359388	4.898281	78	Sudden braking	3.30	3.30	16.7	12.9	1.00	2	1.5	1.000	604F0_Trip559	1
11/05/2026 08:28:47	52.359390	4.898304	78	Sudden braking	3.00	3.00	15.7	9.9	1.00	2	1.2	1.000	604F0_Trip559	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
11/05/2026 08:32:08	52.362794	4.916152	72	Sudden braking	2.10	2.10	19.0	21.5	1.00	2	4.7	1.000	604F0_Trip559	1
11/05/2026 08:32:09	52.362809	4.916217	71	Sudden braking	3.00	3.00	17.2	18.5	1.00	2	4.2	1.000	604F0_Trip559	1
11/05/2026 08:32:10	52.362820	4.916277	73	Sudden braking	3.40	3.40	15.4	15.1	1.00	2	2.9	1.000	604F0_Trip559	1
11/05/2026 08:32:11	52.362829	4.916317	70	Sudden braking	3.10	3.10	13.7	12.0	1.00	2	2.6	1.000	604F0_Trip559	1
11/05/2026 08:32:12	52.362834	4.916354	68	Sudden braking	2.60	2.60	12.0	9.4	1.00	2	1.7	1.000	604F0_Trip559	1
11/05/2026 08:32:13	52.362842	4.916375	58	Sudden braking	2.10	2.10	10.6	7.3	1.00	2	1.5	1.000	604F0_Trip559	1
11/05/2026 08:32:44	52.363427	4.918328	71	Sudden braking	2.80	2.80	17.4	14.9	1.00	2	3.9	1.000	604F0_Trip559	1
11/05/2026 08:32:45	52.363438	4.918383	72	Sudden braking	3.00	3.00	15.7	11.9	1.00	2	1.4	1.000	604F0_Trip559	1
11/05/2026 08:34:17	52.365437	4.914344	299	Sudden braking	2.40	2.40	17.1	17.1	1.00	2	6.1	1.000	604F0_Trip559	1
11/05/2026 08:34:18	52.365489	4.914318	305	Sudden braking	2.50	2.50	16.9	14.6	1.00	2	2.4	1.000	604F0_Trip559	1
11/05/2026 08:36:11	52.369508	4.912345	304	Sudden braking	2.20	2.20	16.5	16.9	1.00	2	3.7	1.000	604F0_Trip559	1
11/05/2026 08:36:12	52.369535	4.912315	317	Sudden braking	2.20	2.20	15.8	14.7	1.00	2	4.3	1.000	604F0_Trip559	1
11/05/2026 08:36:13	52.369572	4.912335	354	Sudden braking	2.00	2.00	15.2	12.7	1.00	2	3.0	1.000	604F0_Trip559	1
11/05/2026 08:37:12	52.370994	4.914981	60	Sudden braking	2.00	2.00	15.8	16.3	1.00	2	3.8	1.000	604F0_Trip559	1
11/05/2026 08:37:13	52.371001	4.915035	70	Sudden braking	2.40	2.40	15.1	13.9	1.00	2	3.1	1.000	604F0_Trip559	1
11/05/2026 08:37:14	52.370999	4.915080	83	Sudden braking	3.10	3.10	14.2	10.8	1.00	2	2.3	1.000	604F0_Trip559	1
11/05/2026 08:37:15	52.371001	4.915114	84	Sudden braking	3.00	3.00	13.3	7.8	1.00	2	1.6	1.000	604F0_Trip559	1
11/05/2026 08:38:14	52.372336	4.918383	45	Sudden braking	2.10	2.10	13.4	13.6	1.00	2	3.1	1.000	604F0_Trip559	1
11/05/2026 08:38:15	52.372352	4.918421	46	Sudden braking	2.40	2.40	12.4	11.2	1.00	2	2.3	1.000	604F0_Trip559	1
11/05/2026 08:38:16	52.372367	4.918445	43	Sudden braking	2.40	2.40	11.5	8.8	1.00	2	1.0	1.000	604F0_Trip559	1
11/05/2026 15:13:20	52.359064	4.784448	172	Sudden braking	2.00	2.00	12.6	10.8	1.00	2	2.2	1.000	604F0_Trip564	1
11/05/2026 15:31:03	52.376126	4.910772	241	Sudden braking	2.10	2.10	18.7	20.0	1.00	3	4.7	1.000	63C0A_Trip568	1
11/05/2026 15:31:04	52.376103	4.910713	240	Sudden braking	2.60	2.60	17.8	17.4	1.00	3	3.4	1.000	63C0A_Trip568	1
11/05/2026 15:31:05	52.376091	4.910668	242	Sudden braking	2.50	2.50	16.8	14.9	1.00	3	3.2	1.000	63C0A_Trip568	1
11/05/2026 15:31:14	52.375828	4.910625	171	Sudden braking	2.00	2.00	9.4	8.5	1.00	3	1.3	1.000	63C0A_Trip568	1
11/05/2026 15:31:37	52.376953	4.910184	353	Sudden braking	2.70	2.70	24.4	24.8	1.00	3	8.6	1.000	63C0A_Trip568	1
11/05/2026 15:31:38	52.377012	4.910101	340	Sudden braking	3.10	3.10	23.5	21.7	1.00	3	3.8	1.000	63C0A_Trip568	1
11/05/2026 15:31:39	52.377046	4.910099	348	Sudden braking	2.20	2.20	22.6	19.5	1.00	3	4.1	1.000	63C0A_Trip568	1
11/05/2026 15:32:16	52.378218	4.907449	282	Sudden braking	2.20	2.20	26.1	28.5	1.00	3	8.1	1.000	63C0A_Trip568	1
11/05/2026 15:32:17	52.378230	4.907332	280	Sudden braking	2.70	2.70	24.0	25.8	1.00	3	6.8	1.000	63C0A_Trip568	1
11/05/2026 15:32:18	52.378238	4.907233	278	Sudden braking	2.90	2.90	23.1	22.9	1.00	2	4.9	1.000	63C0A_Trip568	1
11/05/2026 15:32:19	52.378252	4.907166	283	Sudden braking	3.50	3.50	20.8	19.4	1.00	2	5.1	1.000	63C0A_Trip568	1
11/05/2026 15:32:20	52.378263	4.907092	282	Sudden braking	4.00	4.00	18.6	15.4	1.00	2	4.0	1.000	63C0A_Trip568	1
11/05/2026 15:32:21	52.378271	4.907034	282	Sudden braking	3.10	3.10	16.9	12.3	1.00	2	2.0	1.000	63C0A_Trip568	1
11/05/2026 15:35:12	52.382925	4.893723	267	Sudden braking	2.00	2.00	17.7	17.8	1.00	3	4.4	1.000	63C0A_Trip568	1
11/05/2026 15:35:13	52.382923	4.893658	267	Sudden braking	2.00	2.00	16.8	15.8	1.00	2	4.0	1.000	63C0A_Trip568	1
11/05/2026 15:35:42	52.384861	4.893250	11	Sudden braking	2.80	2.80	29.9	33.2	1.00	3	8.2	1.000	63C0A_Trip568	1
11/05/2026 15:35:43	52.384934	4.893272	7	Sudden braking	3.50	3.50	27.3	29.7	1.00	3	6.9	1.000	63C0A_Trip568	1
11/05/2026 15:35:44	52.384996	4.893280	7	Sudden braking	4.20	4.20	24.4	25.5	1.00	3	5.8	1.000	63C0A_Trip568	1
11/05/2026 15:35:45	52.385047	4.893291	4	Sudden braking	4.50	4.50	23.0	21.0	1.00	3	5.2	1.000	63C0A_Trip568	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
11/05/2026 15:35:46	52.385094	4.893301	4	Sudden braking	4.20	4.20	20.0	16.8	1.00	3	3.1	1.000	63C0A_Trip568	1
11/05/2026 15:35:47	52.385122	4.893304	2	Sudden braking	4.00	4.00	18.2	12.8	1.00	3	2.2	1.000	63C0A_Trip568	1
11/05/2026 15:35:48	52.385142	4.893304	2	Sudden braking	3.30	3.30	16.4	9.5	1.00	3	1.3	1.000	63C0A_Trip568	1
11/05/2026 15:36:48	52.388975	4.891772	345	Sudden braking	2.10	2.10	28.7	29.6	1.00	3	7.7	1.000	63C0A_Trip568	1
11/05/2026 15:36:49	52.389042	4.891744	344	Sudden braking	2.70	2.70	26.7	26.9	1.00	2	7.6	1.000	63C0A_Trip568	1
11/05/2026 15:36:50	52.389108	4.891713	344	Sudden braking	2.90	2.90	25.0	24.0	1.00	3	6.5	1.000	63C0A_Trip568	1
11/05/2026 15:36:51	52.389165	4.891688	344	Sudden braking	2.50	2.50	23.5	21.5	1.00	3	4.7	1.000	63C0A_Trip568	1
11/05/2026 15:36:52	52.389205	4.891668	344	Sudden braking	2.20	2.20	22.3	19.3	1.00	3	4.5	1.000	63C0A_Trip568	1
11/05/2026 15:37:42	52.390509	4.885532	300	Sudden braking	2.10	2.10	25.3	25.6	1.00	2	6.8	1.000	63C0A_Trip568	1
11/05/2026 15:37:43	52.390539	4.885446	300	Sudden braking	2.40	2.40	24.5	23.2	1.00	3	4.6	1.000	63C0A_Trip568	1
11/05/2026 15:37:44	52.390559	4.885387	300	Sudden braking	2.10	2.10	23.9	21.1	1.00	3	4.8	1.000	63C0A_Trip568	1
11/05/2026 15:46:54	52.417875	4.826835	41	Sudden braking	2.10	2.10	10.4	9.0	1.00	2	1.8	1.000	63C0A_Trip568	1
11/05/2026 15:46:55	52.417888	4.826851	39	Sudden braking	2.40	2.40	9.6	6.6	1.00	2	1.4	1.000	63C0A_Trip568	1
11/05/2026 16:09:08	52.433757	4.816169	258	Sudden braking	2.60	2.60	31.5	33.6	1.00	3	9.1	1.000	63C0A_Trip568	1
11/05/2026 16:09:09	52.433738	4.816038	257	Sudden braking	3.50	3.50	30.2	30.1	1.00	3	7.2	1.000	63C0A_Trip568	1
11/05/2026 16:09:10	52.433731	4.815933	262	Sudden braking	3.50	3.50	29.0	26.6	1.00	3	5.4	1.000	63C0A_Trip568	1
11/05/2026 16:09:11	52.433747	4.815858	278	Sudden braking	2.70	2.70	27.8	23.9	1.00	3	5.8	1.000	63C0A_Trip568	1
11/05/2026 16:16:01	52.470160	4.805491	357	Sudden braking	2.00	2.00	27.7	29.5	1.00	3	7.4	1.000	63C0A_Trip568	1
11/05/2026 16:16:02	52.470226	4.805487	358	Sudden braking	2.40	2.40	25.2	27.1	1.00	3	7.2	1.000	63C0A_Trip568	1
11/05/2026 16:16:03	52.470291	4.805483	358	Sudden braking	3.00	3.00	22.7	24.1	1.00	3	5.3	1.000	63C0A_Trip568	1
11/05/2026 16:16:04	52.470339	4.805481	358	Sudden braking	3.60	3.60	20.0	20.5	1.00	3	4.6	0.999	63C0A_Trip568	1
11/05/2026 16:16:04	52.470380	4.805478	358	Sudden braking	3.80	3.80	17.5	16.7	1.00	3	2.7	1.000	63C0A_Trip568	1
11/05/2026 16:16:05	52.470405	4.805477	358	Sudden braking	3.50	3.50	15.1	13.2	1.00	3	2.0	1.000	63C0A_Trip568	1
11/05/2026 16:16:06	52.470423	4.805476	358	Sudden braking	2.90	2.90	13.7	10.3	1.00	2	1.4	1.000	63C0A_Trip568	1
11/05/2026 16:16:07	52.470436	4.805475	358	Sudden braking	2.30	2.30	12.2	8.0	1.00	2	1.8	1.000	63C0A_Trip568	1
11/05/2026 16:19:07	52.484907	4.806175	324	Sudden braking	2.30	2.30	26.9	29.1	1.00	3	8.2	1.000	63C0A_Trip568	1
11/05/2026 16:19:08	52.484966	4.806101	323	Sudden braking	2.70	2.70	24.3	26.4	1.00	3	6.3	1.000	63C0A_Trip568	1
11/05/2026 16:19:09	52.485010	4.806045	322	Sudden braking	3.00	3.00	23.2	23.4	1.00	3	5.2	1.000	63C0A_Trip568	1
11/05/2026 16:19:10	52.485047	4.805998	322	Sudden braking	3.50	3.50	20.2	19.9	1.00	3	4.6	1.000	63C0A_Trip568	1
11/05/2026 16:19:11	52.485080	4.805957	322	Sudden braking	4.30	4.30	17.2	15.6	1.00	3	4.0	1.000	63C0A_Trip568	1
11/05/2026 16:19:12	52.485107	4.805919	320	Sudden braking	4.40	4.40	15.7	11.2	1.00	3	1.6	1.000	63C0A_Trip568	1
11/05/2026 16:19:15	52.485126	4.805884	315	Sudden braking	2.80	2.80	10.3	4.7	1.00	3	0.2	1.000	63C0A_Trip568	1
11/05/2026 16:20:38	52.488421	4.796635	302	Sudden braking	2.30	2.30	31.3	36.3	1.00	3	10.1	1.000	63C0A_Trip568	1
11/05/2026 16:20:39	52.488475	4.796515	302	Sudden braking	3.70	3.70	28.6	32.6	1.00	3	8.8	1.000	63C0A_Trip568	1
11/05/2026 16:20:40	52.488519	4.796408	302	Sudden braking	5.10	5.10	25.8	27.5	1.00	3	6.8	1.000	63C0A_Trip568	1
11/05/2026 16:20:41	52.488549	4.796322	301	Sudden braking	5.80	5.80	23.1	21.7	1.00	2	4.7	1.000	63C0A_Trip568	1
11/05/2026 16:20:42	52.488559	4.796254	301	Sudden braking	5.40	5.40	21.4	16.3	1.00	2	3.0	1.000	63C0A_Trip568	1
11/05/2026 16:20:43	52.488584	4.796233	299	Sudden braking	4.30	4.30	18.8	12.0	1.00	2	1.9	1.000	63C0A_Trip568	1
11/05/2026 16:20:44	52.488592	4.796209	299	Sudden braking	2.20	2.20	16.8	9.8	1.00	3	1.8	1.000	63C0A_Trip568	1
11/05/2026 16:23:15	52.492949	4.776117	290	Sudden braking	2.00	2.00	38.4	37.0	1.00	3	38.0	1.000	63C0A_Trip568	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
11/05/2026 16:35:48	52.521898	4.702511	313	Sudden braking	2.50	2.50	26.5	27.9	1.00	3	7.9	1.000	63C0A_Trip568	1
11/05/2026 16:35:49	52.521947	4.702426	312	Sudden braking	3.30	3.30	25.4	24.6	1.00	3	6.5	1.000	63C0A_Trip568	1
11/05/2026 16:35:50	52.521986	4.702354	311	Sudden braking	3.20	3.20	24.6	21.4	1.00	3	3.8	1.000	63C0A_Trip568	1
11/05/2026 16:35:51	52.522008	4.702310	314	Sudden braking	2.40	2.40	23.6	19.0	1.00	3	2.1	1.000	63C0A_Trip568	1
11/05/2026 20:00:34	52.371072	4.913213	271	Sudden braking	2.11	2.11	6.6	5.8	0.99	2	1.7	0.993	602CA_Trip572	1
11/05/2026 20:01:54	52.368892	4.913992	117	Sudden braking	2.23	2.23	10.8	11.0	0.94	2	3.8	0.941	602CA_Trip572	1
11/05/2026 20:07:50	52.358834	4.903739	251	Sudden braking	2.26	2.26	8.3	9.5	0.97	2	3.5	0.974	602CA_Trip572	1
11/05/2026 20:07:51	52.358822	4.903691	243	Sudden braking	2.39	2.39	7.4	7.1	1.00	2	1.8	1.003	602CA_Trip572	1
11/05/2026 20:07:52	52.358815	4.903667	242	Sudden braking	2.38	2.38	5.3	4.7	1.01	2	0.9	1.007	602CA_Trip572	1
11/05/2026 20:09:15	52.356159	4.904878	167	Sudden braking	2.07	2.07	11.2	12.5	1.01	2	3.8	1.013	602CA_Trip572	1
11/05/2026 20:09:16	52.356125	4.904890	168	Sudden braking	2.12	2.12	10.3	10.4	0.99	2	3.5	0.992	602CA_Trip572	1
11/05/2026 20:09:17	52.356094	4.904898	177	Sudden braking	2.18	2.18	9.4	8.3	0.96	2	3.1	0.965	602CA_Trip572	1
11/05/2026 20:09:18	52.356066	4.904898	184	Sudden braking	2.10	2.10	7.5	6.1	1.05	2	2.4	1.047	602CA_Trip572	1
11/05/2026 20:09:19	52.356046	4.904886	213	Sudden braking	2.06	2.06	5.0	4.1	0.97	2	1.2	0.969	602CA_Trip572	1
11/05/2026 20:12:57	52.347273	4.911372	187	Sudden braking	2.02	2.02	8.9	8.7	0.99	2	2.6	0.989	602CA_Trip572	1
11/05/2026 20:12:58	52.347251	4.911363	190	Sudden braking	2.23	2.23	7.5	6.4	1.03	2	2.0	1.031	602CA_Trip572	1
11/05/2026 20:12:59	52.347233	4.911368	178	Sudden braking	2.14	2.14	5.3	4.3	0.98	2	1.3	0.982	602CA_Trip572	1
11/05/2026 20:19:03	52.333990	4.903650	248	Sudden braking	2.00	2.00	16.0	15.8	1.00	3	5.8	0.999	602CA_Trip572	1
11/05/2026 20:23:50	52.324236	4.894497	185	Sudden braking	2.01	2.01	16.3	15.2	0.99	3	4.9	0.994	602CA_Trip572	1
12/05/2026 05:11:07	52.536429	4.694504	79	Sudden braking	2.40	2.40	34.2	35.4	1.00	3	9.3	1.000	63C0A_Trip574	1
12/05/2026 05:11:08	52.536436	4.694641	89	Sudden braking	2.90	2.90	33.0	32.5	1.00	3	7.8	1.000	63C0A_Trip574	1
12/05/2026 05:11:09	52.536414	4.694751	104	Sudden braking	2.80	2.80	31.9	29.7	1.00	3	7.0	1.000	63C0A_Trip574	1
12/05/2026 05:11:10	52.536369	4.694825	127	Sudden braking	2.00	2.00	30.8	27.7	1.00	3	8.5	1.000	63C0A_Trip574	1
12/05/2026 05:13:36	52.522514	4.702408	131	Sudden braking	2.00	2.00	32.9	34.5	1.00	3	9.2	1.000	63C0A_Trip574	1
12/05/2026 05:13:37	52.522460	4.702511	131	Sudden braking	2.40	2.40	31.2	32.1	1.00	3	8.3	1.000	63C0A_Trip574	1
12/05/2026 05:13:38	52.522409	4.702603	132	Sudden braking	2.90	2.90	29.5	29.2	1.00	3	7.4	1.000	63C0A_Trip574	1
12/05/2026 05:13:39	52.522365	4.702684	132	Sudden braking	2.90	2.90	27.8	26.3	1.00	3	5.4	1.000	63C0A_Trip574	1
12/05/2026 05:13:40	52.522332	4.702743	133	Sudden braking	2.20	2.20	26.1	24.1	1.00	3	2.4	1.000	63C0A_Trip574	1
12/05/2026 05:14:23	52.519942	4.706168	132	Sudden braking	2.00	2.00	34.5	36.6	1.00	3	11.6	1.000	63C0A_Trip574	1
12/05/2026 05:14:24	52.519868	4.706289	138	Sudden braking	2.70	2.70	33.1	33.9	1.00	3	9.2	1.000	63C0A_Trip574	1
12/05/2026 05:14:25	52.519805	4.706376	140	Sudden braking	3.10	3.10	31.8	30.8	1.00	3	7.8	1.000	63C0A_Trip574	1
12/05/2026 05:14:26	52.519749	4.706446	143	Sudden braking	2.80	2.80	30.6	28.0	1.00	3	6.3	1.000	63C0A_Trip574	1
12/05/2026 05:21:00	52.494859	4.759817	105	Sudden braking	2.30	2.30	38.6	36.7	1.00	2	11.4	1.000	63C0A_Trip574	1
12/05/2026 05:21:31	52.494191	4.764514	99	Sudden braking	2.20	2.20	32.2	34.6	1.00	3	7.5	1.000	63C0A_Trip574	1
12/05/2026 05:21:32	52.494182	4.764624	97	Sudden braking	2.80	2.80	29.9	31.8	1.00	3	8.1	1.000	63C0A_Trip574	1
12/05/2026 05:21:33	52.494172	4.764743	97	Sudden braking	3.40	3.40	27.4	28.4	1.00	3	7.1	1.000	63C0A_Trip574	1
12/05/2026 05:21:34	52.494165	4.764847	96	Sudden braking	3.50	3.50	24.9	24.9	1.00	3	5.5	1.000	63C0A_Trip574	1
12/05/2026 05:21:35	52.494160	4.764928	96	Sudden braking	3.50	3.50	22.3	21.4	1.00	3	4.3	1.000	63C0A_Trip574	1
12/05/2026 05:21:36	52.494156	4.764992	96	Sudden braking	3.50	3.50	20.0	17.9	1.00	3	3.6	1.000	63C0A_Trip574	1
12/05/2026 05:21:37	52.494152	4.765045	96	Sudden braking	3.00	3.00	17.7	14.9	1.00	4	2.7	1.000	63C0A_Trip574	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
12/05/2026 05:21:38	52.494150	4.765085	96	Sudden braking	2.10	2.10	15.6	12.8	1.00	4	2.9	1.000	63C0A_Trip574	1
12/05/2026 05:22:19	52.493821	4.768279	93	Sudden braking	3.10	3.10	34.0	33.2	1.00	3	9.6	1.000	63C0A_Trip574	1
12/05/2026 05:22:23	52.494014	4.768713	92	Sudden braking	2.50	2.50	29.1	27.7	1.00	3	4.2	1.000	63C0A_Trip574	1
12/05/2026 05:22:24	52.494013	4.768774	92	Sudden braking	2.00	2.00	28.5	25.7	1.00	3	6.6	1.000	63C0A_Trip574	1
12/05/2026 05:34:58	52.434075	4.815778	171	Sudden braking	2.10	2.10	32.1	33.9	1.00	2	8.9	1.000	63C0A_Trip574	1
12/05/2026 05:34:59	52.433995	4.815792	172	Sudden braking	2.60	2.60	30.6	31.3	1.00	3	8.4	1.000	63C0A_Trip574	1
12/05/2026 05:35:00	52.433920	4.815802	174	Sudden braking	3.30	3.30	29.3	28.0	1.00	3	8.0	1.000	63C0A_Trip574	1
12/05/2026 05:35:01	52.433848	4.815808	173	Sudden braking	3.30	3.30	28.3	24.7	1.00	3	6.3	1.000	63C0A_Trip574	1
12/05/2026 05:35:02	52.433793	4.815827	173	Sudden braking	2.20	2.20	27.3	22.5	1.00	3	5.8	1.000	63C0A_Trip574	1
12/05/2026 05:35:19	52.434242	4.817697	41	Sudden braking	2.00	2.00	31.1	29.8	1.00	3	8.0	1.000	63C0A_Trip574	1
12/05/2026 05:35:50	52.432573	4.821221	131	Sudden braking	2.10	2.10	32.1	32.8	1.00	3	9.1	1.000	63C0A_Trip574	1
12/05/2026 05:35:51	52.432519	4.821322	131	Sudden braking	2.70	2.70	30.1	30.1	1.00	3	7.8	1.001	63C0A_Trip574	1
12/05/2026 05:35:53	52.432472	4.821409	131	Sudden braking	3.10	3.10	26.0	27.0	1.00	3	6.8	1.000	63C0A_Trip574	1
12/05/2026 05:35:54	52.432432	4.821484	131	Sudden braking	3.10	3.10	24.1	23.9	1.00	3	5.5	1.000	63C0A_Trip574	1
12/05/2026 05:35:55	52.432399	4.821545	131	Sudden braking	2.70	2.70	22.4	21.2	1.00	2	5.2	1.000	63C0A_Trip574	1
12/05/2026 05:35:56	52.432369	4.821603	131	Sudden braking	2.10	2.10	21.0	19.1	1.00	3	5.4	1.000	63C0A_Trip574	1
12/05/2026 06:03:03	52.392461	4.866197	105	Sudden braking	2.20	2.20	32.5	36.4	1.00	3	10.2	1.000	63C0A_Trip574	1
12/05/2026 06:03:04	52.392437	4.866342	105	Sudden braking	3.40	3.40	30.3	33.0	1.00	2	8.4	1.000	63C0A_Trip574	1
12/05/2026 06:03:05	52.392423	4.866464	101	Sudden braking	4.30	4.30	28.0	28.7	1.00	2	6.6	1.000	63C0A_Trip574	1
12/05/2026 06:03:06	52.392415	4.866560	97	Sudden braking	4.60	4.60	25.8	24.1	1.00	2	5.2	1.000	63C0A_Trip574	1
12/05/2026 06:03:07	52.392410	4.866635	95	Sudden braking	4.10	4.10	23.9	20.0	1.00	3	4.2	1.000	63C0A_Trip574	1
12/05/2026 06:03:08	52.392408	4.866696	91	Sudden braking	3.00	3.00	22.2	17.0	1.00	3	3.6	1.000	63C0A_Trip574	1
12/05/2026 06:03:24	52.392675	4.867907	56	Sudden braking	2.00	2.00	17.4	18.0	1.00	3	5.9	1.000	63C0A_Trip574	1
12/05/2026 06:03:25	52.392709	4.867840	66	Sudden braking	2.40	2.40	15.7	15.6	1.00	3	18.8	1.000	63C0A_Trip574	1
12/05/2026 06:03:26	52.392678	4.868112	79	Sudden braking	2.30	2.30	14.2	13.3	1.00	3	1.6	1.000	63C0A_Trip574	1
12/05/2026 06:03:27	52.392678	4.868136	69	Sudden braking	2.20	2.20	12.9	11.1	1.00	3	1.9	1.000	63C0A_Trip574	1
12/05/2026 06:03:28	52.392684	4.868162	69	Sudden braking	2.00	2.00	12.0	9.1	1.00	3	2.1	1.000	63C0A_Trip574	1
12/05/2026 06:05:14	52.391285	4.880493	103	Sudden braking	2.00	2.00	33.0	32.9	1.00	1	9.0	1.000	63C0A_Trip574	1
12/05/2026 06:05:45	52.390826	4.884610	127	Sudden braking	3.00	3.00	23.7	26.2	1.00	3	6.8	1.000	63C0A_Trip574	1
12/05/2026 06:05:46	52.390788	4.884690	128	Sudden braking	3.80	3.80	21.5	22.4	1.00	3	4.5	1.000	63C0A_Trip574	1
12/05/2026 06:05:47	52.390763	4.884742	128	Sudden braking	4.00	4.00	19.1	18.4	1.00	3	3.8	1.000	63C0A_Trip574	1
12/05/2026 06:05:48	52.390741	4.884784	132	Sudden braking	3.70	3.70	16.7	14.7	1.00	3	2.8	1.000	63C0A_Trip574	1
12/05/2026 06:05:49	52.390724	4.884815	132	Sudden braking	2.80	2.80	15.3	11.9	1.00	3	2.8	1.000	63C0A_Trip574	1
12/05/2026 06:06:50	52.389756	4.890227	102	Sudden braking	2.10	2.10	31.6	34.7	1.00	3	8.7	1.000	63C0A_Trip574	1
12/05/2026 06:06:51	52.389739	4.890351	102	Sudden braking	2.70	2.70	29.3	32.0	1.00	3	7.7	1.000	63C0A_Trip574	1
12/05/2026 06:06:52	52.389723	4.890461	104	Sudden braking	3.50	3.50	26.6	28.5	1.00	3	7.8	1.000	63C0A_Trip574	1
12/05/2026 06:06:53	52.389700	4.890570	109	Sudden braking	3.90	3.90	23.7	24.6	1.00	2	6.7	1.000	63C0A_Trip574	1
12/05/2026 06:06:54	52.389677	4.890660	111	Sudden braking	4.00	4.00	20.8	20.6	1.00	3	5.1	1.000	63C0A_Trip574	1
12/05/2026 06:06:55	52.389656	4.890728	113	Sudden braking	4.10	4.10	17.9	16.5	1.00	3	3.5	1.000	63C0A_Trip574	1
12/05/2026 06:06:56	52.389640	4.890772	113	Sudden braking	3.90	3.90	15.2	12.6	1.00	3	2.4	1.000	63C0A_Trip574	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_h_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
12/05/2026 06:06:57	52.389631	4.890804	116	Sudden braking	3.20	3.20	12.8	9.4	1.00	3	1.9	1.000	63C0A_Trip574	1
12/05/2026 06:06:58	52.389624	4.890830	116	Sudden braking	2.20	2.20	10.8	7.2	1.00	2	1.6	1.000	63C0A_Trip574	1
12/05/2026 06:07:52	52.386090	4.892893	165	Sudden braking	2.00	2.00	26.3	28.3	1.00	3	7.4	1.000	63C0A_Trip574	1
12/05/2026 06:07:53	52.386027	4.892925	165	Sudden braking	2.30	2.30	24.3	26.0	1.00	3	6.7	1.000	63C0A_Trip574	1
12/05/2026 06:07:54	52.385968	4.892949	165	Sudden braking	2.80	2.80	22.2	23.2	1.00	3	6.2	1.000	63C0A_Trip574	1
12/05/2026 06:07:55	52.385914	4.892974	165	Sudden braking	3.20	3.20	20.0	20.0	1.00	5	5.4	1.000	63C0A_Trip574	1
12/05/2026 06:07:56	52.385868	4.892994	165	Sudden braking	3.10	3.10	17.9	16.9	1.00	3	4.0	1.000	63C0A_Trip574	1
12/05/2026 06:07:57	52.385833	4.893008	165	Sudden braking	2.90	2.90	16.2	14.0	1.00	3	2.9	1.000	63C0A_Trip574	1
12/05/2026 06:07:58	52.385808	4.893019	165	Sudden braking	2.70	2.70	14.8	11.3	1.00	3	2.6	1.000	63C0A_Trip574	1
12/05/2026 06:07:59	52.385786	4.893030	165	Sudden braking	2.00	2.00	14.0	9.3	1.00	3	2.2	1.000	63C0A_Trip574	1
12/05/2026 06:09:00	52.382088	4.895476	139	Sudden braking	2.10	2.10	25.7	27.0	1.00	3	6.7	1.000	63C0A_Trip574	1
12/05/2026 06:09:01	52.382041	4.895538	139	Sudden braking	2.60	2.60	23.8	24.4	1.00	3	6.5	1.000	63C0A_Trip574	1
12/05/2026 06:09:02	52.381995	4.895596	140	Sudden braking	2.70	2.70	21.8	21.7	1.00	3	5.4	1.000	63C0A_Trip574	1
12/05/2026 06:09:03	52.381958	4.895647	142	Sudden braking	2.40	2.40	19.7	19.3	1.00	3	5.2	1.000	63C0A_Trip574	1
12/05/2026 06:09:04	52.381918	4.895687	142	Sudden braking	2.30	2.30	17.6	17.0	1.00	2	4.4	1.000	63C0A_Trip574	1
12/05/2026 06:09:05	52.381886	4.895725	142	Sudden braking	2.30	2.30	15.5	14.7	1.00	2	3.5	1.000	63C0A_Trip574	1
12/05/2026 06:09:06	52.381861	4.895757	142	Sudden braking	2.10	2.10	13.4	12.6	1.00	3	2.8	1.000	63C0A_Trip574	1
12/05/2026 06:10:11	52.380393	4.898985	30	Sudden braking	2.20	2.20	15.7	15.9	1.00	3	5.7	1.000	63C0A_Trip574	1
12/05/2026 06:10:12	52.380445	4.898989	12	Sudden braking	2.60	2.60	14.6	13.3	1.00	3	3.6	1.000	63C0A_Trip574	1
12/05/2026 06:10:13	52.380474	4.899012	12	Sudden braking	2.30	2.30	13.9	11.0	1.00	3	1.8	1.000	63C0A_Trip574	1
12/05/2026 06:11:55	52.377892	4.909601	102	Sudden braking	2.10	2.10	31.0	32.0	1.00	2	8.8	1.000	63C0A_Trip574	1
12/05/2026 06:11:56	52.377875	4.909727	104	Sudden braking	2.50	2.50	29.7	29.5	1.00	2	7.8	1.000	63C0A_Trip574	1
12/05/2026 06:11:57	52.377851	4.909835	110	Sudden braking	2.50	2.50	28.6	27.0	1.00	2	6.6	1.000	63C0A_Trip574	1
12/05/2026 06:11:58	52.377813	4.909910	125	Sudden braking	2.10	2.10	27.5	24.9	1.00	2	6.9	1.000	63C0A_Trip574	1
12/05/2026 06:12:25	52.375894	4.910538	180	Sudden braking	2.30	2.30	22.3	25.3	1.00	4	7.0	1.000	63C0A_Trip574	1
12/05/2026 06:12:26	52.375832	4.910533	185	Sudden braking	3.40	3.40	20.5	21.9	1.00	4	5.2	1.000	63C0A_Trip574	1
12/05/2026 06:12:27	52.375790	4.910498	187	Sudden braking	3.80	3.80	18.8	18.1	1.00	4	2.5	1.000	63C0A_Trip574	1
12/05/2026 06:12:28	52.375770	4.910518	187	Sudden braking	3.70	3.70	17.3	14.4	1.00	4	1.9	1.000	63C0A_Trip574	1
12/05/2026 06:12:29	52.375775	4.910545	191	Sudden braking	3.10	3.10	15.8	11.3	1.00	4	2.6	1.000	63C0A_Trip574	1
12/05/2026 06:14:04	52.374795	4.915051	160	Sudden braking	2.40	2.40	15.8	15.5	1.00	1	4.2	1.000	63C0A_Trip574	1
12/05/2026 06:14:05	52.374761	4.915080	158	Sudden braking	2.40	2.40	14.7	13.1	1.00	1	2.8	1.000	63C0A_Trip574	1
12/05/2026 06:14:13	52.374783	4.915423	128	Sudden braking	2.40	2.40	8.6	5.7	1.00	1	1.7	1.000	63C0A_Trip574	1
12/05/2026 08:28:38	52.310382	4.881637	0	Sudden braking	2.00	2.00	10.2	11.6	1.00	2	4.1	1.002	602CA_Trip581	1
12/05/2026 08:28:39	52.310419	4.881633	358	Sudden braking	2.72	2.72	9.5	8.9	0.99	2	2.1	0.994	602CA_Trip581	1
12/05/2026 08:28:40	52.310433	4.881613	349	Sudden braking	3.10	3.10	7.5	5.8	1.00	1	1.0	1.001	602CA_Trip581	1
12/05/2026 08:28:41	52.310442	4.881609	329	Sudden braking	2.49	2.49	6.8	3.3	1.00	2	1.1	1.005	602CA_Trip581	1
12/05/2026 08:44:53	52.339189	4.908578	51	Sudden braking	3.11	3.11	12.4	14.1	1.00	3	4.1	0.997	602CA_Trip581	1
12/05/2026 08:44:54	52.339214	4.908623	52	Sudden braking	3.31	3.31	11.5	10.8	1.00	3	1.8	0.998	602CA_Trip581	1
12/05/2026 08:44:55	52.339224	4.908643	51	Sudden braking	2.99	2.99	10.9	7.8	1.00	3	0.9	1.002	602CA_Trip581	1
12/05/2026 08:44:56	52.339229	4.908654	46	Sudden braking	2.20	2.20	10.9	5.6	1.00	3	1.1	1.000	602CA_Trip581	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
12/05/2026 08:48:39	52.347073	4.912087	342	Sudden braking	2.22	2.22	7.1	5.3	0.99	1	2.0	0.993	602CA_Trip581	1
12/05/2026 08:48:40	52.347088	4.912073	342	Sudden braking	2.08	2.08	6.3	3.2	1.01	1	1.4	1.008	602CA_Trip581	1
12/05/2026 08:56:02	52.359783	4.908391	91	Sudden braking	2.02	2.02	10.8	9.6	1.04	2	2.5	1.040	602CA_Trip581	1
12/05/2026 08:56:03	52.359783	4.908428	112	Sudden braking	2.38	2.38	10.1	7.3	0.97	2	2.4	0.967	602CA_Trip581	1
12/05/2026 08:56:04	52.359783	4.908463	116	Sudden braking	2.15	2.15	9.2	5.1	1.02	2	2.2	1.025	602CA_Trip581	1
12/05/2026 08:56:05	52.359784	4.908496	123	Sudden braking	2.04	2.04	8.3	3.0	1.03	2	0.2	1.028	602CA_Trip581	1
12/05/2026 08:57:11	52.360243	4.908879	334	Sudden braking	2.38	2.38	8.9	9.7	1.01	2	2.6	1.010	602CA_Trip581	1
12/05/2026 08:57:12	52.360263	4.908859	335	Sudden braking	2.29	2.29	8.9	7.4	1.00	2	2.1	1.003	602CA_Trip581	1
12/05/2026 09:01:51	52.370074	4.908261	63	Sudden braking	2.30	2.30	11.1	13.6	0.96	2	4.3	0.958	602CA_Trip581	1
12/05/2026 09:01:52	52.370088	4.908320	58	Sudden braking	2.40	2.40	11.1	11.1	1.04	2	3.5	1.042	602CA_Trip581	1
12/05/2026 09:01:53	52.370101	4.908366	57	Sudden braking	2.87	2.87	9.4	8.3	0.97	2	1.3	0.975	602CA_Trip581	1
12/05/2026 09:01:54	52.370098	4.908384	62	Sudden braking	3.05	3.05	9.4	5.2	1.02	2	1.5	1.016	602CA_Trip581	1
12/05/2026 09:01:55	52.370093	4.908406	58	Sudden braking	2.41	2.41	8.3	2.8	1.00	2	1.0	0.996	602CA_Trip581	1
12/05/2026 09:04:06	52.370984	4.914972	71	Sudden braking	2.12	2.12	11.4	13.0	0.99	3	3.8	0.991	602CA_Trip581	1
12/05/2026 09:04:07	52.370996	4.915024	80	Sudden braking	2.58	2.58	10.8	10.4	1.01	3	2.8	1.009	602CA_Trip581	1
12/05/2026 09:04:08	52.371004	4.915064	82	Sudden braking	2.72	2.72	8.2	7.7	0.99	2	2.1	0.992	602CA_Trip581	1
12/05/2026 09:04:09	52.371010	4.915093	72	Sudden braking	2.52	2.52	7.0	5.1	1.03	2	1.3	1.031	602CA_Trip581	1
12/05/2026 09:04:10	52.371013	4.915112	66	Sudden braking	2.25	2.25	4.8	3.0	0.93	2	0.5	0.932	602CA_Trip581	1
12/05/2026 10:00:50	52.353828	4.809205	73	Sudden braking	2.00	2.00	13.3	13.0	1.00	2	3.3	1.000	604F0_Trip583	1
12/05/2026 10:04:03	52.356136	4.826976	92	Sudden braking	2.50	2.50	16.9	17.4	1.00	2	4.3	1.000	604F0_Trip583	1
12/05/2026 10:04:04	52.356120	4.827034	107	Sudden braking	3.10	3.10	16.1	14.3	1.00	2	3.3	1.000	604F0_Trip583	1
12/05/2026 10:04:05	52.356108	4.827078	111	Sudden braking	3.70	3.70	15.1	10.6	1.00	2	2.4	1.000	604F0_Trip583	1
12/05/2026 10:04:06	52.356102	4.827111	110	Sudden braking	3.00	3.00	14.0	7.6	1.00	2	1.3	1.000	604F0_Trip583	1
12/05/2026 10:07:17	52.356291	4.843783	89	Sudden braking	2.30	2.30	18.8	20.1	1.00	2	5.9	1.000	604F0_Trip583	1
12/05/2026 10:07:18	52.356293	4.843870	87	Sudden braking	3.10	3.10	17.9	17.0	1.00	2	4.6	1.000	604F0_Trip583	1
12/05/2026 10:07:19	52.356292	4.843937	90	Sudden braking	2.90	2.90	17.1	14.1	1.00	2	1.7	1.000	604F0_Trip583	1
12/05/2026 10:07:20	52.356287	4.843961	97	Sudden braking	2.10	2.10	16.6	12.0	1.00	2	2.1	1.000	604F0_Trip583	1
12/05/2026 11:22:49	52.372711	4.892684	97	Sudden braking	2.10	2.10	12.0	9.2	1.00	2	1.6	1.000	604F0_Trip586	1
12/05/2026 11:29:03	52.371086	4.914998	58	Sudden braking	2.90	2.90	17.1	14.8	1.00	1	2.4	1.000	604F0_Trip586	1
12/05/2026 15:35:34	52.371397	4.915240	240	Sudden braking	2.62	2.62	10.6	11.6	0.99	2	3.5	0.993	604F9_Trip589	1
12/05/2026 15:35:35	52.371381	4.915196	228	Sudden braking	2.84	2.84	9.7	8.7	1.02	2	1.9	1.020	604F9_Trip589	1
12/05/2026 15:35:36	52.371366	4.915183	196	Sudden braking	3.04	3.04	6.1	5.7	0.99	2	1.4	0.987	604F9_Trip589	1
12/05/2026 15:35:37	52.371353	4.915190	169	Sudden braking	2.63	2.63	6.1	3.1	0.99	2	0.5	0.989	604F9_Trip589	1
12/05/2026 15:36:47	52.369935	4.918563	122	Sudden braking	2.73	2.73	19.9	21.2	0.99	3	6.7	0.989	604F9_Trip589	1
12/05/2026 15:36:48	52.369903	4.918647	127	Sudden braking	2.81	2.81	18.4	18.4	0.99	3	4.9	0.995	604F9_Trip589	1
12/05/2026 15:36:49	52.369880	4.918709	127	Sudden braking	2.79	2.79	16.5	15.6	1.00	3	3.9	1.002	604F9_Trip589	1
12/05/2026 15:36:50	52.369864	4.918760	123	Sudden braking	2.39	2.39	15.5	13.2	1.00	2	4.2	1.003	604F9_Trip589	1
12/05/2026 15:38:08	52.367683	4.925233	117	Sudden braking	2.06	2.06	17.0	19.5	0.97	2	6.0	0.971	604F9_Trip589	1
12/05/2026 15:38:09	52.367660	4.925313	120	Sudden braking	3.08	3.08	15.5	16.3	1.04	2	4.8	1.038	604F9_Trip589	1
12/05/2026 15:38:10	52.367635	4.925371	121	Sudden braking	3.94	3.94	10.9	12.4	0.99	2	3.9	0.990	604F9_Trip589	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
12/05/2026 15:38:11	52.367612	4.925414	131	Sudden braking	3.84	3.84	9.9	8.5	1.01	2	2.0	1.015	604F9_Trip589	1
12/05/2026 15:38:12	52.367594	4.925408	161	Sudden braking	3.65	3.65	6.5	4.9	0.99	2	0.6	0.987	604F9_Trip589	1
12/05/2026 15:38:13	52.367589	4.925405	178	Sudden braking	2.66	2.66	5.1	2.2	1.01	2	0.4	1.014	604F9_Trip589	1
12/05/2026 15:39:23	52.366162	4.926354	133	Sudden braking	2.20	2.20	14.4	15.1	1.00	2	3.7	1.001	604F9_Trip589	1
12/05/2026 15:39:24	52.366138	4.926392	137	Sudden braking	2.51	2.51	12.3	12.6	1.00	2	3.8	0.998	604F9_Trip589	1
12/05/2026 15:39:25	52.366114	4.926431	137	Sudden braking	2.70	2.70	9.3	9.9	1.00	2	3.1	0.999	604F9_Trip589	1
12/05/2026 15:39:26	52.366094	4.926463	141	Sudden braking	2.39	2.39	9.3	7.5	1.00	2	2.2	1.004	604F9_Trip589	1
12/05/2026 15:39:27	52.366078	4.926481	144	Sudden braking	2.19	2.19	6.7	5.3	1.00	2	1.3	1.004	604F9_Trip589	1
12/05/2026 15:50:40	52.378295	4.906920	281	Sudden braking	2.40	2.40	18.2	19.3	1.00	2	4.6	1.000	63C0A_Trip593	1
12/05/2026 15:50:41	52.378301	4.906852	282	Sudden braking	2.80	2.80	16.7	16.5	1.00	2	3.8	1.000	63C0A_Trip593	1
12/05/2026 15:50:42	52.378308	4.906798	282	Sudden braking	2.90	2.90	15.3	13.6	1.00	2	2.4	1.000	63C0A_Trip593	1
12/05/2026 15:50:43	52.378311	4.906763	282	Sudden braking	2.50	2.50	14.1	11.1	1.00	2	2.2	1.000	63C0A_Trip593	1
12/05/2026 15:51:14	52.371309	4.912346	256	Sudden braking	2.04	2.04	7.1	5.5	0.98	1	1.3	0.979	602CA_Trip591	1
12/05/2026 15:51:15	52.371300	4.912333	221	Sudden braking	2.07	2.07	7.1	3.4	1.01	1	0.7	1.015	602CA_Trip591	1
12/05/2026 15:51:58	52.380307	4.899527	301	Sudden braking	2.00	2.00	15.5	17.1	1.00	3	4.8	1.000	63C0A_Trip593	1
12/05/2026 15:51:59	52.380329	4.899467	301	Sudden braking	2.80	2.80	14.5	14.3	1.00	3	1.8	1.000	63C0A_Trip593	1
12/05/2026 15:52:00	52.380337	4.899444	301	Sudden braking	2.90	2.90	13.6	11.4	1.00	3	1.0	1.000	63C0A_Trip593	1
12/05/2026 15:52:01	52.380342	4.899431	301	Sudden braking	2.30	2.30	12.8	9.1	1.00	3	1.1	1.000	63C0A_Trip593	1
12/05/2026 15:53:05	52.382930	4.893966	271	Sudden braking	2.20	2.20	29.0	30.7	1.00	2	8.0	1.000	63C0A_Trip593	1
12/05/2026 15:53:06	52.382928	4.893849	269	Sudden braking	2.80	2.80	27.4	27.9	1.00	2	7.1	1.000	63C0A_Trip593	1
12/05/2026 15:53:07	52.382926	4.893744	267	Sudden braking	2.80	2.80	25.8	25.1	1.00	2	6.3	1.000	63C0A_Trip593	1
12/05/2026 15:53:08	52.382923	4.893651	269	Sudden braking	2.50	2.50	24.9	22.6	1.00	2	5.9	1.000	63C0A_Trip593	1
12/05/2026 15:53:09	52.382925	4.893565	275	Sudden braking	2.20	2.20	23.3	20.4	1.00	2	5.8	1.000	63C0A_Trip593	1
12/05/2026 15:53:38	52.384966	4.893285	7	Sudden braking	2.10	2.10	20.7	22.9	1.00	3	7.1	1.000	63C0A_Trip593	1
12/05/2026 15:53:39	52.385030	4.893295	4	Sudden braking	2.90	2.90	18.5	20.0	1.00	3	5.1	1.000	63C0A_Trip593	1
12/05/2026 15:53:40	52.385076	4.893302	4	Sudden braking	3.20	3.20	16.4	16.8	1.00	3	3.3	1.000	63C0A_Trip593	1
12/05/2026 15:53:41	52.385105	4.893307	4	Sudden braking	3.30	3.30	15.3	13.5	1.00	3	2.8	1.000	63C0A_Trip593	1
12/05/2026 15:53:42	52.385130	4.893309	2	Sudden braking	2.90	2.90	14.2	10.6	1.00	3	3.0	1.000	63C0A_Trip593	1
12/05/2026 15:53:43	52.385157	4.893312	2	Sudden braking	2.40	2.40	11.8	8.2	1.00	3	2.3	1.000	63C0A_Trip593	1
12/05/2026 15:53:44	52.385178	4.893313	2	Sudden braking	2.20	2.20	10.4	6.0	1.00	3	1.7	1.000	63C0A_Trip593	1
12/05/2026 15:54:51	52.389025	4.891740	344	Sudden braking	2.00	2.00	22.9	24.2	1.00	3	6.7	1.000	63C0A_Trip593	1
12/05/2026 15:54:52	52.389083	4.891717	344	Sudden braking	2.20	2.20	20.8	22.0	1.00	3	5.6	1.000	63C0A_Trip593	1
12/05/2026 15:54:53	52.389131	4.891693	344	Sudden braking	2.60	2.60	18.7	19.4	1.00	3	4.8	1.000	63C0A_Trip593	1
12/05/2026 15:54:54	52.389172	4.891677	344	Sudden braking	2.90	2.90	16.5	16.5	1.00	2	3.9	1.000	63C0A_Trip593	1
12/05/2026 15:54:55	52.389207	4.891663	344	Sudden braking	2.90	2.90	14.5	13.6	1.00	2	3.0	1.000	63C0A_Trip593	1
12/05/2026 15:54:56	52.389233	4.891653	343	Sudden braking	2.70	2.70	12.6	10.9	1.00	2	2.4	1.000	63C0A_Trip593	1
12/05/2026 15:54:57	52.389254	4.891644	343	Sudden braking	2.30	2.30	11.0	8.6	1.00	2	1.8	1.000	63C0A_Trip593	1
12/05/2026 15:54:58	52.376106	4.902867	325	Sudden braking	2.20	2.20	14.4	14.3	1.00	2	4.1	1.001	602CA_Trip591	1
12/05/2026 15:54:59	52.376135	4.902831	327	Sudden braking	2.00	2.00	13.5	12.3	1.00	2	2.9	1.000	602CA_Trip591	1
12/05/2026 15:56:00	52.390503	4.885548	300	Sudden braking	2.40	2.40	17.8	19.8	1.00	3	4.5	1.000	63C0A_Trip593	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
12/05/2026 15:56:01	52.390523	4.885490	300	Sudden braking	2.90	2.90	16.0	16.9	1.00	3	3.2	1.000	63C0A_Trip593	1
12/05/2026 15:56:02	52.390537	4.885450	300	Sudden braking	3.10	3.10	14.2	13.8	1.00	3	2.4	1.000	63C0A_Trip593	1
12/05/2026 15:56:03	52.390548	4.885420	300	Sudden braking	2.90	2.90	12.2	10.9	1.00	2	1.9	1.000	63C0A_Trip593	1
12/05/2026 15:56:04	52.390556	4.885396	300	Sudden braking	2.30	2.30	11.1	8.6	1.00	3	1.4	1.000	63C0A_Trip593	1
12/05/2026 15:56:26	52.377023	4.898393	320	Sudden braking	2.45	2.45	7.1	7.8	0.98	2	1.3	0.979	602CA_Trip591	1
12/05/2026 15:56:27	52.377032	4.898381	319	Sudden braking	2.53	2.53	6.5	5.2	1.03	2	1.6	1.026	602CA_Trip591	1
12/05/2026 15:56:28	52.377041	4.898362	317	Sudden braking	2.11	2.11	5.8	3.1	0.99	2	0.1	0.993	602CA_Trip591	1
12/05/2026 15:58:04	52.392915	4.870917	269	Sudden braking	2.30	2.30	25.3	26.9	1.00	3	6.8	1.000	63C0A_Trip593	1
12/05/2026 15:58:05	52.392915	4.870817	269	Sudden braking	2.80	2.80	23.0	24.1	1.00	3	5.4	1.000	63C0A_Trip593	1
12/05/2026 15:58:06	52.392911	4.870738	270	Sudden braking	3.10	3.10	20.8	21.0	1.00	3	4.7	1.000	63C0A_Trip593	1
12/05/2026 15:58:07	52.392907	4.870669	270	Sudden braking	3.50	3.50	18.9	17.5	1.00	3	3.7	1.000	63C0A_Trip593	1
12/05/2026 15:58:08	52.392909	4.870614	270	Sudden braking	3.40	3.40	17.3	14.1	1.00	3	3.7	1.000	63C0A_Trip593	1
12/05/2026 15:58:09	52.392908	4.870560	271	Sudden braking	2.40	2.40	16.2	11.7	1.00	3	1.3	1.000	63C0A_Trip593	1
12/05/2026 16:00:33	52.368513	4.889049	220	Sudden braking	2.18	2.18	10.5	11.3	1.01	2	2.7	1.007	602CA_Trip591	1
12/05/2026 16:00:34	52.368494	4.889026	212	Sudden braking	2.78	2.78	9.3	8.6	0.97	2	2.3	0.971	602CA_Trip591	1
12/05/2026 16:00:35	52.368477	4.889005	220	Sudden braking	2.68	2.68	9.3	5.9	1.01	2	1.0	1.009	602CA_Trip591	1
12/05/2026 16:00:36	52.368468	4.889002	225	Sudden braking	2.27	2.27	7.5	3.6	1.01	2	0.4	1.012	602CA_Trip591	1
12/05/2026 16:01:18	52.368733	4.888169	325	Sudden braking	2.79	2.79	10.5	11.4	1.00	2	3.9	1.002	602CA_Trip591	1
12/05/2026 16:01:19	52.368762	4.888138	325	Sudden braking	3.20	3.20	9.5	8.2	1.00	2	2.4	0.999	602CA_Trip591	1
12/05/2026 16:01:20	52.368777	4.888112	327	Sudden braking	2.78	2.78	8.8	5.4	1.01	2	1.4	1.006	602CA_Trip591	1
12/05/2026 16:02:35	52.370336	4.885897	266	Sudden braking	2.00	2.00	10.1	10.1	1.00	2	3.5	0.998	602CA_Trip591	1
12/05/2026 16:02:36	52.370335	4.885846	274	Sudden braking	2.00	2.00	9.0	8.1	1.00	2	2.6	1.001	602CA_Trip591	1
12/05/2026 16:05:24	52.417630	4.826880	20	Sudden braking	2.00	2.00	20.5	20.9	1.00	2	18.8	1.000	63C0A_Trip593	1
12/05/2026 16:05:25	52.417730	4.826657	25	Sudden braking	2.10	2.10	18.9	18.8	1.00	2	4.7	1.000	63C0A_Trip593	1
12/05/2026 16:05:26	52.368523	4.876355	258	Sudden braking	2.91	2.91	10.0	12.3	0.99	2	4.2	0.995	602CA_Trip591	1
12/05/2026 16:05:26	52.417768	4.826687	25	Sudden braking	2.00	2.00	17.3	16.8	1.00	2	4.1	1.000	63C0A_Trip593	1
12/05/2026 16:05:27	52.368505	4.876300	254	Sudden braking	3.40	3.40	9.4	8.8	1.03	2	2.3	1.028	602CA_Trip591	1
12/05/2026 16:05:28	52.368494	4.876271	244	Sudden braking	3.42	3.42	8.7	5.4	0.99	2	1.3	0.993	602CA_Trip591	1
12/05/2026 16:05:29	52.368488	4.876253	238	Sudden braking	2.64	2.64	7.7	2.8	0.99	1	0.4	0.986	602CA_Trip591	1
12/05/2026 16:07:15	52.366206	4.877584	136	Sudden braking	2.56	2.56	14.6	18.9	0.97	2	5.9	0.975	602CA_Trip591	1
12/05/2026 16:07:16	52.366164	4.877638	138	Sudden braking	3.80	3.80	14.6	15.1	1.00	2	5.4	1.001	602CA_Trip591	1
12/05/2026 16:07:17	52.366130	4.877694	138	Sudden braking	4.37	4.37	13.7	10.7	1.01	2	2.9	1.008	602CA_Trip591	1
12/05/2026 16:07:18	52.366107	4.877715	135	Sudden braking	4.07	4.07	12.5	6.6	1.01	1	0.1	1.008	602CA_Trip591	1
12/05/2026 16:07:19	52.366108	4.877715	0	Sudden braking	3.38	3.38	11.0	3.2	1.01	1	0.5	1.007	602CA_Trip591	1
12/05/2026 16:07:20	52.366104	4.877711	134	Sudden braking	2.24	2.24	9.2	1.0	0.98	1	0.1	0.983	602CA_Trip591	1
12/05/2026 16:08:33	52.363918	4.878691	158	Sudden braking	2.14	2.14	7.2	6.4	0.98	2	1.5	0.981	602CA_Trip591	1
12/05/2026 16:17:20	52.351591	4.856416	168	Sudden braking	2.00	2.00	10.0	11.3	1.00	2	3.0	1.001	602CA_Trip591	1
12/05/2026 16:17:21	52.351564	4.856406	171	Sudden braking	2.62	2.62	10.0	8.7	0.99	2	2.8	0.994	602CA_Trip591	1
12/05/2026 16:17:22	52.351539	4.856402	161	Sudden braking	2.69	2.69	9.2	6.0	1.00	2	0.8	1.003	602CA_Trip591	1
12/05/2026 16:17:23	52.351533	4.856406	153	Sudden braking	2.56	2.56	7.3	3.4	1.01	2	0.9	1.014	602CA_Trip591	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
12/05/2026 16:17:24	52.351525	4.856405	144	Sudden braking	2.02	2.02	5.6	1.4	0.99	2	0	0.989	602CA_Trip591	1
12/05/2026 16:19:42	52.345191	4.856597	240	Sudden braking	2.51	2.51	10.3	12.3	1.00	2	4.6	0.997	602CA_Trip591	1
12/05/2026 16:19:43	52.345161	4.856549	207	Sudden braking	2.88	2.88	8.5	9.5	0.97	2	2.7	0.973	602CA_Trip591	1
12/05/2026 16:19:44	52.345138	4.856537	190	Sudden braking	2.75	2.75	8.5	6.7	1.02	2	2.1	1.018	602CA_Trip591	1
12/05/2026 16:19:45	52.345119	4.856533	180	Sudden braking	2.61	2.61	6.4	4.1	1.00	2	1.3	0.996	602CA_Trip591	1
12/05/2026 16:19:46	52.345109	4.856525	181	Sudden braking	2.04	2.04	5.1	2.1	0.98	2	0.1	0.981	602CA_Trip591	1
12/05/2026 16:21:10	52.341331	4.857471	184	Sudden braking	2.11	2.11	17.5	19.5	0.99	2	5.8	0.993	602CA_Trip591	1
12/05/2026 16:21:11	52.341279	4.857469	186	Sudden braking	2.87	2.87	16.2	16.6	1.01	2	4.7	1.009	602CA_Trip591	1
12/05/2026 16:21:12	52.341238	4.857458	197	Sudden braking	3.29	3.29	13.0	13.3	1.00	2	5.0	1.002	602CA_Trip591	1
12/05/2026 16:21:13	52.341197	4.857426	212	Sudden braking	3.46	3.46	11.7	9.9	0.98	2	2.8	0.984	602CA_Trip591	1
12/05/2026 16:21:14	52.341175	4.857405	214	Sudden braking	3.13	3.13	10.3	6.7	1.02	2	0.9	1.021	602CA_Trip591	1
12/05/2026 16:21:15	52.341167	4.857408	201	Sudden braking	2.62	2.62	8.8	4.1	0.99	2	1.0	0.993	602CA_Trip591	1
12/05/2026 16:22:40	52.337231	4.857184	178	Sudden braking	2.07	2.07	17.1	19.2	1.02	2	5.6	1.016	602CA_Trip591	1
12/05/2026 16:22:41	52.337181	4.857179	174	Sudden braking	2.82	2.82	15.4	16.4	0.99	2	5.3	0.993	602CA_Trip591	1
12/05/2026 16:22:42	52.337134	4.857170	177	Sudden braking	3.55	3.55	14.4	12.8	1.01	2	3.3	1.013	602CA_Trip591	1
12/05/2026 16:22:43	52.337105	4.857173	179	Sudden braking	3.10	3.10	13.6	9.8	0.97	2	2.0	0.967	602CA_Trip591	1
12/05/2026 16:25:33	52.328039	4.857311	197	Sudden braking	2.09	2.09	10.9	12.9	1.00	2	4.1	1.003	602CA_Trip591	1
12/05/2026 16:25:34	52.328004	4.857293	200	Sudden braking	2.94	2.94	10.3	10.0	0.99	2	3.6	0.987	602CA_Trip591	1
12/05/2026 16:25:35	52.327973	4.857283	197	Sudden braking	2.89	2.89	9.5	7.1	1.00	2	2.3	1.004	602CA_Trip591	1
12/05/2026 16:25:36	52.327952	4.857280	194	Sudden braking	2.60	2.60	8.6	4.5	1.00	2	1.5	1.000	602CA_Trip591	1
12/05/2026 16:25:37	52.327940	4.857286	193	Sudden braking	2.29	2.29	6.2	2.2	1.01	2	1.1	1.006	602CA_Trip591	1
12/05/2026 16:27:00	52.424039	4.827682	6	Sudden braking	2.40	2.40	36.7	34.9	1.00	3	9.1	1.000	63C0A_Trip593	1
12/05/2026 16:27:01	52.424121	4.827696	5	Sudden braking	2.40	2.40	36.2	32.5	1.00	3	6.8	1.000	63C0A_Trip593	1
12/05/2026 16:27:46	52.321784	4.857373	181	Sudden braking	3.42	3.42	12.6	13.6	0.99	2	4.6	0.995	602CA_Trip591	1
12/05/2026 16:27:47	52.321743	4.857368	186	Sudden braking	3.98	3.98	11.0	9.6	1.00	2	1.8	1.004	602CA_Trip591	1
12/05/2026 16:27:48	52.321728	4.857356	186	Sudden braking	3.95	3.95	9.8	5.7	0.99	1	1.4	0.988	602CA_Trip591	1
12/05/2026 16:27:49	52.321718	4.857346	187	Sudden braking	3.08	3.08	8.2	2.6	1.01	1	1.2	1.006	602CA_Trip591	1
12/05/2026 16:29:22	52.433736	4.816070	257	Sudden braking	2.60	2.60	30.3	31.6	1.00	4	8.1	1.000	63C0A_Trip593	1
12/05/2026 16:29:23	52.433724	4.815952	259	Sudden braking	3.20	3.20	29.4	28.4	1.00	4	6.6	1.000	63C0A_Trip593	1
12/05/2026 16:29:24	52.433731	4.815855	271	Sudden braking	2.80	2.80	28.6	25.6	1.00	4	5.7	1.000	63C0A_Trip593	1
12/05/2026 16:35:24	52.470215	4.805488	358	Sudden braking	2.50	2.50	30.4	33.4	1.00	2	8.6	1.001	63C0A_Trip593	1
12/05/2026 16:35:26	52.470293	4.805483	358	Sudden braking	3.10	3.10	29.5	30.3	1.00	2	7.4	1.000	63C0A_Trip593	1
12/05/2026 16:35:27	52.470359	4.805479	358	Sudden braking	3.60	3.60	27.0	26.7	1.00	2	5.8	0.999	63C0A_Trip593	1
12/05/2026 16:35:27	52.470411	4.805476	358	Sudden braking	4.70	4.70	27.0	22.0	1.00	2	5.1	1.000	63C0A_Trip593	1
12/05/2026 16:35:28	52.470457	4.805474	358	Sudden braking	5.00	5.00	25.5	17.0	1.00	2	3.6	1.000	63C0A_Trip593	1
12/05/2026 16:35:51	52.307748	4.872574	99	Sudden braking	2.40	2.40	20.3	21.4	1.00	4	8.2	1.000	602CA_Trip591	1
12/05/2026 16:35:52	52.307729	4.872689	103	Sudden braking	2.78	2.78	19.2	18.6	1.01	3	8.5	1.009	602CA_Trip591	1
12/05/2026 16:35:53	52.307744	4.872812	107	Sudden braking	2.98	2.98	17.7	15.6	1.01	2	3.5	1.006	602CA_Trip591	1
12/05/2026 16:35:54	52.307724	4.872851	108	Sudden braking	2.71	2.71	15.9	12.9	1.00	2	5.1	0.998	602CA_Trip591	1
12/05/2026 16:36:07	52.470501	4.805471	358	Sudden braking	2.30	2.30	14.1	11.0	1.00	2	2.1	1.000	63C0A_Trip593	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
12/05/2026 16:37:10	52.476484	4.805105	0	Sudden braking	3.20	3.20	28.3	35.4	1.00	1	9.7	1.000	63C0A_Trip593	1
12/05/2026 16:37:11	52.476571	4.805106	1	Sudden braking	5.60	5.60	27.1	29.8	1.00	1	6.5	1.000	63C0A_Trip593	1
12/05/2026 16:37:12	52.476630	4.805108	1	Sudden braking	7.41	7.41	25.7	22.4	1.00	2	1.8	0.999	63C0A_Trip593	1
12/05/2026 16:37:13	52.476646	4.805108	2	Sudden braking	7.80	7.80	23.9	14.6	1.00	1	1.3	1.000	63C0A_Trip593	1
12/05/2026 16:37:14	52.476634	4.805107	2	Sudden braking	6.80	6.80	21.7	7.8	1.00	1	1.1	1.000	63C0A_Trip593	1
12/05/2026 16:37:20	52.476613	4.805107	1	Sudden braking	2.10	2.10	1.3	1.0	1.00	1	1.1	1.000	63C0A_Trip593	1
12/05/2026 16:39:45	52.484882	4.806204	324	Sudden braking	2.60	2.60	28.4	32.4	1.00	3	9.2	1.000	63C0A_Trip593	1
12/05/2026 16:39:46	52.484949	4.806122	323	Sudden braking	4.10	4.10	25.5	28.3	1.00	3	8.1	1.000	63C0A_Trip593	1
12/05/2026 16:39:47	52.485007	4.806049	322	Sudden braking	5.10	5.10	22.5	23.2	1.00	3	5.2	1.000	63C0A_Trip593	1
12/05/2026 16:39:48	52.485044	4.806003	322	Sudden braking	5.00	5.00	19.4	18.2	1.00	3	2.5	1.000	63C0A_Trip593	1
12/05/2026 16:39:49	52.485062	4.805980	322	Sudden braking	4.70	4.70	16.4	13.5	1.00	3	2.8	1.000	63C0A_Trip593	1
12/05/2026 16:39:50	52.485082	4.805954	320	Sudden braking	3.90	3.90	14.5	9.6	1.00	3	4.1	1.000	63C0A_Trip593	1
12/05/2026 16:39:51	52.485109	4.805913	315	Sudden braking	2.50	2.50	11.7	7.1	1.00	3	1.5	1.000	63C0A_Trip593	1
12/05/2026 16:41:12	52.488505	4.796429	302	Sudden braking	2.60	2.60	30.6	31.5	1.00	2	8.7	1.000	63C0A_Trip593	1
12/05/2026 16:41:13	52.488549	4.796324	301	Sudden braking	3.30	3.30	28.3	28.2	1.00	2	7.0	1.000	63C0A_Trip593	1
12/05/2026 16:41:14	52.488571	4.796227	301	Sudden braking	4.20	4.20	26.0	24.0	1.00	2	5.2	1.000	63C0A_Trip593	1
12/05/2026 16:41:15	52.488605	4.796172	299	Sudden braking	4.10	4.10	24.1	19.9	1.00	2	2.2	1.000	63C0A_Trip593	1
12/05/2026 16:43:11	52.491995	4.781559	294	Sudden braking	2.70	2.70	35.8	33.5	1.00	3	10.3	1.000	63C0A_Trip593	1
12/05/2026 16:45:56	52.494261	4.764880	272	Sudden braking	2.10	2.10	28.1	26.6	1.00	3	6.9	1.000	63C0A_Trip593	1
12/05/2026 16:54:32	52.521949	4.702424	312	Sudden braking	2.60	2.60	26.7	26.6	1.00	3	7.1	1.000	63C0A_Trip593	1
12/05/2026 16:54:33	52.521991	4.702346	311	Sudden braking	3.30	3.30	25.9	23.3	1.00	3	5.2	1.000	63C0A_Trip593	1
12/05/2026 16:54:34	52.522021	4.702288	314	Sudden braking	2.50	2.50	24.7	20.8	1.00	3	2.6	1.000	63C0A_Trip593	1
13/05/2026 07:45:53	52.353847	4.809258	73	Sudden braking	2.00	2.00	12.8	11.6	1.00	2	2.6	1.000	604F0_Trip594	1
13/05/2026 07:49:36	52.356123	4.827014	99	Sudden braking	2.50	2.50	18.0	17.1	1.00	2	4.1	1.000	604F0_Trip594	1
13/05/2026 07:49:37	52.356107	4.827069	111	Sudden braking	3.30	3.30	17.3	13.8	1.00	2	3.7	1.000	604F0_Trip594	1
13/05/2026 07:49:38	52.356088	4.827114	118	Sudden braking	3.00	3.00	16.4	10.8	1.00	2	1.8	1.000	604F0_Trip594	1
13/05/2026 07:54:12	52.354957	4.850028	89	Sudden braking	2.50	2.50	17.2	18.3	1.00	2	4.2	1.000	604F0_Trip594	1
13/05/2026 07:54:13	52.354958	4.850090	89	Sudden braking	3.30	3.30	16.6	15.0	1.00	2	3.6	1.000	604F0_Trip594	1
13/05/2026 07:54:14	52.354953	4.850142	89	Sudden braking	3.70	3.70	15.7	11.3	1.00	2	2.0	1.000	604F0_Trip594	1
13/05/2026 07:54:15	52.354951	4.850172	89	Sudden braking	3.00	3.00	14.7	8.3	1.00	2	1.2	1.000	604F0_Trip594	1
13/05/2026 08:00:10	52.361598	4.881558	61	Sudden braking	2.30	2.30	18.2	21.0	1.00	2	6.0	1.000	604F0_Trip594	1
13/05/2026 08:00:11	52.361627	4.881633	60	Sudden braking	3.20	3.20	17.6	17.8	1.00	2	4.4	1.000	604F0_Trip594	1
13/05/2026 08:00:12	52.361653	4.881682	49	Sudden braking	3.80	3.80	16.7	14.0	1.00	2	2.9	1.000	604F0_Trip594	1
13/05/2026 08:00:13	52.361674	4.881708	38	Sudden braking	3.60	3.60	15.8	10.4	1.00	2	1.6	1.000	604F0_Trip594	1
13/05/2026 08:00:14	52.361688	4.881713	17	Sudden braking	2.40	2.40	14.5	8.0	1.00	2	1.1	1.000	604F0_Trip594	1
13/05/2026 08:02:35	52.361120	4.886607	136	Sudden braking	3.10	3.10	19.7	20.8	1.00	2	6.3	1.000	604F0_Trip594	1
13/05/2026 08:02:36	52.361087	4.886684	126	Sudden braking	3.70	3.70	18.7	17.1	1.00	2	3.6	1.000	604F0_Trip594	1
13/05/2026 08:02:37	52.361073	4.886731	119	Sudden braking	3.30	3.30	18.0	13.8	1.00	2	1.9	1.000	604F0_Trip594	1
13/05/2026 08:02:38	52.361071	4.886760	109	Sudden braking	2.20	2.20	17.6	11.6	1.00	2	1.6	1.000	604F0_Trip594	1
13/05/2026 08:03:19	52.359653	4.890144	112	Sudden braking	2.00	2.00	19.0	19.5	1.00	2	4.7	1.000	604F0_Trip594	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
13/05/2026 08:03:20	52.359638	4.890208	113	Sudden braking	2.20	2.20	17.7	17.3	1.00	2	4.6	1.000	604F0_Trip594	1
13/05/2026 08:03:21	52.359613	4.890263	117	Sudden braking	2.10	2.10	16.4	15.2	1.00	2	3.9	1.000	604F0_Trip594	1
13/05/2026 08:04:41	52.359400	4.898175	78	Sudden braking	3.30	3.30	18.9	18.4	1.00	2	5.1	1.000	604F0_Trip594	1
13/05/2026 08:04:42	52.359407	4.898249	78	Sudden braking	4.40	4.40	18.1	14.0	1.00	2	3.0	1.000	604F0_Trip594	1
13/05/2026 08:04:43	52.359409	4.898293	78	Sudden braking	4.00	4.00	17.1	10.0	1.00	2	1.2	1.000	604F0_Trip594	1
13/05/2026 08:06:51	52.361024	4.907704	74	Sudden braking	2.20	2.20	18.1	19.1	1.00	2	4.9	1.000	604F0_Trip594	1
13/05/2026 08:06:52	52.361031	4.907775	78	Sudden braking	3.10	3.10	17.3	16.0	1.00	2	3.9	1.000	604F0_Trip594	1
13/05/2026 08:06:53	52.361030	4.907833	88	Sudden braking	3.40	3.40	16.5	12.6	1.00	2	2.9	1.000	604F0_Trip594	1
13/05/2026 08:06:54	52.361026	4.907875	93	Sudden braking	3.10	3.10	15.5	9.5	1.00	2	1.4	1.000	604F0_Trip594	1
13/05/2026 08:08:01	52.361874	4.911426	53	Sudden braking	2.10	2.10	14.2	12.7	1.00	2	3.4	1.000	604F0_Trip594	1
13/05/2026 08:09:21	52.366128	4.911585	30	Sudden braking	2.00	2.00	14.6	14.8	1.00	2	3.9	1.000	604F0_Trip594	1
13/05/2026 08:09:22	52.366159	4.911614	30	Sudden braking	2.10	2.10	14.1	12.7	1.00	2	2.8	1.000	604F0_Trip594	1
13/05/2026 08:09:23	52.366180	4.911637	30	Sudden braking	2.40	2.40	13.5	10.3	1.00	2	2.5	1.000	604F0_Trip594	1
13/05/2026 08:09:24	52.366199	4.911656	30	Sudden braking	2.10	2.10	12.0	8.2	1.00	2	1.7	1.000	604F0_Trip594	1
13/05/2026 08:11:51	52.371034	4.915036	68	Sudden braking	3.50	3.50	18.4	16.1	1.00	2	3.7	1.000	604F0_Trip594	1
13/05/2026 08:11:52	52.371030	4.915090	82	Sudden braking	4.00	4.00	17.7	12.1	1.00	2	2.0	1.000	604F0_Trip594	1
13/05/2026 08:29:46	52.342306	4.949198	318	Sudden braking	2.10	2.10	8.9	7.5	1.00	2	3.1	1.000	602DE_Trip596	1
13/05/2026 08:29:47	52.342326	4.949164	318	Sudden braking	2.30	2.30	8.3	5.2	1.00	2	2.1	1.000	602DE_Trip596	1
13/05/2026 08:31:04	52.344324	4.945857	316	Sudden braking	2.50	2.50	12.3	11.7	1.00	2	6.1	1.000	602DE_Trip596	1
13/05/2026 08:31:58	52.345946	4.943293	316	Sudden braking	2.20	2.20	12.8	12.1	1.00	2	5.2	1.000	602DE_Trip596	1
13/05/2026 08:32:46	52.347361	4.941033	306	Sudden braking	2.50	2.50	12.3	13.1	1.00	1	4.1	1.000	602DE_Trip596	1
13/05/2026 08:32:47	52.347391	4.940999	318	Sudden braking	2.60	2.60	11.6	10.5	1.00	1	3.3	1.000	602DE_Trip596	1
13/05/2026 08:33:40	52.348325	4.939487	323	Sudden braking	2.00	2.00	12.9	12.7	1.00	2	4.4	1.000	602DE_Trip596	1
13/05/2026 08:33:56	52.348724	4.938883	308	Sudden braking	2.20	2.20	12.4	15.3	1.00	2	4.3	1.000	602DE_Trip596	1
13/05/2026 08:33:57	52.348761	4.938864	315	Sudden braking	2.50	2.50	11.8	12.8	1.00	2	1.2	1.000	602DE_Trip596	1
13/05/2026 08:33:58	52.348751	4.938871	306	Sudden braking	2.70	2.70	11.5	10.1	1.00	2	4.6	1.000	602DE_Trip596	1
13/05/2026 08:33:59	52.348775	4.938815	303	Sudden braking	2.60	2.60	10.8	7.5	1.00	2	1.2	1.000	602DE_Trip596	1
13/05/2026 08:38:08	52.355793	4.928008	338	Sudden braking	2.00	2.00	13.9	14.6	1.00	2	5.0	1.000	602DE_Trip596	1
13/05/2026 08:39:35	52.358734	4.926114	339	Sudden braking	2.00	2.00	10.4	10.7	1.00	2	4.6	1.000	602DE_Trip596	1
13/05/2026 08:43:31	52.362858	4.930609	356	Sudden braking	2.00	2.00	9.8	11.1	1.00	2	1.9	1.000	602DE_Trip596	1
13/05/2026 08:43:32	52.362875	4.930611	356	Sudden braking	2.20	2.20	9.6	8.9	1.00	2	3.0	1.000	602DE_Trip596	1
13/05/2026 08:43:33	52.362902	4.930607	356	Sudden braking	2.10	2.10	9.5	6.8	1.00	2	2.7	1.000	602DE_Trip596	1
13/05/2026 08:46:20	52.367323	4.925692	51	Sudden braking	2.10	2.10	8.5	6.2	1.00	2	1.8	1.000	602DE_Trip596	1
13/05/2026 08:47:57	52.368755	4.922236	303	Sudden braking	2.10	2.10	15.3	14.2	1.00	2	3.2	1.000	602DE_Trip596	1
13/05/2026 09:37:29	52.355906	4.905386	348	Sudden braking	2.22	2.22	8.8	8.8	0.99	2	2.5	0.993	602CA_Trip597	1
13/05/2026 09:37:30	52.355928	4.905384	352	Sudden braking	2.31	2.31	8.0	6.5	1.00	3	1.8	0.996	602CA_Trip597	1
13/05/2026 09:40:06	52.360169	4.908952	338	Sudden braking	2.23	2.23	8.7	10.0	0.98	2	4.6	0.985	602CA_Trip597	1
13/05/2026 09:40:07	52.360209	4.908937	335	Sudden braking	2.33	2.33	8.0	7.7	0.99	2	3.3	0.986	602CA_Trip597	1
13/05/2026 09:40:08	52.360237	4.908922	336	Sudden braking	2.34	2.34	6.4	5.4	0.98	2	2.8	0.985	602CA_Trip597	1
13/05/2026 09:41:41	52.364124	4.906500	338	Sudden braking	2.06	2.06	11.5	12.9	1.02	2	4.0	1.017	602CA_Trip597	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
13/05/2026 09:41:42	52.364158	4.906478	340	Sudden braking	2.93	2.93	10.5	10.0	0.99	2	3.1	0.989	602CA_Trip597	1
13/05/2026 09:41:43	52.364184	4.906461	343	Sudden braking	3.03	3.03	8.6	7.1	0.96	2	1.7	0.958	602CA_Trip597	1
13/05/2026 09:41:44	52.364199	4.906454	343	Sudden braking	2.43	2.43	8.6	4.6	1.03	3	1.2	1.029	602CA_Trip597	1
13/05/2026 09:41:45	52.364202	4.906437	344	Sudden braking	2.26	2.26	5.2	2.3	1.02	3	1.3	1.016	602CA_Trip597	1
13/05/2026 09:46:54	52.372280	4.918318	43	Sudden braking	2.49	2.49	12.3	13.4	1.00	3	5.4	1.005	602CA_Trip597	1
13/05/2026 09:46:55	52.372308	4.918383	48	Sudden braking	3.23	3.23	10.1	10.2	0.99	2	4.2	0.992	602CA_Trip597	1
13/05/2026 09:46:56	52.372335	4.918426	53	Sudden braking	3.10	3.10	8.0	7.1	1.00	3	1.5	0.999	602CA_Trip597	1
13/05/2026 09:46:57	52.372347	4.918434	57	Sudden braking	2.68	2.68	7.7	4.4	1.01	3	2.7	1.006	602CA_Trip597	1
13/05/2026 16:38:55	52.371354	4.915154	231	Sudden braking	2.20	2.20	8.5	5.7	1.00	2	2.3	1.000	602DE_Trip615	1
13/05/2026 16:43:59	52.365401	4.927479	119	Sudden braking	2.20	2.20	15.6	15.1	1.00	2	6.1	1.000	602DE_Trip615	1
13/05/2026 16:57:04	52.354964	4.928552	135	Sudden braking	2.60	2.60	14.8	14.3	1.00	2	6.1	1.000	602DE_Trip617	1
13/05/2026 16:57:12	52.354796	4.928933	112	Sudden braking	2.60	2.60	11.0	9.5	1.00	2	5.8	1.000	602DE_Trip617	1
13/05/2026 16:57:27	52.354264	4.929742	137	Sudden braking	2.60	2.60	15.7	20.3	1.00	2	7.6	1.000	602DE_Trip617	1
13/05/2026 16:57:28	52.354209	4.929809	137	Sudden braking	3.20	3.20	15.1	17.1	1.00	2	7.3	1.000	602DE_Trip617	1
13/05/2026 16:57:29	52.354160	4.929883	137	Sudden braking	2.50	2.50	14.1	14.6	1.00	2	1.8	1.000	602DE_Trip617	1
13/05/2026 16:57:30	52.354148	4.929902	137	Sudden braking	2.80	2.80	12.8	11.8	1.00	2	10.0	1.000	602DE_Trip617	1
13/05/2026 16:57:31	52.354083	4.930003	136	Sudden braking	2.80	2.80	11.4	9.0	1.00	2	2.4	1.000	602DE_Trip617	1
13/05/2026 17:00:27	52.350175	4.935889	148	Sudden braking	2.80	2.80	12.2	13.7	1.00	2	4.1	1.000	602DE_Trip617	1
13/05/2026 17:00:28	52.350150	4.935932	142	Sudden braking	2.40	2.40	11.5	11.3	1.00	2	3.5	1.000	602DE_Trip617	1
13/05/2026 17:00:29	52.350179	4.935946	99	Sudden braking	2.30	2.30	10.9	9.0	1.00	2	4.4	1.000	602DE_Trip617	1
13/05/2026 17:02:38	52.346482	4.942104	136	Sudden braking	2.70	2.70	10.9	7.6	1.00	2	7.8	1.000	602DE_Trip617	1
13/05/2026 17:02:48	52.346156	4.942686	128	Sudden braking	2.00	2.00	12.6	13.6	1.00	2	6.3	1.000	602DE_Trip617	1
13/05/2026 17:03:14	52.345369	4.943849	133	Sudden braking	2.20	2.20	12.6	12.7	1.00	2	5.4	1.000	602DE_Trip617	1
13/05/2026 17:03:15	52.345329	4.943894	137	Sudden braking	2.20	2.20	12.6	10.5	1.00	2	1.7	1.000	602DE_Trip617	1
13/05/2026 17:04:33	52.342788	4.947860	136	Sudden braking	2.00	2.00	14.1	15.5	1.00	2	4.9	1.000	602DE_Trip617	1
13/05/2026 17:04:34	52.342760	4.947917	134	Sudden braking	2.20	2.20	13.3	13.3	1.00	2	1.5	1.000	602DE_Trip617	1
13/05/2026 17:04:35	52.342751	4.947933	133	Sudden braking	2.10	2.10	12.5	11.2	1.00	2	2.6	1.000	602DE_Trip617	1
13/05/2026 17:04:36	52.342738	4.947966	131	Sudden braking	2.10	2.10	11.7	9.1	1.00	2	4.2	1.000	602DE_Trip617	1
13/05/2026 17:06:05	52.340198	4.952388	133	Sudden braking	2.40	2.40	13.1	13.8	1.00	2	6.8	1.000	602DE_Trip617	1
13/05/2026 17:06:06	52.340189	4.952289	131	Sudden braking	2.60	2.60	12.9	11.2	1.00	2	5.7	1.000	602DE_Trip617	1
13/05/2026 17:06:07	52.340148	4.952338	133	Sudden braking	2.70	2.70	12.4	8.5	1.00	2	0.5	1.000	602DE_Trip617	1
13/05/2026 17:38:37	52.371416	4.915252	237	Sudden braking	2.28	2.28	8.4	7.8	1.01	2	2.8	1.008	604F9_Trip621	1
13/05/2026 17:38:38	52.371398	4.915222	223	Sudden braking	2.21	2.21	5.5	5.6	0.99	2	1.8	0.995	604F9_Trip621	1
13/05/2026 17:41:23	52.367686	4.925328	119	Sudden braking	2.01	2.01	11.7	12.0	1.00	2	3.9	0.997	604F9_Trip621	1
13/05/2026 17:41:26	52.367652	4.925446	131	Sudden braking	2.18	2.18	7.5	6.0	1.01	2	1.8	1.011	604F9_Trip621	1
13/05/2026 17:42:44	52.365958	4.926627	171	Sudden braking	2.11	2.11	7.1	7.6	0.99	1	2.2	0.993	604F9_Trip621	1
13/05/2026 17:42:45	52.365940	4.926636	178	Sudden braking	2.28	2.28	5.3	5.3	1.01	1	1.4	1.008	604F9_Trip621	1
13/05/2026 19:16:13	52.366645	4.911989	214	Sudden braking	2.06	2.06	9.9	10.9	1.02	2	3.9	1.018	602CA_Trip620	1
13/05/2026 19:16:14	52.366618	4.911951	214	Sudden braking	2.63	2.63	7.0	8.2	1.02	2	3.1	1.025	602CA_Trip620	1
13/05/2026 19:16:15	52.366597	4.911919	219	Sudden braking	2.85	2.85	6.4	5.5	0.95	2	1.9	0.947	602CA_Trip620	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
13/05/2026 19:16:16	52.366586	4.911898	229	Sudden braking	2.44	2.44	5.6	3.0	1.02	2	0	1.024	602CA_Trip620	1
13/05/2026 19:20:27	52.361202	4.907691	213	Sudden braking	2.11	2.11	6.6	5.8	0.99	2	1.7	0.994	602CA_Trip620	1
13/05/2026 19:22:27	52.358822	4.903721	251	Sudden braking	2.00	2.00	10.3	9.8	1.00	1	3.2	1.001	602CA_Trip620	1
13/05/2026 19:22:28	52.358812	4.903677	251	Sudden braking	2.46	2.46	9.7	7.3	1.02	1	2.5	1.018	602CA_Trip620	1
13/05/2026 19:22:29	52.358805	4.903643	250	Sudden braking	2.56	2.56	8.2	4.8	0.98	1	1.8	0.978	602CA_Trip620	1
13/05/2026 19:22:30	52.358804	4.903616	250	Sudden braking	2.18	2.18	8.2	2.6	1.01	1	0	1.007	602CA_Trip620	1
13/05/2026 19:35:37	52.333917	4.899832	252	Sudden braking	2.00	2.00	14.9	13.1	1.00	2	5.1	0.998	602CA_Trip620	1
14/05/2026 05:15:26	52.339766	4.952702	274	Sudden braking	2.70	2.70	14.1	12.7	1.00	2	4.7	1.000	602DE_Trip622	1
14/05/2026 05:15:27	52.339805	4.952674	334	Sudden braking	2.50	2.50	14.2	10.2	1.00	2	5.2	1.000	602DE_Trip622	1
14/05/2026 05:15:40	52.339444	4.951591	229	Sudden braking	4.10	4.10	13.9	14.0	1.00	2	3.9	1.000	602DE_Trip622	1
14/05/2026 05:15:41	52.339413	4.951564	229	Sudden braking	3.30	3.30	13.2	10.7	1.00	2	1.9	1.000	602DE_Trip622	1
14/05/2026 05:16:11	52.338881	4.950095	242	Sudden braking	2.00	2.00	11.4	12.2	1.00	2	2.8	1.000	602DE_Trip622	1
14/05/2026 05:16:13	52.338858	4.950051	234	Sudden braking	2.00	2.00	9.7	8.3	1.00	2	3.3	1.000	602DE_Trip622	1
14/05/2026 05:17:10	52.338005	4.946770	246	Sudden braking	2.10	2.10	12.4	10.5	1.00	2	4.7	1.000	602DE_Trip622	1
14/05/2026 05:27:30	52.353545	4.920289	319	Sudden braking	2.10	2.10	12.8	12.1	1.00	2	4.5	1.000	602DE_Trip622	1
14/05/2026 05:27:31	52.353585	4.920275	330	Sudden braking	2.20	2.20	12.8	9.9	1.00	2	1.4	1.000	602DE_Trip622	1
14/05/2026 09:54:25	52.360266	4.908817	334	Sudden braking	2.07	2.07	8.6	9.3	0.96	3	2.4	0.965	602CA_Trip635	1
14/05/2026 09:54:26	52.360285	4.908799	330	Sudden braking	2.29	2.29	8.6	7.0	1.00	3	2.3	1.005	602CA_Trip635	1
14/05/2026 09:54:27	52.360302	4.908779	329	Sudden braking	2.16	2.16	7.6	4.8	1.02	3	1.6	1.020	602CA_Trip635	1
14/05/2026 09:54:51	52.361083	4.908260	350	Sudden braking	2.41	2.41	14.0	16.8	1.00	2	5.7	0.997	602CA_Trip635	1
14/05/2026 09:54:52	52.361132	4.908242	346	Sudden braking	3.91	3.91	13.2	13.0	0.97	2	3.9	0.972	602CA_Trip635	1
14/05/2026 09:54:53	52.361167	4.908233	345	Sudden braking	3.94	3.94	12.2	8.9	1.04	2	2.7	1.041	602CA_Trip635	1
14/05/2026 09:54:54	52.361191	4.908223	344	Sudden braking	3.64	3.64	12.2	5.2	1.02	2	0.4	1.016	602CA_Trip635	1
14/05/2026 09:54:55	52.361192	4.908229	343	Sudden braking	3.05	3.05	9.2	2.2	0.98	2	0	0.983	602CA_Trip635	1
14/05/2026 09:57:53	52.368016	4.904948	77	Sudden braking	2.24	2.24	9.7	10.5	0.98	2	2.9	0.984	602CA_Trip635	1
14/05/2026 09:57:54	52.368019	4.904990	87	Sudden braking	2.64	2.64	8.8	7.9	0.99	2	1.5	0.986	602CA_Trip635	1
14/05/2026 09:57:55	52.368018	4.905011	100	Sudden braking	2.54	2.54	8.0	5.3	1.02	2	1.2	1.022	602CA_Trip635	1
14/05/2026 09:57:56	52.368012	4.905027	116	Sudden braking	2.02	2.02	5.3	3.2	1.04	2	1.4	1.039	602CA_Trip635	1
14/05/2026 10:01:14	52.371027	4.915039	70	Sudden braking	2.77	2.77	8.7	10.2	0.97	2	2.7	0.975	602CA_Trip635	1
14/05/2026 10:01:15	52.371031	4.915078	81	Sudden braking	2.81	2.81	8.7	7.3	1.03	2	2.9	1.033	602CA_Trip635	1
14/05/2026 10:01:16	52.371032	4.915120	86	Sudden braking	2.62	2.62	7.7	4.7	0.99	2	0.5	0.994	602CA_Trip635	1
14/05/2026 10:01:17	52.371034	4.915127	0	Sudden braking	2.23	2.23	6.7	2.5	0.99	2	0.3	0.986	602CA_Trip635	1
14/05/2026 13:11:13	52.350224	4.924716	138	Sudden braking	2.40	2.40	19.2	18.3	1.00	2	5.8	1.000	602DE_Trip639	1
14/05/2026 13:13:34	52.345450	4.932617	135	Sudden braking	2.60	2.60	16.7	15.8	1.00	2	5.4	1.000	602DE_Trip639	1
14/05/2026 13:13:35	52.345416	4.932673	135	Sudden braking	2.40	2.40	16.7	13.4	1.00	2	1.5	1.000	602DE_Trip639	1
14/05/2026 13:14:04	52.344382	4.934264	140	Sudden braking	2.10	2.10	14.4	14.4	1.00	2	4.5	1.000	602DE_Trip639	1
14/05/2026 13:14:05	52.344348	4.934300	147	Sudden braking	2.30	2.30	13.1	12.1	1.00	2	2.9	1.000	602DE_Trip639	1
14/05/2026 13:16:42	52.346548	4.941962	134	Sudden braking	2.50	2.50	14.4	14.7	1.00	2	5.4	1.000	602DE_Trip639	1
14/05/2026 13:16:45	52.346488	4.942072	133	Sudden braking	2.10	2.10	11.9	9.9	1.00	2	3.5	1.000	602DE_Trip639	1
14/05/2026 13:20:44	52.339360	4.954910	111	Sudden braking	2.00	2.00	10.9	8.6	1.00	2	1.7	1.000	602DE_Trip639	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_h_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
14/05/2026 15:51:12	52.371050	4.913238	289	Sudden braking	2.10	2.10	13.1	13.9	1.00	2	3.8	1.000	604F0_Trip641	1
14/05/2026 15:51:13	52.371051	4.913182	279	Sudden braking	3.10	3.10	12.9	10.8	1.00	2	2.1	1.000	604F0_Trip641	1
14/05/2026 15:52:11	52.369588	4.912265	222	Sudden braking	2.00	2.00	15.5	13.8	1.00	2	3.7	1.000	604F0_Trip641	1
14/05/2026 15:52:36	52.368879	4.913948	119	Sudden braking	2.00	2.00	16.9	16.1	1.00	2	3.5	1.000	604F0_Trip641	1
14/05/2026 15:52:37	52.368861	4.913991	119	Sudden braking	2.00	2.00	16.0	14.1	1.00	2	3.8	1.000	604F0_Trip641	1
14/05/2026 15:53:11	52.367415	4.912616	210	Sudden braking	2.20	2.20	18.7	18.3	1.00	2	5.0	1.000	604F0_Trip641	1
14/05/2026 15:53:12	52.367374	4.912587	210	Sudden braking	2.10	2.10	18.1	16.2	1.00	2	3.7	1.000	604F0_Trip641	1
14/05/2026 15:54:49	52.364367	4.906339	245	Sudden braking	2.20	2.20	12.6	12.0	1.00	2	1.3	1.000	604F0_Trip641	1
14/05/2026 15:54:50	52.364365	4.906321	248	Sudden braking	2.60	2.60	11.7	9.4	1.00	2	1.8	1.000	604F0_Trip641	1
14/05/2026 15:54:51	52.364354	4.906301	243	Sudden braking	2.70	2.70	10.8	6.7	1.00	1	1.7	1.000	604F0_Trip641	1
14/05/2026 15:59:49	52.359659	4.891566	276	Sudden braking	2.40	2.40	13.0	14.5	1.00	2	3.5	1.000	604F0_Trip641	1
14/05/2026 15:59:50	52.359662	4.891514	277	Sudden braking	2.70	2.70	12.4	11.8	1.00	2	2.7	1.000	604F0_Trip641	1
14/05/2026 15:59:51	52.359664	4.891475	275	Sudden braking	2.70	2.70	11.5	9.1	1.00	2	1.8	1.000	604F0_Trip641	1
14/05/2026 15:59:52	52.359664	4.891448	273	Sudden braking	2.60	2.60	10.5	6.5	1.00	1	1.3	1.000	604F0_Trip641	1
14/05/2026 15:59:53	52.359663	4.891429	271	Sudden braking	2.30	2.30	9.4	4.2	1.00	1	1.0	1.000	604F0_Trip641	1
14/05/2026 16:02:35	52.362546	4.883894	308	Sudden braking	2.00	2.00	15.4	14.8	1.00	2	3.7	1.000	604F0_Trip641	1
14/05/2026 16:08:17	52.355001	4.855934	253	Sudden braking	2.10	2.10	17.6	17.3	1.00	2	4.7	1.000	604F0_Trip641	1
14/05/2026 16:08:18	52.354984	4.855870	250	Sudden braking	2.20	2.20	16.7	15.1	1.00	2	3.9	1.000	604F0_Trip641	1
14/05/2026 16:09:19	52.354962	4.850779	269	Sudden braking	2.00	2.00	14.4	14.6	1.00	2	4.1	1.000	604F0_Trip641	1
14/05/2026 16:09:20	52.354961	4.850718	269	Sudden braking	2.00	2.00	13.6	12.6	1.00	2	3.4	1.000	604F0_Trip641	1
14/05/2026 16:09:21	52.354958	4.850668	269	Sudden braking	2.00	2.00	12.2	10.6	1.00	2	2.6	1.000	604F0_Trip641	1
14/05/2026 16:09:22	52.354958	4.850629	269	Sudden braking	2.00	2.00	11.1	8.6	1.00	2	1.9	1.000	604F0_Trip641	1
14/05/2026 16:10:39	52.355706	4.844620	269	Sudden braking	2.10	2.10	19.8	19.7	1.00	2	4.8	1.000	604F0_Trip641	1
14/05/2026 16:10:40	52.355709	4.844550	272	Sudden braking	2.30	2.30	19.2	17.4	1.00	2	4.1	0.999	604F0_Trip641	1
14/05/2026 16:16:02	52.355415	4.816273	251	Sudden braking	2.10	2.10	20.9	20.1	1.00	2	4.8	1.000	604F0_Trip641	1
14/05/2026 16:16:03	52.355410	4.816203	260	Sudden braking	2.10	2.10	20.4	18.0	1.00	2	4.8	1.000	604F0_Trip641	1
14/05/2026 16:16:48	52.357757	4.814915	341	Sudden braking	2.10	2.10	14.4	13.8	1.00	2	4.0	1.000	604F0_Trip641	1
14/05/2026 16:16:49	52.357789	4.814891	338	Sudden braking	2.10	2.10	13.8	11.7	1.00	2	2.4	1.000	604F0_Trip641	1
14/05/2026 16:17:52	52.356686	4.809523	253	Sudden braking	2.10	2.10	15.2	14.9	1.00	2	3.8	1.000	604F0_Trip641	1
14/05/2026 16:17:53	52.356676	4.809470	253	Sudden braking	2.40	2.40	14.3	12.5	1.00	2	3.1	1.000	604F0_Trip641	1
14/05/2026 16:17:54	52.356668	4.809426	254	Sudden braking	2.90	2.90	13.3	9.6	1.00	2	2.3	1.000	604F0_Trip641	1
14/05/2026 16:17:55	52.356663	4.809393	255	Sudden braking	2.40	2.40	12.3	7.2	1.00	2	1.1	1.000	604F0_Trip641	1
14/05/2026 19:45:36	52.346019	4.914346	161	Sudden braking	2.27	2.27	16.6	16.4	1.01	3	5.3	1.013	602CA_Trip643	1
14/05/2026 19:45:37	52.345973	4.914367	158	Sudden braking	2.23	2.23	15.7	14.2	0.99	3	4.2	0.987	602CA_Trip643	1
14/05/2026 19:46:00	52.345316	4.915732	134	Sudden braking	2.64	2.64	10.8	10.0	0.95	2	3.4	0.947	602CA_Trip643	1
14/05/2026 19:46:01	52.345321	4.915780	132	Sudden braking	2.08	2.08	10.8	7.9	1.01	2	2.9	1.009	602CA_Trip643	1
14/05/2026 19:48:18	52.338192	4.921431	155	Sudden braking	2.00	2.00	8.0	8.4	1.00	2	3.0	0.999	602CA_Trip643	1
14/05/2026 19:55:39	52.331174	4.914489	149	Sudden braking	2.20	2.20	15.1	15.7	1.00	2	4.4	1.000	602CA_Trip644	1
14/05/2026 19:55:40	52.331139	4.914520	156	Sudden braking	2.20	2.20	14.1	13.5	1.00	2	3.1	0.998	602CA_Trip644	1
14/05/2026 19:55:41	52.331112	4.914532	182	Sudden braking	2.20	2.20	13.6	11.3	1.00	2	2.3	0.999	602CA_Trip644	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
14/05/2026 19:56:58	52.328147	4.916860	161	Sudden braking	2.45	2.45	19.2	18.0	1.02	2	9.9	1.019	602CA_Trip644	1
14/05/2026 20:02:10	52.318570	4.910488	285	Sudden braking	2.18	2.18	13.8	14.5	1.01	2	5.1	1.010	602CA_Trip644	1
14/05/2026 20:02:11	52.318580	4.910415	282	Sudden braking	2.21	2.21	12.8	12.3	0.99	2	3.3	0.994	602CA_Trip644	1
14/05/2026 20:02:12	52.318588	4.910368	281	Sudden braking	2.01	2.01	12.6	10.3	0.99	2	2.1	0.993	602CA_Trip644	1
15/05/2026 08:11:02	52.353814	4.809140	72	Sudden braking	2.10	2.10	17.2	16.9	1.00	2	4.3	1.000	604F0_Trip654	1
15/05/2026 08:11:03	52.353826	4.809201	72	Sudden braking	2.20	2.20	15.5	14.7	1.00	2	3.8	1.001	604F0_Trip654	1
15/05/2026 08:11:05	52.353837	4.809254	72	Sudden braking	2.10	2.10	12.9	12.6	1.00	2	2.8	1.000	604F0_Trip654	1
15/05/2026 08:11:06	52.353845	4.809293	72	Sudden braking	2.30	2.30	11.9	10.3	1.00	2	2.0	1.000	604F0_Trip654	1
15/05/2026 08:11:07	52.353851	4.809320	72	Sudden braking	2.20	2.20	10.9	8.1	1.00	2	1.4	1.000	604F0_Trip654	1
15/05/2026 08:14:23	52.340532	4.952178	-1	Sudden braking	2.50	2.50	2.0	4.5	1.00	2	2.2	1.000	602DE_Trip655	1
15/05/2026 08:15:42	52.340438	4.952024	-1	Sudden braking	2.00	2.00	1.9	2.3	1.00	2	1.2	1.000	602DE_Trip655	1
15/05/2026 08:19:58	52.354747	4.854960	75	Sudden braking	2.10	2.10	20.4	22.6	1.00	2	6.0	1.000	604F0_Trip654	1
15/05/2026 08:19:59	52.354761	4.855046	75	Sudden braking	2.80	2.80	18.6	19.8	1.00	2	4.7	1.000	604F0_Trip654	1
15/05/2026 08:20:00	52.354775	4.855112	72	Sudden braking	3.10	3.10	16.7	16.7	1.00	2	3.5	1.000	604F0_Trip654	1
15/05/2026 08:20:01	52.354785	4.855161	72	Sudden braking	3.00	3.00	14.8	13.7	1.00	2	1.6	1.000	604F0_Trip654	1
15/05/2026 08:20:02	52.354791	4.855181	62	Sudden braking	2.70	2.70	13.0	11.0	1.00	2	2.6	1.000	604F0_Trip654	1
15/05/2026 08:20:03	52.354802	4.855214	62	Sudden braking	2.20	2.20	11.4	8.8	1.00	2	1.7	1.000	604F0_Trip654	1
15/05/2026 08:25:01	52.361640	4.881709	54	Sudden braking	2.10	2.10	21.3	21.3	1.00	2	5.4	1.000	604F0_Trip654	1
15/05/2026 08:25:02	52.361678	4.881757	45	Sudden braking	2.10	2.10	20.6	19.2	1.00	2	3.5	1.000	604F0_Trip654	1
15/05/2026 08:25:26	52.362324	4.883287	56	Sudden braking	2.50	2.50	16.1	14.8	1.00	1	4.1	1.000	604F0_Trip654	1
15/05/2026 08:25:27	52.362358	4.883310	41	Sudden braking	3.70	3.70	14.2	11.1	1.00	1	2.5	1.000	604F0_Trip654	1
15/05/2026 08:27:29	52.359388	4.925733	338	Sudden braking	2.10	2.10	9.6	8.5	1.00	2	1.4	1.000	602DE_Trip655	1
15/05/2026 08:28:04	52.359525	4.890976	99	Sudden braking	3.50	3.50	16.5	16.3	1.00	2	4.0	1.000	604F0_Trip654	1
15/05/2026 08:28:05	52.359513	4.891031	104	Sudden braking	4.30	4.30	16.0	12.0	1.00	2	2.6	1.000	604F0_Trip654	1
15/05/2026 08:29:28	52.359377	4.898107	77	Sudden braking	2.10	2.10	16.1	16.7	1.00	2	3.9	1.000	604F0_Trip654	1
15/05/2026 08:29:29	52.359384	4.898163	78	Sudden braking	2.30	2.30	14.5	14.4	1.00	2	3.5	1.000	604F0_Trip654	1
15/05/2026 08:29:30	52.359390	4.898214	78	Sudden braking	2.30	2.30	13.1	12.1	1.00	2	2.6	1.000	604F0_Trip654	1
15/05/2026 08:29:31	52.359395	4.898252	78	Sudden braking	2.10	2.10	11.7	10.0	1.00	2	1.6	1.000	604F0_Trip654	1
15/05/2026 08:31:26	52.360982	4.907757	74	Sudden braking	2.00	2.00	17.1	18.5	1.00	2	4.8	1.000	604F0_Trip654	1
15/05/2026 08:31:27	52.360994	4.907825	76	Sudden braking	3.00	3.00	16.6	15.5	1.00	2	3.7	1.000	604F0_Trip654	1
15/05/2026 08:31:28	52.361004	4.907877	74	Sudden braking	3.50	3.50	15.9	12.0	1.00	2	2.5	1.000	604F0_Trip654	1
15/05/2026 08:34:22	52.368743	4.922286	293	Sudden braking	2.60	2.60	14.0	14.4	1.00	2	4.3	1.000	602DE_Trip655	1
15/05/2026 08:34:23	52.368764	4.922233	299	Sudden braking	2.70	2.70	14.1	11.7	1.00	2	1.1	1.000	602DE_Trip655	1
15/05/2026 08:35:28	52.370760	4.912852	45	Sudden braking	2.60	2.60	18.1	19.0	1.00	2	4.5	1.000	604F0_Trip654	1
15/05/2026 08:35:29	52.370785	4.912904	49	Sudden braking	3.10	3.10	16.2	15.9	1.00	2	3.0	1.000	604F0_Trip654	1
15/05/2026 08:35:30	52.370797	4.912944	54	Sudden braking	3.70	3.70	14.2	12.2	1.00	2	2.0	1.000	604F0_Trip654	1
15/05/2026 08:35:31	52.370072	4.918280	291	Sudden braking	2.10	2.10	12.5	14.0	1.00	2	3.8	1.000	602DE_Trip655	1
15/05/2026 08:35:31	52.370806	4.912970	56	Sudden braking	3.40	3.40	12.4	8.8	1.00	2	1.6	1.000	604F0_Trip654	1
15/05/2026 08:35:32	52.370095	4.918238	296	Sudden braking	2.40	2.40	12.0	11.6	1.00	2	1.5	1.000	602DE_Trip655	1
15/05/2026 08:35:33	52.370106	4.918249	309	Sudden braking	2.20	2.20	11.7	9.4	1.00	2	3.2	1.000	602DE_Trip655	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
15/05/2026 08:36:02	52.371032	4.915009	66	Sudden braking	2.10	2.10	16.0	15.1	1.00	2	3.4	1.000	604F0_Trip654	1
15/05/2026 08:36:03	52.371032	4.915059	78	Sudden braking	2.60	2.60	15.3	12.5	1.00	2	2.6	1.000	604F0_Trip654	1
15/05/2026 08:36:04	52.371025	4.915096	89	Sudden braking	2.60	2.60	14.6	9.9	1.00	3	1.9	1.000	604F0_Trip654	1
15/05/2026 15:56:16	52.371421	4.915286	240	Sudden braking	2.00	2.00	10.2	9.5	1.00	3	1.9	1.001	602DE_Trip680	1
15/05/2026 15:59:18	52.367678	4.925389	118	Sudden braking	2.10	2.10	10.3	9.4	1.00	2	2.4	1.000	602DE_Trip680	1
15/05/2026 15:59:19	52.367658	4.925404	135	Sudden braking	2.30	2.30	9.7	7.1	1.00	2	2.1	1.000	602DE_Trip680	1
15/05/2026 15:59:20	52.367641	4.925392	172	Sudden braking	2.50	2.50	9.0	4.6	1.00	2	1.4	1.000	602DE_Trip680	1
15/05/2026 16:00:58	52.365950	4.926598	184	Sudden braking	2.20	2.20	9.8	7.0	1.00	2	1.3	1.000	602DE_Trip680	1
15/05/2026 16:03:39	52.361377	4.930328	186	Sudden braking	2.30	2.30	10.1	7.8	1.00	2	2.3	1.000	602DE_Trip680	1
15/05/2026 16:08:00	52.355786	4.927816	159	Sudden braking	2.00	2.00	10.1	7.4	1.00	2	1.5	1.000	602DE_Trip680	1
15/05/2026 16:14:19	52.344306	4.945524	135	Sudden braking	2.20	2.20	10.5	9.9	1.00	2	3.2	1.000	602DE_Trip680	1
15/05/2026 16:14:20	52.344287	4.945558	134	Sudden braking	2.20	2.20	9.9	7.7	1.00	3	3.1	1.000	602DE_Trip680	1
15/05/2026 16:14:56	52.343147	4.947321	130	Sudden braking	2.10	2.10	13.2	13.6	1.00	2	3.1	1.000	602DE_Trip680	1
15/05/2026 16:15:12	52.342724	4.948045	120	Sudden braking	2.00	2.00	11.5	10.5	1.00	2	4.9	1.000	602DE_Trip680	1
15/05/2026 16:16:46	52.340160	4.952333	145	Sudden braking	2.40	2.40	11.3	11.5	1.00	2	1.1	1.000	602DE_Trip680	1
15/05/2026 16:16:47	52.340153	4.952344	139	Sudden braking	3.30	3.30	11.0	8.2	1.00	2	1.3	1.000	602DE_Trip680	1
16/05/2026 05:18:56	52.340765	4.936636	315	Sudden braking	2.20	2.20	13.0	14.3	1.00	2	5.5	1.000	602DE_Trip685	1
16/05/2026 05:18:57	52.340801	4.936582	316	Sudden braking	2.20	2.20	12.0	12.1	1.00	2	1.4	1.000	602DE_Trip685	1
16/05/2026 05:18:58	52.340807	4.936565	314	Sudden braking	2.20	2.20	11.0	9.9	1.00	2	3.2	1.000	602DE_Trip685	1
16/05/2026 05:18:59	52.340822	4.936524	300	Sudden braking	2.30	2.30	10.1	7.6	1.00	2	3.2	1.000	602DE_Trip685	1
16/05/2026 05:19:23	52.341589	4.935349	313	Sudden braking	2.00	2.00	13.0	10.6	1.00	2	3.4	1.000	602DE_Trip685	1
16/05/2026 05:21:15	52.344994	4.933592	310	Sudden braking	2.10	2.10	9.8	9.6	1.00	2	2.4	1.000	602DE_Trip685	1
16/05/2026 05:21:16	52.345009	4.933568	306	Sudden braking	2.20	2.20	8.9	7.4	1.00	2	3.6	1.000	602DE_Trip685	1
16/05/2026 10:46:16	52.301147	4.870957	202	Sudden braking	2.13	2.13	16.2	15.0	1.03	3	7.1	1.033	602CA_Trip696	1
16/05/2026 10:54:46	52.291722	4.843896	286	Sudden braking	2.13	2.13	6.8	5.8	0.98	2	1.9	0.984	602CA_Trip696	1
16/05/2026 11:13:15	52.291527	4.843324	109	Sudden braking	2.07	2.07	7.9	8.8	1.01	2	2.7	1.014	602CA_Trip697	1
16/05/2026 11:13:16	52.291517	4.843361	111	Sudden braking	2.65	2.65	7.1	6.3	0.94	2	1.1	0.942	602CA_Trip697	1
16/05/2026 11:13:17	52.291510	4.843372	115	Sudden braking	2.35	2.35	6.4	3.8	1.06	2	1.3	1.062	602CA_Trip697	1
16/05/2026 11:13:18	52.291505	4.843389	119	Sudden braking	2.01	2.01	4.0	1.8	0.99	2	1.0	0.995	602CA_Trip697	1
16/05/2026 11:21:38	52.298709	4.869333	9	Sudden braking	2.09	2.09	16.5	17.3	1.00	3	10.6	1.004	602CA_Trip697	1
17/05/2026 09:49:33	52.355908	4.905385	343	Sudden braking	2.65	2.65	10.9	11.7	0.98	3	3.7	0.982	602CA_Trip700	1
17/05/2026 09:49:34	52.355939	4.905366	345	Sudden braking	3.18	3.18	10.2	8.4	1.04	3	3.2	1.038	602CA_Trip700	1
17/05/2026 09:49:35	52.355964	4.905343	341	Sudden braking	2.89	2.89	8.4	5.5	1.00	4	1.5	1.002	602CA_Trip700	1
17/05/2026 09:51:33	52.359820	4.908448	75	Sudden braking	2.71	2.71	11.6	11.8	1.00	2	0.6	0.998	602CA_Trip700	1
17/05/2026 09:51:34	52.359825	4.908447	88	Sudden braking	3.05	3.05	10.8	8.7	1.02	2	0.7	1.018	602CA_Trip700	1
17/05/2026 09:51:35	52.359828	4.908456	85	Sudden braking	3.11	3.11	8.7	5.6	1.00	2	1.0	0.996	602CA_Trip700	1
17/05/2026 09:51:36	52.359821	4.908448	89	Sudden braking	2.76	2.76	7.4	2.9	0.98	2	1.2	0.979	602CA_Trip700	1
17/05/2026 09:58:45	52.372335	4.918396	44	Sudden braking	2.26	2.26	12.5	13.2	0.97	3	4.0	0.972	602CA_Trip700	1
17/05/2026 09:58:46	52.372366	4.918424	42	Sudden braking	2.42	2.42	11.6	10.7	1.03	3	3.7	1.033	602CA_Trip700	1
17/05/2026 09:58:47	52.372397	4.918441	38	Sudden braking	2.41	2.41	10.9	8.3	1.00	3	2.8	0.997	602CA_Trip700	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
17/05/2026 18:20:55	52.369735	4.912450	204	Sudden braking	2.21	2.21	18.5	20.0	1.04	3	7.0	1.043	602CA_Trip701	1
17/05/2026 18:20:56	52.369677	4.912407	220	Sudden braking	2.95	2.95	16.6	17.2	0.95	3	5.1	0.949	602CA_Trip701	1
17/05/2026 18:20:57	52.369640	4.912364	238	Sudden braking	2.80	2.80	16.6	14.4	1.00	3	5.1	1.001	602CA_Trip701	1
17/05/2026 18:20:58	52.369608	4.912309	246	Sudden braking	2.19	2.19	15.4	12.2	1.00	3	3.4	1.003	602CA_Trip701	1
17/05/2026 18:22:20	52.366669	4.911944	215	Sudden braking	2.21	2.21	12.1	12.4	1.00	2	3.5	0.996	602CA_Trip701	1
17/05/2026 18:22:21	52.366644	4.911913	216	Sudden braking	2.93	2.93	11.3	9.5	0.99	2	3.1	0.991	602CA_Trip701	1
17/05/2026 18:22:22	52.366619	4.911894	215	Sudden braking	3.03	3.03	10.4	6.4	1.02	2	2.7	1.023	602CA_Trip701	1
17/05/2026 18:22:23	52.366599	4.911872	223	Sudden braking	2.41	2.41	7.1	4.0	1.00	2	1.7	0.996	602CA_Trip701	1
17/05/2026 18:24:21	52.362626	4.907413	256	Sudden braking	2.13	2.13	8.0	7.2	0.99	2	1.9	0.987	602CA_Trip701	1
17/05/2026 18:25:03	52.361202	4.907626	173	Sudden braking	2.37	2.37	9.6	11.2	0.97	2	3.3	0.972	602CA_Trip701	1
17/05/2026 18:25:04	52.361174	4.907642	169	Sudden braking	2.64	2.64	9.6	8.6	0.98	2	2.7	0.985	602CA_Trip701	1
17/05/2026 18:25:05	52.361156	4.907667	164	Sudden braking	2.50	2.50	7.7	6.0	1.04	2	1.9	1.041	602CA_Trip701	1
17/05/2026 18:25:06	52.361143	4.907686	166	Sudden braking	2.23	2.23	6.6	3.8	0.98	2	0.9	0.985	602CA_Trip701	1
17/05/2026 18:26:55	52.358828	4.903755	253	Sudden braking	2.58	2.58	9.3	10.7	0.93	2	3.4	0.931	602CA_Trip701	1
17/05/2026 18:26:56	52.358820	4.903707	256	Sudden braking	2.47	2.47	9.3	8.1	1.05	2	2.0	1.052	602CA_Trip701	1
17/05/2026 18:26:57	52.358812	4.903680	257	Sudden braking	2.40	2.40	6.8	5.7	1.00	2	2.0	0.998	602CA_Trip701	1
17/05/2026 18:26:58	52.358809	4.903651	246	Sudden braking	2.23	2.23	5.5	3.5	0.99	2	0.8	0.987	602CA_Trip701	1
17/05/2026 18:44:49	52.317405	4.881580	193	Sudden braking	2.69	2.69	12.4	12.6	1.00	2	4.2	1.005	602CA_Trip701	1
17/05/2026 18:44:50	52.317379	4.881534	214	Sudden braking	2.76	2.76	11.8	9.8	1.02	2	3.5	1.016	602CA_Trip701	1
17/05/2026 18:44:51	52.317371	4.881484	244	Sudden braking	2.34	2.34	10.4	7.5	0.98	2	1.5	0.985	602CA_Trip701	1
18/05/2026 06:40:36	52.344180	4.912844	345	Sudden braking	3.50	3.50	14.6	12.2	1.00	2	5.3	1.001	602CA_Trip703	1
18/05/2026 06:45:06	52.355844	4.905309	340	Sudden braking	2.29	2.29	11.4	13.8	1.00	2	4.5	1.005	602CA_Trip703	1
18/05/2026 06:45:07	52.355883	4.905297	338	Sudden braking	3.15	3.15	10.4	10.7	0.98	2	3.8	0.983	602CA_Trip703	1
18/05/2026 06:45:08	52.355917	4.905285	339	Sudden braking	3.25	3.25	9.2	7.5	0.99	2	2.4	0.986	602CA_Trip703	1
18/05/2026 06:45:08	52.355938	4.905279	339	Sudden braking	2.78	2.78	9.2	4.7	1.01	2	0.5	1.006	602CA_Trip703	1
18/05/2026 06:45:09	52.355942	4.905284	340	Sudden braking	2.26	2.26	8.0	2.4	1.02	2	0.8	1.016	602CA_Trip703	1
18/05/2026 06:47:11	52.359912	4.908429	68	Sudden braking	2.04	2.04	10.1	10.4	0.98	2	2.8	0.979	602CA_Trip703	1
18/05/2026 06:47:54	52.360261	4.908843	337	Sudden braking	2.82	2.82	11.2	12.6	0.99	2	3.9	0.992	602CA_Trip703	1
18/05/2026 06:47:55	52.360294	4.908823	337	Sudden braking	3.11	3.11	11.2	9.5	1.00	2	2.9	0.997	602CA_Trip703	1
18/05/2026 06:47:55	52.360318	4.908807	334	Sudden braking	3.05	3.05	8.2	6.4	1.01	2	0.9	1.015	602CA_Trip703	1
18/05/2026 06:47:57	52.360325	4.908800	331	Sudden braking	3.15	3.15	6.1	3.3	0.98	2	0.5	0.983	602CA_Trip703	1
18/05/2026 06:47:57	52.360321	4.908804	319	Sudden braking	2.22	2.22	4.2	1.1	0.99	2	0	0.993	602CA_Trip703	1
18/05/2026 06:53:52	52.371021	4.915021	79	Sudden braking	2.56	2.56	11.9	12.3	1.01	2	3.4	1.014	602CA_Trip703	1
18/05/2026 06:53:53	52.371023	4.915072	84	Sudden braking	2.93	2.93	9.2	9.4	0.99	2	3.2	0.990	602CA_Trip703	1
18/05/2026 06:53:54	52.371026	4.915119	83	Sudden braking	3.04	3.04	9.2	6.4	0.99	2	1.5	0.987	602CA_Trip703	1
18/05/2026 06:53:55	52.371032	4.915140	89	Sudden braking	2.73	2.73	7.3	3.6	1.02	2	0.6	1.025	602CA_Trip703	1
18/05/2026 06:53:56	52.371029	4.915148	97	Sudden braking	2.01	2.01	4.2	1.6	1.00	2	0.4	0.996	602CA_Trip703	1
18/05/2026 07:24:26	52.367034	4.871669	58	Sudden braking	2.36	2.36	12.5	14.0	0.97	2	4.1	0.975	604F9_Trip704	1
18/05/2026 07:24:27	52.367053	4.871720	55	Sudden braking	2.51	2.51	12.5	11.5	0.99	2	3.0	0.995	604F9_Trip704	1
18/05/2026 07:24:28	52.367065	4.871759	57	Sudden braking	2.45	2.45	11.0	9.0	1.02	2	2.4	1.019	604F9_Trip704	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
18/05/2026 07:26:05	52.368188	4.876036	67	Sudden braking	2.08	2.08	12.4	12.6	1.01	1	3.6	1.010	604F9_Trip704	1
18/05/2026 07:26:06	52.368195	4.876087	70	Sudden braking	2.48	2.48	10.6	10.1	1.01	1	2.9	1.008	604F9_Trip704	1
18/05/2026 07:26:07	52.368205	4.876127	68	Sudden braking	2.49	2.49	8.8	7.6	1.01	1	1.8	1.006	604F9_Trip704	1
18/05/2026 07:26:08	52.368209	4.876152	67	Sudden braking	2.53	2.53	6.5	5.1	0.99	1	0.7	0.988	604F9_Trip704	1
18/05/2026 07:26:09	52.368215	4.876156	67	Sudden braking	2.23	2.23	5.5	2.8	1.03	1	0.7	1.033	604F9_Trip704	1
18/05/2026 07:31:47	52.367143	4.893359	99	Sudden braking	2.03	2.03	10.0	10.3	0.99	3	2.9	0.987	604F9_Trip704	1
18/05/2026 07:31:48	52.367139	4.893402	107	Sudden braking	2.00	2.00	9.3	8.3	1.00	2	1.8	0.998	604F9_Trip704	1
18/05/2026 07:32:26	52.366991	4.895676	90	Sudden braking	2.14	2.14	10.2	9.4	0.98	2	2.6	0.980	604F9_Trip704	1
18/05/2026 07:34:29	52.370849	4.898884	39	Sudden braking	2.10	2.10	11.8	11.9	1.00	3	3.4	1.002	604F9_Trip704	1
18/05/2026 07:34:30	52.370872	4.898917	42	Sudden braking	2.62	2.62	10.2	9.3	0.99	3	2.8	0.994	604F9_Trip704	1
18/05/2026 07:34:31	52.370893	4.898942	49	Sudden braking	2.00	2.00	10.1	7.3	1.00	3	1.7	1.002	604F9_Trip704	1
18/05/2026 07:38:51	52.371742	4.910192	126	Sudden braking	2.34	2.34	14.4	14.6	1.02	3	4.0	1.025	604F9_Trip704	1
18/05/2026 07:38:52	52.371722	4.910241	124	Sudden braking	3.03	3.03	11.8	11.6	0.99	3	3.1	0.991	604F9_Trip704	1
18/05/2026 07:38:53	52.371707	4.910280	124	Sudden braking	3.11	3.11	10.6	8.5	1.00	3	2.7	0.998	604F9_Trip704	1
18/05/2026 07:38:54	52.371695	4.910315	125	Sudden braking	2.58	2.58	8.6	5.9	1.01	2	1.0	1.008	604F9_Trip704	1
18/05/2026 07:41:52	52.367758	4.925158	119	Sudden braking	2.37	2.37	16.9	19.1	1.01	2	5.5	1.014	604F9_Trip704	1
18/05/2026 07:41:53	52.367738	4.925232	117	Sudden braking	2.86	2.86	14.7	16.3	0.98	2	4.9	0.978	604F9_Trip704	1
18/05/2026 07:41:54	52.367718	4.925296	122	Sudden braking	2.57	2.57	14.7	13.7	1.01	2	4.0	1.013	604F9_Trip704	1
18/05/2026 07:41:55	52.367702	4.925348	121	Sudden braking	2.74	2.74	11.3	11.0	0.98	2	3.2	0.984	604F9_Trip704	1
18/05/2026 07:41:56	52.367690	4.925391	121	Sudden braking	2.77	2.77	9.4	8.2	1.01	2	2.5	1.011	604F9_Trip704	1
18/05/2026 07:41:57	52.367674	4.925417	136	Sudden braking	2.32	2.32	8.2	5.9	0.99	2	1.6	0.993	604F9_Trip704	1
18/05/2026 07:42:26	52.367108	4.924936	217	Sudden braking	2.21	2.21	6.6	6.7	0.99	1	1.8	0.994	604F9_Trip704	1
18/05/2026 07:42:27	52.367093	4.924925	210	Sudden braking	2.18	2.18	6.0	4.5	1.01	1	0.5	1.008	604F9_Trip704	1
18/05/2026 07:42:28	52.367089	4.924925	204	Sudden braking	2.03	2.03	4.7	2.5	0.99	1	1.0	0.986	604F9_Trip704	1
18/05/2026 07:44:22	52.365980	4.926571	172	Sudden braking	2.29	2.29	9.8	9.7	0.96	1	2.8	0.961	604F9_Trip704	1
18/05/2026 07:44:23	52.365956	4.926574	191	Sudden braking	2.01	2.01	9.0	7.6	1.04	1	1.7	1.044	604F9_Trip704	1
18/05/2026 07:44:24	52.365941	4.926567	206	Sudden braking	2.06	2.06	6.5	5.6	0.97	1	1.2	0.970	604F9_Trip704	1
18/05/2026 07:46:33	52.362823	4.932158	92	Sudden braking	2.22	2.22	18.5	17.9	0.99	3	6.3	0.992	604F9_Trip704	1
18/05/2026 07:46:34	52.362826	4.932251	90	Sudden braking	2.11	2.11	18.2	15.8	0.98	3	5.7	0.982	604F9_Trip704	1
18/05/2026 16:35:14	52.360598	4.904610	164	Sudden braking	2.10	2.10	16.1	15.3	1.00	2	3.4	1.000	604F0_Trip736	1
18/05/2026 16:35:15	52.360573	4.904638	158	Sudden braking	2.10	2.10	15.5	13.2	1.00	2	2.8	1.000	604F0_Trip736	1
18/05/2026 16:36:10	52.359716	4.899577	259	Sudden braking	2.00	2.00	17.4	17.5	1.00	2	4.0	1.000	604F0_Trip736	1
18/05/2026 16:36:11	52.359706	4.899519	258	Sudden braking	2.20	2.20	16.3	15.3	1.00	2	3.4	1.000	604F0_Trip736	1
18/05/2026 16:36:12	52.359699	4.899470	258	Sudden braking	2.10	2.10	15.4	13.2	1.00	2	2.8	1.000	604F0_Trip736	1
18/05/2026 16:37:42	52.359700	4.891534	271	Sudden braking	2.10	2.10	11.8	10.4	1.00	2	2.4	1.000	604F0_Trip736	1
18/05/2026 16:37:43	52.359692	4.891501	267	Sudden braking	2.40	2.40	10.9	8.0	1.00	2	2.4	1.000	604F0_Trip736	1
18/05/2026 16:40:38	52.362594	4.883942	307	Sudden braking	2.00	2.00	18.5	19.7	1.00	2	4.7	1.000	604F0_Trip736	1
18/05/2026 16:40:39	52.362628	4.883902	313	Sudden braking	2.20	2.20	16.6	17.5	1.00	2	3.9	1.000	604F0_Trip736	1
18/05/2026 16:40:40	52.362656	4.883866	315	Sudden braking	2.30	2.30	15.8	15.2	1.00	2	2.9	1.000	604F0_Trip736	1
18/05/2026 16:40:41	52.362671	4.883832	308	Sudden braking	2.60	2.60	13.8	12.6	1.00	2	3.6	1.000	604F0_Trip736	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
18/05/2026 16:40:42	52.362699	4.883804	318	Sudden braking	2.80	2.80	12.8	9.8	1.00	2	2.1	1.000	604F0_Trip736	1
18/05/2026 16:40:43	52.362711	4.883780	318	Sudden braking	2.40	2.40	11.0	7.4	1.00	2	1.1	1.000	604F0_Trip736	1
18/05/2026 16:41:12	52.362033	4.882125	226	Sudden braking	2.00	2.00	15.7	16.2	1.00	2	3.7	0.999	604F0_Trip736	1
18/05/2026 16:41:12	52.362009	4.882087	228	Sudden braking	2.00	2.00	14.2	14.2	1.00	2	3.6	1.000	604F0_Trip736	1
18/05/2026 16:48:38	52.355702	4.844587	268	Sudden braking	2.00	2.00	19.8	19.7	1.00	2	4.7	1.000	604F0_Trip736	1
18/05/2026 16:48:39	52.355702	4.844517	269	Sudden braking	2.20	2.20	19.1	17.5	1.00	2	3.9	1.000	604F0_Trip736	1
18/05/2026 16:48:40	52.355713	4.844464	280	Sudden braking	2.00	2.00	18.5	15.5	1.00	2	4.0	1.000	604F0_Trip736	1
18/05/2026 16:54:45	52.354347	4.810820	252	Sudden braking	2.00	2.00	17.6	17.0	1.00	2	4.0	1.000	604F0_Trip736	1
18/05/2026 16:56:06	52.354776	4.806284	253	Sudden braking	2.40	2.40	10.9	9.1	1.00	2	1.9	1.000	604F0_Trip736	1
18/05/2026 16:56:16	52.354774	4.806221	221	Sudden braking	2.00	2.00	2.5	2.4	1.00	2	2.3	1.000	604F0_Trip736	1
19/05/2026 05:06:57	52.536437	4.694505	79	Sudden braking	2.40	2.40	34.0	35.1	1.00	3	9.4	1.000	63C0A_Trip742	1
19/05/2026 05:06:58	52.536423	4.694642	89	Sudden braking	2.70	2.70	32.9	32.4	1.00	3	7.5	1.000	63C0A_Trip742	1
19/05/2026 05:06:59	52.536418	4.694752	104	Sudden braking	2.60	2.60	31.9	29.8	1.00	3	7.7	1.000	63C0A_Trip742	1
19/05/2026 05:07:00	52.536368	4.694832	127	Sudden braking	2.00	2.00	31.0	27.8	1.00	3	8.8	1.000	63C0A_Trip742	1
19/05/2026 05:09:38	52.522483	4.702466	131	Sudden braking	2.30	2.30	32.4	33.2	1.00	3	9.6	1.000	63C0A_Trip742	1
19/05/2026 05:09:39	52.522418	4.702557	132	Sudden braking	2.50	2.50	31.0	30.7	1.00	3	7.9	1.000	63C0A_Trip742	1
19/05/2026 05:09:40	52.522380	4.702656	132	Sudden braking	2.50	2.50	29.6	28.2	1.00	3	6.7	1.000	63C0A_Trip742	1
19/05/2026 05:09:41	52.522340	4.702730	133	Sudden braking	2.20	2.20	28.1	26.0	1.00	4	4.0	1.000	63C0A_Trip742	1
19/05/2026 05:10:29	52.519872	4.706283	138	Sudden braking	2.30	2.30	33.0	33.6	1.00	3	8.8	1.000	63C0A_Trip742	1
19/05/2026 05:10:30	52.519811	4.706367	140	Sudden braking	2.50	2.50	31.7	31.1	1.00	3	7.7	1.000	63C0A_Trip742	1
19/05/2026 05:10:31	52.519756	4.706437	143	Sudden braking	2.40	2.40	30.6	28.7	1.00	3	6.2	1.000	63C0A_Trip742	1
19/05/2026 05:18:21	52.493824	4.768295	93	Sudden braking	2.40	2.40	31.8	30.8	1.00	3	8.3	1.000	63C0A_Trip742	1
19/05/2026 05:21:04	52.489487	4.792631	109	Sudden braking	2.00	2.00	32.4	33.8	1.00	3	9.3	1.000	63C0A_Trip742	1
19/05/2026 05:21:05	52.489460	4.792760	109	Sudden braking	2.40	2.40	31.2	31.4	1.00	3	8.0	1.000	63C0A_Trip742	1
19/05/2026 05:21:06	52.489437	4.792872	109	Sudden braking	2.40	2.40	29.9	29.0	1.00	3	8.3	1.000	63C0A_Trip742	1
19/05/2026 05:21:07	52.489381	4.792953	111	Sudden braking	2.10	2.10	28.6	26.9	1.00	3	6.9	1.000	63C0A_Trip742	1
19/05/2026 05:31:39	52.433869	4.815812	176	Sudden braking	2.40	2.40	29.7	29.5	1.00	3	8.3	1.000	63C0A_Trip742	1
19/05/2026 05:31:40	52.433795	4.815825	173	Sudden braking	2.70	2.70	29.1	26.8	1.00	3	4.8	1.000	63C0A_Trip742	1
19/05/2026 05:31:56	52.434191	4.817632	40	Sudden braking	2.10	2.10	31.0	30.1	1.00	2	7.8	1.000	63C0A_Trip742	1
19/05/2026 06:05:32	52.390947	4.883232	102	Sudden braking	2.00	2.00	27.8	29.5	1.00	3	7.9	1.000	63C0A_Trip742	1
19/05/2026 06:05:33	52.390937	4.883347	102	Sudden braking	2.50	2.50	25.7	27.0	1.00	3	6.8	1.000	63C0A_Trip742	1
19/05/2026 06:05:34	52.390920	4.883443	102	Sudden braking	2.90	2.90	23.6	24.1	1.00	3	6.1	1.000	63C0A_Trip742	1
19/05/2026 06:05:35	52.390907	4.883531	102	Sudden braking	3.00	3.00	21.4	21.1	1.00	3	4.9	1.000	63C0A_Trip742	1
19/05/2026 06:05:36	52.390899	4.883603	102	Sudden braking	2.90	2.90	19.2	18.2	1.00	3	4.2	1.000	63C0A_Trip742	1
19/05/2026 06:05:37	52.390894	4.883665	99	Sudden braking	2.70	2.70	17.0	15.5	1.00	3	3.6	1.000	63C0A_Trip742	1
19/05/2026 06:05:38	52.390895	4.883718	96	Sudden braking	2.20	2.20	14.9	13.3	1.00	3	3.2	1.000	63C0A_Trip742	1
19/05/2026 06:08:46	52.382617	4.894756	134	Sudden braking	2.50	2.50	26.8	30.4	1.00	2	8.0	1.000	63C0A_Trip742	1
19/05/2026 06:08:47	52.382562	4.894831	140	Sudden braking	3.70	3.70	24.2	26.7	1.00	2	7.6	1.000	63C0A_Trip742	1
19/05/2026 06:08:48	52.382509	4.894902	140	Sudden braking	4.20	4.20	21.5	22.5	1.00	2	5.7	1.000	63C0A_Trip742	1
19/05/2026 06:08:49	52.382469	4.894954	142	Sudden braking	4.40	4.40	18.9	18.1	1.00	3	3.3	1.000	63C0A_Trip742	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
19/05/2026 06:08:50	52.382445	4.894981	142	Sudden braking	4.80	4.80	16.5	13.3	1.00	3	3.0	1.000	63C0A_Trip742	1
19/05/2026 06:08:51	52.382423	4.895008	142	Sudden braking	4.20	4.20	14.3	9.1	1.00	3	2.1	1.000	63C0A_Trip742	1
19/05/2026 06:08:52	52.382408	4.895025	142	Sudden braking	2.20	2.20	12.5	6.9	1.00	2	1.1	1.000	63C0A_Trip742	1
19/05/2026 06:11:32	52.377874	4.909737	104	Sudden braking	2.60	2.60	29.6	30.1	1.00	2	8.3	1.000	63C0A_Trip742	1
19/05/2026 06:11:33	52.377852	4.909853	110	Sudden braking	3.00	3.00	28.3	27.1	1.00	2	7.1	1.000	63C0A_Trip742	1
19/05/2026 06:11:34	52.377814	4.909937	125	Sudden braking	2.60	2.60	27.4	24.5	1.00	3	5.3	1.000	63C0A_Trip742	1
19/05/2026 06:11:47	52.376894	4.910020	161	Sudden braking	3.00	3.00	28.1	28.3	1.00	4	6.0	1.000	63C0A_Trip742	1
19/05/2026 06:11:48	52.376842	4.910047	158	Sudden braking	2.70	2.70	27.5	25.6	1.00	3	2.8	1.000	63C0A_Trip742	1
19/05/2026 06:11:49	52.376818	4.910063	158	Sudden braking	2.20	2.20	26.9	23.4	1.00	4	5.9	1.000	63C0A_Trip742	1
19/05/2026 06:12:03	52.375903	4.910555	180	Sudden braking	3.30	3.30	19.0	18.5	1.00	3	5.3	1.000	63C0A_Trip742	1
19/05/2026 06:12:04	52.375859	4.910528	185	Sudden braking	3.90	3.90	17.5	14.6	1.00	4	4.0	1.000	63C0A_Trip742	1
19/05/2026 06:13:30	52.374791	4.915126	161	Sudden braking	2.40	2.40	15.8	14.7	1.00	2	2.5	1.000	63C0A_Trip742	1
19/05/2026 06:13:31	52.374771	4.915145	155	Sudden braking	2.20	2.20	14.5	12.5	1.00	2	3.0	1.000	63C0A_Trip742	1
19/05/2026 06:54:32	52.310098	4.881581	359	Sudden braking	2.13	2.13	11.2	8.9	1.03	2	2.9	1.034	602CA_Trip743	1
19/05/2026 07:10:24	52.339362	4.908962	57	Sudden braking	2.13	2.13	12.5	10.7	0.99	3	4.5	0.988	602CA_Trip743	1
19/05/2026 07:18:14	52.355836	4.905241	343	Sudden braking	2.42	2.42	10.1	12.3	0.99	1	4.5	0.991	602CA_Trip743	1
19/05/2026 07:18:15	52.355877	4.905247	341	Sudden braking	3.05	3.05	9.5	9.3	0.98	2	4.0	0.983	602CA_Trip743	1
19/05/2026 07:18:16	52.355913	4.905252	342	Sudden braking	2.84	2.84	8.4	6.4	1.02	2	2.0	1.022	602CA_Trip743	1
19/05/2026 07:18:17	52.355930	4.905247	342	Sudden braking	2.63	2.63	6.7	3.8	0.99	2	0.9	0.990	602CA_Trip743	1
19/05/2026 07:20:29	52.360247	4.908802	339	Sudden braking	2.21	2.21	13.3	12.6	0.99	2	2.9	0.994	602CA_Trip743	1
19/05/2026 07:22:07	52.364943	4.905960	342	Sudden braking	3.07	3.07	11.5	14.4	0.98	1	4.8	0.977	602CA_Trip743	1
19/05/2026 07:22:08	52.364982	4.905932	340	Sudden braking	3.66	3.66	11.5	10.7	1.01	2	3.4	1.010	602CA_Trip743	1
19/05/2026 07:22:09	52.365010	4.905915	350	Sudden braking	3.78	3.78	8.9	6.9	1.00	2	1.6	1.004	602CA_Trip743	1
19/05/2026 07:22:10	52.365025	4.905912	359	Sudden braking	3.18	3.18	6.4	3.7	1.01	2	0.6	1.006	602CA_Trip743	1
19/05/2026 07:22:11	52.365026	4.905921	7	Sudden braking	2.01	2.01	5.3	1.7	0.99	2	0.1	0.993	602CA_Trip743	1
19/05/2026 07:23:19	52.368025	4.904941	88	Sudden braking	2.06	2.06	14.9	15.7	1.02	2	6.4	1.019	602CA_Trip743	1
19/05/2026 07:23:20	52.368045	4.905030	87	Sudden braking	2.68	2.68	14.5	13.1	0.97	2	4.4	0.970	602CA_Trip743	1
19/05/2026 07:23:21	52.368069	4.905081	77	Sudden braking	2.09	2.09	14.1	11.0	1.00	2	3.0	1.003	602CA_Trip743	1
19/05/2026 07:24:31	52.370053	4.908364	63	Sudden braking	2.42	2.42	9.3	11.2	0.95	1	3.1	0.952	602CA_Trip743	1
19/05/2026 07:24:32	52.370063	4.908407	65	Sudden braking	2.70	2.70	9.3	8.5	1.00	1	2.6	1.000	602CA_Trip743	1
19/05/2026 07:24:33	52.370079	4.908435	70	Sudden braking	2.44	2.44	8.5	6.0	1.02	1	2.0	1.023	602CA_Trip743	1
19/05/2026 07:24:34	52.370088	4.908460	70	Sudden braking	2.34	2.34	6.5	3.7	0.98	1	0.8	0.982	602CA_Trip743	1
19/05/2026 07:26:19	52.371034	4.915010	67	Sudden braking	3.03	3.03	11.0	12.1	1.02	1	3.7	1.024	602CA_Trip743	1
19/05/2026 07:26:20	52.371032	4.915065	85	Sudden braking	3.60	3.60	10.1	8.6	0.97	1	2.5	0.973	602CA_Trip743	1
19/05/2026 07:26:21	52.371034	4.915102	77	Sudden braking	3.33	3.33	8.9	5.4	0.96	1	0.4	0.962	602CA_Trip743	1
19/05/2026 07:26:22	52.371035	4.915108	0	Sudden braking	2.66	2.66	8.9	2.7	1.01	1	0.3	1.014	602CA_Trip743	1
19/05/2026 07:27:21	52.372292	4.918247	54	Sudden braking	2.38	2.38	7.4	8.6	0.97	2	4.3	0.968	602CA_Trip743	1
19/05/2026 07:27:22	52.372324	4.918281	51	Sudden braking	2.16	2.16	6.8	6.4	1.02	2	2.7	1.020	602CA_Trip743	1
19/05/2026 07:27:23	52.372347	4.918291	48	Sudden braking	2.03	2.03	5.3	4.3	1.03	2	3.2	1.034	602CA_Trip743	1
19/05/2026 07:27:24	52.372371	4.918267	35	Sudden braking	2.10	2.10	3.9	2.3	0.95	2	3.2	0.951	602CA_Trip743	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
15/06/2026 07:44:36	52.356110	4.826957	89	Sudden braking	2.20	2.20	20.1	22.2	1.00	1	5.1	1.000	604F0_Trip982	1
15/06/2026 07:44:37	52.356113	4.827032	92	Sudden braking	2.60	2.60	19.4	19.6	1.00	1	3.8	1.000	604F0_Trip982	1
15/06/2026 07:44:38	52.356111	4.827088	98	Sudden braking	3.20	3.20	18.6	16.4	1.00	1	3.6	1.000	604F0_Trip982	1
15/06/2026 07:44:39	52.356097	4.827135	108	Sudden braking	3.50	3.50	17.6	12.9	1.00	1	2.7	1.000	604F0_Trip982	1
15/06/2026 07:44:40	52.356079	4.827163	122	Sudden braking	2.60	2.60	16.4	10.3	1.00	2	1.3	1.000	604F0_Trip982	1
15/06/2026 07:49:59	52.354752	4.854993	75	Sudden braking	2.10	2.10	17.6	17.7	1.00	3	4.6	1.000	604F0_Trip982	1
15/06/2026 07:50:00	52.354763	4.855058	75	Sudden braking	2.10	2.10	16.3	15.6	1.00	3	3.5	1.000	604F0_Trip982	1
15/06/2026 07:54:47	52.361593	4.881642	58	Sudden braking	2.10	2.10	14.0	13.3	1.00	2	2.7	1.000	604F0_Trip982	1
15/06/2026 07:54:48	52.361608	4.881675	56	Sudden braking	2.20	2.20	13.1	11.1	1.00	2	2.3	1.000	604F0_Trip982	1
15/06/2026 07:54:49	52.361625	4.881692	50	Sudden braking	2.20	2.20	12.2	8.9	1.00	2	2.1	1.000	604F0_Trip982	1
15/06/2026 07:57:06	52.359547	4.890365	119	Sudden braking	2.10	2.10	12.0	10.6	1.00	2	2.3	1.000	604F0_Trip982	1
15/06/2026 07:57:07	52.359543	4.890397	109	Sudden braking	2.60	2.60	11.2	8.0	1.00	2	1.8	1.000	604F0_Trip982	1
15/06/2026 08:04:01	52.366135	4.911578	30	Sudden braking	2.30	2.30	17.2	19.7	1.00	2	7.2	1.000	604F0_Trip982	1
15/06/2026 08:04:02	52.366200	4.911582	30	Sudden braking	2.90	2.90	15.2	16.8	1.00	2	1.8	1.000	604F0_Trip982	1
15/06/2026 08:04:03	52.366204	4.911609	30	Sudden braking	3.00	3.00	14.2	13.8	1.00	2	2.4	1.000	604F0_Trip982	1
15/06/2026 08:04:04	52.366218	4.911636	30	Sudden braking	2.90	2.90	12.2	10.9	1.00	2	1.9	1.000	604F0_Trip982	1
15/06/2026 08:04:05	52.366229	4.911658	30	Sudden braking	2.40	2.40	12.2	8.5	1.00	2	1.3	1.000	604F0_Trip982	1
15/06/2026 08:05:49	52.369468	4.912275	309	Sudden braking	2.00	2.00	14.6	14.5	1.00	3	3.8	1.000	604F0_Trip982	1
15/06/2026 08:05:50	52.369502	4.912270	334	Sudden braking	2.40	2.40	13.7	12.1	1.00	3	3.5	1.000	604F0_Trip982	1
15/06/2026 08:05:51	52.369525	4.912304	11	Sudden braking	2.40	2.40	13.0	9.7	1.00	3	2.6	1.000	604F0_Trip982	1
15/06/2026 08:06:48	52.370960	4.914852	54	Sudden braking	2.00	2.00	19.2	20.9	1.00	2	5.3	1.000	604F0_Trip982	1
15/06/2026 08:06:49	52.370987	4.914916	55	Sudden braking	2.30	2.30	17.5	18.6	1.00	2	3.9	1.000	604F0_Trip982	1
15/06/2026 08:06:50	52.371003	4.914969	60	Sudden braking	2.50	2.50	16.6	16.1	1.00	2	3.5	1.000	604F0_Trip982	1
15/06/2026 08:06:51	52.371007	4.915020	71	Sudden braking	2.60	2.60	15.7	13.5	1.00	2	3.1	1.000	604F0_Trip982	1
15/06/2026 08:06:52	52.371007	4.915065	81	Sudden braking	2.90	2.90	14.6	10.6	1.00	2	2.4	1.000	604F0_Trip982	1
15/06/2026 08:06:53	52.371009	4.915100	84	Sudden braking	2.60	2.60	13.4	8.0	1.00	2	1.8	1.000	604F0_Trip982	1
17/06/2026 06:54:14	52.356125	4.826869	90	Sudden braking	2.40	2.40	17.2	18.2	1.00	2	4.2	1.000	604F0_Trip1004	1
17/06/2026 06:54:15	52.356128	4.826930	90	Sudden braking	2.90	2.90	15.6	15.3	1.00	2	3.2	1.000	604F0_Trip1004	1
17/06/2026 06:54:16	52.356130	4.826977	90	Sudden braking	2.80	2.80	14.7	12.5	1.00	2	2.2	1.000	604F0_Trip1004	1
17/06/2026 06:54:17	52.356126	4.827008	97	Sudden braking	2.30	2.30	13.3	10.2	1.00	2	1.7	1.000	604F0_Trip1004	1
17/06/2026 06:58:20	52.355722	4.847597	92	Sudden braking	2.10	2.10	18.9	18.3	1.00	2	3.9	1.000	604F0_Trip1004	1
17/06/2026 06:58:21	52.355722	4.847655	91	Sudden braking	2.00	2.00	18.3	16.3	1.00	2	3.7	1.000	604F0_Trip1004	1
17/06/2026 06:59:08	52.354951	4.850108	89	Sudden braking	2.30	2.30	11.9	9.2	1.00	2	2.0	1.000	604F0_Trip1004	1
17/06/2026 06:59:09	52.354951	4.850137	89	Sudden braking	2.70	2.70	10.0	6.5	1.00	2	1.7	1.000	604F0_Trip1004	1
17/06/2026 07:05:28	52.361605	4.881669	57	Sudden braking	2.00	2.00	14.6	14.5	1.00	2	3.6	1.000	604F0_Trip1004	1
17/06/2026 07:05:29	52.361628	4.881708	52	Sudden braking	2.30	2.30	13.9	12.2	1.00	2	2.7	1.000	604F0_Trip1004	1
17/06/2026 07:05:30	52.361643	4.881738	51	Sudden braking	2.60	2.60	13.1	9.6	1.00	2	1.7	1.000	604F0_Trip1004	1
17/06/2026 07:05:31	52.361653	4.881757	49	Sudden braking	2.00	2.00	12.1	7.6	1.00	2	1.1	1.000	604F0_Trip1004	1
17/06/2026 07:08:23	52.359598	4.890169	117	Sudden braking	2.10	2.10	17.0	17.7	1.00	2	4.1	1.000	604F0_Trip1004	1
17/06/2026 07:08:24	52.359581	4.890221	119	Sudden braking	2.40	2.40	15.7	15.3	1.00	2	3.2	1.000	604F0_Trip1004	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
17/06/2026 07:08:25	52.359561	4.890255	127	Sudden braking	2.30	2.30	14.4	13.0	1.00	2	3.1	1.000	604F0_Trip1004	1
17/06/2026 07:12:08	52.360970	4.907588	75	Sudden braking	2.00	2.00	10.1	9.1	1.00	2	2.1	1.000	604F0_Trip1004	1
17/06/2026 07:12:09	52.360980	4.907614	74	Sudden braking	2.20	2.20	9.5	6.9	1.00	2	1.6	1.000	604F0_Trip1004	1
17/06/2026 07:17:30	52.370998	4.914904	56	Sudden braking	2.10	2.10	13.7	13.9	1.00	2	3.1	1.000	604F0_Trip1004	1
17/06/2026 07:17:31	52.371013	4.914943	58	Sudden braking	2.20	2.20	12.5	11.7	1.00	2	2.4	1.000	604F0_Trip1004	1
17/06/2026 07:17:32	52.371018	4.914977	67	Sudden braking	2.00	2.00	11.5	9.7	1.00	2	1.9	1.000	604F0_Trip1004	1
17/06/2026 07:18:25	52.372364	4.918168	14	Sudden braking	2.70	2.70	10.5	7.7	1.00	2	2.8	1.000	604F0_Trip1004	1
17/06/2026 07:18:26	52.372390	4.918167	6	Sudden braking	2.30	2.30	9.8	5.4	1.00	2	1.4	1.000	604F0_Trip1004	1
22/06/2026 15:59:49	52.366780	4.911961	210	Sudden braking	2.00	2.00	18.9	20.3	1.00	2	5.0	1.000	604F0_Trip1042	1
22/06/2026 15:59:50	52.366744	4.911918	212	Sudden braking	2.60	2.60	18.3	17.7	1.00	2	4.5	1.000	604F0_Trip1042	1
22/06/2026 15:59:51	52.366708	4.911887	212	Sudden braking	3.60	3.60	17.6	14.1	1.00	2	3.3	1.000	604F0_Trip1042	1
22/06/2026 15:59:52	52.366685	4.911858	214	Sudden braking	3.90	3.90	15.2	10.2	1.00	2	1.8	1.000	604F0_Trip1042	1
22/06/2026 16:02:07	52.361402	4.908509	252	Sudden braking	2.10	2.10	19.4	20.2	1.00	2	5.1	1.000	604F0_Trip1042	1
22/06/2026 16:02:08	52.361389	4.908437	252	Sudden braking	2.80	2.80	18.8	17.4	1.00	2	4.0	1.000	604F0_Trip1042	1
22/06/2026 16:02:09	52.361383	4.908380	255	Sudden braking	2.90	2.90	18.0	14.5	1.00	2	2.8	1.000	604F0_Trip1042	1
22/06/2026 16:02:10	52.361379	4.908340	257	Sudden braking	2.60	2.60	17.1	11.9	1.00	2	1.6	1.000	604F0_Trip1042	1
22/06/2026 16:04:18	52.359735	4.899630	257	Sudden braking	2.00	2.00	16.1	16.0	1.00	2	3.9	1.000	604F0_Trip1042	1
22/06/2026 16:06:08	52.359705	4.891525	276	Sudden braking	2.20	2.20	14.0	13.2	1.00	2	2.5	1.000	604F0_Trip1042	1
22/06/2026 16:06:09	52.359709	4.891489	277	Sudden braking	3.00	3.00	13.2	10.2	1.00	2	1.7	1.000	604F0_Trip1042	1
22/06/2026 16:06:10	52.359711	4.891464	273	Sudden braking	3.30	3.30	12.3	6.9	1.00	2	1.4	1.000	604F0_Trip1042	1
22/06/2026 16:08:03	52.361219	4.886943	306	Sudden braking	2.00	2.00	18.7	18.0	1.00	2	4.9	1.000	604F0_Trip1042	1
22/06/2026 16:08:47	52.362664	4.883899	309	Sudden braking	2.00	2.00	12.4	12.3	1.00	2	2.5	1.000	604F0_Trip1042	1
22/06/2026 16:08:48	52.362677	4.883870	306	Sudden braking	2.20	2.20	11.1	10.1	1.00	2	2.0	1.000	604F0_Trip1042	1
22/06/2026 16:14:30	52.355021	4.856155	253	Sudden braking	2.00	2.00	19.0	21.2	1.00	2	5.2	1.000	604F0_Trip1042	1
22/06/2026 16:14:31	52.355008	4.856082	253	Sudden braking	2.60	2.60	17.9	18.6	1.00	2	3.7	1.000	604F0_Trip1042	1
22/06/2026 16:14:32	52.354998	4.856030	253	Sudden braking	2.70	2.70	16.7	15.9	1.00	2	2.9	1.000	604F0_Trip1042	1
22/06/2026 16:14:33	52.354989	4.855989	252	Sudden braking	2.40	2.40	15.3	13.5	1.00	2	2.9	1.000	604F0_Trip1042	1
22/06/2026 16:17:28	52.355719	4.844553	270	Sudden braking	2.10	2.10	18.9	17.5	1.00	2	4.1	1.000	604F0_Trip1042	1
22/06/2026 16:20:33	52.356333	4.827597	265	Sudden braking	2.20	2.20	14.9	16.4	1.00	2	3.7	1.000	604F0_Trip1042	1
22/06/2026 16:20:34	52.356352	4.827552	281	Sudden braking	2.70	2.70	14.0	13.7	1.00	2	3.3	1.000	604F0_Trip1042	1
22/06/2026 16:20:35	52.356375	4.827522	302	Sudden braking	3.20	3.20	13.0	10.5	1.00	2	2.2	1.000	604F0_Trip1042	1
22/06/2026 16:20:36	52.356391	4.827502	316	Sudden braking	3.20	3.20	11.9	7.3	1.00	2	1.2	1.000	604F0_Trip1042	1
22/06/2026 16:20:37	52.356385	4.827487	301	Sudden braking	2.30	2.30	10.7	5.0	1.00	2	1.6	1.000	604F0_Trip1042	1
22/06/2026 16:24:09	52.354362	4.810777	257	Sudden braking	2.50	2.50	18.6	19.2	1.00	2	4.5	1.000	604F0_Trip1042	1
22/06/2026 16:24:10	52.354357	4.810711	261	Sudden braking	2.90	2.90	17.8	16.3	1.00	2	3.5	1.000	604F0_Trip1042	1
22/06/2026 16:24:11	52.354364	4.810661	272	Sudden braking	3.60	3.60	16.8	12.7	1.00	2	2.6	1.000	604F0_Trip1042	1
22/06/2026 16:24:12	52.354377	4.810630	286	Sudden braking	3.50	3.50	15.7	9.2	1.00	2	1.8	1.000	604F0_Trip1042	1
22/06/2026 16:25:12	52.353722	4.807406	248	Sudden braking	2.00	2.00	16.8	16.7	1.00	3	4.0	1.000	604F0_Trip1042	1
22/06/2026 16:25:13	52.353705	4.807354	247	Sudden braking	2.20	2.20	16.2	14.5	1.00	2	3.3	1.000	604F0_Trip1042	1
23/06/2026 07:19:32	52.356096	4.827065	103	Sudden braking	2.60	2.60	12.6	10.0	1.00	2	2.5	1.000	604F0_Trip1046	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
23/06/2026 07:19:33	52.356091	4.827100	104	Sudden braking	2.70	2.70	11.8	7.3	1.00	2	1.3	1.000	604F0_Trip1046	1
23/06/2026 07:25:13	52.354677	4.855236	94	Sudden braking	2.00	2.00	15.2	16.3	1.00	3	3.4	1.000	604F0_Trip1046	1
23/06/2026 07:25:14	52.354669	4.855284	99	Sudden braking	2.10	2.10	13.2	14.2	1.00	3	1.9	1.000	604F0_Trip1046	1
23/06/2026 07:25:15	52.354678	4.855309	91	Sudden braking	2.70	2.70	11.1	11.5	1.00	3	4.1	1.000	604F0_Trip1046	1
23/06/2026 07:25:16	52.354683	4.855369	87	Sudden braking	3.00	3.00	10.1	8.5	1.00	2	2.9	1.000	604F0_Trip1046	1
23/06/2026 07:25:17	52.354696	4.855405	84	Sudden braking	2.60	2.60	8.2	5.9	1.00	3	1.1	1.000	604F0_Trip1046	1
23/06/2026 07:25:18	52.354702	4.855392	90	Sudden braking	2.20	2.20	7.0	3.7	1.00	3	2.0	1.000	604F0_Trip1046	1
23/06/2026 07:25:19	52.354719	4.855381	90	Sudden braking	2.00	2.00	5.4	1.7	1.00	3	1.1	1.000	604F0_Trip1046	1
23/06/2026 07:30:18	52.361614	4.881633	54	Sudden braking	2.40	2.40	14.4	11.8	1.00	1	2.8	1.000	604F0_Trip1046	1
23/06/2026 07:30:19	52.361629	4.881666	51	Sudden braking	2.60	2.60	13.6	9.2	1.00	1	1.8	1.000	604F0_Trip1046	1
23/06/2026 07:37:42	52.366143	4.911551	28	Sudden braking	2.10	2.10	13.5	13.1	1.00	3	3.1	1.000	604F0_Trip1046	1
23/06/2026 07:37:43	52.366170	4.911564	24	Sudden braking	2.30	2.30	12.6	10.8	1.00	3	2.3	1.000	604F0_Trip1046	1
23/06/2026 07:39:07	52.369464	4.912326	299	Sudden braking	2.00	2.00	17.9	17.5	1.00	3	4.4	1.000	604F0_Trip1046	1
23/06/2026 07:39:08	52.369497	4.912292	299	Sudden braking	2.00	2.00	17.1	15.5	1.00	3	4.2	1.000	604F0_Trip1046	1
23/06/2026 07:39:26	52.370106	4.911964	319	Sudden braking	2.00	2.00	18.0	16.4	1.00	3	4.2	1.000	604F0_Trip1046	1
23/06/2026 07:40:57	52.372282	4.918166	41	Sudden braking	2.40	2.40	14.3	14.6	1.00	3	4.0	1.000	604F0_Trip1046	1
23/06/2026 07:40:58	52.372305	4.918211	41	Sudden braking	2.80	2.80	13.1	11.8	1.00	3	2.6	1.000	604F0_Trip1046	1
23/06/2026 07:40:59	52.372327	4.918226	27	Sudden braking	2.30	2.30	12.1	9.5	1.00	2	1.1	1.000	604F0_Trip1046	1
04/08/2026 06:56:28	52.353825	4.808945	72	Sudden braking	2.00	2.00	15.6	16.5	1.00	1	3.8	1.000	604F0_Trip1461	1
04/08/2026 06:56:29	52.353836	4.808998	72	Sudden braking	2.10	2.10	14.4	14.4	1.00	1	3.0	1.000	604F0_Trip1461	1
04/08/2026 07:04:18	52.354959	4.850044	89	Sudden braking	2.00	2.00	17.7	17.0	1.00	3	4.0	1.000	604F0_Trip1461	1
04/08/2026 07:04:19	52.354958	4.850103	89	Sudden braking	2.00	2.00	17.6	15.0	1.00	3	3.0	1.000	604F0_Trip1461	1
04/08/2026 07:10:06	52.361554	4.881439	59	Sudden braking	2.00	2.00	18.4	20.0	1.00	3	5.4	1.000	604F0_Trip1461	1
04/08/2026 07:10:07	52.361579	4.881508	56	Sudden braking	2.60	2.60	16.7	17.4	1.00	3	4.9	1.000	604F0_Trip1461	1
04/08/2026 07:10:08	52.361603	4.881569	58	Sudden braking	2.80	2.80	15.9	14.6	1.00	3	3.7	1.000	604F0_Trip1461	1
04/08/2026 07:10:09	52.361623	4.881612	55	Sudden braking	2.60	2.60	14.1	12.0	1.00	2	2.8	1.000	604F0_Trip1461	1
04/08/2026 07:10:10	52.361638	4.881645	54	Sudden braking	2.20	2.20	12.5	9.8	1.00	2	2.1	1.000	604F0_Trip1461	1
04/08/2026 07:12:10	52.359628	4.890215	112	Sudden braking	2.20	2.20	18.0	19.0	1.00	2	4.7	1.000	604F0_Trip1461	1
04/08/2026 07:12:11	52.359611	4.890279	113	Sudden braking	2.40	2.40	16.1	16.6	1.00	2	4.3	1.000	604F0_Trip1461	1
04/08/2026 07:12:12	52.359589	4.890331	121	Sudden braking	2.40	2.40	15.2	14.2	1.00	3	3.5	1.000	604F0_Trip1461	1
04/08/2026 07:12:13	52.359568	4.890370	124	Sudden braking	2.40	2.40	14.2	11.8	1.00	3	3.2	1.000	604F0_Trip1461	1
04/08/2026 07:12:14	52.359557	4.890413	115	Sudden braking	2.60	2.60	13.1	9.2	1.00	3	2.1	1.000	604F0_Trip1461	1
04/08/2026 07:12:15	52.359556	4.890444	105	Sudden braking	2.30	2.30	11.9	6.9	1.00	3	1.5	1.000	604F0_Trip1461	1
04/08/2026 07:15:27	52.361008	4.907590	71	Sudden braking	2.30	2.30	17.5	18.9	1.00	2	5.2	1.000	604F0_Trip1461	1
04/08/2026 07:15:28	52.361021	4.907664	71	Sudden braking	2.60	2.60	15.7	16.3	1.00	2	3.3	1.000	604F0_Trip1461	1
04/08/2026 07:15:29	52.361030	4.907710	72	Sudden braking	2.70	2.70	13.8	13.6	1.00	2	2.9	1.000	604F0_Trip1461	1
04/08/2026 07:15:30	52.361035	4.907752	77	Sudden braking	2.80	2.80	12.0	10.8	1.00	2	2.6	1.000	604F0_Trip1461	1
04/08/2026 07:15:31	52.361038	4.907791	79	Sudden braking	2.30	2.30	10.3	8.5	1.00	2	2.1	1.000	604F0_Trip1461	1
04/08/2026 07:18:07	52.366066	4.911485	30	Sudden braking	2.20	2.20	19.8	21.7	1.00	2	5.3	1.000	604F0_Trip1461	1
04/08/2026 07:18:08	52.366105	4.911530	30	Sudden braking	3.00	3.00	17.7	18.7	1.00	2	4.7	1.000	604F0_Trip1461	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
04/08/2026 07:18:09	52.366145	4.911556	30	Sudden braking	3.00	3.00	15.5	15.7	1.00	2	3.3	1.000	604F0_Trip1461	1
04/08/2026 07:18:10	52.366166	4.911590	30	Sudden braking	2.80	2.80	14.4	12.9	1.00	2	1.6	1.000	604F0_Trip1461	1
04/08/2026 07:18:11	52.366180	4.911598	30	Sudden braking	3.00	3.00	13.2	9.9	1.00	2	3.7	1.000	604F0_Trip1461	1
04/08/2026 07:18:12	52.366200	4.911641	30	Sudden braking	2.90	2.90	11.8	7.0	1.00	2	1.1	1.000	604F0_Trip1461	1
04/08/2026 07:18:13	52.366203	4.911656	30	Sudden braking	2.00	2.00	9.5	5.0	1.00	2	1.0	1.000	604F0_Trip1461	1
09/08/2026 08:49:23	52.353864	4.809135	72	Sudden braking	2.00	2.00	15.5	15.5	1.00	3	3.4	1.000	604F0_Trip1464	1
09/08/2026 08:49:24	52.353873	4.809183	72	Sudden braking	2.20	2.20	14.5	13.3	1.00	3	2.9	1.000	604F0_Trip1464	1
09/08/2026 08:49:25	52.353882	4.809223	71	Sudden braking	2.10	2.10	13.8	11.2	1.00	3	2.4	1.000	604F0_Trip1464	1
09/08/2026 08:51:36	52.357833	4.814896	354	Sudden braking	2.00	2.00	11.4	11.5	1.00	2	2.9	1.000	604F0_Trip1464	1
09/08/2026 08:51:37	52.357854	4.814922	16	Sudden braking	2.80	2.80	10.9	8.7	1.00	2	2.8	0.999	604F0_Trip1464	1
09/08/2026 08:51:37	52.357867	4.814957	42	Sudden braking	3.00	3.00	10.3	5.7	1.00	2	1.0	1.000	604F0_Trip1464	1
09/08/2026 08:54:11	52.355982	4.819006	193	Sudden braking	2.00	2.00	14.4	13.6	1.00	2	2.5	1.000	604F0_Trip1464	1
10/08/2026 08:20:42	52.356131	4.826993	98	Sudden braking	2.20	2.20	19.6	18.6	1.00	3	5.4	1.000	604F0_Trip1465	1
10/08/2026 08:20:43	52.356113	4.827068	107	Sudden braking	2.00	2.00	18.7	16.6	1.00	3	4.1	1.001	604F0_Trip1465	1
10/08/2026 08:25:47	52.354821	4.853240	99	Sudden braking	2.00	2.00	16.2	14.9	1.00	3	3.7	1.000	604F0_Trip1465	1
10/08/2026 08:26:11	52.354770	4.855087	72	Sudden braking	2.00	2.00	16.1	16.0	1.00	2	3.9	1.000	604F0_Trip1465	1
10/08/2026 08:26:12	52.354781	4.855142	72	Sudden braking	3.10	3.10	15.5	12.9	1.00	2	2.5	1.000	604F0_Trip1465	1
10/08/2026 08:26:13	52.354790	4.855176	69	Sudden braking	3.30	3.30	14.7	9.6	1.00	2	1.4	1.000	604F0_Trip1465	1
10/08/2026 08:31:46	52.361603	4.881558	52	Sudden braking	2.60	2.60	17.4	18.8	1.00	3	5.0	1.000	604F0_Trip1465	1
10/08/2026 08:31:47	52.361631	4.881615	50	Sudden braking	3.00	3.00	16.5	15.8	1.00	2	3.9	1.000	604F0_Trip1465	1
10/08/2026 08:31:48	52.361656	4.881657	47	Sudden braking	3.20	3.20	15.6	12.6	1.00	2	4.1	1.000	604F0_Trip1465	1
10/08/2026 08:31:49	52.361657	4.881717	38	Sudden braking	3.00	3.00	14.4	9.6	1.00	2	2.0	1.000	604F0_Trip1465	1
10/08/2026 08:31:50	52.361671	4.881737	39	Sudden braking	2.10	2.10	12.4	7.5	1.00	2	1.2	1.000	604F0_Trip1465	1
10/08/2026 08:32:28	52.362535	4.883569	61	Sudden braking	2.20	2.20	18.3	15.9	1.00	3	4.8	1.000	604F0_Trip1465	1
10/08/2026 08:33:48	52.359639	4.890107	113	Sudden braking	2.20	2.20	18.6	19.4	1.00	1	4.8	1.000	604F0_Trip1465	1
10/08/2026 08:33:49	52.359624	4.890172	112	Sudden braking	2.40	2.40	17.1	17.0	1.00	1	3.9	1.000	604F0_Trip1465	1
10/08/2026 08:33:50	52.359613	4.890227	112	Sudden braking	2.20	2.20	15.4	14.8	1.00	1	3.4	1.000	604F0_Trip1465	1
10/08/2026 08:37:11	52.361039	4.907784	69	Sudden braking	3.00	3.00	17.9	16.9	1.00	2	4.8	1.000	604F0_Trip1465	1
10/08/2026 08:37:12	52.361048	4.907854	69	Sudden braking	3.80	3.80	17.5	13.1	1.00	2	2.0	1.000	604F0_Trip1465	1
10/08/2026 08:37:30	52.361055	4.907897	77	Sudden braking	2.70	2.70	10.8	6.5	1.00	3	1.7	1.000	604F0_Trip1465	1
10/08/2026 08:41:00	52.368519	4.913718	30	Sudden braking	2.00	2.00	18.5	18.6	1.00	3	3.9	1.000	604F0_Trip1465	1
10/08/2026 08:41:01	52.368549	4.913748	30	Sudden braking	2.00	2.00	17.6	16.6	1.00	2	3.9	0.999	604F0_Trip1465	1
10/08/2026 08:42:43	52.371030	4.915015	72	Sudden braking	2.00	2.00	14.4	13.1	1.00	2	3.3	1.000	604F0_Trip1465	1
10/08/2026 08:42:44	52.371031	4.915064	80	Sudden braking	2.10	2.10	13.8	11.0	1.00	3	2.4	1.000	604F0_Trip1465	1
11/08/2026 05:48:46	52.353870	4.809166	72	Sudden braking	2.10	2.10	14.6	15.1	1.00	2	3.7	1.000	604F0_Trip1466	1
11/08/2026 05:48:47	52.353881	4.809218	72	Sudden braking	2.20	2.20	13.8	12.9	1.00	2	3.1	1.000	604F0_Trip1466	1
11/08/2026 05:48:48	52.353890	4.809261	71	Sudden braking	2.20	2.20	13.0	10.7	1.00	2	2.5	1.000	604F0_Trip1466	1
11/08/2026 05:48:49	52.353898	4.809297	70	Sudden braking	2.20	2.20	12.0	8.5	1.00	2	1.8	1.000	604F0_Trip1466	1
11/08/2026 05:52:41	52.356155	4.826911	88	Sudden braking	2.00	2.00	17.4	17.5	1.00	3	4.5	1.000	604F0_Trip1466	1
11/08/2026 05:52:42	52.356157	4.826977	88	Sudden braking	2.30	2.30	16.5	15.2	1.00	3	3.8	1.000	604F0_Trip1466	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
11/08/2026 05:52:43	52.356158	4.827033	87	Sudden braking	2.20	2.20	15.8	13.0	1.00	3	2.8	1.000	604F0_Trip1466	1
11/08/2026 05:57:58	52.354728	4.855003	82	Sudden braking	2.10	2.10	17.1	18.7	1.00	2	4.4	1.000	604F0_Trip1466	1
11/08/2026 05:57:59	52.354735	4.855066	82	Sudden braking	2.40	2.40	15.3	16.3	1.00	2	3.1	1.000	604F0_Trip1466	1
11/08/2026 05:58:00	52.354753	4.855102	71	Sudden braking	2.80	2.80	13.5	13.5	1.00	3	2.6	1.000	604F0_Trip1466	1
11/08/2026 05:58:01	52.354766	4.855134	65	Sudden braking	2.80	2.80	12.5	10.7	1.00	3	2.5	1.000	604F0_Trip1466	1
11/08/2026 05:58:02	52.354768	4.855170	72	Sudden braking	2.30	2.30	11.4	8.4	1.00	2	1.6	1.000	604F0_Trip1466	1
11/08/2026 05:58:03	52.354774	4.855193	71	Sudden braking	2.10	2.10	10.3	6.3	1.00	2	1.7	1.000	604F0_Trip1466	1
11/08/2026 06:02:49	52.360718	4.879509	67	Sudden braking	2.30	2.30	24.3	22.5	1.00	2	7.2	1.000	604F0_Trip1466	1
11/08/2026 06:03:46	52.361759	4.881859	35	Sudden braking	2.10	2.10	15.6	18.2	1.00	2	4.4	1.000	604F0_Trip1466	1
11/08/2026 06:03:47	52.361788	4.881902	39	Sudden braking	2.20	2.20	15.5	16.0	1.00	2	4.1	1.000	604F0_Trip1466	1
11/08/2026 06:05:40	52.359612	4.890243	114	Sudden braking	2.00	2.00	15.4	15.8	1.00	2	3.8	1.000	604F0_Trip1466	1
11/08/2026 06:05:41	52.359594	4.890290	119	Sudden braking	2.20	2.20	13.7	13.6	1.00	2	3.3	1.000	604F0_Trip1466	1
11/08/2026 06:05:42	52.359573	4.890326	124	Sudden braking	2.20	2.20	12.8	11.4	1.00	2	2.9	1.000	604F0_Trip1466	1
11/08/2026 06:05:44	52.359549	4.890385	117	Sudden braking	2.00	2.00	10.2	7.5	1.00	2	1.9	1.000	604F0_Trip1466	1
11/08/2026 06:11:00	52.366159	4.911588	30	Sudden braking	2.50	2.50	18.3	18.1	1.00	2	5.0	1.000	604F0_Trip1466	1
11/08/2026 06:11:01	52.366202	4.911610	30	Sudden braking	3.80	3.80	17.5	14.3	1.00	2	3.9	1.000	604F0_Trip1466	1
11/08/2026 06:12:14	52.368463	4.913684	29	Sudden braking	2.00	2.00	16.2	16.5	1.00	3	3.8	1.000	604F0_Trip1466	1
11/08/2026 06:12:15	52.368493	4.913710	28	Sudden braking	2.10	2.10	15.4	14.4	1.00	3	3.0	1.000	604F0_Trip1466	1
11/08/2026 06:13:57	52.371029	4.914853	56	Sudden braking	2.10	2.10	14.0	14.5	1.00	3	3.6	1.000	604F0_Trip1466	1
11/08/2026 06:13:58	52.371047	4.914896	54	Sudden braking	2.20	2.20	12.6	12.3	1.00	3	3.2	1.000	604F0_Trip1466	1
11/08/2026 06:13:59	52.371063	4.914935	58	Sudden braking	2.00	2.00	11.8	10.3	1.00	3	2.2	1.000	604F0_Trip1466	1
11/08/2026 06:14:50	52.372347	4.918096	43	Sudden braking	2.00	2.00	12.7	12.3	1.00	2	3.0	1.000	604F0_Trip1466	1
11/08/2026 09:59:01	52.376122	4.910731	243	Sudden braking	2.30	2.30	20.2	19.3	1.00	2	4.3	1.000	604F0_Trip1467	1
11/08/2026 09:59:02	52.376105	4.910674	244	Sudden braking	2.20	2.20	19.8	17.1	1.00	2	3.7	1.000	604F0_Trip1467	1
11/08/2026 16:43:30	52.371002	4.913221	299	Sudden braking	2.40	2.40	13.1	13.8	1.00	3	3.0	1.000	604F0_Trip1471	1
11/08/2026 16:43:31	52.371012	4.913180	296	Sudden braking	3.00	3.00	12.2	10.8	1.00	2	2.0	1.000	604F0_Trip1471	1
11/08/2026 16:43:32	52.371020	4.913153	296	Sudden braking	2.70	2.70	11.1	8.1	1.00	3	0.8	1.000	604F0_Trip1471	1
11/08/2026 16:43:33	52.371023	4.913143	296	Sudden braking	2.00	2.00	10.0	6.1	1.00	3	0	1.000	604F0_Trip1471	1
11/08/2026 16:44:47	52.368865	4.913857	119	Sudden braking	2.00	2.00	19.0	18.3	1.00	3	4.6	1.000	604F0_Trip1471	1
11/08/2026 16:44:48	52.368845	4.913917	119	Sudden braking	2.00	2.00	18.6	16.3	1.00	3	3.2	1.000	604F0_Trip1471	1
11/08/2026 16:45:33	52.366704	4.911970	212	Sudden braking	2.40	2.40	18.4	19.0	1.00	2	4.9	1.000	604F0_Trip1471	1
11/08/2026 16:45:34	52.366668	4.911929	214	Sudden braking	3.10	3.10	17.6	15.9	1.00	2	4.0	1.000	604F0_Trip1471	1
11/08/2026 16:45:35	52.366639	4.911893	214	Sudden braking	3.60	3.60	16.6	12.3	1.00	2	3.0	1.000	604F0_Trip1471	1
11/08/2026 16:45:36	52.366617	4.911866	219	Sudden braking	3.10	3.10	15.5	9.2	1.00	2	1.5	1.000	604F0_Trip1471	1
11/08/2026 16:47:19	52.364401	4.906577	258	Sudden braking	2.40	2.40	16.6	17.4	1.00	1	4.0	1.000	604F0_Trip1471	1
11/08/2026 16:47:20	52.364399	4.906519	252	Sudden braking	2.70	2.70	15.0	14.7	1.00	1	3.2	1.000	604F0_Trip1471	1
11/08/2026 16:47:21	52.364389	4.906474	252	Sudden braking	2.40	2.40	14.1	12.3	1.00	1	2.1	1.000	604F0_Trip1471	1
11/08/2026 16:48:24	52.363746	4.903241	254	Sudden braking	2.50	2.50	20.0	19.0	1.00	2	4.6	1.000	604F0_Trip1471	1
11/08/2026 16:48:25	52.363727	4.903181	250	Sudden braking	3.20	3.20	18.3	15.8	1.00	2	3.6	1.000	604F0_Trip1471	1
11/08/2026 16:48:26	52.363726	4.903128	259	Sudden braking	3.00	3.00	16.8	12.8	1.00	3	2.4	1.000	604F0_Trip1471	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
11/08/2026 16:49:24	52.362931	4.898803	252	Sudden braking	2.50	2.50	15.1	13.8	1.00	4	2.8	1.000	604F0_Trip1471	1
11/08/2026 16:49:25	52.362924	4.898764	250	Sudden braking	2.90	2.90	14.4	10.9	1.00	4	2.0	1.000	604F0_Trip1471	1
11/08/2026 16:50:30	52.359781	4.898748	199	Sudden braking	2.40	2.40	18.3	18.7	1.00	3	4.9	1.000	604F0_Trip1471	1
11/08/2026 16:50:31	52.359741	4.898717	203	Sudden braking	2.50	2.50	17.1	16.2	1.00	3	3.9	1.000	604F0_Trip1471	1
11/08/2026 16:50:32	52.359707	4.898702	199	Sudden braking	2.30	2.30	16.0	13.9	1.00	3	3.1	1.000	604F0_Trip1471	1
11/08/2026 16:50:33	52.359681	4.898685	200	Sudden braking	2.00	2.00	15.3	11.9	1.00	3	2.7	1.000	604F0_Trip1471	1
11/08/2026 16:51:45	52.359637	4.891575	279	Sudden braking	2.10	2.10	14.9	15.3	1.00	2	4.2	1.000	604F0_Trip1471	1
11/08/2026 16:51:46	52.359640	4.891513	278	Sudden braking	2.20	2.20	13.1	13.1	1.00	2	3.5	1.000	604F0_Trip1471	1
11/08/2026 16:51:47	52.359643	4.891462	277	Sudden braking	2.20	2.20	11.3	10.9	1.00	2	2.8	1.000	604F0_Trip1471	1
11/08/2026 16:51:48	52.359648	4.891422	277	Sudden braking	2.10	2.10	10.3	8.8	1.00	2	2.0	1.000	604F0_Trip1471	1
11/08/2026 16:53:57	52.362538	4.883893	311	Sudden braking	2.20	2.20	16.7	16.6	1.00	2	4.5	1.000	604F0_Trip1471	1
11/08/2026 16:53:58	52.362565	4.883845	315	Sudden braking	2.30	2.30	15.9	14.3	1.00	2	3.6	1.000	604F0_Trip1471	1
11/08/2026 16:53:59	52.362588	4.883807	319	Sudden braking	2.10	2.10	14.7	12.2	1.00	3	2.6	1.000	604F0_Trip1471	1
11/08/2026 16:54:34	52.361935	4.881969	234	Sudden braking	2.20	2.20	11.3	8.6	1.00	1	1.9	1.000	604F0_Trip1471	1
11/08/2026 17:00:20	52.354975	4.855823	245	Sudden braking	2.00	2.00	15.1	15.6	1.00	2	4.2	1.000	604F0_Trip1471	1
11/08/2026 17:00:21	52.354958	4.855767	246	Sudden braking	2.20	2.20	14.2	13.4	1.00	2	3.4	1.000	604F0_Trip1471	1
11/08/2026 17:00:22	52.354946	4.855721	248	Sudden braking	2.50	2.50	12.4	10.9	1.00	2	2.6	1.000	604F0_Trip1471	1
11/08/2026 17:00:23	52.354942	4.855683	255	Sudden braking	2.30	2.30	10.8	8.6	1.00	2	1.8	1.000	604F0_Trip1471	1
11/08/2026 17:01:39	52.354902	4.850800	269	Sudden braking	2.00	2.00	19.6	21.8	1.00	3	5.9	1.000	604F0_Trip1471	1
11/08/2026 17:01:40	52.354901	4.850713	269	Sudden braking	2.60	2.60	17.9	19.2	1.00	3	4.7	1.000	604F0_Trip1471	1
11/08/2026 17:01:41	52.354901	4.850644	269	Sudden braking	2.90	2.90	16.2	16.3	1.00	3	3.4	1.000	604F0_Trip1471	1
11/08/2026 17:01:42	52.354901	4.850595	269	Sudden braking	3.00	3.00	15.3	13.3	1.00	3	2.9	1.000	604F0_Trip1471	1
11/08/2026 17:01:43	52.354900	4.850553	269	Sudden braking	2.80	2.80	13.7	10.5	1.00	4	2.3	1.000	604F0_Trip1471	1
11/08/2026 17:01:44	52.354900	4.850519	269	Sudden braking	2.20	2.20	12.5	8.3	1.00	4	1.8	1.000	604F0_Trip1471	1
11/08/2026 17:03:00	52.355714	4.844582	269	Sudden braking	2.40	2.40	20.2	19.7	1.00	2	5.0	1.000	604F0_Trip1471	1
11/08/2026 17:03:01	52.355713	4.844508	270	Sudden braking	2.40	2.40	19.5	17.3	1.00	2	4.2	1.000	604F0_Trip1471	1
11/08/2026 17:05:58	52.356269	4.827785	268	Sudden braking	2.20	2.20	18.7	20.0	1.00	2	5.3	1.000	604F0_Trip1471	1
11/08/2026 17:05:59	52.356267	4.827707	268	Sudden braking	2.50	2.50	17.0	17.5	1.00	2	4.3	1.000	604F0_Trip1471	1
11/08/2026 17:06:00	52.356265	4.827644	268	Sudden braking	2.60	2.60	16.2	14.9	1.00	2	3.1	1.000	604F0_Trip1471	1
11/08/2026 17:06:01	52.356264	4.827599	268	Sudden braking	2.60	2.60	15.2	12.3	1.00	2	2.9	1.000	604F0_Trip1471	1
11/08/2026 17:06:02	52.356263	4.827556	268	Sudden braking	2.30	2.30	14.1	10.0	1.00	2	1.8	1.000	604F0_Trip1471	1
11/08/2026 17:07:12	52.356220	4.821855	270	Sudden braking	3.10	3.10	19.1	19.8	1.00	4	5.6	1.000	604F0_Trip1471	1
11/08/2026 17:07:13	52.356223	4.821773	270	Sudden braking	3.60	3.60	18.2	16.2	1.00	3	3.2	1.000	604F0_Trip1471	1
11/08/2026 17:07:14	52.356223	4.821726	270	Sudden braking	2.90	2.90	17.5	13.3	1.00	3	1.5	1.000	604F0_Trip1471	1
11/08/2026 17:09:19	52.354187	4.809625	250	Sudden braking	2.00	2.00	21.4	20.2	1.00	4	4.5	1.000	604F0_Trip1471	1
11/08/2026 17:10:17	52.354770	4.806215	251	Sudden braking	2.20	2.20	10.4	8.7	1.00	2	2.4	1.000	604F0_Trip1471	1
11/08/2026 17:10:22	52.354797	4.806190	251	Sudden braking	2.40	2.40	3.7	3.9	1.00	2	1.6	1.000	604F0_Trip1471	1
12/08/2026 05:54:53	52.353695	4.807269	155	Sudden braking	2.40	2.40	13.0	11.2	1.00	2	1.3	1.001	604F0_Trip1474	1
12/08/2026 05:54:54	52.353688	4.807285	151	Sudden braking	2.40	2.40	12.2	8.8	1.00	2	2.4	1.000	604F0_Trip1474	1
12/08/2026 05:55:26	52.353775	4.808939	71	Sudden braking	2.20	2.20	18.7	19.0	1.00	3	4.6	1.000	604F0_Trip1474	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
12/08/2026 05:55:27	52.353787	4.809005	73	Sudden braking	2.50	2.50	17.1	16.5	1.00	3	4.0	1.000	604F0_Trip1474	1
12/08/2026 05:55:28	52.353798	4.809061	72	Sudden braking	2.50	2.50	15.5	14.0	1.00	3	3.4	1.001	604F0_Trip1474	1
12/08/2026 05:55:30	52.353808	4.809109	72	Sudden braking	2.30	2.30	12.3	11.7	1.00	3	2.4	1.000	604F0_Trip1474	1
12/08/2026 05:58:56	52.356158	4.827046	88	Sudden braking	2.50	2.50	16.1	14.4	1.00	3	3.6	1.000	604F0_Trip1474	1
12/08/2026 05:58:57	52.356160	4.827099	88	Sudden braking	2.70	2.70	15.2	11.7	1.00	4	2.2	1.000	604F0_Trip1474	1
12/08/2026 05:58:58	52.356160	4.827132	88	Sudden braking	2.30	2.30	14.2	9.4	1.00	3	1.3	1.000	604F0_Trip1474	1
12/08/2026 06:04:10	52.354819	4.853058	94	Sudden braking	2.30	2.30	20.2	19.8	1.00	3	4.8	1.000	604F0_Trip1474	1
12/08/2026 06:04:11	52.354816	4.853128	94	Sudden braking	2.10	2.10	19.3	17.7	1.00	3	4.2	1.000	604F0_Trip1474	1
12/08/2026 06:08:55	52.360644	4.879232	66	Sudden braking	2.60	2.60	23.1	22.0	1.00	1	7.3	1.000	604F0_Trip1474	1
12/08/2026 06:10:04	52.361749	4.881845	37	Sudden braking	2.40	2.40	14.4	17.2	1.00	4	4.2	1.000	604F0_Trip1474	1
12/08/2026 06:10:05	52.361779	4.881883	38	Sudden braking	2.60	2.60	14.5	14.6	1.00	4	3.9	1.000	604F0_Trip1474	1
12/08/2026 06:11:59	52.359599	4.890281	120	Sudden braking	2.10	2.10	17.8	19.5	1.00	2	4.9	1.000	604F0_Trip1474	1
12/08/2026 06:12:00	52.359575	4.890340	121	Sudden braking	3.00	3.00	17.4	16.5	1.00	2	3.8	1.000	604F0_Trip1474	1
12/08/2026 06:12:01	52.359556	4.890388	120	Sudden braking	3.60	3.60	16.7	12.9	1.00	2	2.9	1.000	604F0_Trip1474	1
12/08/2026 06:12:02	52.359548	4.890429	111	Sudden braking	3.10	3.10	15.9	9.8	1.00	3	1.7	1.000	604F0_Trip1474	1
12/08/2026 06:13:52	52.359395	4.898156	75	Sudden braking	2.10	2.10	13.6	12.9	1.00	4	3.2	1.000	604F0_Trip1474	1
12/08/2026 06:13:53	52.359402	4.898202	75	Sudden braking	2.20	2.20	12.8	10.7	1.00	3	2.6	1.000	604F0_Trip1474	1
12/08/2026 06:17:29	52.366029	4.911496	30	Sudden braking	2.10	2.10	18.3	18.5	1.00	2	4.7	1.000	604F0_Trip1474	1
12/08/2026 06:17:30	52.366067	4.911525	30	Sudden braking	2.10	2.10	16.8	16.4	1.00	2	4.2	1.000	604F0_Trip1474	1
12/08/2026 06:17:31	52.366099	4.911560	30	Sudden braking	2.00	2.00	15.4	14.4	1.00	2	4.2	1.000	604F0_Trip1474	1
12/08/2026 06:17:32	52.366134	4.911582	30	Sudden braking	2.00	2.00	14.3	12.4	1.00	2	4.0	1.000	604F0_Trip1474	1
12/08/2026 06:18:58	52.369486	4.912247	299	Sudden braking	2.10	2.10	16.2	14.9	1.00	3	1.7	1.000	604F0_Trip1474	1
12/08/2026 06:20:40	52.372412	4.918202	45	Sudden braking	2.00	2.00	15.4	14.4	1.00	2	3.0	1.000	604F0_Trip1474	1
17/08/2026 07:33:26	52.355721	4.818306	72	Sudden braking	2.10	2.10	20.5	20.5	1.00	2	5.5	1.000	604F0_Trip1482	1
17/08/2026 07:33:27	52.355735	4.818384	72	Sudden braking	2.40	2.40	20.1	18.1	1.00	2	4.2	1.000	604F0_Trip1482	1
17/08/2026 07:34:57	52.356090	4.826897	91	Sudden braking	2.40	2.40	17.0	16.7	1.00	2	4.3	1.000	604F0_Trip1482	1
17/08/2026 07:34:58	52.356096	4.826959	91	Sudden braking	2.40	2.40	15.3	14.3	1.00	2	3.0	1.000	604F0_Trip1482	1
17/08/2026 07:34:59	52.356089	4.827002	100	Sudden braking	2.20	2.20	13.6	12.1	1.00	2	2.3	1.000	604F0_Trip1482	1
17/08/2026 07:35:00	52.356081	4.827033	109	Sudden braking	2.10	2.10	11.8	10.0	1.00	2	1.9	1.001	604F0_Trip1482	1
17/08/2026 07:39:42	52.354950	4.850003	89	Sudden braking	2.00	2.00	15.1	14.0	1.00	2	2.7	1.000	604F0_Trip1482	1
17/08/2026 07:45:31	52.361597	4.881617	57	Sudden braking	2.00	2.00	14.3	15.9	1.00	2	3.8	1.000	604F0_Trip1482	1
17/08/2026 07:45:32	52.361615	4.881666	56	Sudden braking	2.20	2.20	13.5	13.7	1.00	2	3.1	1.000	604F0_Trip1482	1
17/08/2026 07:45:33	52.361632	4.881702	53	Sudden braking	2.20	2.20	11.6	11.5	1.00	2	2.4	1.000	604F0_Trip1482	1
17/08/2026 07:45:34	52.361647	4.881727	49	Sudden braking	2.30	2.30	10.6	9.2	1.00	2	1.8	1.000	604F0_Trip1482	1
17/08/2026 07:45:35	52.361661	4.881740	40	Sudden braking	2.20	2.20	9.6	7.0	1.00	2	1.3	1.000	604F0_Trip1482	1
17/08/2026 07:47:54	52.359517	4.890470	106	Sudden braking	2.00	2.00	20.8	20.3	1.00	3	5.1	1.000	604F0_Trip1482	1
17/08/2026 07:49:06	52.359278	4.897752	77	Sudden braking	2.20	2.20	19.5	20.3	1.00	2	4.4	1.000	604F0_Trip1482	1
17/08/2026 07:49:07	52.359287	4.897816	77	Sudden braking	2.30	2.30	18.0	18.0	1.00	2	3.7	1.000	604F0_Trip1482	1
17/08/2026 07:49:08	52.359287	4.897870	77	Sudden braking	2.20	2.20	16.3	15.8	1.00	2	3.5	1.000	604F0_Trip1482	1
17/08/2026 07:49:09	52.359295	4.897920	77	Sudden braking	2.00	2.00	14.6	13.8	1.00	2	3.6	1.000	604F0_Trip1482	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
17/08/2026 07:51:38	52.360979	4.907617	73	Sudden braking	2.20	2.20	20.2	19.7	1.00	2	4.4	1.000	604F0_Trip1482	1
17/08/2026 07:51:39	52.360990	4.907679	73	Sudden braking	2.10	2.10	19.4	17.6	1.00	2	3.8	1.000	604F0_Trip1482	1
17/08/2026 07:52:24	52.361808	4.911383	66	Sudden braking	2.00	2.00	14.7	15.3	1.00	2	3.6	1.000	604F0_Trip1482	1
17/08/2026 07:52:25	52.361823	4.911431	61	Sudden braking	2.30	2.30	13.2	13.0	1.00	2	2.6	1.000	604F0_Trip1482	1
17/08/2026 07:52:26	52.361840	4.911457	48	Sudden braking	2.30	2.30	11.9	10.7	1.00	2	2.2	1.000	604F0_Trip1482	1
17/08/2026 07:52:27	52.361858	4.911468	30	Sudden braking	2.00	2.00	10.9	8.7	1.00	2	1.5	1.000	604F0_Trip1482	1
17/08/2026 07:52:45	52.362430	4.911134	341	Sudden braking	2.00	2.00	17.2	15.9	1.00	3	4.0	1.000	604F0_Trip1482	1
17/08/2026 07:53:50	52.366084	4.911595	30	Sudden braking	2.20	2.20	15.5	13.9	1.00	2	3.7	1.000	604F0_Trip1482	1
17/08/2026 07:53:51	52.366116	4.911610	30	Sudden braking	2.20	2.20	13.6	11.7	1.00	2	1.4	1.000	604F0_Trip1482	1
17/08/2026 07:53:52	52.366124	4.911626	30	Sudden braking	2.40	2.40	12.7	9.3	1.00	2	2.3	1.001	604F0_Trip1482	1
17/08/2026 07:55:22	52.369479	4.912401	298	Sudden braking	2.00	2.00	16.2	17.8	1.00	2	4.4	1.000	604F0_Trip1482	1
17/08/2026 07:55:23	52.369500	4.912347	300	Sudden braking	2.60	2.60	15.4	15.2	1.00	2	3.5	1.000	604F0_Trip1482	1
17/08/2026 07:55:24	52.369525	4.912317	313	Sudden braking	2.30	2.30	14.8	12.9	1.00	2	2.8	1.000	604F0_Trip1482	1
19/08/2026 12:50:26	52.367135	4.924994	212	Sudden braking	2.33	2.33	4.9	6.2	0.94	1	1.2	0.943	604F0_Trip1498	1
19/08/2026 12:50:27	52.367126	4.924986	202	Sudden braking	2.20	2.20	4.9	4.0	1.00	1	0.7	1.001	604F0_Trip1498	1
19/08/2026 12:51:33	52.366006	4.926529	144	Sudden braking	2.74	2.74	17.6	16.3	1.02	3	4.8	1.021	604F0_Trip1498	1
19/08/2026 12:51:34	52.365970	4.926569	147	Sudden braking	2.69	2.69	17.3	13.7	0.97	3	3.9	0.967	604F0_Trip1498	1
19/08/2026 12:52:59	52.363131	4.920514	261	Sudden braking	2.13	2.13	9.3	8.6	1.03	2	3.4	1.033	604F0_Trip1498	1
19/08/2026 12:53:00	52.363128	4.920464	262	Sudden braking	2.41	2.41	7.0	6.2	0.99	2	2.0	0.995	604F0_Trip1498	1
19/08/2026 12:53:01	52.363127	4.920435	258	Sudden braking	2.08	2.08	5.2	4.1	1.01	2	1.3	1.009	604F0_Trip1498	1
19/08/2026 12:53:40	52.362899	4.919901	212	Sudden braking	2.08	2.08	8.4	10.1	1.01	2	0.8	1.009	604F0_Trip1498	1
19/08/2026 12:53:41	52.362893	4.919896	0	Sudden braking	3.72	3.72	7.3	6.4	0.99	2	0.7	0.994	604F0_Trip1498	1
19/08/2026 12:53:42	52.362888	4.919904	0	Sudden braking	3.15	3.15	6.4	3.4	0.95	2	1.2	0.952	604F0_Trip1498	1
19/08/2026 12:54:59	52.361763	4.915503	245	Sudden braking	2.59	2.59	11.2	12.1	1.00	2	3.5	1.005	604F0_Trip1498	1
19/08/2026 12:55:00	52.361746	4.915460	238	Sudden braking	3.12	3.12	8.4	9.1	0.96	1	2.8	0.960	604F0_Trip1498	1
19/08/2026 12:55:01	52.361731	4.915427	234	Sudden braking	2.78	2.78	8.4	6.3	1.01	1	1.8	1.006	604F0_Trip1498	1
19/08/2026 12:55:02	52.361720	4.915407	230	Sudden braking	2.26	2.26	6.6	4.0	1.02	1	1.4	1.017	604F0_Trip1498	1
19/08/2026 12:59:42	52.368034	4.904950	81	Sudden braking	2.25	2.25	18.2	17.0	0.98	2	4.7	0.978	604F0_Trip1498	1
19/08/2026 12:59:54	52.368390	4.904467	307	Sudden braking	2.85	2.85	17.0	16.0	1.02	2	6.3	1.019	604F0_Trip1498	1
19/08/2026 12:59:55	52.368431	4.904402	318	Sudden braking	2.17	2.17	17.5	13.9	0.97	2	2.9	0.966	604F0_Trip1498	1
19/08/2026 13:01:31	52.371306	4.911995	118	Sudden braking	2.46	2.46	8.1	8.3	0.93	2	2.9	0.934	604F0_Trip1498	1
20/08/2026 07:12:24	52.353822	4.809154	73	Sudden braking	2.10	2.10	16.4	17.4	1.00	2	4.1	1.000	604F0_Trip1501	1
20/08/2026 07:12:25	52.353833	4.809212	73	Sudden braking	2.40	2.40	14.8	15.0	1.00	2	3.3	1.000	604F0_Trip1501	1
20/08/2026 07:12:26	52.353840	4.809259	74	Sudden braking	2.40	2.40	14.0	12.6	1.00	2	2.6	1.000	604F0_Trip1501	1
20/08/2026 07:12:27	52.353848	4.809295	73	Sudden braking	2.20	2.20	13.1	10.4	1.00	2	2.2	1.000	604F0_Trip1501	1
20/08/2026 07:26:31	52.361562	4.881465	58	Sudden braking	2.20	2.20	18.0	18.8	1.00	2	5.1	1.000	604F0_Trip1501	1
20/08/2026 07:26:32	52.361588	4.881528	56	Sudden braking	2.30	2.30	16.3	16.5	1.00	2	4.2	1.000	604F0_Trip1501	1
20/08/2026 07:26:33	52.361611	4.881576	52	Sudden braking	2.30	2.30	14.5	14.2	1.00	2	3.4	1.000	604F0_Trip1501	1
20/08/2026 07:26:34	52.361631	4.881615	50	Sudden braking	2.20	2.20	12.7	12.0	1.00	2	3.7	1.000	604F0_Trip1501	1
20/08/2026 07:26:35	52.361635	4.881669	52	Sudden braking	2.00	2.00	11.7	10.0	1.00	2	2.6	1.000	604F0_Trip1501	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
20/08/2026 07:29:05	52.359647	4.890072	112	Sudden braking	2.10	2.10	16.2	16.3	1.00	2	4.3	1.000	604F0_Trip1501	1
20/08/2026 07:29:06	52.359631	4.890129	113	Sudden braking	2.10	2.10	14.7	14.2	1.00	2	3.4	1.000	604F0_Trip1501	1
20/08/2026 07:30:44	52.359375	4.898015	77	Sudden braking	2.30	2.30	17.0	18.1	1.00	2	4.8	1.000	604F0_Trip1501	1
20/08/2026 07:30:45	52.359383	4.898084	77	Sudden braking	2.70	2.70	15.2	15.4	1.00	2	3.7	1.000	604F0_Trip1501	1
20/08/2026 07:30:46	52.359390	4.898138	78	Sudden braking	2.80	2.80	14.2	12.6	1.00	2	3.0	1.000	604F0_Trip1501	1
20/08/2026 07:30:47	52.359395	4.898180	78	Sudden braking	2.70	2.70	13.2	9.9	1.00	2	2.2	1.000	604F0_Trip1501	1
20/08/2026 07:30:48	52.359400	4.898212	78	Sudden braking	2.30	2.30	12.1	7.6	1.00	2	1.7	1.000	604F0_Trip1501	1
20/08/2026 07:33:43	52.361849	4.911343	66	Sudden braking	2.20	2.20	13.8	14.0	1.00	2	3.7	1.000	604F0_Trip1501	1
20/08/2026 07:33:44	52.361860	4.911393	66	Sudden braking	2.50	2.50	13.1	11.5	1.00	2	2.7	1.000	604F0_Trip1501	1
20/08/2026 07:33:45	52.361868	4.911431	66	Sudden braking	2.50	2.50	12.3	9.0	1.00	2	2.0	1.000	604F0_Trip1501	1
20/08/2026 07:33:46	52.361873	4.911460	72	Sudden braking	2.40	2.40	11.4	6.6	1.00	2	1.2	1.000	604F0_Trip1501	1
20/08/2026 07:35:16	52.365899	4.911349	29	Sudden braking	2.00	2.00	21.1	22.1	1.00	2	5.9	1.000	604F0_Trip1501	1
20/08/2026 07:35:17	52.365945	4.911389	29	Sudden braking	2.20	2.20	19.5	19.9	1.00	2	5.1	1.000	604F0_Trip1501	1
20/08/2026 07:35:18	52.365978	4.911442	29	Sudden braking	2.20	2.20	17.7	17.7	1.00	2	4.5	1.000	604F0_Trip1501	1
20/08/2026 07:35:19	52.366009	4.911484	30	Sudden braking	2.10	2.10	15.8	15.6	1.00	2	4.1	1.000	604F0_Trip1501	1
20/08/2026 07:35:20	52.366040	4.911518	30	Sudden braking	2.00	2.00	14.0	13.6	1.00	2	3.6	1.000	604F0_Trip1501	1
20/08/2026 07:35:23	52.366110	4.911586	30	Sudden braking	2.00	2.00	10.3	7.9	1.00	2	2.1	1.000	604F0_Trip1501	1
20/08/2026 07:36:36	52.368567	4.913762	29	Sudden braking	2.00	2.00	18.8	19.6	1.00	2	3.9	1.000	604F0_Trip1501	1
20/08/2026 07:38:05	52.370998	4.914896	56	Sudden braking	2.10	2.10	17.8	19.2	1.00	2	4.7	1.000	604F0_Trip1501	1
20/08/2026 07:38:06	52.371017	4.914958	62	Sudden braking	2.60	2.60	17.0	16.6	1.00	3	4.0	1.000	604F0_Trip1501	1
20/08/2026 07:38:07	52.371022	4.915016	75	Sudden braking	2.90	2.90	16.1	13.7	1.00	3	3.5	1.000	604F0_Trip1501	1
20/08/2026 07:38:08	52.371024	4.915068	81	Sudden braking	2.80	2.80	15.1	10.9	1.00	2	2.3	1.000	604F0_Trip1501	1
20/08/2026 07:38:09	52.371027	4.915101	83	Sudden braking	2.20	2.20	14.0	8.7	1.00	2	1.3	1.000	604F0_Trip1501	1
24/08/2026 07:54:34	52.353795	4.809098	68	Sudden braking	2.23	2.23	10.4	12.4	0.99	2	3.5	0.986	604F0_Trip1512	1
24/08/2026 07:54:35	52.353805	4.809147	71	Sudden braking	2.58	2.58	8.8	10.0	0.93	3	2.8	0.931	604F0_Trip1512	1
24/08/2026 07:54:36	52.353813	4.809187	74	Sudden braking	2.30	2.30	8.2	7.6	1.04	3	2.6	1.043	604F0_Trip1512	1
24/08/2026 07:58:05	52.356161	4.826119	83	Sudden braking	2.28	2.28	17.3	18.1	1.01	2	5.0	1.007	604F0_Trip1512	1
24/08/2026 07:58:06	52.356167	4.826192	80	Sudden braking	3.36	3.36	16.1	14.7	1.01	2	4.1	1.012	604F0_Trip1512	1
24/08/2026 07:58:07	52.356167	4.826253	85	Sudden braking	2.49	2.49	14.8	12.1	1.04	2	3.3	1.044	604F0_Trip1512	1
24/08/2026 07:58:19	52.356097	4.826944	95	Sudden braking	2.68	2.68	10.4	12.4	0.97	3	3.0	0.971	604F0_Trip1512	1
24/08/2026 07:58:20	52.356088	4.826986	114	Sudden braking	3.29	3.29	10.1	9.1	1.00	3	3.2	1.004	604F0_Trip1512	1
24/08/2026 07:58:21	52.356077	4.827030	115	Sudden braking	3.22	3.22	8.8	5.9	0.99	3	1.6	0.993	604F0_Trip1512	1
24/08/2026 07:58:22	52.356078	4.827054	0	Sudden braking	2.01	2.01	7.6	3.8	1.05	3	0.2	1.046	604F0_Trip1512	1
24/08/2026 08:02:32	52.355703	4.847771	110	Sudden braking	2.27	2.27	16.9	14.6	0.97	3	4.0	0.971	604F0_Trip1512	1
24/08/2026 08:02:47	52.355061	4.847981	180	Sudden braking	2.18	2.18	15.7	14.9	1.05	2	4.7	1.054	604F0_Trip1512	1
24/08/2026 08:04:08	52.354652	4.854613	103	Sudden braking	3.20	3.20	16.2	18.4	1.03	3	6.8	1.031	604F0_Trip1512	1
24/08/2026 08:04:09	52.354635	4.854710	107	Sudden braking	3.93	3.93	15.2	14.8	0.92	3	4.9	0.915	604F0_Trip1512	1
24/08/2026 08:04:10	52.354627	4.854780	105	Sudden braking	2.84	2.84	15.2	11.8	1.06	3	2.6	1.056	604F0_Trip1512	1
24/08/2026 08:04:11	52.354629	4.854818	91	Sudden braking	2.59	2.59	13.9	9.3	0.97	3	1.7	0.967	604F0_Trip1512	1
24/08/2026 08:05:52	52.356253	4.864998	87	Sudden braking	2.42	2.42	21.5	20.2	1.03	3	6.7	1.032	604F0_Trip1512	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
24/08/2026 08:09:15	52.361652	4.881693	45	Sudden braking	2.04	2.04	11.6	11.3	1.03	2	2.6	1.031	604F0_Trip1512	1
24/08/2026 08:09:16	52.361668	4.881722	47	Sudden braking	2.42	2.42	8.9	9.0	0.95	2	1.6	0.952	604F0_Trip1512	1
24/08/2026 08:09:17	52.361680	4.881734	34	Sudden braking	2.34	2.34	7.2	6.6	1.02	2	0.9	1.025	604F0_Trip1512	1
24/08/2026 08:09:18	52.361687	4.881742	28	Sudden braking	2.05	2.05	5.6	4.4	1.07	2	0.4	1.071	604F0_Trip1512	1
24/08/2026 08:10:33	52.362655	4.883744	34	Sudden braking	2.19	2.19	10.9	7.4	1.01	3	3.1	1.006	604F0_Trip1512	1
24/08/2026 08:11:47	52.365091	4.880402	326	Sudden braking	2.22	2.22	15.2	16.4	0.99	3	4.6	0.991	604F0_Trip1512	1
24/08/2026 08:11:48	52.365128	4.880371	329	Sudden braking	2.00	2.00	14.4	14.4	1.00	3	3.1	1.000	604F0_Trip1512	1
24/08/2026 08:11:49	52.365155	4.880360	339	Sudden braking	2.11	2.11	12.9	12.4	0.95	3	2.7	0.948	604F0_Trip1512	1
24/08/2026 08:11:50	52.365179	4.880354	342	Sudden braking	2.10	2.10	11.5	10.2	1.05	3	3.6	1.049	604F0_Trip1512	1
24/08/2026 08:12:28	52.366072	4.882006	57	Sudden braking	2.37	2.37	18.2	18.1	1.05	3	6.3	1.054	604F0_Trip1512	1
24/08/2026 08:12:29	52.366102	4.882086	59	Sudden braking	2.88	2.88	17.0	15.2	1.01	3	4.8	1.008	604F0_Trip1512	1
24/08/2026 08:12:30	52.366119	4.882151	61	Sudden braking	2.44	2.44	15.1	12.8	0.98	3	3.6	0.985	604F0_Trip1512	1
24/08/2026 08:13:06	52.366658	4.884581	47	Sudden braking	2.81	2.81	15.7	15.9	1.00	3	4.4	0.996	604F0_Trip1512	1
24/08/2026 08:13:07	52.366681	4.884634	54	Sudden braking	2.82	2.82	15.7	13.1	0.99	3	3.6	0.994	604F0_Trip1512	1
24/08/2026 08:13:34	52.365949	4.886004	128	Sudden braking	2.84	2.84	10.7	13.6	0.95	3	4.2	0.951	604F0_Trip1512	1
24/08/2026 08:13:35	52.365923	4.886050	130	Sudden braking	3.46	3.46	10.7	10.0	1.04	3	4.1	1.041	604F0_Trip1512	1
24/08/2026 08:13:36	52.365901	4.886099	126	Sudden braking	2.98	2.98	7.9	6.9	1.04	4	1.1	1.042	604F0_Trip1512	1
24/08/2026 08:13:37	52.365899	4.886116	0	Sudden braking	2.83	2.83	6.1	4.1	0.99	4	0.3	0.990	604F0_Trip1512	1
24/08/2026 08:13:38	52.365901	4.886117	0	Sudden braking	2.49	2.49	4.6	1.7	0.96	4	1.0	0.965	604F0_Trip1512	1
24/08/2026 08:14:35	52.364262	4.888668	132	Sudden braking	2.29	2.29	15.0	14.3	1.05	2	4.5	1.046	604F0_Trip1512	1
24/08/2026 08:14:36	52.364235	4.888717	132	Sudden braking	2.41	2.41	12.1	11.9	0.99	3	4.1	0.994	604F0_Trip1512	1
24/08/2026 08:15:23	52.365506	4.890822	63	Sudden braking	2.08	2.08	15.6	16.3	0.96	3	3.4	0.963	604F0_Trip1512	1
24/08/2026 08:18:13	52.372217	4.893030	3	Sudden braking	2.16	2.16	12.9	14.0	0.97	3	3.4	0.973	604F0_Trip1512	1
24/08/2026 08:18:14	52.372247	4.893031	3	Sudden braking	2.42	2.42	12.5	11.6	0.99	4	3.2	0.991	604F0_Trip1512	1
24/08/2026 08:18:15	52.372276	4.893027	358	Sudden braking	2.63	2.63	11.6	9.1	0.95	4	2.5	0.950	604F0_Trip1512	1
24/08/2026 08:18:39	52.373185	4.893422	21	Sudden braking	2.00	2.00	19.6	20.1	0.95	3	5.7	0.951	604F0_Trip1512	1
24/08/2026 08:18:40	52.373233	4.893453	25	Sudden braking	2.28	2.28	19.1	17.7	1.05	3	5.4	1.052	604F0_Trip1512	1
24/08/2026 08:22:46	52.372650	4.907428	143	Sudden braking	2.26	2.26	16.1	11.9	0.97	4	4.8	0.974	604F0_Trip1512	1
24/08/2026 08:23:22	52.371579	4.909703	129	Sudden braking	2.97	2.97	11.8	14.7	0.98	2	5.0	0.976	604F0_Trip1512	1
24/08/2026 08:23:23	52.371556	4.909766	127	Sudden braking	3.92	3.92	10.3	10.9	0.97	2	3.4	0.969	604F0_Trip1512	1
24/08/2026 08:23:24	52.371540	4.909808	134	Sudden braking	3.22	3.22	10.3	7.5	1.05	2	2.0	1.055	604F0_Trip1512	1
24/08/2026 08:23:25	52.371530	4.909832	146	Sudden braking	2.21	2.21	7.2	5.3	1.00	2	1.0	0.997	604F0_Trip1512	1
24/08/2026 08:24:34	52.371260	4.911484	122	Sudden braking	2.00	2.00	20.0	20.2	1.00	3	6.1	0.999	604F0_Trip1512	1
24/08/2026 08:25:27	52.371071	4.915277	58	Sudden braking	2.20	2.20	15.5	14.3	1.04	2	4.5	1.044	604F0_Trip1512	1
24/08/2026 08:25:28	52.371094	4.915331	57	Sudden braking	2.01	2.01	15.0	12.2	1.04	2	4.2	1.045	604F0_Trip1512	1
24/08/2026 08:26:07	52.370121	4.918201	120	Sudden braking	2.26	2.26	20.9	20.4	1.02	3	6.8	1.018	604F0_Trip1512	1
24/08/2026 08:26:13	52.369972	4.918621	122	Sudden braking	2.06	2.06	16.0	15.2	1.26	3	7.1	1.262	604F0_Trip1512	1
24/08/2026 15:46:20	52.370980	4.913287	299	Sudden braking	2.50	2.50	16.6	18.4	1.00	2	4.0	1.000	604F0_Trip1514	1
24/08/2026 15:46:21	52.370996	4.913234	296	Sudden braking	3.00	3.00	15.9	15.4	1.00	2	3.4	1.000	604F0_Trip1514	1
24/08/2026 15:46:22	52.371010	4.913189	296	Sudden braking	3.30	3.30	15.0	12.1	1.00	2	2.3	1.000	604F0_Trip1514	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
24/08/2026 15:46:23	52.371019	4.913158	296	Sudden braking	3.10	3.10	13.9	9.0	1.00	2	1.4	1.000	604F0_Trip1514	1
24/08/2026 15:46:24	52.371024	4.913140	295	Sudden braking	2.20	2.20	12.6	6.8	1.00	2	0.5	1.000	604F0_Trip1514	1
24/08/2026 15:46:58	52.370232	4.911944	232	Sudden braking	2.00	2.00	19.3	18.0	1.00	2	4.2	1.000	604F0_Trip1514	1
24/08/2026 15:48:33	52.366734	4.911999	212	Sudden braking	2.10	2.10	17.0	18.5	1.00	2	4.5	1.000	604F0_Trip1514	1
24/08/2026 15:48:34	52.366698	4.911967	212	Sudden braking	2.50	2.50	16.3	16.0	1.00	2	3.9	1.000	604F0_Trip1514	1
24/08/2026 15:48:35	52.366668	4.911937	214	Sudden braking	2.80	2.80	14.4	13.2	1.00	2	3.3	1.000	604F0_Trip1514	1
24/08/2026 15:48:36	52.366644	4.911909	214	Sudden braking	2.80	2.80	13.4	10.4	1.00	2	2.4	1.000	604F0_Trip1514	1
24/08/2026 15:48:37	52.366626	4.911889	214	Sudden braking	2.50	2.50	12.3	7.9	1.00	2	1.8	1.000	604F0_Trip1514	1
24/08/2026 15:50:20	52.364410	4.906644	265	Sudden braking	2.00	2.00	17.1	18.1	1.00	2	3.6	1.000	604F0_Trip1514	1
24/08/2026 15:50:21	52.364415	4.906592	262	Sudden braking	2.10	2.10	15.7	16.0	1.00	2	3.1	1.000	604F0_Trip1514	1
24/08/2026 15:50:22	52.364412	4.906546	258	Sudden braking	2.30	2.30	14.2	13.7	1.00	3	4.7	1.000	604F0_Trip1514	1
24/08/2026 15:50:23	52.364408	4.906477	250	Sudden braking	2.00	2.00	12.5	11.7	1.00	3	3.5	1.000	604F0_Trip1514	1
24/08/2026 15:52:20	52.362937	4.898838	252	Sudden braking	2.10	2.10	11.3	10.9	1.00	2	2.0	1.000	604F0_Trip1514	1
24/08/2026 15:52:21	52.362933	4.898809	252	Sudden braking	2.10	2.10	10.2	8.8	1.00	2	1.6	1.000	604F0_Trip1514	1
24/08/2026 15:53:30	52.360334	4.899198	211	Sudden braking	2.10	2.10	18.2	17.5	1.00	2	4.4	1.000	604F0_Trip1514	1
24/08/2026 15:53:31	52.360300	4.899164	210	Sudden braking	2.00	2.00	17.3	15.5	1.00	2	3.7	1.000	604F0_Trip1514	1
24/08/2026 15:55:02	52.359614	4.891742	278	Sudden braking	2.00	2.00	18.2	19.5	1.00	2	5.3	1.000	604F0_Trip1514	1
24/08/2026 15:55:03	52.359617	4.891665	276	Sudden braking	2.40	2.40	16.5	17.1	1.00	2	4.3	1.000	604F0_Trip1514	1
24/08/2026 15:55:04	52.359622	4.891601	276	Sudden braking	2.60	2.60	14.8	14.5	1.00	2	3.5	1.000	604F0_Trip1514	1
24/08/2026 15:55:05	52.359627	4.891550	277	Sudden braking	2.50	2.50	13.0	12.0	1.00	2	2.9	1.000	604F0_Trip1514	1
24/08/2026 15:55:06	52.359630	4.891508	277	Sudden braking	2.10	2.10	11.1	9.9	1.00	2	2.2	1.000	604F0_Trip1514	1
24/08/2026 15:57:13	52.362553	4.883866	311	Sudden braking	2.00	2.00	16.3	15.9	1.00	2	4.4	1.000	604F0_Trip1514	1
24/08/2026 15:57:14	52.362581	4.883820	319	Sudden braking	2.30	2.30	15.6	13.6	1.00	2	3.0	1.000	604F0_Trip1514	1
24/08/2026 15:57:15	52.362591	4.883779	319	Sudden braking	2.30	2.30	14.9	11.3	1.00	2	2.5	1.000	604F0_Trip1514	1
24/08/2026 15:59:26	52.360297	4.875991	246	Sudden braking	2.30	2.30	18.5	17.0	1.00	2	4.3	1.000	604F0_Trip1514	1
24/08/2026 16:03:14	52.354974	4.855877	253	Sudden braking	2.50	2.50	18.7	18.4	1.00	3	4.8	1.000	604F0_Trip1514	1
24/08/2026 16:03:15	52.354958	4.855811	251	Sudden braking	2.50	2.50	17.4	15.9	1.00	2	3.6	1.001	604F0_Trip1514	1
24/08/2026 16:03:17	52.354945	4.855762	249	Sudden braking	2.10	2.10	15.3	13.8	1.00	2	2.9	1.000	604F0_Trip1514	1
24/08/2026 16:05:26	52.355683	4.844589	268	Sudden braking	2.10	2.10	17.3	17.8	1.00	2	3.9	1.000	604F0_Trip1514	1
24/08/2026 16:05:27	52.355686	4.844533	271	Sudden braking	2.40	2.40	16.5	15.4	1.00	2	3.6	1.000	604F0_Trip1514	1
24/08/2026 16:05:28	52.355694	4.844481	280	Sudden braking	2.10	2.10	16.6	13.3	1.00	2	3.1	1.000	604F0_Trip1514	1
24/08/2026 16:06:14	52.356378	4.841103	271	Sudden braking	2.40	2.40	19.9	21.3	1.00	2	6.0	1.000	604F0_Trip1514	1
24/08/2026 16:06:15	52.356376	4.841015	268	Sudden braking	3.20	3.20	18.9	18.1	1.00	2	7.9	1.000	604F0_Trip1514	1
24/08/2026 16:06:16	52.356436	4.840955	273	Sudden braking	3.00	3.00	18.0	15.1	1.00	2	1.4	1.000	604F0_Trip1514	1
24/08/2026 16:06:17	52.356445	4.840941	281	Sudden braking	2.10	2.10	17.3	13.0	1.00	2	1.5	1.000	604F0_Trip1514	1
24/08/2026 16:08:37	52.356268	4.827757	268	Sudden braking	2.00	2.00	17.6	17.6	1.00	2	4.4	1.000	604F0_Trip1514	1
24/08/2026 16:11:43	52.354342	4.810774	254	Sudden braking	2.00	2.00	15.7	16.3	1.00	1	4.3	1.000	604F0_Trip1514	1
24/08/2026 16:11:44	52.354320	4.810721	254	Sudden braking	2.50	2.50	15.0	13.8	1.00	1	3.7	1.000	604F0_Trip1514	1
24/08/2026 16:11:45	52.354309	4.810670	262	Sudden braking	3.20	3.20	14.2	10.6	1.00	1	4.2	1.000	604F0_Trip1514	1
24/08/2026 16:11:46	52.354299	4.810610	280	Sudden braking	2.90	2.90	13.2	7.7	1.00	1	1.5	1.000	604F0_Trip1514	1

timestamp	latitude	longitude	heading	event_type	avg_deceleration_kmh_s	peak_deceleration_kmh_s	surrounding_speed_kmh	speed_at_braking_segment_kmh	duration_flagged_interval_s	road_quality	gps_distance_m	time_interval_s	trip_id	segments_represented
24/08/2026 16:12:45	52.353643	4.807452	249	Sudden braking	2.00	2.00	19.9	18.9	1.00	2	4.5	1.000	604F0_Trip1514	1
24/08/2026 16:12:46	52.353629	4.807389	251	Sudden braking	2.10	2.10	19.3	16.8	1.00	2	3.4	1.000	604F0_Trip1514	1
30/08/2026 18:38:08	52.354358	4.802242	251	Sudden braking	2.10	2.10	17.0	17.1	1.00	2	4.0	1.000	604F0_Trip1522	1
30/08/2026 18:38:09	52.354347	4.802186	253	Sudden braking	2.10	2.10	15.7	15.0	1.00	2	3.3	1.000	604F0_Trip1522	1
30/08/2026 18:38:10	52.354339	4.802139	253	Sudden braking	2.00	2.00	14.6	13.0	1.00	2	3.0	1.000	604F0_Trip1522	1
03/09/2026 14:10:15	52.373754	4.915850	314	Sudden braking	2.20	2.20	13.5	12.0	1.00	2	2.4	1.000	604F0_Trip1529	1
09/09/2026 13:35:14	52.374643	4.921895	290	Sudden braking	2.00	2.00	9.2	6.8	1.00	2	1.7	1.000	604F0_Trip1552	1
09/09/2026 13:35:15	52.374655	4.921879	294	Sudden braking	2.00	2.00	8.5	4.8	1.00	2	1.2	1.000	604F0_Trip1552	1
09/09/2026 13:36:19	52.373548	4.922505	229	Sudden braking	2.10	2.10	18.7	20.9	1.00	2	4.6	1.000	604F0_Trip1552	1
09/09/2026 13:36:20	52.373519	4.922456	227	Sudden braking	2.80	2.80	18.4	18.1	1.00	2	3.2	1.000	604F0_Trip1552	1
09/09/2026 13:36:21	52.373499	4.922422	227	Sudden braking	2.60	2.60	18.0	15.5	1.00	2	3.3	1.000	604F0_Trip1552	1
09/09/2026 13:36:36	52.373035	4.921693	226	Sudden braking	2.00	2.00	15.3	14.1	1.00	2	3.0	1.000	604F0_Trip1552	1
09/09/2026 13:36:37	52.373018	4.921657	229	Sudden braking	2.30	2.30	14.7	11.8	1.00	2	2.6	1.000	604F0_Trip1552	1

The braking intensity values are the existing braking_intensity values from the GeoJSON. Surrounding speed is calculated from stored Speed values within ±5 seconds of the first flagged segment. 'Road quality' is the existing road_quality score, not a new classification.