Shop Name: Care Auto Repair
Tel: 0567411142
Email: info@careautorepair.ae
Address: UAE - DUBAI

Report ID: MAXIA20261024171523
Test Time: 2026-10-24 17:15:23
Technician: --

Benz Vehicle Diagnostic Report

Vehicle Information

--/Benz/GLE (292)/
VIN: WDCED6EB1JA114327

Odometer Reading: 111136km
License Plate: --

Customer Information

Name: --

Tel: --

Scan to download PDF

Device information

Scanner: MaxiSys MS909
Version: V6.42

Serial Number: VA9GR6C01696
Repair Order Number: VA9GR6C0169620261024171436840

System Scanned (54)

System	Status/DTC
ECM(Engine Control Unit)	0
TCM(Transmission Control Unit)	3
ESP(Electronically controlled vehicle stability braking system control unit)	1
SRS(Supplemental Restraint System Control Unit)	0
LIN:WSS-1(Weight Sensing Sensor Control Unit)	0
KI(Instrument Cluster)	0
EPB(Electric Parking Brake)	0
TPM(Tire Pressure Monitor Control Unit)	0
PTS(Parking System) ADAS	0
SAM(Signal Acquisition Control Unit)	3
LIN:AISP(Interior mirror)	0
LIN:BSN(Battery Sensor)	0
LIN:DBE-1(Sunroof Control Unit)	1
LIN:LCP(Off-Road Mode Body Lift Button)	0
LIN:OBF(Upper Control Panel)	0
LIN:SHM(Seat Heating)	0
LIN:UBF(Lower Control Panel)	0
LIN:VCS-1(Light Sensor)	0
SAMR(Rear SAM signal acquisition control unit)	0

EZS(Electronic Ignition Lock Control Unit)		0
ES(Electric Power Steering)		0
KLA(Air Conditioner Control Unit)		3
ADS(Suspension)		0
HU(Head Unit Control Unit)		0
KG(Keyless Go Control Unit)		0
SW-SW-R(Right Headlamp Control Unit)	ADAS	0
LIN:LAMSR(Right Front LED Lamp Unit Actuation Control Unit)		0
SW-SW-L(Left Headlamp Control Unit)	ADAS	0
LIN:LAMSL(Left Front LED Lamp Unit Actuation Control Unit)		0
SGR(Radar sensors control unit)	ADAS	0
DTR-1(Front Radar Sensor)	ADAS	0
DMFL(Left Front Door Control Unit)		1
LIN:DSM_MFL(Left Front Seat Adjustment Switch)		0
DMFR(Right Front Door Control Unit)		0
LIN:DSM_MFR(Right Front Seat Adjustment Switch)		0
DMRR(Right Rear Door Control Unit)		0
DMRL(Left Rear Door Control Unit)		0
ZBE(Head Unit Display)		1
TPAD(TPAD)		1
ZAN(Center Display Control Unit)		0
SVS(360° Surround view system)	ADAS	0
SG-MSND(Engine Sound Control Unit)		0
RBTMFR(Right Front Seat Belt Tensioner Control Unit)		0
RBTMFL(Left Front Seat Belt Tensioner Control Unit)		0
PSD(Sunroof Control Unit)		0
MRM(Steering Column Control Unit)		0

MFK(Multifunction Camera)	ADAS	0
HVACR(Rear Air Conditioner Control Panel)		0
HKS(Trunk Lid Control Unit)		0
FWGW(Chassis Bus Gateway Control Unit)		0
FSCU(Fuel Pump Control Unit)		0
ESEP(Passenger Side Electric Seat Adjustment Control Unit)		0
ESED(Driver Side Electric Seat Adjustment Control Unit)		0
DTA(Telematics Service Control Unit)		0

DTC (14)

TCM(Transmission Control Unit) (3 DTCs)

DTC	Description	Status
U140B00	An implausible left rear wheel speed signal received	Not defined(Event codes)
U140A00	An implausible right front wheel speed signal received	Not defined(Event codes)
U140900	An implausible left front wheel speed signal received	Not defined(Event codes)

ESP(Electronically controlled vehicle stability braking system control unit) (1 DTC)

DTC	Description	Status
C01FD00	This fault code can be ignored and erased.	Stored

SAM(Signal Acquisition Control Unit) (3 DTCs)

DTC	Description	Status
B1F4500	The starter battery has excessive resistance.	Active and stored
B181E64	The sensor for the engine hood has a malfunction. There is an implausible signal. If there is no specific customer complaint, ignore the fault.	Stored
B21059A	The capacity of the starter battery is too low. The operating conditions for the component or the system are not satisfied.	Active and stored

LIN:DBE-1(Sunroof Control Unit) (1 DTC)

DTC	Description	Status
B174901	The rear interior illumination has a malfunction. There is a general electrical fault.	Stored

KLA(Air Conditioner Control Unit) (3 DTCs)

DTC	Description	Status

912749	The air quality sensor has a malfunction. There is an internal electrical fault.	Active and stored
907D11	The additional coolant pump has a malfunction. There is a short circuit to ground.	Stored
905207	The actuator motor for the rear blend air flap has a malfunction. There is a mechanical fault.	Active and stored

DMFL(Left Front Door Control Unit) (1 DTC)

DTC	Description	Status
B18B113	The output for the central locking motor has a malfunction. There is an open circuit.	Stored

ZBE(Head Unit Display) (1 DTC)

DTC	Description	Status
B15062A	The Audio/COMAND controller has a malfunction. There is no signal change.	Stored

TPAD(TPAD) (1 DTC)

DTC	Description	Status
B1F6647	'Touchpad' has a malfunction. There is a runtime error.	Stored

Technician Notes

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.