# SPECIFICALIZATION OF THE PROPERTY OF THE PROPE

REGISTERED BY AUSTRALIA POST PUBLICATION NO. TBH 0917 CATEGORY "B"

ISSUE No.

2 - 4

DATE

JAN - 1985

INTRODU	G710	W	,					9			*	×		S		×	,			7			2
TERROR		+ =		*		+	*	,	,	,								,				ie.	3
MENU PR	OGRA	M	(Z	E	0	8	4	2							,								4
CAR RAC	ING						,																6
NO COLO	URTT					+														9			8
AUTO LZ	NE N	WM.	BE	R	5	F	0	R	9	N	I	N	P	U	7	#							9
CONVERT.	ING	161	*	RI	9/	1	7	0		6	4	K		R	A	M							10
DOUBLE :	SIDE	DI	22	S	F	D	R	Ï	V	E	S			×									11
LIBRARY	NOT	ES																	-	_			12
BIRD .								4.	+				×		,					ı			13
LIERARY	LIS	7																			_		10
BUY, SEL	110	R 7	P	AL	Œ					*			*		40			4					16

ALL CORRESPONDENCE TO:

S.A.U.G., P.O. BOX 191, SOUTH LAUNCESTON, TASMANIA, 7249.

(003) 312648

ANNUAL SUBSCRIPTION

OVERSEAS AIRMAIL . \$25.50



### INTRODUCTION By the Ed.

First let me welcome you all to the New Year, I hope 1985 will be a good year for you all.

As Christmas and New Year fade away again for another year it's time to get back to some serious computing.

To start off on a dim note: THE STOCK OF NEWSLETER ARTICLES IS AT AN ALL TIME LOW. Next months newsletter should dry it up completely. We are a large Users Group with around 350 members and we are growing quickly. So were have all the articles gone? We need your support.

This months Newsletter is a good example of the type of articles we are looking for.

### TERROR

is a bit of fun and is an idea generating article that the user can build on.

### CAR RACING

This is a program in which you drive a "CAR" through a snaking course as the scren scrolls past you. Again this is a building block for you to build from and learn.

### NO COLOUR

Here is an article by a user which shows a Mardware problem and it's cure.

### AUTO LINE NUMBER FOR "INPUT"

This article springs from a previous article.

### CONVERTING 16K TO 64K RAM.

A good article for you 318 owners.

### DOUBLE SIDED DISK DRIVES

Once in a while some one comes up with a real winner. Well here is one. I have been using these drives now for some months and I find them the best. They are very reliable and the BIOS is a joy to use.

### LIBRARY NOTES

They explain themselves.

### BIRD

I liked the display so I included this short program.

Thats all from me folks, but please remember. WE WANT ARTICLES. Just one article from each member would fill the Newsletter for the next 3 years.

### ZERROR

by B. Windsor

This little routine is idea! for discouraging your kids from pressing CONTROL-STOP so that they can modify your precious programs. Try it, placing your program where line 30 is in the listing. Alter the numbers of lines 100 to 140 as necessary and, of course, the GOSUB number in line 10.

If CONTROL-STOP is pressed while the program is running, the screen shows on "Ok" message which looks like the Basic Ok prompt. After a short pause, there is a message "Erasing the following files", followed by a list of all the files on the disk in use. The disk drive then operates, and the system re-boots.

The effect on li-year-old boys has to be seen to be believed ...

Unfortunately, it cannot prevent people from LOADing the program and then altering it. The only answer to that problem is to keep a back-up copy in a safe place. Where the kids can't find it.

### TERROR by : 8. Windsor

1Ø 'TERROR BM 20 'by Brian Windsor for Spectravideo SV-328 ED 30 . CK DE 4Ø CN STOP GOSUB 7Ø AE 5Ø STOP ON 60 GOTO 60: REM your program goes here TA DI 7Ø PRINT "CK" BO 8Ø FOR L=1 TO 5ØØ:NEXT CI 9Ø PRINT"Erasing the tollowing files:" CG 100 FILES AK 11@ DEF USR@=@: X=USR@(@) END



### MENU PROGRAM SDEC 842 additions by the ED.

In the we goofed it department last month, we goofed it. Well I can't help it I'm only human. Although I do own a computer, I do on the rare occasions make a mistake. And I do not appreciate members being rude about it.

For all you members who don't know what I'm talking about I'll explain. In last months newsletter we had an article which gave a program that produced a MENU of a BASIC disk.

Well somewhere along the line I succeeded in losing the last 22 lines of the program.

Following you will find the missing lines. I'm very sorry about the slight inconvenience but such things do happen.

Also I'm told that this program will not load and run binary files. Thank you very much to Steve McNamee who kindly sent me a modified version so below also you will find a patch which checks for binary files and loads them correctly.

### MODIFY EXISTING SECTION AS SHOWN

- 10 471Ø PRINT\*Make selection by pressing key or\*:PRINT\*Press (ESC) to retur
   n to menu.\*;
- EE 4720 AS=INKEYS:IFAS=""THEN4720
- AK 4725 IFAS=CHR\$(27)THEN100
- CP 473Ø DC=ASC(A\$):IFDC>57THEND1=DC-55ELSED1=DC-48
- FI 474Ø IFD1=>DTHEN472Ø
- AE 475Ø IFDV=1THEND1\$="1:"+D\$(D1)ELSED1\$="2:"+D\$(D1)
- AM 477Ø IFDA(D1)=192THENPOKE-456, Ø: SCREEN, 1: RUND1\$
- CD 478Ø IFDA(D1)=1THENPOKE-456, Ø:SCREEN, 1:BLOADD1\$, R
- DG 479Ø BEEP: GDT0472Ø
- CG 5000 GOTOLOU: INPUTAS
- EH 5010 GOTO100: As="10"+A\$



### MISSING SECTION FOLLOWS

8719 DATA 67,83,65,86,69,34,0,0,0,0,0,0,0,0,0,0:'KEY19 FL 9000 CLS: N=1 9005 CLS:PRINTTAB(10)CHR#(27)+"p"+" KEY MENU No.";N;" "+CHR#(27)+"q" II 9010 PRINT:PRINT 9020 PRINTTAB(5) 'KEY No. "TAB(20) "DEFENITION": PRINT AL 9100 FORL=1T010:PRINTTAB(8)LTAB(18)K#(N-1,L):NEXTL GC NB 9150 LOCATEO,18:PRINT"Press space bar to see next key menu, ":PRINT"press (Enter) to select menu displayed": PRINT and press (Esc) to return to main menu." EE 9200 As=INKEYs:IFAs=""THEN9200 921Ø IFA\$=CHR\$(27)THEN1ØØ DF 922Ø IFA\$=CHR\$(13)THEN95ØØ AK 923Ø IFA#=" "THENN=N+1ELSEGOTO92ØØ 924Ø IFN>3THENN=1:GOTO9ØØ5ELSEGOTO9ØØ5 FC 9500 ONNGOTD9510,9600,9700 CO 951Ø RESTORE851Ø:FORM=ØT09:FORL=ØT014 DH 952@ READCH: POKE64@3@!+M#16+L, CH: NEXTL, M: BEEP: GOTO1@@ CN 9600 RESTORES610:FORM=0T09:FORL=0T014 DF 961Ø READCH: POKE64Ø3Ø!+N\*16+L, CH: NEXTL, M: BEEP: GOTO1ØØ CN 9700 RESTORE8710:FORM=0T09:FORL=0T014 971Ø READCH: POKE64Ø3Ø!+M\*16+L, CH: NEXTL, M: BEEF: GOTO1ØØ

BM 10000 DATA RUN (ENTER>, LIST, LOCATE, PRINT", PRINT, LOAD"1, SAVE"1, "COLOR12, 1

AL 10020 DATA LOAD"1, LIST, FILES (ENTER), PRINT, RUN (ENTER), SAVE"1, "COLOR12, 1 (ENTER)", SCREEN, GOTO, CSAVE"

END

0.00





### CAR RACING

4,32m144,16"


```
by : J. May.
```

```
1Ø CLS: COLOR15, 1, 1: SCREENI, 1: GOSUB45Ø
EB
      20 LOCATE, 0: CLICKOFF
EN
      3Ø KEY1, "LOCATE,,1"+CHR$(13)
FJ
      4Ø DATA"■
BK
      5Ø DATA"
IM
      60 DATA BOSCOCCOC
TL
      7Ø DATA"
DP
IJ
      SØ DATA"
II
      9Ø DATA"
     100 DATA"
MC
    11Ø DX=Ø: DATA"■
HC
   12Ø PRINTCHR$(27) + "P"
EG
                           ■";T=(9)="
FL
     13Ø T$(8)=*#
                     .
     140 CLS:SCREENØ, Ø
CL
     15Ø RESTORE:FORT=1T07:READT#(T):NEXTT
     150 COLOR1, 15
RH
     170 LOCATE,,Ø
BE
     180 LOCATE15,24:PRINT" START SE":FORT=1T025:PRINTTAB(15); "SE
AH
          ": VPOKE1ØØ, 225: NEXTT
     190 'PRINTCHR$ (27) +"p"
DG
BK
     200 X=100
BP
     210 5=15
     22Ø W=1
BL
     23Ø FORT=1T06
AN
     24Ø 5=5+D
FE
GE
     25Ø IFS(10RS)25THEND=-D:S=S+D
     26€ PRINTSTRINGS(S," ...
GC
     27Ø IFW(>6THENGQ=WELSEIFINT(RND(-TIME) #5) =1THENGQ=SELSEIFINT(RND(-TIME)
AP
          #51 = 1 THENQQ=9ELSEQQ=6
AF.
     28g PRINTTAB(S); T$(QQ);
     29Ø PRINTSTRING#(39-(5+11), " ");
GI
     300 IFW=ZANDSC=JANDJ=0THENLOCATE5, 21: PRINTCHR# (27) + "p"; : PRINT" by Jonath
JB
          an May";:PRINTCHR$(27)+"q":J=190
AF
     31Ø IFSTICK(Ø)=3THENDX=1
DH
     32Ø IFSTICK(Ø)=7THENDX=-1
AG
     33Ø IFSTICK(Ø)=5THENDX=Ø
     34Ø X=X+DX
AF
     35Ø IFVPEEK(X)=233THENGOT042Ø
GK
     36Ø VPOKEX, 225
DP
DF
     37Ø NEXTT
     38@ D=INT(RND(-TIME) #3)-1
DI
     39Ø SC=SC+1:IFSC=1ØTHENSC=Ø:D=Ø:W=W+1
ΕI
BC
     4ØØ IFW=BTHENGOTO52Ø
AH
     41@ GOTO23@
     420 SOUND6, 155: SOUND7, 7: SOUND8, 16: SOUND9, 18: SOUND10, 16: SOUND12, 36: SOUND
ED
          13.0
     43Ø FORT=1T03Ø:FORTT=1T014:COLOR,TT:NEXTTT,T
FL.
BM
      44Ø CLEAR: GOTD4Ø
BK
     45Ø FORX=2T015:LOCATE13Ø,184:COLORX
      469 DRAW*c=x;bm96,32m96,16m104,16m104,32bm104,24m96,24bm112,16m112,32m1
AP
          20,32m120,16bm128,16m136,16bm132,32m132,16bm144,16m152,16m152,32m14
```



- NH 47Ø DRAW"bm60,48m60,72m68,72m68,64m72,72m80,72m74,60m80,60m80,48m60,48b m68.52m73.52m73.56m68,56m68,56m68,52"
- FD 48Ø DRAW bm132,48m132,56m12Ø,56m12Ø,64m132,64m132,72m112,72m112,48m132, 48bm1Ø4,48m1Ø4,72m98,72m98,64m94,64m94,72m88,72m88,48m1Ø4,48"
- MK 49Ø DRAW\*bm94,54m98,54m98,6@m94,6@m94,54bm17Ø,54m174,54m174,6@m17Ø,6@m17Ø,54\*
- GJ 500 DRAW bm140,48m140,72m156,72m156,66m146,66m146,64m152,64m152,58m146, 58m146,56m154,56m154,48m140,48bm164,48m178,48m178,64m184,72m176,72m 170,64m170,72m164,72m164,48m178,48
- CP 510 IFINKEY == "THENRETURNELSENEXTX: GOTO450
- GF 53Ø FORG=1T05:SOUND9,10:SOUND8,10:FORT=5T0200STEP3:SOUND2,T:SOUND1,T-2: SOUND0,T+2:NEXTT
- GN 54Ø FORT=2ØØT05STEP-3:SOUNDØ,T:SOUND1,T-2:SOUND2,T+2:NEXTT:SOUND8,Ø:SOU ND9,Ø:NEXTG
- CI 550 IFSTRIG(0) =- 1THENRUNELSEGOT0550
- AD 360 GOTO560

END





NO COLOURTEZ By M.J. Tyeson.

Here's a good one for you all, after using my Computer for a few minutes I noticed that all the colour began to drain from the monitor. I then began to wonder what was going on, was it the monitor or was it the computer. I began to investigate as all good Technicians do.

The first thing I did was to switch the monitor back to a normal Television Sct tuned to a normal station and you guessed it, the pictures were in colour. Sc the next thing to do was to check out the Modulator in the computer. I did and the picture was in living Black and White. This didn't do me any good so I thought that the next thing to do was to get into the computer and see what the stupid thing was doing to me.

I successfully took the lid off and had an initial look around to see if there was anything closely resembling the original Blue Smoke and Mushroom Cloud. Nothing. Well I then began to check the Circuit Diagrams and Service Manual as to what voltages feed the Modulator. That was easy, there was only one, +5V, which also feeds the Video Processing Circuitry and the PAL Encoder and the VRAM. Well I thought if the Video Processing Circuitry was playing up it may produce monochrome pictures or if the Pal Encoder was playing up it would certainly give monochrome pictures or if the Modulator was faulty then the same would happen. The thing that turned me away from the Modulator was the fact that there was no colour coming out of the Modulator or out of the Video Output.

I then put tongue in cheek and started to poke around the board with a CRO. All the video waveforms had low amplitude subcarrier superimposed on the luminance but when I turned the computer off for a period of time and turned it back on there was sufficient level to be decoded as colour.

Anyway to cut a long story shortish the problem turned out to be a 'tired' +5V regulator. Over the period of time that I've had the computer and the number of times I've used it the regulator has heated up and the output had dropped down to +4.86V. The replacement cost me about \$4.00 plus an extra \$2.00 for extra Heatsinking to dissipate the heat generated by it. A better fix is to relocate the power supply outside the computer and make it a Switched Mode Supply but that would cost about \$50.00 but it can supply in excess of about 15A.

Oh by the way the regulator in question is a National 7805K Steel. You have to specify the K Steel as that is the package type.

The time taken to extract the old regulator, replace it with the new one and fit all the new Heatsinking takes about I Hour and as I said would only cost about \$6.00 to \$8.00 depending on where you get the parts from.



## BY R. Duffy,

Congratulations on your program 'INPUT'. It really works well and should be a boon to people like myself who use the "Biblical" method of typing (Seek and ye shall find!). I haven't been able to fault it yet, but then I havent really tried!

There is, however, one facility I miss with the program and that is the AUTO Line Numbering Function. To rectify that situation, I have written the following additional lines which provide a "semi" auto line numbering system. Key in the lines and then re-number as you please.

NOTE - Line Nos. 80 and 320 of the original program are modified.

8Ø SCREEN, 1

122 INPUT "Starting Line No"; LN

124 INPUT "Line Increment"; J

126 GOSUB 500

195 LN=LN+J: GOSUB 500

320 BEEP: LN=LN-J: GOSUB500


500 KEY 2, " "+STR\$(LN)+" "

51Ø RETURN

To use the program, after entering the starting line No. and the increment, first type the checksum characters the press Soft-Key No. 2. The first Line No. will be printed. then type in the rest of the line and press ENTER. If the line is accepted by the program then KEY 2 will be incremented to the next line No. ELSE it will remain the same No. until the line is accepted.

Pressing ENTER without typing a line of code will increment KEY 2.

The next line No. to be printed will always be visable on the KEY 2 enunciator (in place of "auto").





### CONVERTING 16K RAM TO 64K RAM By T. Colverd.

Here are details of the 64K conversion to the SV 318. It sounds complicated when written down but is quite simple really. The cost of parts is approx \$70-\$75 and takes about 1 hour to complete.

I haven't included details of Dis-assembling the computer but assume familiarity.

If you have any queries I'll be happy to help or if you don't want to attempt it I'll do it for \$95.

Contact : Tim Colverd,

27 Jennings Road,

Bayswater,

VIC. 3153. Phone: H Ø3-729-7383

W Ø3-862-2888

- Desolder IC1 to IC8 Part No: 4116
   IC9 to IC16 is Video RAM. (Dont Touch)
- 2) Replace with Type 4164(TMM not TMS) or 6555
  - a Pin 8 on 4116 was the 12v supply, but on the 4164 it needs to be 5 volt, so at a convenient spot cut the 12v supply rail to the Pin 8's and reconnect Pin 8 to a 5 volt rail.
  - b Pin 9 on 4116 was 5 volts but on 4164 needs to go to IC17 Pin 12, so cut track from 5 volt suppy and put in a link to IC17 Fin 12.
- 3) Link Pin's 4 to 5 on IC27.
- 4) Cut track from Pin 5 of IC27 (which used to go to IC47 Pin 8).
- 5) Finally link IC27 Pin 9 to IC24 Pin 9.

# poubleided Dish Drives

Double sided 40 track disk drives are now available for use with super expander SV 601 and disk controller SV 801.

The drives come complete with modified CP/M BIOS to allow reading and writing of 3 different formats

- 1. Custom double sided format
- 2. Spectravideo single sided format
- 3. New Spectravideo double sided format

BASIC disks can still be used but only as normal single sided disks.

Under the CP/M operating system each drive has a massive formatted capacity of 324k .

The drives need a small modification to the disk controller card and instructions for doing this are included. Alternatively the card may be sent with your order and the modification will be done free of charge.

Standard Spectravideo disk drives will still work with the modified controller card.

The disk drives come with the manufacturers guarantee and all other work is guaranteed for three (3) months from date of dispatch.

Prices: 1 Drive - \$450.00

2 Drives - \$850.00 Including Post and Pack.

To order send cheque or money order with your CP/M master disk (to avoid infringing copyright) and disk controller card (if you want the modification done) to:

Further Details Phone

S.W. McNames 5/15 Stuckey Rd., Clayfield 4011.

Ø7-26Ø996Ø

During Working Hours.

Members who own the new SPECTRAVIDEO Expander and Double Sided Disk Drives are also invited to enquire about a modified CP/M BIOS for them. Cost is \$25.



# LIBRARY NOTES by Jim Collins.

Because of the high number of orders received for software which have not included payment for cassette or disk the Editor and myself have decided to republish these notes rather than the intended library article. An updated software price list is also included with this newsletter. Please read carefully and save yourself inconvenience. A point worth mentioning is the program Mysterious Manor. Despite having warned several times in past issues that this program could not be supplied on disk I have had five orders in the past two weeks all requesting M/Manor on DISK.

IMPORTANT NOTE ---- WE DO NOT PAY THE COST OF CASSETTE OR DISK ON ANY PROGRAM SUPPLIED THROUGH THE LIBRARY EXCEPT FOR THE OFFER DN PREVIOUS NEWSLETTER PROGRAMS. ALL OTHER MEDIA COSTS MUST BE MET BY MEMBERS.

First service we offer is the cassette or disk with all those programs which appeared in newsletters from No 1 through to No 12. There are some fourteen programs on offer here and although we used to charge only for the cassette and supply the programs free we now find that increasing costs force us to charge \$10.00 for this service. At that it is still very good value as I'm sure you will agree. We will of course still supply any single program which has appeared in any newsletter if you are having difficulty entering it from the newsletter itself. Only charge made here will be for the media....cassette \$4.00 or disk \$6.00...we will pay postage one way on this service but of course will not object if you want to pay this yourself.

Second service is the answering of any technical queries wherever this is possible and here we definitely would appreciate a reply paid envelope as this can become quite a drain on the slender resources of the group finances.

Third service is the Group Author Software List wherein we will advertise for sale any suitable program submitted by any financial group member at the price asked for by that member plus nominal amount to cover cost of copying, care-packing, and postage to I would point out here that in order to keep the costs of administrating this service to the lowest possible, royalties due to successful authors will be remitted whenever sales amount to more than \$50.00 for any particular program. To do this any other way would involve your editor and myself in a much greater work load but more importantly would be a huge financial drain we just can not In this issue you will find an updated list of all those programs currently accepted for publication. Please note that only the programs on this list are now available and all previous lists are No correspondence will be entered into on the matter of programs previously listed which now do not appear.



hardware/software any member may have which he/she no longer wants. We will print details of the item in the newsletter in order that all members may see and make an offer etc. Same applies if you want something in particular. We will run your want ad in the newsletter. No charge is made for this service.

REMEMBER TO INCLUDE COST OF CASSETTE \$4.00 OR COST OF DISK \$6.00 WITH ANY ORDER FOR LIBRARY PROGRAMS....OR SEND YOUR OWN CASSETTE OR DISK WHEN YOU PLACE YOUR ORDER.

IF YOU WANT PROGRAMS OR OTHER LIBRARY SERVICES YOU WILL GET A SPEEDIER REPLY IF LETTERS ARE ADDRESSED DIRECT TO THE LIBRARY AT THE PUBLISHED ADDRESS. CHEQUES OR MONEY ORDERS MUST BE MADE FAYABLE TO THE S.A.U.G. AND NOT TO ANY INDIVIDUAL.

### BIRD

by : ??? (CIO Wellington Users Group)

GD 1Ø COLOR15,4,4:SCREEN1

IK 2Ø DRAW\*c15bm1@5,39m119,5@m12@,59m122,76m118,93m11@,1@8m1@7,122m11@,12 1m113,123m114,124m124,131m114,131m1@4,136m96,139m8@,139m8@,139m72,1 37m67,136m62,137m56,142m48,139m4@,137m32,136m28,136m83,125m95,93\*

DA 3Ø DRAW\*c15bm95,93m99,92m1ØØ,91m1Ø1,9@m1ØØ,89m99,88m97,87m1Ø2,8@m1Ø6,7 2m11Ø,62m111,57m11Ø,53m111,52m11Ø,51m1Ø8,45m1Ø5,39\*

J6 4Ø DRAW"c15bm25,81m25,83m28,96m3Ø,1Ø4m33,112m36,12Øm38,122m45,12Øm51,1 23m6@,127m81,124m82,121m58,1Ø5m52,1Ø7m35,95m25,81"

DI 50 PAINT (48, 112), 15: PAINT (56, 141), 15

AH 6Ø CIRCLE(145,86),86,15

7Ø CIRCLE(145,86),82,15

HM 80 PAINT(145,1),15

AP 90 G0T090

END

AE





### GROUP AUTHOR SOFTWARE - LIBRARY PROGRAM LIST

ASKING PRICE	MEDIA SUPPLIED	BY LIBRARY	MEDIA SUPP	LIED BY YOU
(Including Pack and Postage)	CASSETTE	DISK	CASSETT	E DISK
	(Maze Skill)			
500	900	1100	500	500
ADHEX.COM	(CP/M Search and i	ind Utility)		
1000		1600		1900
ADVENT. COM	(CP/M The Original	l Adventure) fu	ll disk	
200	NO	800	NO	200
ALGOLM.COM	(CP/M Language) fo	ull disk		
200	NO	800	NO	200
BURGER	(Arcade Skill)			
500	900	1100	500	500
CALEND. ARS	(Calendar Generato	or)		
300	700	900	300	300
COUNT DRACULAR	(Text Adventure)			
1000	1400	NO	1000	NO
CRUNCH	(Program Squeezer	ř.	(4)	
1000	1400	1600	1660	1000
DISASSEMBLER	(Utility)			
200	600	800	200	200
DISK.COM	(CP/M Directory Ma	anager)		
1000	NO	1600	NO	1000
FILES	(File Manager)			
500	900	1100	500	500
ELIZA	(Medical Madness 1	?)		
700	1100	1300	788	700
HOUSE/FRANKENST	EIN (Text Adventus	·p)		
500	900	1100	500	500
JUMBLE	(Spelling Skill)			
599	900	1100	500	500



MARVYN	(Intelligent 'el	iza*)		
700	NO	1300	NO	799
1970 MARCON IS			- 5:-1: 0	
MFT.COM		Transfer for Singl	NO NO	209
Z90	NO	899	NO	2
MIGHTY MORMAR	(Text Adventure)			
500	900	1100	500	500
MURDER AT THE	MANOR (Graphic an	d Text Board Type	Game)	
1000	1400	1600	1999	1000
MYSTERIOUS MAN	OR (Text Adventur	e)		
500	900	NO	590	NO
PACMAN	(Champ Champ!)			
1000	1400	1699	1050	1000
DUDING CURE	(Calue the Cubel			
RUBIKS CUBE 500	(Solve the Cube)	1100	500	500
500	7	111.00	3	31.20
SPIDER ISLAND	(Arcade Skill)			
5##	900	1100	500	500
TRON RIDER	(Arcade Skill)			
598	900	1100	500	500
UNERA. COM	(CP/M Restore Er	ased Files)		
1659	NO	1600	NO	1000
WP / 318	(Simple Wordproc	essor)		
300	700	900	300	300
WP /328	(Simple Wordproc		528 528	120 120
300	700	900	300	300
X-BERT	(Arcade Skill)			
1000	1400	1600	1000	1000
XDIR.COM	(CP/M Sorted Dir	ectory)		
200	NO	800	NO	200
ZCPR.COM	(CP/M Replacemen	it for CCP) full di	sk	
200	NO	899	NO	200
MODEM7.COM	ICP/M Modem Soft		NO.	2 44
200	NO	800	NO	200

IMPORTANT NOTICE ......

MYSTERIOUS MANOR and COUNT DRACULAR ARE BOTH TOO LONG TO FIT INTO DISK BASIC.....THEY WILL NOT LOAD INTO UNEXPANDED 318 s...THEY WILL ONLY BE SUPPLIED ON CASSETTE. IT IS NOT PHYSICALLY POSSIBLE TO PUT THEM ON DISK.

bull

sell

d

riode

### WANTED

An SV8Ø4 (BØ Column Card)

The card must be in working order.

Please contact:

Mr. C. Ryan, 70 Railway Road, Carnegie, Victoria. 3163

or phone (Ø3) 211-2575

### FOR SALE

only JP-80 Dot Matrix Printer. Print Quality is the same as that used in this Newsletter.

Unit cost \$499.00 will sell for \$320.00 with printer cable or \$520.00 with printer cable and Centronics Interface.

Contact the Editor by writting too SAUG P.O. Box or phoning the SAUG number.