

ROOF CONSTRUCTION 1:100.

THE GREENHILLS FOUNDATION LIMITED.

DINING ROOM/HALL: STRUCTURE.

CORDON DOERING BCF., MIEAUST CONSULTING ENGINEER OLINDA, VICTORIA. TEL. (03) 7511068.

OCTOBER 1981.