SCARA ARM Type A : Part List

	PART NAME	PART NUMBER	QTY	STATUS	IMAGE
1	Bearing	6800ZZ ID x OD x D 10 x 19 x 5	3	ORDER	
2	Bearing Oval	LMH12UU	3	ORDER	Resize Image to see dimension
3	Coupling	Coupling 6 to 10 mm	1	ORDER	
4	Coupling	Flange Coupling Bore 5 mm	1	ORDER	Resize Image to see dimension
5	Bracket Horz	SHF12	9	ORDER	SHF12 SH
6	Pulley Belt	Pitch 2 mm Width 10 mm Length 240 mm	1	ORDER	
7	Pulley Dummy or use Bearing	Width 10 mm	2-Jan	ORDER	
8	Pulley	GT2 20T Bore 5 / 6.35 mm Width 10 mm (ref to NEMA 17 Shaft)	1	ORDER	
9	Stepper	Nema 17 Shaft 5 / 6.35 mm (use pulley)	1	ORDER	
10	Stepper	NEMA 17 Shaft 5 mm	1	ORDER	
11	Stepper	NEMA 23 shaft 6.35 mm	1	ORDER	
12	Nut T10	T10 Lead Screw	1	ORDER	Resize Image to see dimension

13	Pillow	KFL10	2	ORDER	Resize Image to see dimension
14	Shaft	Stainless Shaft 12 x 350 mm	3	ORDER	Stainless Steel 304 Shaft
15	Lead Screw	T10 x 300 Lead Screw Pitch 2mm	1	ORDER	T10 Pitch 2 mm
16	Motor Servo	Servo SG90	1	ORDER	
17	Spicer	Hex Spicer M3 x 6 mm	10	ORDER	Resize Image to see dimension
18	Spicer	Hex Spicer M3 x 10 mm	10	ORDER	Jan Jan
19	Baut JP	M3 x 6	~~	ORDER	
20	Baut JP	M3 x 10	~~	ORDER	
21	Baut JP	M4 x 20	10	ORDER	
22	Baut Flat Head	M4 x 20	16	ORDER	F. Salahan
23	Baut Flat Head	M4 x 30 mm	10	ORDER	
24	Baut Hex	M10 x 45 mm	1	ORDER	C Salaman
25	Mur	M3	~~	ORDER	
26	Mur	M4	~~	ORDER	
27	Mur	M10	2	ORDER	