BETHELMIND DIGITAL SOLUTIONS

CAC CERTIFIED ENTERPRISE • RC 7034297 • NIGERIAN TRADE & CUSTOMS DESK

OFFICIAL TOKUNBO INSPECTION PASSPORT

REP-JHLRD1851WC804433-2026-NCS

VERIFIED VEHICLE IDENTIFICATION NUMBER

JHLRD1851WC804433

1998 HONDA CR-V LX (5-Door Compact SUV / MPV)

Sayama Assembly, Saitama Prefecture, Japan

SCORE: 30 / 100 • LOW STRUCTURAL RISK

1. STATUTORY NIGERIA CUSTOMS SERVICE (NCS) 2026 PORT VALUATION

EST. PORT CLEARANCE DUTY

₦1,800,000 NGN

20% Duty + 15% NAC Levy + 7.5% VAT + Port Dwell

FAIR LAGOS MARKET PRICE

₦7,500,000 NGN

Dealer Spread: ₦7,125,000 – ₦8,625,000 NGN

"TRAP PRICE" WARNING FLOOR

Below ₦5,250,000 NGN (Extreme Salvage / Flood Trap)

Severe Saltwater Immersion / Total Loss Alert

2. TECHNICAL & ASSEMBLY SPECIFICATIONS

SPECIFICATION	DECODED VALUE	SPECIFICATION	DECODED VALUE
Engine & Displacement	2.0L (1,972cc) DOHC 16-Valve B20B 4-Cylinder	**Power Output**	126 HP @ 5,400 RPM / 133 lb-ft @ 4,300 RPM
Drivetrain / Transmission	Front-Wheel Drive (FWD) • 4-Speed Hydraulic Automatic with Grade Logic	**Chassis Origin / WMI**	JHL (Honda Motor Co., Ltd. Japan) (Sayama, Japan)
Body Style & Class	LX (5-Door Compact SUV / MPV)	**NHTSA Active Recalls**	0 OPEN RECALLS DETECTED
Estimated Lifetime Usage	~350,000 Miles (Operational Age-Curve)	**Fuel & Induction System**	Unleaded Gasoline (Direct Fuel Injection)

3. NORTH AMERICAN SALVAGE & HURRICANE FLOOD CORRIDOR PROVENANCE

COPART / IAAI TOTAL LOSS AUCTION REGISTER

CLEAN AUCTION TITLE RECORD

No recorded uncorrected structural rollover or insurance write-off detected.

FLORIDA & TEXAS FLOOD CORRIDOR AUDIT

ZERO HURRICANE WATER IMMERSION

Vehicle provenance originated outside FEMA saltwater disaster flood zones.

4. NIGERIAN ROADSIDE MECHANIC PHYSICAL INSPECTION PROTOCOL

COMPONENT UNDER AUDIT	THREAT LEVEL	INSPECTION DIRECTIVE & NIGERIAN FRAUD PREVENTION ACTION
Catalytic Converter ("Indomie")	THEFT RISK	**Inspect exhaust manifold immediately.** Lagos port dockers and car lot attendants frequently slice open exhaust canisters to extract the precious platinum honeycomb scrap.
Hydraulic Transmission Clutch	MAJOR REPAIR	**Perform cold engagement test.** Shift from Neutral to Drive and Reverse. Any lag over 2.0 seconds or violent mechanical jerk signals internal forward clutch wear.
Floorpan & ECU Silt Check	FLOOD TRAP	**Unfasten driver-side lower kick panel.** Inspect the ECU harness connector and seat base mounting bolts for orange rust and dried muddy silt deposits.
Cluster Bulb Warning Fraud	TAMPER FRAUD	**Turn key to Position II (Ignition ON).** Check Engine Light (CEL) and SRS Airbag bulbs MUST illuminate and shut off upon crank. If absent, bulbs were removed to mask faults.
Front Lower Ball Joints	SAFETY RISK	**Pry lower control arm ball joints.** First-generation CR-Vs suffer known lower ball-joint pop-out on rugged Nigerian terrain. Check dust boots for tears or play.

OFFICIAL SECURITY VALIDATION & STAMP

Issued by Bethelmind Automotive Advisory & Customs Clearance Desk

BETHELMIND DIGITAL SOLUTIONS
Chief Automotive Technical Analyst
Hotline: 0802 279 1227 • Moniepoint Settlement 6805375225

Certified Date: 25 October 2026 • Reference: REP-JHLRD1851WC804433-2026-NCS • RC 7034297

This certificate is an official pre-purchase advisory valuation document issued by Bethelmind Digital Solutions (RC 7034297).
Verify certificate authenticity and run free live VIN audits at **https://www.bethelmindanalytics.com/vin**