

RFI-052 -- STRUCTURAL: BEAM POCKET CLEARANCE AT GRID C-4

Synthetic public fixture · not a real project document

Question: The steel beam pocket detailed at Grid C-4 conflicts with an electrical conduit run shown on the coordination drawings. Please confirm whether the beam pocket depth can be reduced.

Response: The structural engineer confirmed the beam pocket depth may be reduced by 25mm without affecting the bearing capacity. The electrical subcontractor should re-route the conduit run through the adjusted pocket at the next site visit.