WIRING DIAGRAMS

Fig. 13: Instrument Clstr, Courtesy Lts, A/T Ind Sw (Grid 48-51)

1992 Lexus LS 400

For Kuper

Copyright © 1998 Mitchell Repair Information Company, LLC Tuesday, July 29, 2008 06:21PM

