WIRING DIAGRAMS

Fig. 3: TCCS ECU, Airflow Mtr, Throttle Pos Sensors (Grid 8-11)

1992 Lexus LS 400

For Kuper

Copyright © 1998 Mitchell Repair Information Company, LLC Tuesday, July 29, 2008 06:15PM

