WIRING DIAGRAMS

Fig. 9: Air Suspension ECU, Susp Ctrl Actuators, (Grid 32-35)

1992 Lexus LS 400

For Kuper

Copyright © 1998 Mitchell Repair Information Company, LLC Tuesday, July 29, 2008 06:19PM

