WIRING DIAGRAMS

Fig. 11: Airbag Sensors, Seat Belt Relay, ABS ECU (Grid 40-43)

1992 Lexus LS 400

For Kuper

Copyright © 1998 Mitchell Repair Information Company, LLC Tuesday, July 29, 2008 06:21PM

