Keep the wires as short as possible
with the minimum loop area

D — A

C   B

+   -   +   -

12V   12V

Negative supply voltage   Positive supply voltage