Crash Summary

Unannotated Image

Annotated Image

Incident Information

Incident Detected	True
Status	active
Types	collision
Confidence	1.0
Why	Two passenger vehicles (a dark grey minivan/station wagon and a silver sedan) have collided. They are stopped in a collision configuration, and smoke is visible from the front of the silver sedan.
Actual Accident Verified By Gemini	True
Accident Verification Status	confirmed_by_both
Accident Verification Note	Both the unannotated image and video clip confirm a true accident. Image note: The image clearly shows two vehicles in a collision position with visible front-end damage to both, including a buckled hood on the silver car. There is also smoke or steam emanating from the front of the silver vehicle, providing strong evidence of a recent accident. Video note: The video clearly shows a black minivan colliding with a silver sedan. Upon impact, the silver sedan's hood crumples, and smoke is visible, indicating a clear accident with damage.

Verification Details

Image Verification	True
Image Verification Note	The image clearly shows two vehicles in a collision position with visible front-end damage to both, including a buckled hood on the silver car. There is also smoke or steam emanating from the front of the silver vehicle, providing strong evidence of a recent accident.
Video Verification	True
Video Verification Note	The video clearly shows a black minivan colliding with a silver sedan. Upon impact, the silver sedan's hood crumples, and smoke is visible, indicating a clear accident with damage.

Severity Assessment



Score: 34 **Category:** MODERATE

Severity Criteria

Lane Blockage Score	2

Lane Blockage Evidence	Two vehicles are positioned in a collision blocking at least one traversable path on the paved surface.
Lane Blockage Confidence	0.8
Vehicle Count Score	1
Vehicle Count Evidence	Two vehicles are involved in the collision.
Vehicle Count Confidence	1.0
Vehicle Type Score	0
Vehicle Type Evidence	All involved vehicles are passenger vehicles (minivan/station wagon and sedan).
Vehicle Type Confidence	1.0
Hazards Score	3
Hazards Evidence	Smoke is clearly visible emanating from the front of the silver sedan.
Hazards Confidence	1.0
Vehicle Orientation Score	1
Vehicle Orientation Evidence	Both vehicles are upright but are angled relative to each other and the general direction of travel indicated by road markings.
Vehicle Orientation Confidence	0.9
Damage / Deformation Score	2
Damage / Deformation Evidence	The silver sedan has significant crumpling and deformation of the front hood. The dark grey vehicle also shows impact damage to its front right side. No cabin deformation is visible.
Damage / Deformation Confidence	0.9
Debris Extent Score	0
Debris Extent Evidence	No visible debris on the roadway.
Debris Extent Confidence	1.0
Fire Visible Trigger	NO
Rollover Confirmed Trigger	NO
Major Structural Collapse Trigger	NO
Full Roadway Blocked Trigger	NO
Large Debris Field Across Multiple Lanes Trigger	NO
Critical Unknown Count	0
Should Return Unknown	NO
Severity Notes / Uncertainty	

General Information

Camera ID	b300be2300a4005c0055fa36c4235c0a
Camera Name	RUBY LOCKHART AT ST. JOSEPH'S DR
Description	RUBY LOCKHART AT ST. JOSEPH'S DR
Public URL	https://strmr10.sha.maryland.gov/rtplive/b300be2300a4005c0055fa36c4235c0a/playlist.m3u8
Latitude	38.918093
Longitude	-76.84265
City	Lake Arbor
Categories	Wash. DC
Route	MD202[]
Milepost	9.13
Direction	
Direction Confidence	
Weather	sunny
Lane Count	
Operational Status	OK
Camera IP	strmr10.sha.maryland.gov

Vehicle Summary

Vehicle Count	2
Count Confidence	1.0
Type Confidence	1.0

People

People Visible	0
Injuries	UNKNOWN
Signs	
Confidence	0.0

Hazards

Fire	NO
Smoke	YES
Debris	NO
Fluid Spill	YES
Notes	Smoke is visible from the front of the silver sedan, indicating a potential engine issue or fluid leak.
Confidence	0.9

Lane Impact

Lanes Affected	
Shoulder	NO
Traffic Flow	stopped
Confidence	0.8
Notes	The two vehicles are positioned on a paved surface, effectively blocking at least one path of travel. The exact nature of 'lanes' in a highway context is unclear from the image, but the area of impact is obstructed.

Location in View

Region	center
Distance	medium
Lane	UNKNOWN
Shoulder	UNKNOWN
Median	UNKNOWN
Statement	Incident involving two vehicles on a paved roadway with white markings, possibly a parking lot or intersection, within the central frame of view.

Media Inputs

Unannotated Image	/home/group1/chart-incident-management/chart-incident-management/Final Detection From Video Files/accident_run_video_3xioiu7d/best_accident_frame_raw.jpg
Annotated Image	/home/group1/chart-incident-management/chart-incident-management/Final Detection From Video Files/accident_run_video_3xioiu7d/best_accident_frame_annotated.jpg
Video	/home/group1/chart-incident-management/chart-incident-management/Final Detection From Video Files/accident_run_video_3xioiu7d/accident_context_clip_raw.mp4