



More Definitions

DOE/DP (Department of Energy's Defense Program)

- Verification The process of determining, that a Computational Software implementation, correctly represents a model of a Physical Process.
- Validation Process of determining the degree to which a computer model is an accurate representation of the real world from the perspective of the intended model Applications