Quick Start for Simple Serial Interface to NDI Tracking Systems

- 1. Turn on Linux machine and log in.
- 2. Open a terminal, issue the following command
 - > cd ~/github/tracker-serial-interface

Stream mode: capture frames (all tools) at full speed	> ./track_server
Manual mode: capture one frame (all tools) when Enter is pressed	> ./track_server -m
Listen mode: monitor serial port for capture request packets	> ./track_server -1