Step 1: Change Request Overview

Requesting Company | Department | Ticket Number:	Multi Ply Paper | QA Section | Ticket No. 36728
Charge to:	Multi Ply QAS - QAIMP
Requested By | Contact Number:	Gerald Flores | +639178012778
Application | Program:	LS10
Date of Request:	June 6, 2025

Reason for Request:	**Type of Request:**	**Criticality:**
■ System Enhancement ☐ System / Application Error ☐ Human Error ☐ Others: _____	☐ Add ☐ Delete ■ Revise ■ Others: Enhancement	☐ Nice to Have ■ Must Have ☐ Show Stopper

Description of Change Request

To ensure that the Certificates of Analysis (COAs) being received by our customers are filled out with the necessary quality results.

Proposed Change

1. Quality results from "Maintain QC" table to be supplied to the corresponding COA rpt file whether weighing of the roll comes first before encoding of quality results into the said table.
2. Fix and prevent mix up of data encoded to Multi Ply (8898) Warehouses 1, 2, 3, and 4
3. Prevent blank or zero entries by copying the data from the preceding winder reel as the test frequencies are every other reel. Please see Fig. 2 and Fig. 3 for more info.
4. "NA" to appear on the CMT or Concora for all Test Liner or TL products. TL products, however, have Cobb test results.
5. "NA" to appear on Cobb Test results for all CM products. CM products, however, have CMT test results.

Reason for Change

The COAs being generated are reportedly not displaying the rolls' quality results from the "Maintain QC" table. The customers always require every delivery to have corresponding certificates of analysis containing the test results generated and obtained from the "Maintain QC" table encoded by the Quality Inspectors.

As sampled during the initial verification of the problem (Fig. 1), it can be observed that the **basis weight average** and **moisture** columns have no data, but the results were encoded into the system. There were also actual data encoded for the **Ring Crush** but on the COA, the values that appear are the minimum

value per specification. The same issue is being encountered for **Burst**. The quality results from the "Maintain QC" table do not automatically generate when the COA is being run.

MULTI PLY PAPER VENTURES INC.
Bo. Paralayunan, Mabalacat Pampanga

MULTIPLY

CERTIFICATE OF ANALYSIS

PRODUCT : *CM 140* WR NO. : *WR030028*
CUSTOMER : *TRIPLESTAR PACKAGING CORPORATION-PPS* TRUCK NO. : *RNA 529*

NO	ROLL ID	BASIS WT. (gsm)	MOISTURE (%)	CONCORA / CMT (kgf)	RING CRUSH / RCT (kgf)	BURST (kPa)	COBB TEST (actual)	
							TOP	BOTTOM
	Specification	*140 +/- 3%*	*6 - 9*	*target - 22.5 n*	*17 target - 15 mir*			
1	MP133C1005199	0.00	0.00	N/A	15.00	0.00	N/A	N/A
2	MP133C1303299	0.00	0.00	N/A	15.00	0.00	N/A	N/A
3	MP133C1206299	0.00	0.00	N/A	15.00	0.00	N/A	N/A
4	MP133C1303199	0.00	0.00	N/A	15.00	0.00	N/A	N/A

Fig. 1. COA of WR030028

Winder Reel Date : 13/03/2023

PN #	PN Reel Time	Set	Customer	INO No.	BW F	BW FC	BW C	BW BC	BW B	BW Ave
1	6:13	2.00	CE/LO	3C-0525	140.40	140.40	141.20	141.90	141.60	141.10
2	6:41	2.00	TR/LO	3C-0513	0.00	0.00	0.00	0.00	0.00	0.00
3	7:08	2.00	TR/LO	3C-0513	139.50	136.80	138.90	139.30	136.20	138.14
4	7:36	2.00	TR	3C-0572	0.00	0.00	0.00	0.00	0.00	0.00
5	8:04	2.00	TR	3C-0572	141.20	137.60	140.50	143.50	138.50	140.26
6	8:31	2.00	TR	3C-0572	0.00	0.00	0.00	0.00	0.00	0.00
7	9:00	2.00	TR	3C-0572	143.80	144.20	143.50	142.20	137.20	142.18
8	9:27	2.00	TR	3C-0572	0.00	0.00	0.00	0.00	0.00	0.00
9	9:55	2.00	TR	3C-0574	140.80	138.20	143.70	138.60	140.50	140.36
10	10:23	2.00	TR	3C-0574	0.00	0.00	0.00	0.00	0.00	0.00
11	10:50	2.00	TR	3C-0574	139.50	137.30	139.70	138.20	136.50	138.24
12	11:18	2.00	TR	3C-0574	0.00	0.00	0.00	0.00	0.00	0.00
13	11:46	2.00	TR	3C-0574	142.80	140.10	140.70	132.30	138.20	138.82
14	12:13	2.00	TR	3C-0573	0.00	0.00	0.00	0.00	0.00	0.00

Fig. 2. "Maintain QC" Table with BW Ave data of MP133C1303299 and MP133C1303199

Winder Reel Date : 13/03/2023

L*	a*	b*	RCT MD	RCT CD	CMT MD
58.17	5.70	22.69	13.90	10.30	10.40
57.95	5.76	22.78	13.80	10.40	0.00
57.82	5.66	22.86	13.80	11.10	10.90
57.58	5.68	22.87	13.50	10.90	0.00
57.57	5.59	22.66	13.60	10.80	10.70
57.37	5.69	22.71	13.20	11.60	0.00
57.36	5.59	22.42	13.40	11.20	10.90
57.09	5.59	22.42	13.10	11.40	0.00
57.20	5.63	22.38	13.20	11.50	10.80
57.21	5.73	22.40	13.40	11.40	0.00
57.52	5.66	22.30	14.30	11.10	10.90
57.34	5.70	22.36	14.10	11.20	0.00
57.34	5.84	22.76	14.20	11.30	11.00
57.44	5.81	22.70	14.00	11.30	0.00

Fig. 3. RCT and CMT data

If this kind of problem persists, the data in the Certificates of Analysis in every delivery will not be credible and the trust of our customers to our products' quality will be lost.

Impact Assessment

Using Multi Ply's Risk and Opportunities Assessment Procedure, MPP-QM-006(003)

Risk Assessment: Customer (S x Lx D = 8, Significant)
Severity: 2 – May result to customer complaint
Likelihood: 2 – Possible. Currently there are some customers that are particular to the COAs like Boxfield, Goodyear, Sunpack, Central, and United Container Corp.
Detection: 2 – with potential Engineering controls like IT improvements

Benefits: Customer (S x L = 6)
Severity: 2 – May enhance customer satisfaction/ increase positive feedback
Likelihood: 3 – Customer satisfaction may be realized within a year

Solution Recommendation

1. Quality results from "Maintain QC" table to be supplied to the corresponding COA rpt file whether weighing of the roll comes first before encoding of quality results into the said table.
2. Fix and prevent mix up of data encoded to Multi Ply (8898) Warehouses 1, 2, 3, and 4
3. Prevent blank or zero entries by copying the data from the preceding winder reel as the test frequencies are every other reel. Please see Fig. 2 and Fig. 3 for more info.
4. "NA" to appear on the CMT or Concora for all Test Liner or TL products. TL products, however, have Cobb test results.
5. "NA" to appear on Cobb Test results for all Corrugating Medium or CM products. CM products, however, have CMT test results.

Change Request Prepared By:	
Name: Gerald Regan C. Flores	Date: June 6, 2025
Signature:	

Step 2: Change Evaluation Analysis (To be filled out by the Consultant | ICT Personnel)	
Est Cost Impact:	
Comments:	

Reviewed By:	**Approved By:**
KIM BRYAN LOBRINO Application Development Supervisor	**JERWIN ALIMUIN** ICT Department Head

Step 3: Module Sign-Off by the Requesting Department's Team Leader	
Reviewed and Noted By:	**MDSR**
Signature:	
This acknowledges that any incurred cost will be charged to my department's budget.	
Affected Department (If applicable):	
Department:	**Shipping/SPEx**
Team Leader:	**Mr. Ronald F. Cunanan**
Signature:	
This acknowledges that I agree to the proposed changes.	

Step 4: Final Approver
Approved By:
JERRY MIRANDA Senior Vice President for Manufacturing