Sheet1

| Name F1 | State Register Transfer 0 [PC] → MAR | Control Lines opc, imar | Next State 1 | |
|---------------|--------------------------------------|--|--|--|
| | 1 [[MAR]] → MDR 2 [MDR] → IR | read, inhibit if not mfc omdr, iir | 2 if MFC = 1 1 if MFC = 0 3 | |
| | 3 [PC] + 1 → Q | opc, ib, p1, iq | 4 | |
| | | | 5 14 if ADD(X) | |
| F2 | 4 [Q] → PC 5 [PC] → MAR | oq, ipc opc, imar | or INC X 6 | |
| 1 2 | | ope, imai | 7 if MFC = 1 | |
| | 6 [[MAR]] → MDR | read inhibit if not mfc | 6 if MFC = 0 15 if JMP | |
| | 7 [PC] + 1 → Q | opc, ib, p1, iq | 8 | |
| | 8 [Q] → PC | oq, ipc | 9 | |
| S1 | 9 [MDR] → MAR | omdr, imar | 10 | |
| | 10 [[MAR]] → MDR | read, inhibit if not mfc | 11 if MFC = 1 10 if MFC = 0 | |
| | 44 [MDD] T4 | and the | 12 | |
| E1 | 11 [MDR] → T1 | omdr, it1 oac, ia, ib, iq | 16 if INC addr | |
| <u></u> | 12 [T1] + [AC] → Q 13 [Q] → AC | oq, iac | 13 0 | |
| | 10[6] - 110 | oq, 140 | 10 | |
| S2 | $14[X] \rightarrow MAR$ | ox, imar | 16 if INC X | |
| E2 | 15 [MDR] → PC | omdr, ipc | 0 | |
| E3 | $16 [T1] + 1 \rightarrow Q$ | ia, p1, iq | 17 | |
| | 17 [Q] → [MDR] | oq, imdr, write, Inhibit if not MFC | 0 if MFC = 1 17 if MFC = 0 | |
| | 7. [6] → [mp./] | THINGE IT FIGURE | 17 11 1011 0 | |
| IPC | T4 + T8 + T15 | Memory | Content | |
| OPC | T0 + T3 + T5 + T7 | | 0 b01000001000000000 | |
| IMAR | T0 + T5 + T9 + T14 | | 1 b000000010000000 | |
| IMDR | T17 | | 2 b001011111000000000 | |
| OMDR | T2 + T9 + T11 + T15 | | 3 b00110001000100100 | |
| Read Write | T1 + T6 + T10 T17 | | 4 b0000111000000000 5 b01000001000000000 | |
| Inhibit | T1 + T6 + T10 + T17 | | 6 b000000000000000000000000000000000000 | |
| IIR | T2 | | 7 b00110001000100100 | |
| IA | T12 + T16 | | 8 b00001110000000000 | |
| IB | T7 | | 9 b01000111000000000 | |
| P1 | T3 + T7 + T16 | | 10 b00000000010000000 | |
| IT1 IQ | T11 T3 + T7 + T12 + T16 | | 11 b11000111000000000 12 b00110010000001100 | |
| oQ | T4 + T8 + T13 + T17 | | 13 b00110010000001100 | |
| OX | T14 | | 14 b01000011000000000 | |
| IAC | T13 | | 15 b00001111000000000 | |
| OAC | T12 | | 16 b00110000000101000 | |
| Preset | T4 + T6 + T11 + T13 + T1 | 4 + T15 + T16 | 17 b10000110100000000 | |
| | | - · · - · · - · | | |

Sheet1

| D4 | T11 + T14 AND INC X |
|----|---------------------|
| D3 | T4 + T6 + T14 |
| D2 | T4 + T6 |
| D1 | T4 + T6 + T14 |
| D0 | Т6 |

Sheet1

| INC addr | High Lvl Register Transfers [[PC]] → IR | Name F1 |
|----------|--|------------|
| | [PC] + 1 → PC [[PC]] → MDR [PC] + 1 → PC | F2 |
| | [[MDR]] → T1 [T1] + 1 → MDR | S1 E3 |
| INC (X) | [[PC]] → IR [PC] + 1 → PC | F1 |
| | [[MDR]] → T1 | S1 |
| | [[X]] → T1 | S2 |
| | [T1] + 1 → Q | E3 |
| | $[Q] \rightarrow MDR$ | |