Prelab 3
Wednesday, February 18, 2026 9:59 PM

Name: Tahia Bano
PID: 6145164
Mail: tbano@ucsd.edu
Info: ECE
Group: 7

Ans. to the Q. No. 1(a)

RMS value of a square wave

From fig 1,
For one period, $T = 2$ sec, signal $f(t)$ is defined as:

$$f(t) = \begin{cases} 1 & 0 \le t \le 1 \\ 0 & 1 \le t < 2 \end{cases}$$

The RMS value is given by:

$$RMS = \sqrt{\frac{1}{T}\int_0^T (f(t))^2 dt}$$

$$= \sqrt{\frac{1}{2}\left[\int_0^1 (1)^2 dt + \int_1^2 (0)^2 dt\right]}$$

$$= \sqrt{\frac{1}{2}(1+0)}$$

$$\therefore \text{RMS value} = \frac{1}{\sqrt{2}} \approx 0.707$$

Ans. to the Q. No. 1(b)

RMS value of a sawtooth wave

From fig 2,
For one period, $T = 1$ sec, signal $f(t)$ is defined as:

$$f(t) = t \quad \text{for } -0.5 \le t < 0.5$$

The RMS value is given by:

$$RMS = \sqrt{\frac{1}{T}\int_0^T (f(t))^2 dt}$$

$$= \sqrt{\frac{1}{1}\left[\int_{-0.5}^{0.5} t^2 dt\right]}$$

$$= \sqrt{\frac{t^3}{3}\Big|_{-0.5}^{0.5}}$$

$$= \sqrt{\left(\frac{0.5^3}{3}\right) - \left(\frac{-0.5^3}{3}\right)}$$

$$= \sqrt{\frac{0.125}{3} + \frac{0.125}{3}}$$

$$= \sqrt{\frac{0.25}{3}}$$

$$= \frac{1}{\sqrt{12}}$$

$$= \frac{1}{2\sqrt{3}}$$

$$\therefore \text{RMS value} = \frac{1}{2\sqrt{3}} \approx 0.289$$

Ans. to the Q. No. 1(c)

RMS value of a sine wave

From fig 3,
For one period, $T = 4$ ms, signal $f(t)$ is defined as:

$$f(t) = \underbrace{2.4}_{B}\sin\left(\underbrace{\frac{\pi}{2}}_{\omega} t\right) \quad \text{for } 0 \le t \le 4, \text{ where}$$

peak amplitude (B) = 2.4 (maximum vertical displacement from 0)
period (T) = 4 ms (signal completes one full cycle from 0 ms to 4 ms)
angular frequency (ω) = $\frac{2\pi}{T} = \frac{2\pi}{4} = \frac{\pi}{2}$ rad/ms

The RMS value is given by:

$$RMS = \sqrt{\frac{1}{T}\int_0^T (f(t))^2 dt}$$

$$= \sqrt{\frac{1}{4}\int_0^4 (2.4\sin(\omega t))^2 dt}$$

$$= \sqrt{\frac{2.4^2}{4}\int_0^4 \sin^2(\omega t)\, dt}$$

Now, $\int_0^4 \sin^2(\omega t)\, dt = \int_0^4 \frac{1-\cos(2\omega t)}{2} dt$; [We know this identity: $\cos(2\theta) = \cos^2\theta - \sin^2\theta$
$\Rightarrow \sin^2\theta = \cos^2\theta - \cos(2\theta)$; $[\because \sin^2\theta + \cos^2\theta = 1]$
$\Rightarrow \sin^2\theta = 1 - \sin^2\theta - \cos(2\theta)$
$\Rightarrow 2\sin^2\theta = 1 - \cos(2\theta)$
$\therefore \sin^2\theta = \frac{1-\cos(2\theta)}{2}$]

$$= \frac{1}{2}\int_0^4 \left(1 - \cos(2\omega t)\right) dt$$

$$= \frac{1}{2}\left[\int_0^4 dt - \int_0^4 \cos(2\omega t)\, dt\right]$$

$$= \frac{1}{2}\left[t\Big|_0^4 - \frac{\sin(2\omega t)}{2\omega}\Big|_0^4\right]$$

$$= \frac{1}{2}\left[[4-0] - \left[\frac{\sin\left(2\left(\frac{\pi}{2}\right)(4)\right)}{2\left(\frac{\pi}{2}\right)} - \frac{\sin\left(2\left(\frac{\pi}{2}\right)(0)\right)}{2\left(\frac{\pi}{2}\right)}\right]\right] \quad [\omega = \tfrac{\pi}{2}]$$

$$= \frac{1}{2}\left[4 - \left(\sin(4\pi) - \sin(0)\right)\right]$$

$$= \frac{1}{2}\left[4 - (0-0)\right]$$

$$= \frac{1}{2}(4)$$

$$= 2$$

$$\therefore RMS = \sqrt{\frac{2.4^2}{4}(2)}$$

$$= \sqrt{\frac{2.4^2}{2}}$$

$$= \frac{2.4}{\sqrt{2}}$$

$$\therefore \text{RMS value} = \frac{2.4}{\sqrt{2}} \approx 1.697$$

Ans to the Q. No. 2(a)

The frequency at which the magnitude (dB) drops by 3dB from its max passband value.
From fig 4 or figure, the passband gain is 0 dB.
Locating -3 dB on the magnitude curve corresponds to a frequency of 10^{-5} Hz.
$\therefore$ Cutoff frequency $10^{-5} \approx 0.21\epsilon$ Hz.

Ans to the Q. No. 2(b)

Based on the amplitude-frequency plot (fig 5),
The filter has a max gain of 1 at low frequencies.
On a linear amplitude scale, the cutoff occurs when the amplitude is $\frac{1}{\sqrt{2}} \approx 0.707$.
In fig 5, 0.7 in the vertical amplitude axis is found when frequency (x-axis) is around 1.5×10^{5} Hz.
$\therefore$ Cutoff frequency $= 1.5\times10^{5}$ Hz

Ans to the Q. No. 2(c)

In figure 6,
The filter has a max gain of 1 at low frequencies.
On a linear amplitude scale, the cutoff occurs when the amplitude is $\frac{1}{\sqrt{2}} \approx 0.707$.
In fig 6, 0.7 in the vertical amplitude axis is found when frequency (x-axis) is around 1 (no units because x-axis is dimensionless frequency)
$\therefore$ Cutoff frequency = 1 (normalized).