

SW1
Pin Mode[1:5] with P1V8 Pull up

MODE5	MODE4	MODE3	MODE2	MODE1
ATE_TESTMODE	GPIO3	GPIO2	GPIO1	GPIO0


GPIO0 is connected to M.2 connector Pin 42


GPIO1 is connected to M.2 connector Pin 44

GPIO2 is connected to M.2 connector Pin 46

GPIO3 is connected to M.2 connector Pin 48

ATE_TESTMODE is connected to M.2 connector Pin 6





M.2 connector		Pin36	Pin22	Pin32			Pin46	
	JTAG16_P15	GND	M2_UART_TX2	M2_UART_RX	M2_UART_TX	JT_TCK	JT_TMS	GPIO_2
	M2_RESET#	JTAG16_VCC	GPIO_1	JT_TDO	GPIO_0	JT_RTCK	JT_TRST#	JT_TDI
M	.2 connecto	or	Pin44		Pin42	Pin67		