

LEGEND

- Circuit breaker
- Isolator / disconnector
- Contactor
- Fuse
- Protection relay
- Two-winding transformer
- Standby generator
- Automatic transfer switch
- Uninterruptible power supply
- Load / equipment

BOARD COMPONENTS & CONTROL GEAR (schedule):

- HV DC fuse on busbar link inside cassette (X-140)
- HV DC busbar link (ETP Cu, tin-plated) — short run connector-to-DC-link (X-141)
- AC Phase Busbar Pierce (X-105)

PROTECTION & METERING (callouts):

- Phase Current Sensor (I-1)
- Current Sensor (I-3)
- Resolver Signal Interface (X-151)
- Voltage Sensor (I-2)

FRACTIONAL FORGE · ForgeOS

SINGLE-LINE DIAGRAM — Formula e front mgu

Scope: major electrical distribution as modelled (projected from the connection schedule).

- Sealed traction pack: vehicle HV DC feeds the SiC MCU and IPMSM through the pack HV bus — not a plant LV switchboard.
- LV control, gate-drive, resolver and NTC signal paths are named below; detailed harness routing stays on the Connection trace.

Auto-generated · drawn ForgeOS auto-projection · not for construction.

DRAWING No.	FF-SLD-001
REV	P1
DATE	2026-08-05
SCALE	NTS

GENERAL TOLERANCES: ISO 2768-mK unless noted (linear & angular class m — medium, ISO 2768-1; geometrical class K, ISO 2768-2) · corrosion allowance per material schedule · dimensions in mm · not for construction