

Automotive Technician

Here are a few pictures from restoring a 1995 3.4L V6 Camaro along with my father as a personal project. I wish I had taken more of the technical work, but enjoy!



Figure 1: Moments after purchase from FaceBook Marketplace



Figure 2: Determining root cause of engine misfires from previous night




Figure 3: Preparing for rocker arm and timing belt adjustment



Figure 4: Removal of Seats and Interior Carpet




Figure 5: Grinding away rust to prevent further deterioration



Figure 6: Applying bondo to seal body



Figure 7: Going out for a ride with new red leather seats and removed T-tops