
DISPENSADOR DE ALIMENTOS

1. Black-Box



J	Κ	Q(t+1)
0	0	Q1
0	1	D
1	0	1
1	1	Qc

ENTRADA M				
M1	M0			
0	0	no moneda		
0	1	moneda 25		
1	0	moneda 50		
1	1	moneda 100		


SALIDA T	
Т	
0	NO
1	SI

M1	M2	ENTRADA
0	0	M0
0	1	25
1	0	50
1	1	100

C1	CO	CAMBIO
0	0	0
0	1	25
1	0	50
1	1	75

RUPIAS	C1	C0	
0	0	0	NO HAY CAMBIO
25	0	1	CAMBIO DE 25
50	1	0	CAMBIO DE 50
75	1	1	CAMBIO DE 75

2. DIAGRAMA DE ESTADOS



3. # F-F's y tipo

ENTRADAS: TIPO: # DE ESTADOS: # DE FLIP-FLOP:

M1 M0 / T C1 C0 JK $2^n \rightarrow n = 2$ n = 2

4. Asignación de números binarios

X	Υ	Z1Z0	Z1	Z0	A2A1A0	B2B1B0
0	0	0	0	0	000	000
0	1	25	5	5	010	101
1	0	50	0	0	101	000
1	1	75	7	5	111	101

A2 = X Q1 B2 = Y Q0 B2 = jQ0

A1 = Y Q0 B1= 0

A0 = X Q1 B0= Y Q0 B0 = ¡Q0

Q1Q0	A2A1A0	B2B1B0
01	010	101
10	101	000
11	111	101
00	000	000

A2 = !A*B + A*!B *(A♥B)

A1 = !Q0

A0= (Q1 ♥ Q0)

5. Tabla de Excitación

ENTR	ADAS	ESTADO	ACTUAL	ESTADO	FUTURO	EXCITA	ACION		SALIDAS	
M1	M0	Q1	Q0	Q1*	Q0*	JK1	JK0	T	C1	CO
0	0	0	0	0	0	0	0	0	0	0
0	0	0	1	0	1	0	0	0	0	0
0	0	1	0	1	0	0	0	0	0	0
0	0	1	1	1	1	0	0	0	0	0
0	1	0	0	0	1	0	1	0	0	0
0	1	0	1	1	0	1	1	0	0	0
0	1	1	0	1	1	0	1	0	0	0
0	1	1	1	0	0	1	1	1	0	0
1	0	0	0	1	0	1	0	0	0	0
1	0	0	1	1	1	0	1	0	0	0
1	0	1	0	0	0	1	0	1	0	1
1	0	1	1	0	0	1	0	1	1	0
1	1	0	0	0	0	0	0	1	0	0
1	1	0	1	0	0	0	1	1	0	1
1	1	1	0	0	0	1	0	1	1	0
1	1	1	1	0	0	1	1	1	1	1

MAPA DE KARNAUGH:

JK1						
Q1Q0	00	01	11	10		
M1M0	00	01	11	10		
00	0	0	0	0		
01	0	1	1	0		
11	0	0	1	1		
10	1	0	1	1		

JK1 = M1Q1 + M1!M0!Q0 + !M1M0Q0

 $JK1 = M1Q1 + (M1 \Leftrightarrow M0Q0)$

JKO						
Q1Q0	00	01	11	10		
M1M0	00	O1	11	10		
00	0	0	0	0		
01	1	1	1	1		
11	0	1	1	0		
10	0	1	0	0		

JK0 = !M1M0 + M0Q0 + M1!Q1Q0JK0 = M0 (jM1 + Q0) + M1!Q1Q0

		Т		
Q1Q0	00	01	11	10
M1M0	00	01	11	10
00	0	0	0	0
01	0	0	1	0
11	1	1	1	1
10	0	0	1	1

T = M1M0 + M1Q1 + MOQ1Q0T = M1 (M0 + Q1) + MOQ1Q0


C1					
Q1Q0	00	01	11	10	
M1M0	00	01	11	10	
00	0	0	0	0	
01	0	0	0	0	
11	0	0	1	1	
10	0	0	0	0	


C1 = M1M0Q1

CO					
Q1Q0	0	01	11	10	
M1M0	00	01	11	10	
00	0	0	0	0	
01	0	0	0	0	
11	0	1	1	0	
10	0	0	1	0	

C0 = M1M0Q0 + M1Q1Q0C0 = M1Q0 (M0 + Q1)


CIRCUITO:






ELECTRO MECANICA

1. Black-Box



2. DIAGRAMA DE ESTADOS



3. # F-F's y tipo

2^k=#estados

k=#F-F's

k=2

Tipo=D

4. Asignación de números binarios

Sn	# binario	
S0		00
S1		01
S2		10
Error		11

5. Tabla de Excitación

Α	Qb	Qa	Sn	Sn+	Qb+	Qa+	Db	Da
0	0	0	S0	S2	1	0	1	0
0	0	1	S1	SO	0	0	0	0
0	1	0	S2	Error	1	1	1	1
0	1	1	S3	Error	1	1	1	1
1	0	0	S0	S1	0	1	0	1
1	0	1	S1	Error	1	1	1	1
1	1	0	S2	S0	0	0	0	0
1	1	1	S3	Error	1	1	1	1

Db: (A xor Qa)' + Qb.Qa Da: (A xor Qb) + A.Qa

CIRCUITO:

