



WHAT IT IS

One shop-floor system in place of spreadsheets, paper forms and chat groups. Every shift is opened, run, checked and closed inside it — so **production, quality, maintenance and logistics read the same numbers at the same moment.**




IN USE TODAY

2 months live

202	27
operators tracked	production lines
518	109
machines & dies	part numbers
4,740	1,086
stop events logged	4M changes controlled
8,885	898
attendance + PPE records	PFMEA failure modes


BUILT ON

Platform	React 19 · PostgreSQL · realtime sync
Devices	Shop-floor TV · tablet · phone (installable)
Alerts	In-app · push · Telegram by topic
Control	11 roles · 35 forms · full audit log




THE DAILY OPERATING LOOP

one shift, eight steps



ONE ORDER, FULL TRACEABILITY



A customer concern is answered by searching one order number: **which shift and line, which machine and die, whether PM was overdue, who was at the station and their skill level, what 4M changed that day** — then matched back to the failure mode already listed in the PFMEA.

MODULE MAP

57 screens · 9 areas

Overview

- Live plant map (colour by OEE / downtime / manpower)
- Department dashboards
- Executive & group roll-up

Production

- Attendance & PPE · line manning by skill-fit
- Daily report · shift close approval
- Production planning (OT / night / holiday)

Analytics

- OEE / OOE / TEEP · true-OEE
- Root-cause engine (7 automatic findings)
- Order traceability · Value Stream Map

People

- Skill matrix 0-100 · auto EXP
- OJT training records
- Shift roster A/B/C

Logistics

- Store & kanban pull · rundown stock
- Delivery walk-back schedule
- Shortage alert · route & transport

Maintenance

- Work order 7 steps · response / MTTR KPI
- AM / PM planning & forecast
- Spare part rank A/B/C · QR scan

Quality

- Inspection check sheet
- SPC / Cp-Cpk · NCR · CAPA-8D
- Scrap report · CQI-15 log

Engineering

- Process flow · PFMEA · Control Plan
- Excel import / export
- Revision history by root cause

Master data

- Parts · BOM · routing
- Equipment & die registry
- Document control · role permission matrix

ALIGNED TO

- IATF 16949** Process approach, competence records, change control
- CQI-15** Welding event log with approval routing
- APQP / PPAP** PFMEA & Control Plan linked by operation no.
- 8D** 3-legged root cause from a real shift
- TPM** AM by operators · PM by technicians
- Lean** 6 big losses · 8 wastes · VSM · kaizen

WHAT IT CHANGES

- Answer in seconds, not days**
"Which shift, which machine, who ran it, was PM overdue, what changed?" — one search on the order number.
- Loss you can act on**
Every stop and defect is classified the moment it happens, then ranked by minutes and money.
- Change control that holds**
Any Man / Machine / Material / Method change raises a 4M record needing supervisor + QA approval before it runs. 35 controlled forms print from the system.