

**TIMBI OMNI HOLDINGS (PTY) LTD**

Company No: K2026275701

Hikvision Partner ID: 10382980

IT Specialists: Tshireletso Timbi | Siyabonga Dithale

076 223 4837

ttimbi51@gmail.com

Tshireletso@omnisecure.co.za

INSURANCE INSPECTION & REPLACEMENT REPORT

Date of Report: Saturday, 04 July 2026**Installation Address**

3 Langeberg Place

Azalea Park

Rustenburg

This report confirms that TIMBI Omni Technologies attended an after-hours emergency call-out on the instruction of Mrs Naidoo. The existing TF-8608 8 Channel DVR (S/N 354201502020168) was inspected and found to have faulty BNC input ports, failed network connectivity and a burnt power adapter which no longer supplied power to the outdoor cameras. The unit was declared unsuitable for continued use.

Replacement Installed

Hikvision 8 Channel DVR

Serial Number: GS3362354

New CCTV power supply, RG59 cable, BNC connectors, DC connectors and cable management were installed. The system was tested and confirmed operational.

Charges

Materials: R2,600.00

After-hours labour, installation and cable management: R3,700.00

Total: R6,300.00

Prepared by:

Tshireletso Timbi

IT Technician / IT Specialist

TIMBI Omni Technologies